

WISCONSIN MOTOR VEHICLE
CRASH REPORT

Location

ON STH23 WB 1295 FT S OF FELDMAN DR IN THE TOWN OF WESTFIELD IN SAUK COUNTY	Latitude 43.402195551	Longitude -90.032218666
	X Coordinate 254460.421875	Y Coordinate 4809946
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location SHOULDER RIGHT	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DUSK	
Road Surface Condition(s) SNOW, ICE	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR			Operating As Endorsements		
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With DITCH		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE RIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

Vehicle

VEHICLE	License Plate Number AEZ7008	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
	Vehicle Identification Number 2FMGK5B88HBA08118	Make FORD	Year 2017	Model FLEX	
	Color GRY - GRAY	Body Style UT - SPORT UTILITY VEHICLE		Bus Use	
	Initial Contact Point 00 - NON-COLLISION	Vehicle Damage			
	Extent Of Damage NO DAMAGE	00 - NO DAMAGE			



WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By STEVES AUTO SERVICE	
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions SPEED TOO FAST/COND			
01	Owner Name JADA GOODWIN		Owner Address 457 S CHURCH ST RICHLAND CENTER, WI 53581 , US	
	Sequence Of Events			
01	Event DITCH			
	Event			
	Event			
	Event			
UNIT	Policy Holder			
	Insurance Company PROGRESSIVE-CLASSIC-INS-CO		Individual JADA GOODWIN	
UNIT	Individual			
	Driver MARK BROOKS (608) 475-3067		Citations Issued 0	Sex MALE
	Address 457 S CHURCH ST RICHLAND CENTER, WI 53581 , US		Date of Birth	Race WHITE
			Driver License Number	
01	Safety Equipment		On Duty Crash	
			Safety Equipment SHOULDER & LAP BELT	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT		
	Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance		
001	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #
	Hospital		Date of Death	Time of Death
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
	Action Other					To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO		
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
	Drug Type						
	Individual Condition		APPEARED NORMAL				
	01	001					