6TL08WW13Q

19-13833

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	ingenity countries			ating Officer/Deputy ENANT E. VANDENHEUVEL			
Crash Date	Crash Time	Date Arrived		Time Arrived			
11/06/2019 Date Notified	09:56 AM Time Notified	11/06/2019 Total Units		10:09 AM Total Injured	Total Killed	1	
11/06/2019	10:07 AM	01		00	00		
On Emergency Hit	and Run Lane Clos		k Zone	Trailer or	Towed	Reporting Threshold	
Government Property	roperty Active School Zone NO		Tags				
Reportable	Distribution (Civildan Stradity		Amended		Secondary Crash		
Diagram Diagram					construction		
SLIDE OOR INJUOUS IN THE SECOND SERVING ON THE SECOND IN T	ot added any CJ	OR S data in this	Ad NO	otos By ditional Information			
UNIT 1 WAS WESTBOUND ON CT ROAD CONDITIONS. UNIT 1 CRC BEFORE COMING TO REST. OPE OBSERVED. UNIT 1 PULLED FRO	SSED THE CENTER LINE, DEPA ERATOR STATED HE WAS GOIN	RTED THE ROADV G "54" MPH WHEN	'AY LEFT, AND (HE LOST CONTE	CONTINUED AT L ROL. NO DAMAG	EAST 100 FI E OR INJUR	EET INTO A YARD IES REPORTED OR	
Location			1 00 1				
ON CTHH EB 509 FT E			Latitude 43.592007297	7	Longitud	de 6452015	
OF TOWN HALL RD IN THE TOWN OF DELLONA IN SAUK COUNTY			X Coordinate 264655.3125		Y Coord 483069	inate	
Structure Type					IDE		

6TL08WW13Q 19-13833

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Scene

First Harmful Event		First Harmful Event Location				
DITCH		SHOULDER LEFT				
Manner of Collision		Light Condition	Light Condition			
NO COLLISION W/VEHIC	CLE IN TRANSPORT	DAYLIGHT	DAYLIGHT			
Road Surface Condition(s)		Roadway Factor(s)				
SNOW, SLUSH						
Environment Factor(s)			-			
WEATHER CONDITIONS	WEATHER CONDITIONS Weather Condition(s)			ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)		
Weather Condition(s)						
SNOW						
Animal Type			Relation To Trafficway			
			TRAFFICWAY - ON ROAD			
Crash Classification - Locatio	n		Crash Classification - Jurisdiction			
PUBLIC PROPERTY			NO SPECIAL JURISDICTION			
Tribal Land			Access Control	Special Study		
			NO CONTROL			
Within Interchange Area	Junction Location	Intersection	tion Type			
NO	NON-JUNCTION	NOT AN	NOT AN INTERSECTION			

ı	In	iŧ	Si	ım	m	ar۱	,
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		.71			<i>a</i> ı \	•

	Onit Summary —						
	Unit Status		Vehicle Operating As Classification		Unit Type		
	IN TRANSIT		D CLASS	D CLASS		AUTOMOBILE	
_	Vehicle Type		•		Operating As Endorsements		
2	PASSENGER CAR						
İ	Total Occs	Train/Bus # Recorded	Total # Citations Issued Total Traile		ers	Total HazMat Types	
	1		0	0		0	
İ	Insurance?	Direction Of Travel	Pre CrashTire	Speed Lim	nit	Total Lanes	
l⊨	YES	EASTBOUND	ND Mark			2	
L	Most Harmful Event: Collision With		Special Function		Emergency Motor Vehicle Use		
_	DITCH		NO SPECIAL FUNCTION		NOT APPLICABLE		
İ	Traffic Way		Traffic Control		Traffic Control Inoperative/Missing		
	TWO-WAY, NOT DIVIDED		NO CONTROL		NO		
İ	Surface Type		Road Curvature		Road Grade		
	BLACKTOP (BITUMINOUS)	CURVE RIGHT		LEVEL		
1	Truck Bus or HazMat		•				
	NO						

	٧	е	hi	Cl

	License Plate Number	Plate Type	St	Country of Issuance		
	ADZ5381	AUT - AUTOMOBILE	WI	UNITED STATES		
	Vehicle Identification Number	Make	Year	Model		
9	3FA6P0HD7KR164156	FORD	2019	FUSION		
	Color	Body Style		Bus Use		
	CPR - COPPER	4D - 4DR		NOT A BUS		
Щ	Initial Contact Point	Vehicle Damage				
5	12FRONT					
포	Extent Of Damage	NO DAMAGE				
5	NO DAMAGE					
	Towed Due To Damage	Vehicle Removed By				
	NOT TOWED	OPERATOR				
	What Driver Was Doing	Vehicle Factors				
	GOING STRAIGHT					
	Driver Prior Action Other	NOT APPLICABLE				
	VEHICLE 01	ADZ5381 Vehicle Identification Number 3FA6P0HD7KR164156 Color CPR - COPPER Initial Contact Point 12FRONT Extent Of Damage NO DAMAGE Towed Due To Damage NOT TOWED What Driver Was Doing GOING STRAIGHT	ADZ5381 Vehicle Identification Number 3FA6P0HD7KR164156 Color CPR - COPPER Initial Contact Point 12FRONT Extent Of Damage NO DAMAGE Towed Due To Damage NOT TOWED What Driver Was Doing GOING STRAIGHT AUT - AUTOMOBILE Make FORD Body Style 4D - 4DR Vehicle Damage NO DAMAGE NO DAMAGE Vehicle Removed By OPERATOR	ADZ5381 Vehicle Identification Number 3FA6P0HD7KR164156 Color CPR - COPPER Initial Contact Point 12FRONT Extent Of Damage NO DAMAGE Towed Due To Damage NOT TOWED What Driver Was Doing GOING STRAIGHT AUT - AUTOMOBILE Wi Make Year 2019 Make Year Year Year Year AD - 4DR Vehicle Damage NO DAMAGE Vehicle Removed By OPERATOR Vehicle Factors		

6TL08WW13Q

19-13833

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN **1300 LANGE COURT BARABOO, WI 53913** (608) 356-4895

959 , US								
Event RUN OFF ROADWAY LEFT								
Event DITCH								
To.								
Sex MALE								
Race								
WHITE								
Driver License Number								
STATE: WISCONSIN COUNTRY: UNITED STATES								
LT								
Helmet Compliance								
Tint Compliance								
Trapped/Extricated								
NOT TRAPPED EMS Run #								
LIVIS INGILITY								
Time of Death								
I								

6TL08WW13Q

19-13833

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

I		Action							
LINI	INDIVIDUAL								
j 5	INDIV								
		Action Other						To/From School	
	L	Drug & Alcoh	Suspected Alcohol U	se	Suspected Drug Use NO				
		Alcohol Test Giver TEST NOT GIV	GIVEN		9		Alcohol Test Results		
		Drug Test Given TEST NOT GIVEN		Drug Test Type Drug Test Result					
6	Drug Type								
		Individual Condition							
		APPEARED NO	DRMAL						
	Pro	perty Owne	r 						
Government TOWNSHIP OF DELLONA (608) 524-0800					Address E8062 CTH H REEDSBURG, WI 539	59 , US			
		d Objects St	ruck						
	5	Striking Unit 01	Struck Object DITCH				Structure Number	Damage Tag Number	