

### Septic Suitability

*Legend*

Traditional Septic Probability

- High
- Moderate
- Low
- Very Low


This map shows initial septic suitability for "traditional" systems (conventional, at grade, mound) that were permitted prior to a change in state code-COMM 62 in 2000.

Boundaries

- Parcel Boundary
- Town of Ironton
- Town Boundaries
- County Boundary
- River/Stream

Transportation

- State Highway
- County Highway
- Town Road
- Municipal Street
- "400" State Trail



Source:  
Soil information including parcels, waterways and roadways produced by the Sank County Mapping Department.  
Soil information and interpretation courtesy of Natural Resources Conservation Service and United States Department of Agriculture.

