

APPENDIX

CHAPTER 9

SAUK COUNTY FLOODPLAIN ZONING ORDINANCE

SUBCHAPTER I

GENERAL PROVISIONS

9.002 General provisions.

(2) OFFICIAL MAPS AND REVISIONS.

(d) *Official Maps: based on other studies.* Any maps referenced in this section must be approved by the DNR and be more restrictive than those based on the FIS at the site of the proposed development.

4. Floodplain map dated August 24, 2005 and titled, "Hydraulic Shadow Dutch Hollow Lake Dam". Earthen dam failure boundary, shown in blue, between cross-sections XS #1 and XS #7, prepared by Vierbicher Associates, and floodplain map dated December 2, 2020 and titled "Dutch Hollow Dam Break Analysis 2021 Map Revision". Earthen dam failure boundary, shown in pink, between cross-sections XS #1 and XS #2, prepared by Vierbicher Associates. The dashed pink line in the "Dutch Hollow Dam Break Analysis 2021 Map Revision" represents the nearest developable area. The associated table in the "Dutch Hollow Dam Break Analysis 2021 Map Revision" updates elevations to North American Vertical Datum of 1988 (NAVD 88) from cross-sections XS#1 to XS#12. The updated NAVD 88 table shall only be used to reference elevations from X-Sec 3 through X-Sec 12. Elevations between X-Sec 1 and X-Sec 2 shall be interpolated off the "Dutch Hollow Dam Break Analysis 2021 Map Revision"

Amended by the Sauk County Board of Supervisors on June 15, 2021 – Ordinance No. ____ -21.