WISCONSIN MOTOR VEHICLE CRASH REPORT

Document Number Override	· · · · · · · · · · · · · · · · · · ·		,	Agency Crash Number Investigating 20-01639 DEPUTY E		Officer/Deputy : KNULL				
Crash Date 02/13/2020	Crash Time 04:58 AM			Date Arrived 02/13/2020		Time Arrived 05:18 AM				
O2/13/2020 Date Notified O2/13/2020 On Emergency Government Property				nits	Total Injured	Total Killed				
On Emergency	Hit and Run	✓ Lane Clo	sure	Work Zone	Trailer	or Towed	Reporting Threshold			
Government Property	Active S	School Zone	School Bus Related Tags			-				
Reportable	Crash Type DT4000 (ST	ANDARD CRAS	ASH)Amer			ed	Secondary Crash			
Description	escription									
Diagram						Reconstructio	··,			
Slide	off or	nly. N	lo			Photos By				
		•		hv						
	damage observed by Deputy on scene.									
Бери	ty Oii	30011	C.							
I, a sworn law enforce						ST SIDE DITCH	NO DAMAGE OP			
INJURIES. VEHICLE TOWED B		OTH 130. OPERA	ION LUST (CONTROL ON ICT RUAL	, WENT INTO WE	ST SIDE DITOR	. NO DAINAGE OR			

WISCONSIN MOTOR VEHICLE CRASH REPORT

L	_OC	ation ====									
·	ON	STH23 WB					Latitude			Longitud	de
	1031 FT E						43.53261	17573		-89.960	721698
	OF STH23 WB IN THE TOWN OF REEDSBURG						X Coordinate Y Coordinate			linate	
	IN SAUK COUNTY						260765.734375 4824223			23	
							Structure Type				
							NO STR	UCTURE			
(Cra	sh Scene									
T	First	Harmful Event					First Harm	nful Event Lo	ocation		
	DIT	СН					SHOULE	ER RIGH	Т		
-	Manı	ner of Collision					Light Cond	dition			
	00 -	NO COLLISION W/VE	HICLE IN TRANSPORT				DARK/UNLIT Roadway Factor(s)				
-	Road	Surface Condition(s)									
	SNC	NOW, ICE									
F	Envi	ronment Factor(s)									
	WE	ATHER CONDITIONS					ROAD S	URFACE	CONDITION	(WET, IC	CY, SNOW, SLUSH,
f	Wea	ther Condition(s)					1				
	CLC	OUDY, BLOWING SNC	w								
ŀ	Anim	al Type						o Trafficway			
-	Crash Classification - Location						TRAFFICWAY - NOT ON ROAD				
		BLIC PROPERTY					Crash Classification - Jurisdiction NO SPECIAL JURISDICTION				
	Tribal Land						Access Control Special Study				
							NO CONTROL				
		n Interchange Area	Junction Location			Intersection	on Type				
L						NOT AN INTERSECTION					
					Reaso	Reasons for Closure					
L		IE CLOSURE									
	Date Initial Lane/Rd Closed Time Initial Lane/Rd Closed				TOW	TRUCK					
L	02/13/2020 06:32 AM			- I -			Constant				
	Date All Lanes Open Time All Lanes Open 02/13/2020 06:52 AM				Date Scene Cleared 02/13/2020				Time Scene Cleared 07:01 AM		
L			00.32 AW		02/13	0/2020		07	.VI AIVI		
		Summary =		1.7.1.					T		
		Status			-	erating As C	lassification		Unit Type		
		RANSIT		DC	LASS				TRUCK Operating As Endorsements		manta
		cle Type LITY TRUCK/PICKUP	TRUCK						Operating As	Endorse	ments
L			Train/Bus # Recorded	Tota	I # Cita	tions Issued		Total Trail	ers	Total Haz	:Mat Types
	Total Occs Train/Bus # Recorded			0			0			0	//
L	Insurance? Direction Of Travel			-	Pre CrashTire						es
	UNKNOWN WESTBOUND				Mark		•	55		2	
	Most Harmful Event: Collision With S				Special Function NO SPECIAL FUNCTION		TION	1		mergency Motor Vehicle Use OT APPLICABLE	
) I CII				raffic Control			Traffic Control Inoperative/Missing		
	TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) NO CONT Road Curva STRAIGH			CONTROL			NO				
j				Road	Road Curvature			Road Grade			
L				STRAIGHT			UPHILL				
	Trucl	k Bus or HazMat									
1		Vehicle									
				Pla	Plate Type			St	Country of Issuance		
	Vehicle Identification Number Make			LTK - LIGHT TRUC			Year		UNITED STATES		
					Model						
5	6	1GTEC19R6TE52345	54	GE	NERA	L MOTOR	S COR	1996	SIERRA		

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Color	Body Style		Bus Use				
		TRQ - TURQUOISE Initial Contact Point	PK - PICKUP Vehicle Damage						
LIND	끘	00 - NON-COLLISION	Verliele Barriage						
	VEHICLE	Extent Of Damage	00 - NO DAMAGE	00 - NO DAMAGE					
_	K	NO DAMAGE							
		Towed Due To Damage		Vehicle Removed By					
		TOWED BUT NOT DUE TO DISABLING DAMAG What Driver Was Doing	STEVES AUTO SERVICE Vehicle Factors						
		GOING STRAIGHT	Verlicie Factors						
		Driver Prior Action Other	NOT APPLICABLE						
		Driver Actions							
L١	쁫	SPEED TOO FAST/COND							
LNO	呈								
٦	VEHICL								
		Owner Name EVARISTO ARRIETA	Owner Address						
2	5	(608) 957-3782	230 W WISCONSIN ST #5 PORTAGE, WI 53901 , US						
	;	Sequence Of Events							
	2	Event DITCH							
	0								
	05	Event							
	03	Event							
		Event							
	04								
	ı	<u>Individual</u>							
		Driver PEDRO MIRANDA	Citations Issued		Sex				
	A F	(608) 963-1862	Date of Birth		MALE Race				
∟ l	INDIVIDUAL		Date of Billi		HISPANIC				
	₹	Address	Driver License Nu	Driver License Number					
٦	2	503 7TH ST BARABOO, WI 53913	STATE: WISCONSIN COUNTRY: UNITED STATES						
	_	DAKABOO, W 33313 , 00							
		On Duty Crash	Safety Equipment	Safety Equipment					
	Sat	fety Equipment							
		Row Seat Position	SHOULDER & LAP BELT						
		01 - FRONT ROW 07 - LEFT							
		Helmet Use	Helmet Compliance						
		Eye Protection	Tint Compliance						
۶	00	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYE	 ED					
		Ejected Ejection Path	Trapped/Extricated						
		NOT EJECTED NOT EJECTED/NOT AI			NOT TRAPPED				
		Medical Transport NOT TRANSPORTED	EMS Agency Iden	itifier	EMS Run #				
		Hospital	Date of Death		Time of Death				
		·							

WISCONSIN MOTOR VEHICLE CRASH REPORT

			NOT APPLICABL	E (NOT DISTRAC	CTED)			
		Distracted By Action NOT DISTRACTE						
		Non Motorist	Striking Unit #	Location				
		Prior Action						
		Action						
	JAL							
L	INDIVIDUAL							
	INDI							
		Action Other						To/From School
	L	Drug & Alcohol	Suspected Alcohol U NO	se	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
2	001	Drug Type						
		Individual Condition						
		NOT OBSERVED						