6TL08F2KVS

19-00930

WISCONSIN MOTOR VEHICLE CRASH REPORT

	Document Number Override	Primary Crash Do	ocument #	Agency 19-009	Crash Number 30		stigating Off PUTY T. S		
0	Crash Date 01/23/2019	Crash Time 10:15 AM Time Notified 10:20 AM		01/23/2019 10:42		e Arrived 12 AM			
UI LUOF ZNV J	Date Notified 01/23/2019						Total Injured Total Killed 00 00		ed
-00-	On Emergency	t and Run	Lane Clos	ure	Work Zone		Trailer or	Towed	Reporting Threshold
	Government Property	Active Sch	ool Zone	School NO	Bus Related	Tags	6		
	✓ Reportable	Crash Type DT4000 (STAN	IDARD CRASH	H)			Amended		Secondary Crash
l	Description							econstructio	- Du
		Power Pole			01	Ø	Ad	notos By Iditional Info ONE	ormation
	Not To Scale	STH 154					_		
	Not To Scale	ent officer. agree	e that I have n	ot added	any CJIS data in	this repo	rt.		
	ON 01-23-19 VEHICLE OPERATO	OR WAS EASTBOL	JND ON STH 154	4 AND LO	ST CONTROL OF TR	UCK ON SI	NOW COVE		
	SOUTH DITCH LINE AND STRUC SNOW. NO INJURIES REPORTED		POWER PULE.	IRUCK C	AWE TO REST IN THE	= 5001H L	IT CH LINE	AND BECA	IVIE STUCK IN THE

19-00930

WISCONSIN MOTOR VEHICLE CRASH REPORT

	Loc	ation									
Ī	ON STH154 EB						Latitude			Longitude	
	345 FT E						43.405490473		-90.171440143		
		RUSTIC VIEW RD HE TOWN OF WASHI		X Coordinate		Y Coordinate					
		AUK COUNTY	243200 4810732			32					
					Structure Type NO STRUCTURE						
	Cra	sh Scene									
ī		Harmful Event				First Harm	nful Event L	ocation			
	UTII	LITY POLE				SHOULDER RIGHT					
ŀ	Man	ner of Collision				Light Condition DAYLIGHT					
	NO	COLLISION W/VEHIC	LE IN TRANSPORT								
ſ	Road	d Surface Condition(s)			Roadway Factor			(s)			
	SNC	W									
ľ	Envi	ronment Factor(s)									
	WE	ATHER CONDITIONS				ROAD S ETC)	URFACE	CONDITION	I (WET, IC	CY, SNOW, SLUSH,	
Ī	Wea	ther Condition(s)									
	SNC	w									
ŀ	Anim	al Type				Relation To Trafficway					
								OT ON ROA	D		
		h Classification - Location				Crash Classification - Jurisdiction NO SPECIAL JURISDICTION					
ŀ	-	al Land				Access Co				Special Study	
						NO CONTROL					
[Within Interchange Area Junction Location Intersection									
l	NO		NON-JUNCTION		NOTAN	AN INTERSECTION					
		t Summary		Viabiala Ora	antin a An Ol						
	Unit Status Vehicle Operating As C IN TRANSIT B CLASS				erating As Ci	Classification Unit Type					
-	IN TRANSIT B CLASS Vehicle Type					Operating As Endorsements			ments		
6	STRAIGHT TRUCK (INSERT TRUCK)										
ľ	Total Occs Train/Bus # Recorded			Total # Cita	tions Issued		Total Tra	lers	Total Haz	Mat Types	
	1			1		0		0			
	Insurance? Direction Of Travel YES EASTBOUND			Pre	Pre CrashTire		Speed Lir 55		Total Lan 2	es	
		/ES EASTBOUND //ost Harmful Event: Collision With			Mark Special Function			Emergency	ency Motor Vehicle Use		
5					NO SPECIAL FUNCTION			NOT APP			
ľ		ic Way		Traffic Cont	Traffic Control NO CONTROL Road Curvature CTD ALOUT			Traffic Control Inoperative/Missing NO Road Grade		tive/Missing	
		D-WAY, NOT DIVIDED									
		ace Type CKTOP (BITUMINOU)	C)	Road Curva STRAIGH							
ŀ		k Bus or HazMat	5)	STRAIGH	1	LEVEL					
			BINATION > 10,000LBS G	WWR/GCWR							
		Vehicle									
		License Plate Number			Plate Type		St	Country of Issuance			
					HTK - HEAVY TRUCK		MN	UNITED STATES			
		0345PRA					Veer	N4 1 1			
6	01			Make		DR TRU	Year 2016	Model BOX TRUC	ж		
01	01	0345PRA Vehicle Identification Nur 2NKHHM7X6GM4630 Color		Make KENWOF Body Style	RTH MOTO	DR TRU		BOX TRUC Bus Use			
01		0345PRA Vehicle Identification Nur 2NKHHM7X6GM4630 Color WHI - WHITE		Make KENWOF Body Style 2D - 2DR	RTH MOTO	DR TRU		BOX TRUC			
IT 01	Е	0345PRA Vehicle Identification Nur 2NKHHM7X6GM4630 Color		Make KENWOF Body Style	RTH MOTO	OR TRU		BOX TRUC Bus Use			
UNIT 01		0345PRA Vehicle Identification Nur 2NKHHM7X6GM4630 Color WHI - WHITE Initial Contact Point		Make KENWOF Body Style 2D - 2DR Vehicle Da	RTH MOTO			BOX TRUC Bus Use			

6TL08F2KVS

19-00930

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage	Vehicle Removed By							
		NOT TOWED	ARNESON SERVICE							
		What Driver Was Doing	Vehicle Factors							
		GOING STRAIGHT								
		Driver Prior Action Other	NOT APPLICABLE							
		Driver Actions								
	ш	SPEED TOO FAST/COND								
н										
UNIT	H									
2	VEHICL									
	-									
		Owner Name	Owner Address							
~	1	RESTAURANT TECHNOLOGIES	2250 PILOT KNOB ROAD MILWAUKEE, WI 53225 ,US							
5	01	(800) 327-3636								
		Sequence Of Events								
	01	Event DITCH								
	02	Event UTILITY POLE								
	03	Event								
		Event								
	04									
E		Policy Holder								
UNIT		Insurance Company	Organization/Company RESTAURANT TECHNOLOGIES							
		HARTFORD-FIRE-INS-CO								
		Individual								
		Driver CROS COLN	Citations Issued	Sex MALE						
	AL	(219) 433-3032	Date of Birth	Race						
⊢	NDIVIDUA			BLACK						
UNIT	N	Address	Driver License Number							
	ND	8713 W APPLETON AVE MILWAUKEE, WI 53225 ,US	STATE: WISCONSIN COUNTRY: UNITED STATES							
	-									
		On Duty Crash	Safety Equipment							
	Saf	fety Equipment	SHOULDER & LAP BELT							
		Seat Position								
		1FRONT SEAT-LEFT SIDE (DRIVER/MOTORCY								
		Helmet Use	Helmet Compliance							
		Eye Protection	Tint Compliance							
2	001	Injury Severity	Airbag							
	0		NON DEPLOYED	Trapped/Extricated						
		Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT APF		NOT TRAPPED						
		Medical Transport	EMS Agency Identifier	EMS Run #						
		NOT TRANSPORTED								
		Hospital	Date of Death	Time of Death						
		Distracted By Source								
		Distracted By Action								
		NOT DISTRACTED								

6TL08F2KVS

19-00930

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Non Motorist	Striking Un	nit #	Location						
		Prior Action									
		Action									
	_										
⊢	UAI										
UNIT	INDIVIDUAL										
	IND										
		Action Other								To/From School	
		Suspected Alcohol Use Suspected Drug Use									
	L	Drug & Alcohol Alcohol Test Given	NO		Alcohol Test Type	NO			Alcohol Test Results		
		TEST NOT GIVEN			Alcohol Test Type				Alcohor rest Results		
		Drug Test Given TEST NOT GIVEN	Test Given Γ NOT GIVEN		Drug Test Type			Drug Test Re	esults		
6	001	Drug Type									
	0										
		Individual Condition									
		APPEARED NORMAL									
		Violations UTC Number	Issue To?	Stati	ute Number	Descri	ation				
	0	BB336962	001		.57(3)		NG TOO FAST		DITIONS		
	(Carrier Source									
		Use Vehicle Owner Same as Carrier					DRIVER				
2	01	Name RESTAURANT TECHNOLOGIES				Address 2250 PILOT KNOB ROAD					
		USDOT# 0868				MILWAUKEE,	, WI 53225,	, US			
	BUS	GVWR Vehicle C			onfiguration			Cargo Body Type			
١	Bl	10,001-26,000 LBS US DOT #		SINGLE-I	LE-UNIT TRUCK (2-AXLE AND GVWR MORE THA				A VAN/ENCLOSED BOX Permitted Load		
	JCK	0868454 INTERS		INTERST	TATE CARRIER			NOT APPLICABLE			
	TRUCK	OS/OW Load			Permitted Vehicle On Escort Vehicle Required Permitted Route By Permit			By Permit	Escort Vehicle Present		
		Measured Height		Measure	ed Length		Measured Width		Measured Weight		
	Pro	perty Owner									
01	Orga	nization/Company				Address 4902 N	BILTMORE				
PROP OWNER	(608) 000-0000					MADISON, WI 53707 1077, US					
	Fixe	d Objects Stru	ck								
	01	Striking Unit Str	uck Object	-					Structure Number	Damage Tag Number	
	0	01 UT		LE						19-00930	