WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

O		Agency Crash Number 20-01932	Investigating Officer/Deputy DEPUTY A. BREUNIG	
Crash Date 02/20/2020	Crash Time 07:35 AM	Date Arrived 02/20/2020	Time Arrived 11:12 AM	
Date Notified 02/20/2020	Time Notified 10:48 AM	Total Units 01	Total Injured Total Killed 00	
On Emergency	lit and Run La	ne Closure Work Zor	ne Trailer or Towed Reporti	
Government Property	Active School Zo	School Bus Related NO	Tags	
▼ Reportable	Crash Type DT4000 (STANDARI	CRASH)	Amended Second	
Description Diagram	•			
>	9		Photos By	
			Additional Information NONE	
	LYNDON RD			
NOT	TO SCALE			

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/20/2020

Crash Time 07:35 AM

	0.64 OF	LYNDON RD 4 MI N CTHH NB THE TOWN OF DELLON	JΔ		43.6261 X Coordin	Latitude 43.62610057 X Coordinate		Longitude -89.856842446 Y Coordinate		
		SAUK COUNTY	1 0		269517		4834312			
					Structure	Structure Type				
(Cra	sh Scene								
Ī		Harmful Event			First Har	mful Event	Location			
	TRE	E			ON RO	ADWAY				
		ner of Collision			_	Light Condition				
		NO COLLISION W/VEH	HICLE IN TRANSPORT			DAYLIGHT				
		d Surface Condition(s)			Roadway	Roadway Factor(s)				
	ICE									
Ī	Envi	ironment Factor(s)								
	NOI	NE			NONE					
ŀ	Wea	ather Condition(s)								
	CLE	EAR								
-	Anin	nal Type			Relation To Trafficwa		av			
							ON ROAD			
-		sh Classification - Location					n - Jurisdiction JRISDICTION			
	_	BLIC PROPERTY								
	Triba	al Land			Access C NO COI		Special Study			
-	With	in Interchange Area	Junction Location	In	Intersection Type					
	NO		NON-JUNCTION	N	OT AN INTERSI	ECTION				
Į	Jni	t Summary								
	11.5	it Status Vehicle Operating As C				- 71				
	-			•	ing As Classificatio	""		D		
	IN T	TRANSIT		D CLASS	ing As Classificatio		AUTOMO			
	IN T			•	ing As Classificatio		AUTOMO	BILE As Endorsements		
	Vehi	TRANSIT icle Type	Train/Bus # Recorded	•		Total Tr	AUTOMO Operating A			
	Vehi PAS Tota 1	TRANSIT icle Type SSENGER CAR al Occs		D CLASS		Total Tr	AUTOMO Operating A	As Endorsements Total HazMat Types 0		
01	IN T Vehi PAS Tota 1	TRANSIT icle Type SSENGER CAR al Occs rance?	Direction Of Travel	Total # Citation 0	s Issued	Total Tr 0 Speed L	AUTOMO Operating A	Total HazMat Types O Total Lanes		
10	Vehi PAS Tota 1 Insur	FRANSIT icle Type SSENGER CAR al Occs rance?	Direction Of Travel SOUTHBOUND	Total # Citation 0	s Issued ashTire ark	Total Tr	AUTOMO Operating A	Total HazMat Types O Total Lanes 2		
01	Vehi PAS Tota 1 Insur	TRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision W	Direction Of Travel SOUTHBOUND	Total # Citation 0	s Issued ashTire ark	Total Tr 0 Speed L	AUTOMO Operating A	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
10	IN T Vehi PAS Tota 1 Insu YES Mos: TRE	FRANSIT icle Type SSENGER CAR II Occs rance? S t Harmful Event: Collision W EE	Direction Of Travel SOUTHBOUND	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control	s Issued ashTire ark n - FUNCTION	Total Tr 0 Speed L	AUTOMO Operating A ailers imit Emergency NOT APP Traffic Cont	Total HazMat Types O Total Lanes 2 Motor Vehicle Use		
I.O	IN T Vehi PAS Tota 1 Insu YES Most TRE Traff	FRANSIT icle Type SSENGER CAR II Occs rance? S t Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED	Direction Of Travel SOUTHBOUND	D CLASS Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO	s Issued ashTire ark n - FUNCTION	Total Tr 0 Speed L	AUTOMO Operating A ailers Emergency NOT APP Traffic Cont NO	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing		
I.O	IN T Vehi PAS Tota 1 Insu YES Moss TRE Traff TWO	FRANSIT icle Type SSENGER CAR II Occs rance? S It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type	Direction Of Travel SOUTHBOUND //ith	D CLASS Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature	s Issued ashTire ark n - FUNCTION	Total Tr 0 Speed L	AUTOMO Operating A ailers Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing		
10	IN T Vehi PAS Tota 1 Insu YES Mos: TRE Traff TWO Surfa	FRANSIT icle Type SSENGER CAR II Occs rance? S t Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED	Direction Of Travel SOUTHBOUND //ith	D CLASS Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO	s Issued ashTire ark n - FUNCTION	Total Tr 0 Speed L	AUTOMO Operating A ailers Emergency NOT APP Traffic Cont NO	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing		
10	IN T Vehi PAS Tota 1 Insu YES Mos: TRE Traff TWO Surfa	FRANSIT icle Type SSENGER CAR il Occs rance? S It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ik Bus or HazMat	Direction Of Travel SOUTHBOUND //ith	D CLASS Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature	s Issued ashTire ark n - FUNCTION	Total Tr 0 Speed L	AUTOMO Operating A ailers Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing		
10	IN T Vehi PAS Tota 1 Insu YES Mos TRE Traff TWO Surfa BLA Truc NO	FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS kk Bus or HazMat	Direction Of Travel SOUTHBOUND //ith	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT	s Issued ashTire ark n - FUNCTION	Total Tr 0 Speed L 55	AUTOMO Operating A allers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		
I.O	IN T Vehi PAS Tota 1 Insu YES Mos TRE Traff TWO Surfa BLA Truc NO	FRANSIT icle Type SSENGER CAR II Occs rance? S It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ek Bus or HazMat Vehicle License Plate Number	Direction Of Travel SOUTHBOUND //ith	D CLASS Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEF	s Issued ashTire ark n - FUNCTION DL	Total Tr 0 Speed L 55	AUTOMO Operating A ailers Limit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		
10	IN T Vehi PAS Tota 1 Insu YES Mos TRE Traff TWO Surfa BLA Truc NO	FRANSIT icle Type SSENGER CAR II Occs rance? S It Harmful Event: Collision W. EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ER Bus or HazMat Vehicle License Plate Number AGN9698	Direction Of Travel SOUTHBOUND //ith	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT	s Issued ashTire ark n - FUNCTION DL	Total Tr 0 Speed L 55	AUTOMO Operating A ailers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		
	IN T Vehi PAS Tota 1 Insu YES Mos TRE Traff TWO Surfa BLA Truc NO	FRANSIT icle Type SSENGER CAR II Occs rance? S It Harmful Event: Collision W EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ek Bus or HazMat Vehicle License Plate Number	Direction Of Travel SOUTHBOUND //ith	D CLASS Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEF	s Issued ashTire ark n - FUNCTION DL	Total Tr 0 Speed L 55	AUTOMO Operating A ailers Limit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		
ONI OT	IN T Vehi PAS Tota 1 Insur YES Mos: TRE Traff TWO Surfa BLA	FRANSIT icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision W. EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ER Bus or HazMat Vehicle License Plate Number AGN9698 Vehicle Identification Num	Direction Of Travel SOUTHBOUND //ith	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make	s Issued ashTire ark n - FUNCTION DL	Total Tr 0 Speed L 55	AUTOMO Operating A ailers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		
01 01	IN T Vehi PAS Tota 1 Insur YES Mos: TRE Traff TWO Surfa BLA	TRANSIT icle Type SSENGER CAR II Occs rance? St Harmful Event: Collision Well Effic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS EX Bus or HazMat Vehicle License Plate Number AGN9698 Vehicle Identification Num 1HGEM22561L019667	Direction Of Travel SOUTHBOUND //ith	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make HONDA Body Style CP - COUPE	s Issued ashTire ark FUNCTION DL GT DMOBILE	Total Tr 0 Speed L 55	AUTOMO Operating A Tailers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S Model CIVIC	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		
01 ONI 01	IN T Vehi PAS Tota 1 InsuryES Most TREE Truck BLA Truck NO	TRANSIT icle Type SSENGER CAR II Occs Trance? St Harmful Event: Collision W. EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS EX Bus or HazMat Vehicle License Plate Number AGN9698 Vehicle Identification Num 1HGEM22561L019667 Color BLK - BLACK Initial Contact Point	Direction Of Travel SOUTHBOUND //ith	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make HONDA Body Style	s Issued ashTire ark FUNCTION DL GT DMOBILE	Total Tr 0 Speed L 55	AUTOMO Operating A Tailers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S Model CIVIC	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		
01 ONI 01	IN T Vehi PAS Tota 1 InsuryES Most TREE Truck BLA Truck NO	ITRANSIT icle Type SSENGER CAR II Occs rance? S It Harmful Event: Collision W. EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS EX Bus or HazMat Vehicle License Plate Number AGN9698 Vehicle Identification Num 1HGEM22561L019667 Color BLK - BLACK Initial Contact Point 12 - FRONT	Direction Of Travel SOUTHBOUND //ith	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make HONDA Body Style CP - COUPE Vehicle Dama	s Issued ashTire ark FUNCTION DL OMOBILE	Total Tr 0 Speed L 55	AUTOMO Operating A Taillers Limit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S' Model CIVIC Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL ssuance TATES		
	IN T Vehi PAS Tota 1 InsuryES Most TREE Truck Surfa BLA Truck NO	TRANSIT icle Type SSENGER CAR II Occs Trance? St Harmful Event: Collision W. EE fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS EX Bus or HazMat Vehicle License Plate Number AGN9698 Vehicle Identification Num 1HGEM22561L019667 Color BLK - BLACK Initial Contact Point	Direction Of Travel SOUTHBOUND Vith ber	Total # Citation 0 Pre Cra Ma Special Function NO SPECIAL Traffic Control NO CONTRO Road Curvature CURVE LEFT Plate Type AUT - AUTO Make HONDA Body Style CP - COUPE Vehicle Dama	s Issued ashTire ark FUNCTION DL OMOBILE	Total Tr 0 Speed L 55	AUTOMO Operating A Taillers Limit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S' Model CIVIC Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE trol Inoperative/Missing e LL		

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

		Towed Due To Damage		Ve	hicle Removed By				
		NOT TOWED		OV	VNER				
		What Driver Was Doing		Vehicle Factors					
		NEGOTIATING CURVE							
		Driver Prior Action Other		NC	OT APPLICABLE				
		Driver Actions							
	щ	FAILURE TO CONTROL							
╘	VEHICLE								
LINO	Ĭ								
_	8								
		Owner Name SALLY KAY MCDOWELL (608) 434-2675			Owner Address				
5	2			S132 LYNDON RD WISCONSIN DELLS, WI 53965, US					
0		(000) 101 - 010			,				
		Common Of France							
	,	Sequence Of Events Event							
	9	RUN OFF ROADWAY RIG	НТ						
	05	Event REENTERING ROADWAY	,						
	~~	Event							
	03	RUN OFF ROADWAY LEF	T						
	04	TREE							
_	1	Policy Holder							
UNIT		Insurance Company			Individual				
ر		AMERICAN-FAMILY-INS-CO			SALLY MCDOWELL				
	ı	Individual							
		Driver		1	Citations Issued	Sex			
	إ	SALLY KAY MCDOWELL (608) 434-2675			0	FEMALE			
_	INDINIDUAL				Date of Birth	Race WHITE			
UNI	1	Address		_	Driver License Number				
5	₫	S132 LYNDON RD WISCONSIN DELLS, WI 53965, US			STATE: WISCONSIN COUNTRY: UNITED STATES				
	Z								
	0-1	On Duty Crash		Safety Equipment					
	Sa	fety Equipment							
		Row	Seat Position	;	SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LEFT	Halmat Campliana					
		Helmet Use		Helmet Compliance					
		Eye Protection			Tint Compliance				
_	Ξ	Injury Severity			Airbag				
2 8		110 111 1111			NON DEPLOYED				
		Ejected	Ejection Path			Trapped/Extricated			
		NOT EJECTED NOT EJECTED/NOT A				NOT TRAPPED			
		Medical Transport			EMS Agency Identifier	EMS Run #			
		NOT TRANSPORTED		_	Date of Dooth	Time of Death			
		Hospital		[Date of Death	Time of Death			
		Distracted Pu	ed By Source						
		Distracted By NOT A	PPLICABLE (NOT DISTR	(AC	IED)				
	Distracted By Action NOT DISTRACTED								

Crash Time 07:35 AM

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/20/2020

Crash Time 07:35 AM

		Non Motorist	Striking Unit #	Location				
		Prior Action						
LIND	INDIVIDUAL	Action						Tarran Osbasi
		Action Other						To/From School
	I	Drug & Alcohol	Suspected Alcohol L NO	Jse	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN	l	Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	I	Drug Test Type	Drug Test Resu			
2	001	Drug Type						
		NOT OBSERVED						