#### 6TL0BNZM1S 20-13973

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

					(000) 330-403	
Document Number Override	Primary Crash Document#	Agency Crash Number 20-13973	Investigating Of DEPUTY A. B			
Crash Date 12/12/2020	Crash Time 12:00 PM	Date Arrived 12/12/2020	Time Arrived 01:07 PM			
Date Notified 12/12/2020	Time Notified 01:07 PM	Total Units 01	Total Injured 01	Total Kille	led	
On Emergency	Hit and Run Lane	Closure Work Zone	Trailer or	Towed	Reporting  Threshold	
Government Property	Active School Zone	School Bus Related NO	Tags		1	
<b>▼</b> Reportable	Crash Type DT4000 (STANDARD C	RASH)	Amended		Secondary Crash	
Description <b>—</b>			Successado		·········	
NOT TO SCALE	BRIDGE			ectos By BREUNIG Iditional Info		
	стно	<b>€</b>				

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING WESTBOUND ON CTH O. THE ROAD SURFACE HAD SCATTERED PATCHES OF SNOW AND SLUSHES. UNIT 1 WAS TRAVELING UP A BRIDGE APPROACH. UNIT 1 TRAVELED INTO A SECTION OF SLUSH. UNIT 1 LOST CONTROL AND CROSSED THE CENTERLINE. UNIT 1 SIDE SWIPED THE BRIDGE RAIL. UNIT 1 TRAVELED ACROSS THE CENTERLINE AGAIN AND TRAVELED OFF THE NORTH SIDE OF THE ROAD. UNIT 1 TRAVELED DOWN INTO THE DITCH AND STRUCK AN EMBANKMENT. UNIT 1 CAME TO REST.

# **6TL0BNZM1S** 20-13973

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/12/2020

Crash Time 12:00 PM

	Location <b>—</b>									
ſ	ON CTHO WB					Latitude		Longitud	Longitude	
	907 FT E				43.278115875			-89.835	389555	
	OF SKUNK VALLEY RD							Y Coord	inate	
	IN THE TOWN OF PRAIRIE DU SAC IN SAUK COUNTY				269931.3	375		479560	4	
	IN SAUR COUNTY				Structure Type					
(	Crash Scene									
Ī	First Harmful Event				FirstHarm	ful Event L	ocation.			
						DWAY				
Ī	Manner of Collision I 00 - NO COLLISION W/VEHICLE IN TRANSPORT I				Light Condition					
					DAYLIGH	łΤ				
Ī					Roadway	Factor(s)				
ľ										
	NONE				NONE					
ľ	Weather Condition(s)				1					
	CLOUDY									
ŀ	Animal Type				Relation T		•			
	0 101 12 11				TRAFFIC					
	Crash Classification - Location -	on					-Jurisdiction			
ł	TribalLand				Access Co				Special Study	
	Those Early				NO CONTROL					
				••						
	Within Interchange Area			1		CTION				
	NO	Junction Location NON-JUNCTION		1	n Type INTERSE	CTION				
[	NO Unit Summary ■			NOT AN	INTERSE					
	NO Unit Summary Unit Status		1	NOT AN	INTERSE		UnitType			
	NO Unit Summary Unit Status IN TRANSIT		Vehicle Ope	NOT AN	INTERSE		AUTOMO			
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type		1	NOT AN	INTERSE				ments	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN	NON-JUNCTION	D CLASS	NOT AN	INTERSE		AUTOMO Operating A	As Endorse		
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs		D CLASS  Total#Citat	NOT AN	INTERSE	TotalTra	AUTOMO Operating A	As Endorse	ments Mat Types	
	Unit Summary Unit Status Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1	NON-JUNCTION  Train/Bus#Recorded	D CLASS	NOT AN	INTERSE	TotalTra	AUTOMO Operating A	As Endorse Total Haz	Mat Types	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance?	Train/Bus#Recorded  Direction Of Travel	D CLASS  Total#Citat 0	NOT AN erating As Cl	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A	As Endorse Total Haz 0 Total Land	Mat Types	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES	Train/Bus#Recorded  Direction Of Travel WESTBOUND	Total#Citat 0 Pre	erating As Continued tions Issued  Crash Tire Mark	INTERSE	TotalTra	AUTOMO Operating A	Total Haz  Total Lane  Total Lane	Mat Types es	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio	Train/Bus#Recorded  Direction Of Travel WESTBOUND	Total#Citat 0 Pre SpecialFur	NOT AN erating As Cl tions Issued CrashTire Mark notion	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers mit Emergency	Total Haz  Total Lane  Motor Veh	Mat Types es	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL	Train/Bus#Recorded  Direction Of Travel WESTBOUND	Total#Citat 0 Pre SpecialFur NO SPEC	erating As Continued tions Issued  Crash Tire Mark Inction IAL FUNC	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers mit Emergency NOT APP	Total Haz  0 Total Lane 2 / Motor Veh	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way	Train/Bus#Recorded  Direction Of Travel  WESTBOUND	Total#Citat 0 Pre SpecialFur NO SPEC Traffic Cont	erating As Control  Crash Tire Mark Inction IAL FUNC	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers mit Emergency NOT APP Traffic Con	Total Haz  0 Total Lane 2 / Motor Veh	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE	Train/Bus#Recorded  Direction Of Travel  WESTBOUND	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	erating As Co	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers  mit  Emergency NOT APP  Traffic Con	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With	Total#Citat 0 Pre SpecialFur NO SPEC Traffic Cont	erating As Co	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers  mit  Emergency NOT APP Traffic Con NO Road Grad	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	erating As Co	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers  mit  Emergency NOT APP  Traffic Con	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	erating As Co	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers  mit  Emergency NOT APP Traffic Con NO Road Grad	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	erating As Co	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers  mit  Emergency NOT APP Traffic Con NO Road Grad	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat	NON-JUNCTION  Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  US)	Total# Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	not an erating As Continued tions issued Crash Tire Mark nation IAL FUNCTorol ROL ature	INTERSE	TotalTra 0 SpeedLi	AUTOMO Operating A illers  mit  Emergency NOT APP Traffic Con NO Road Grad	Total Haz  0 Total Land 2 Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	NO Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle	NON-JUNCTION  Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  US)	Total# Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	not an erating As Continued tions issued Crash Tire Mark nation IAL FUNCTorol ROL ature	INTERSE	Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Con NO Road Grad UPHILL	Total Haz  0 Total Land 2 Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO  Vehicle License Plate Number AEP1916 Vehicle Identification N	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  D	Total# Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	NOT AN erating As Continued tions issued  Crash Tire Mark nation IAL FUNCTOR ROL ature	INTERSE	Total Tra  0 Speed Li  55	AUTOMO Operating A illers mit  Emergency NOT APP Traffic Con NO Road Grad UPHILL  Country of Is	Total Haz  0 Total Land 2 Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO  Vehicle License Plate Number AEP1916	NON-JUNCTION  Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  US)	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	NOT AN erating As Continued tions issued  Crash Tire Mark nation IAL FUNCTOR ROL ature	INTERSE	Total Tra 0 Speed Li 55	AUTOMO Operating A illers  mit  Emergency NOT APP Traffic Con NO Road Grad UPHILL  Country of is UNITED S	Total Haz  0 Total Lane 2 / Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO  Vehicle License Plate Number AEP1916 Vehicle Identification N	NON-JUNCTION  Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  US)	Total# Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve	NOT AN erating As Ci tions Issued  CrashTire Mark notion IAL FUNC trol PROL ature	INTERSE	Total Tra  0 Speed Li  55  St  WI Year	AUTOMO Operating A illers  mit  Emergency NOT APP Traffic Con NO Road Grad UPHILL  Country of is UNITED S' Model	Total Haz  0 Total Lane 2 / Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO  Vehicle License Plate Number AEP1916 Vehicle Identification N 3FAHP0HA3CR248	NON-JUNCTION  Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  US)	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva  Plate Type AUT - AU Make FORD	NOT AN erating As Ci tions Issued  CrashTire Mark notion IAL FUNC trol ROL ature	INTERSE	Total Tra  0 Speed Li  55  St  WI Year	AUTOMO Operating A  illers  mit  Emergency NOT APP Traffic Con NO Road Grad UPHILL  Country of Is UNITED S' Model FUSION Si	Total Haz  0 Total Lane 2 / Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO  Vehicle License Plate Number AEP1916 Vehicle Identification N 3FAHP0HA3CR248 Color BLU - BLUE Initial Contact Point	NON-JUNCTION  Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  US)	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva  Plate Type AUT - AU Make FORD Body Style	NOT AN erating As Continued tions Issued CrashTire Mark Inction IAL FUNCTOR ROL STOMOBIL	INTERSE	Total Tra  0 Speed Li  55  St  WI Year	AUTOMO Operating A  illers  mit  Emergency NOT APP Traffic Con NO Road Grad UPHILL  Country of Is UNITED S' Model FUSION Si	Total Haz  0 Total Lane 2 / Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO  Vehicle License Plate Number AEP1916 Vehicle Identification N 3FAHP0HA3CR248 Color BLU - BLUE Initial Contact Point	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  D  US)	Total # Citat 0  Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve  Plate Type AUT - AU Make FORD Body Style 4D - 4DR Vehicle Da	erating As Ci	INTERSE (Intersection)	Total Tra 0 Speed Li 55 St WI Year 2012	AUTOMO Operating A illers mit  Emergency NOT APP Traffic Con NO Road Grad UPHILL  Country of is UNITED S Model FUSION Si Bus Use	Total Haz  Total Lane  Total Lane  Motor Veh  LICABLE  trol Inopera  suance  TATES	Mat Types  es  icle Use  tive/Missing	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio BRIDGE RAIL Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO  Vehicle License Plate Number AEP1916 Vehicle Identification N 3FAHP0HA3CR248 Color BLU - BLUE Initial Contact Point	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  n With  D  US)	Total# Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva  Plate Type AUT - AU Make FORD Body Style 4D - 4DR Vehicle Da  01 - RIGH	erating As Ci	INTERSE (  lassification  TION  CORNER	Total Tra 0 Speed Li 55 St WI Year 2012	AUTOMO Operating A illers mit  Emergency NOT APP Traffic Con NO Road Grad UPHILL  Country of is UNITED S Model FUSION Si Bus Use	Total Haz  Total Land  Total Land  Motor Veh  LiCABLE  trol Inopera  TATES  E  AR, 09 - Li	MatTypes  es  icle Use  tive/Missing  EFT SIDE MIDDLE, 10	

#### 6TL0BNZM1S

20-13973

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/12/2020

Crash Time 12:00 PM

		Towed Due To Damage	10 DAMA 05	Vehicle Removed By				
		TOWED DUE TO DISABLING DAMAGE  What Driver Was Doing		EVERETTS TOWING  Vehicle Factors				
		GOING STRAIGHT		, consider details				
		Driver Prior Action Other		NOT APPLICABLE				
LINO	VEHICLE	Driver Actions SPEED TOO FAST/COND, I	FAILURE TO CONTROL					
٦	5	OwnerName DIMITRI ROBERT PHILLIPS (608) 434-7746	В	Owner Address 401 JOHN QUINCY ADAMS ST SAUK CITY, WI 53583 , US				
		Sequence Of Events		1				
	8	Event CROSS CENTERLINE						
	8	Event						
	8	Event RUN OFF ROADWAY RIGH	т					
	3	Event						
N		Insurance Company		Individual				
_		USAA-CASUALTY-INS-CO		DIMITRI PHILLIPS				
		Individual						
		Individual Driver		Citations   ssued				
		Driver PAYTEN TAYLOR PHILLIPS		Citations issued	Sex FEMALE			
⊢		Driver		Citations Issued	Sex			
TINO	INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS	3	Citations Issued  0	Sex FEMALE Race WHITE			
TINO	INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US	3	Citations Issued  0  Date of Birth  Driver License Number	Sex FEMALE Race WHITE			
TINO	INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  Tety Equipment	S Grash	Citations Issued  0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment	Sex FEMALE Race WHITE			
TINO	INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  Fety Equipment  Row 01 - FRONT ROW	3	Citations Issued  0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT	Sex FEMALE Race WHITE			
TIND	INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  Fety Equipment Row 01 - FRONT ROW  Helmet Use	Scrash Seat Position	Citations Issued  0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment	Sex FEMALE Race WHITE			
TINO	INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  Fety Equipment  Row 01 - FRONT ROW	Scrash Seat Position	Citations Issued  0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT	Sex FEMALE Race WHITE			
	INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  ety Equipment  Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Sev SUSPEC	Seat Position 07 - LEFT  verity CTED MINOR INJURY	Citations Issued  0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT  Helmet Compliance	Sex FEMALE Race WHITE STATES			
	S INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  Fety Equipment  Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Sev SUSPEC	Seat Position 07 - LEFT	Citations Issued 0 Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance  Tint Compliance  Airbag  NON DEPLOYED	Sex FEMALE Race WHITE			
	S INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  Fety Equipment  Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Sev SUSPEC Ejected NOT EJECTED Medical Transport	Seat Position 07 - LEFT  Verity CTED MINOR INJURY	Citations Issued 0 Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance  Tint Compliance  Airbag  NON DEPLOYED	Sex FEMALE Race WHITE  IITED STATES  Trapped/Extricated			
	S INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  Fety Equipment  Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Sev SUSPEC NOT EJECTED	Seat Position 07 - LEFT  Verity CTED MINOR INJURY	Citations Issued 0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance  Tint Compliance  Airbag  NON DEPLOYED	Sex FEMALE Race WHITE  HITED STATES  Trapped/Extricated NOT TRAPPED			
	S INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  ety Equipment Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Sev SUSPEC Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT  verity CTED MINOR INJURY Ejection Path	Citations Issued 0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT  Helmet Compliance  Tint Compliance  Airbag NON DEPLOYED  PLICABLE  EMS Agency Identifier	Sex FEMALE Race WHITE  HITED STATES  Trapped/Extricated NOT TRAPPED EMS Run #			
	S INDIVIDUAL	Driver PAYTEN TAYLOR PHILLIPS (608) 370-4352  Address 191 GROVE ST MERRIMAC, WI 53561 , US  ety Equipment Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Sev SUSPEC Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT  Verity CTED MINOR INJURY Ejection Path NOT EJECTED/NOT API	Citations issued 0  Date of Birth  Driver License Number  STATE: WISCONSIN COUNTRY: UN  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance  Tint Compliance  Airbag  NON DEPLOYED  PLICABLE  EMS Agency Identifier  Date of Death	Sex FEMALE Race WHITE  HITED STATES  Trapped/Extricated NOT TRAPPED EMS Run #			

# **6TL0BNZM1S** 20-13973

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/12/2020

Crash Time 12:00 PM

		Non Motor	Striking Unit#	Location				
		Prior Action						
UNIT	INDIVIDUAL	Action						
		Action Other						To/From School
	Ĺ	Drug & Alcol	Suspected Alcohol U	lse	Suspected Drug Use NO			
		Alcohol Test Give		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	3	
01	001	Drug Type						
		Individual Condition	on					
		APPEARED NO						
	Pro <sub>l</sub>	perty Owne	r					
PROP 01	Government SAUK COUNTY HIGHWAY DEPARTMENT (608) 356-4865			Address 620 LINN ST PO BOX 26 BARABOO, WI 53913	, US			
	Fixe	ed Objects S	truck Struck Object				Structure Number	Towns Towns
	9	Striking Unit 01	BRIDGE RAIL					Damage Tag Number D000000000