## 6TL0B4X4P8

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

0-1	13974	CRASH REPURT						BARABOO, WI 5391; (608) 356-489	
	Document Number Override	Primary Crash E	Ocument#	Agend 20-13	cy Crash Number 1974	Investigating Of DEPUTY E. K		у	
Ď	Crash Date 12/12/2020	Crash Time 01:51 PM		Date Arrived 12/12/2020		Time Arrived 02:15 PM			
.0B4X4P8	Date Notified 12/12/2020	Time Notified 01:51 PM		Total Units 01		Total Injured 01	Total Killed 00		
	On Emergency Hi	t and Run Lane Clos				Trailer or Towed			Reporting Threshold
٦ ٥	Government Property	Active School Zone		School Bus Related NO		Tags			
	<b>▼</b> Reportable	Crash Type DT4000 (STA	NDARD CRAS	SH)		Amended			Secondary Crash
	Description					'		<b>'</b>	
		Kinnamon Rd		ଜ୍	emetery Rd		notos By  dditional Inf	ormation	
			A TOP OF THE PROPERTY OF THE P			a)EMES	ONE		

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

Kinnamon Rd

OPERATOR WB ON CEMETARY RD AND STATED HER BRAKES FAILED AND SHE TRIED TO TURN SOUTH ONTO KINNAMON RD AND WENT INTO THE DITCH. DRIVER WAS TRANSPORTED BY PRIVATE VEHICLE TO HOSPITAL WITH BACK AND HEAD PAIN. VEHICLE WAS REMOVED BY STEVES TOWING. OPERATOR ADMITTED TO NOT HAVING INSURANCE AND WAS ISSUED CITATION FOR OPERATE WITHOUT INSURANCE.

### 6TL0B4X4P8 20-13974

Location

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/12/2020

Crash Time 01:51 PM

IN THE TOWN OF RONTON IN SAUK COUNTY  A28895-53125  STUCCURE  FIRST-HARMFULE VENT DITCH  FIRST-HARMFULE VENT DITCH  Marmar of Collision Or - NO COLLISION W/VEHICLE IN TRANSPORT  ROAD SURFACE CONDITION (WET, ICV, SNOW, SLUSH, ETV, SNOW, SLUSH, E		ON KINNAMIN RD 19 FT S OF CEMETERY RD	Latitude 43.547710285		Longitude -90.107601643					
Crash Scene    First Hamful Event   First Hamful Event Location   ROADSIDE		IN THE TOWN OF IRON	NTON							
First-Hamful Event   Direct   ROADSIDE   Name of Collision   Light Condition   Light Condition   DAYLIGHT   Road Surface Condition(s)   WET, SLUSH   Environment Factor(s)   ROAD Surface Condition(s)   WET, SLUSH   Environment Factor(s)   ROAD Surface Condition(s)   ROAD Surface C					1					
DITCH   ROADSIDE		Crash Scene								
Manner of Collision W/VEHICLE IN TRANSPORT   DAYLIGHT		First Harmful Event			First Harmful Ever	nt Location				
DAYLIGHT   Road Surface Condition(s)   Roadway Factor(s)   Roadw		DITCH			ROADSIDE					
Road Surface Condition(s) WET, SLUSH Environment Factor(s) NONE  Weather Condition(s)  CLEAR  Animal Type Relation To Traffic.wey TRAFFICWAY - NOT ON ROAD  Crash Classification - Jurisdiction NO SPECIAL JURISDICTION  Within Interchange Area NO Unit Summary  Unit Summary  Unit Status IN TRANSIT D CLASS Vehicle Operating As Classification IN Total Trailing As Endorsements IN Total Trailing Total Trailing Access Control Total Cocs Train/Bus # Recorded Total # Crash Tire No SPECIAL FUNCTION  Total Cocs Train/Bus # Recorded Total # Crash Tire No SPECIAL FUNCTION  Total Cocs Train/Bus # Recorded Total # Crash Tire No SPECIAL FUNCTION  Total Cocs Train/Bus # Recorded Total # Crash Tire No SPECIAL FUNCTION  Total Cocs Train/Bus # Recorded Total # Crash Tire No SPECIAL FUNCTION No SPECIAL FUNCTION Total Cocs Train/Bus # Recorded Total # Crash Tire No SPECIAL FUNCTION NO SPECIAL FUNC		Manner of Collision			Light Condition					
WET, SLUSH  Environment Factor(s) NONE  Westher Condition(s) CLEAR  Animal Type  Transficurary Not On ROAD  Crash Classification - Location PUBLIC PROPERTY  Tribal Land  No SPECIAL JURISDICTION  Within Interchange Avea NO INTERSECTION  Unit Summary  IN TRANSIT  D CLASS  Vehicle Type PASSENGER VAN  Total Oces 1 Train Bus # Recorded 1 Insurance?  Direction Off Travel No Westbound  Westbound  Mark  No SPECIAL FUNCTION  Unit Jurian  Total Teals In Total Train lens  Total Haz/Mat Types  1 0 0 0 Insurance?  Direction Off Travel No SPECIAL FUNCTION  Master  No Westbound  Mark  Total Control No SPECIAL FUNCTION  Traffic Way Traffic Control No SPECIAL FUNCTION  Traffic Way Traffic Control No SPECIAL FUNCTION  Traffic Control No SPECIAL FUNCTION  No SPECIAL FUNCTION  No SPECIAL FUNCTION  No SPECIAL FUNCTION  Traffic Control No TAPPLICABLE  Traffic Control Traffic Way Traffic Control Traffic Control Traffic Way Traffic Control Traffic Way Traffic Control Traffic Control Traffic Special Function No SPECIAL FUNCTION No SPECIAL FUNCTION  No SPECIAL FUNCTION  No TAPPLICABLE  Traffic Control Traffic Control Traffic Control Traffic Control Traffic Control Traffic Way Traffic Control Traffic Special Function No SPECIAL FUNCTION No SPECIAL FUNCTION No TAPPLICABLE Traffic Control Traffic Contr		00 - NO COLLISION W/	VEHICLE IN TRANSPORT		°					
ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)   ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH		Road Surface Condition(s)			Roadway Factor(s	Roadway Factor(s)				
NONE  Weather Condition(s)  CLEAR  Animal Type  Crash Classification - Location  PUBLIC PROPERTY  Tribal Land  Within Interchange Area NO INTERSECTION  Unit Status  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  AUTOMOBILE  Vehicle Operating As Classification  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  AUTOMOBILE  Vehicle  Vehicle  Unit Type  AUTOMOBILE  Traffic Way  Traffic Control  NO SPECIAL FUNCTION  NO APPLICABLE  Traffic Way  Traffic Control  Traffic Control  NO CONTROL  NO  Surface Type  Road Grade  DLACKTOPP (BITUMINIOUS)  CURVE RIGHT  Vehicle  Unit ED STATES  Vehicle  Unit ED STATES  Unit ED STATE		WET, SLUSH								
NONE  Weather Condition(s)  CLEAR  Animal Type  Crash Classification - Location  PUBLIC PROPERTY  Tribal Land  Within Interchange Area NO INTERSECTION  Unit Status  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  AUTOMOBILE  Vehicle Operating As Classification  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  Unit Type  AUTOMOBILE  Vehicle Operating As Classification  AUTOMOBILE  Vehicle  Vehicle  Unit Type  AUTOMOBILE  Traffic Way  Traffic Control  NO SPECIAL FUNCTION  NO APPLICABLE  Traffic Way  Traffic Control  Traffic Control  NO CONTROL  NO  Surface Type  Road Grade  DLACKTOPP (BITUMINIOUS)  CURVE RIGHT  Vehicle  Unit ED STATES  Vehicle  Unit ED STATES  Unit ED STATE		Environment Factor(s)			$\dashv$					
Weather Condition(s)   CLEAR						E CONDITION	N (WET, ICY, SNOW, SLUS	Н,		
CLEAR  Animal Type  Relation To Trafficway TRAFFICWAY - NOT ON ROAD  Crash Classification - Location PUBLIC PROPERTY Tribal Land  Access Control NO SPECIAL JURISDICTION  Tribal Land  Access Control NO CONTROL  Within Interchange Area NO INTERSECTION  Unit Summary  Unit Status IN TRANSIT  D CLASS  AUTOMOBILE  IN TRANSIT  PASSENGER VAN  Total Occs Train/Bus# Recorded 1 Total # Clations Issued 1 Total Trailers 1 Total Lanes  Operating As Endorsements  PASSENGER VAN  Total Occs Train/Bus# Recorded 1 Total # Clations Issued 1 Total Trailers 1 Total Lanes  NO WESTBOUND  Mark 45 2  Most Harmful Event: Collision With DITCH Traffic Way TWO-WAY, NOT DIVIDED NO CONTROL  NO SPECIAL FUNCTION NO TAPPLICABLE  Traffic Control NO CONTROL NO SUrface Type BLACKTOP (BITUMINOUS) CURVE RIGHT NO  Vehicle License Plate Number ADE Type License Plate Number ADE Country of Issuance ADE Type License Plate Number ADE Country of Issuance ADE Type License Plate Number ADE Country of Issuance ADE Type License Plate Number ADE Country of Issuance ADE Country of Issua					ETC)					
Animal Type    Relation To Trafficway TRAFFICWAY - NOT ON ROAD		Weather Condition(s)								
TRAFFICWAY - NOT ON ROAD  Crash Classification - Jurisdiction PUBLIC PROPERTY  Tribal Land  Access Control NO SPECIAL JURISDICTION  Access Control NO CONTROL  Within Interchange Area NO INTERSECTION  Unit Summary  Unit Summary  Unit Summary  Unit Summary  Unit Status  Vehicle Operating As Classification Intersection Type Y-INTERSECTION  Unit Status  Vehicle Operating As Classification Intersection Type AutoMOBILE  Operating As Endorsements  Operating As Endorsements  Operating As Endorsements  Total Trailers  Total Trailers  Total Trailers  Total Trailers  Total Trailers  Total Lanes  On		CLEAR								
TRAFFICWAY - NOT ON ROAD  Crash Classification - Location PUBLIC PROPERTY  Tribal Land  Access Control NO SPECIAL JURISDICTION  Within Interchange Area NO INTERSECTION  Unit Summary  Unit Summary  Vehicle Operating As Classification Intersection Type Y-INTERSECTION  Unit Status IN TRANSIT  O CLASS  Operating As Classification Operating As Endorsements  PASSENGER VAN  Total Occs Train/Bus # Recorded 1 Total # Citations Issued 1 Total Trailers Operating As Endorsements  PASSENGER VAN  Total Occs Train/Bus # Recorded 1 Total # Citations Issued 1 Total Trailers O 0  Most Harmful Event Collision With NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO ONAPY, NOT DIVIDED NO CONTROL NO Surface Type BLACKTOP (BITUMINOUS) CURVE RIGHT Traffic Control Inoperative/Missing NO Vehicle Identification Number ADMAN NO Vehicle Plate Type ADMAN AUT - AUTOMOBILE  Plate Type ADMAN AUT - AUTOMOBILE  St. Country of issuence AUT - AUTOMOBILE Vehicle Identification Number AUT - AUTOMOBILE Vehicle Courter AUT - AUTOMOBILE Vehicle Courter AUT - AUTOMOBILE AUTOMOBILE AUTOMOBILE AUTOMOBILE AUTOMOBILE AUTOMOBILE AUTOMOBILE AUTOMOBILE AUTOMOBILE AUTOMOBIL		Animal Type			Relation To Traffic	Relation To Trafficway				
PUBLIC PROPERTY Tribal Land Access Control NO CONTROL  Within Interchange Area NO INTERSECTION  Unit Summary  Unit Status IN TRANSIT D CLASS Vehicle Operating As Classification D CLASS  Unit Status IN TRANSIT IN TRANSIT D CLASS  Unit Status IN TRANSIT IN					I					
Tribal Land  Access Control NO CONTROL  Within Interchange Area Intersection Type Y-INTERSECTION  Unit Summary  Unit Status Vehicle Operating As Classification D CLASS AUTOMOBILE  Vehicle Type PASSENGER VAN  Total Occs Train/Bus#Recorded Total# Citations Issued Total Trailers Total HazMat Types 1 1		Crash Classification - Loca	tion		Crash Classification	Crash Classification - Jurisdiction				
Within Interchange Area   Junction Location   Intersection Type   INTERSECTION   Valid Summary   Vehicle Operating As Classification   Unit Type   AUTOMOBILE		PUBLIC PROPERTY			NO SPECIAL J					
Within Interchange Area NO INTERSECTION INTERSECTION  Unit Summary  Vehicle Operating As Classification Unit Type AUTOMOBILE IN TRANSIT Vehicle Type PASSENGER VAN  Total Occs Train/Bus # Recorded 1 Insurance? Direction Of Travel WESTBOUND POT CHARLES AUTOMOBILE  NO WESTBOUND PROCESS AUTOMOBILE  Traffic Way Traffic Control NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO SURFACE TYPE BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Vehicle License Plate Number ADF8716 AUT - AUTOMOBILE WI UNITED STATES  Vehicle Insurance Area Junction Location Type Y-Intersection Type Y-Intersection Type Y-Intersection Type AUTOMOBILE WI UNITED STATES  Vehicle Intersection Type AUTOMOBILE WI UNITED STATES  Vehicle Intersect		Tribal Land					Special Study			
Unit Summary    Vehicle Operating As Classification   Unit Type   AUTOMOBILE										
Unit Summary  Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs Train/Bus # Recorded 1 Direction Of Travel NO Most Harmful Event: Collision With DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or Haz/Mat NO  Vehicle Unit Status Vehicle Operating As Classification D CLASS AUTOMOBILE  Operating As Endorsements  Vehicle departments  Total Accitations Issued 1 Total Trailiers Total Trailiers Total Haz/Mat Types 1 1 0 0 0 Insurance? NO Mark 45 2  Speed Limit Total Lanes 2 2  Most Harmful Event: Collision With NO SPECIAL FUNCTION NO TAPPLICABLE Traffic Control NO CONTROL NO Surface Type BLACKTOP (BITUMINOUS) CURVE RIGHT NO  Vehicle dentification Number ADF8716 Vehicle dentification Number ADF8716 Vehicle dentification Number ADF8716 Vehicle dentification Number Make Year Model Color SiL - SILVER (ALUMINUM) VN - VAN  Veh VAN  Vehicle Bus Use  Vehicle Bus Use		_								
Unit Status   Vehicle Operating As Classification   Unit Type   AUTOMOBILE   Vehicle Type   PASSENGER VAN			INTERSECTION	1-IN I E	RSECTION					
IN TRANSIT  Vehicle Type  PASSENGER VAN  Total Occs  1		Linit Cilmmanı								
Vehicle Type PASSENGER VAN  Total Occs 1 Train/Bus # Recorded 1 1 Direction Of Travel Mest Harmful Event: Collision With DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS)  Truck Bus or Haz/Mat NO  Vehicle dentification Number ADF8716 Vehicle Identification Number ADF8716 Vehicle Identification Number 1B46P25352B543549 DODGE ATTION DIVIDED DIRECTION Total Haz/Mat Types O					01 10 11					
PASSENGER VAN  Total Occs   Train/Bus # Recorded   Total # Citations Issued   Total Trailers   Total HazMat Types    Insurance?   Direction Of Travel   Pre Crash Tire   Mark   45   2    Most Harmful Event: Collision With   WESTBOUND   DITCH   Traffic Control   NO SPECIAL FUNCTION   Emergency Motor Vehicle Use   NOT APPLICABLE    Traffic Way   Traffic Control   NO CON		Unit Status			Classification	1	DBH E			
1		Unit Status IN TRANSIT			Classification	AUTOMO				
Insurance? NO  Insurance Insurance? NO  Insurance Insura		Unit Status IN TRANSIT Vehicle Type			Classification	AUTOMO				
Most Harmful Event: Collision With DITCH    Most Harmful Event: Collision With DITCH   Special Function NO SPECIAL FUNCTION   Emergency Motor Vehicle Use NOT APPLICABLE		Unit Status IN TRANSIT Vehicle Type PASSENGER VAN	Train/Bus#Recorded	D CLASS		AUTOMO Operating	As Endorsements			
Most Harmful Event: Collision With DITCH  Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or Haz!Mat NO  Vehicle  License Plate Number ADF8716  Vehicle Identification Number 1B4GP25352B543549 Color Sit Sit. VER (ALUMINUM)  Special Function NO SPECIAL FUNCTION  Traffic Control NO CONTROL NO Road Curvature Road Curvature Road Grade DOWNHILL  Truck Bus or Haz!Mat NO  Vehicle  License Plate Number AUT - AUTOMOBILE Will UNITED STATES  Make Year Model Locar Model Color Sit Sit. VER (ALUMINUM)  NO SPECIAL FUNCTION NO TAPPLICABLE  Financian NO APPLICABLE  Traffic Control Inoperative //Missing NO  NO  NO CONTROL NO  Traffic Control Inoperative //Missing NO  NO  NO  NO  NO  NO  Plate Type AUT - AUTOMOBILE Will UNITED STATES  Model Locar Model Color Sit Sit. VER (ALUMINUM)  NO  Special Function NO SPECIAL FUNCTION NO APPLICABLE  Traffic Control NO		Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs	Train/Bus#Recorded	D CLASS  Total#Citations Issue	ed Total T	AUTOMO Operating	As Endorsements  Total HazMat Types			
Traffic Way Traffic Control Traffic Way TWO-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number ADF8716 Vehicle Identification Number 184GP25352B543549 Color SiL - SILVER (ALUMINUM)  Traffic Control NO  Traffic Control NO  Road Curvature Road Grade DOWNHILL  Truck Bus or HazMat NO  Vehicle License Plate Number AUT - AUTOMOBILE WI UNITED STATES  Bus Use  Bus Use		Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1	Direction Of Travel	Total#Citations Issue	od TotalT	AUTOMO Operating	As Endorsements  Total HazMat Types  0  Total Lanes			
Traffic Way TWO-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number ADF8716 Vehicle Identification Number 184GP25352B543549 Color SiL - SILVER (ALUMINUM)  Traffic Control NO  Traffic Control NO  Road Curvature CURVE RIGHT DOWNHILL  Road Grade DOWNHILL  Road Grade DOWNHILL  Venue Bus or HazMat NO  Vehicle United States Will United States Wodel Caravan Se Body Style Vn - VAN  Bus Use	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs Insurance?	Direction Of Travel WESTBOUND	Total#Citations Issue 1 Pre CrashTir	re Speed	AUTOMC Operating railers	As Endorsements  Total HazMat Types  Total Lanes  2			
TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Plate Type ADF8716  Vehicle  License Plate Number ADF8716  Vehicle Identification Number 1B4GP25352B543549  Color SiL - SiLVER (ALUMINUM)  NO  NO  Road Curvature Road Grade DOWNHILL  Road Grade Road	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs I Insurance? NO Most Harmful Event: Collisi	Direction Of Travel WESTBOUND	Total#Citations Issue 1 Pre CrashTir Mark Special Function	Total T 0 Speed 45	AUTOMO Operating railers Limit Emergence	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use			
Surface Type BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Vehicle  License Plate Number ADF8716  Vehicle Igar State Vehicle Igar State AUT - AUTOMOBILE Vehicle Igar Model 184GP25352B543549  Color StL - SILVER (ALUMINUM)  Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOBILE Vi UNITED STATES  Model Year ADF8746  Body Style VN - VAN  Bus Use	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH	Direction Of Travel WESTBOUND	Total#Citations Issue 1  Pre CrashTir Mark  Special Function NO SPECIAL FUNC	Total T 0 Speed 45	AUTOMO Operating  railers  Limit  Emergenc NOT APF	As Endorsements  Total HazMat Types 0  Total Lanes 2  y Motor Vehicle Use PLICABLE			
Truck Bus or HazMat NO  Vehicle  License Plate Number ADF8716  Vehicle Identification Number 1B4GP25352B543549  Color SiL - SiLVER (ALUMINUM)  Plate Type AUT - AUTOMOBILE Wi UNITED STATES Wi UNITED STATES  Make Year DODGE 2002 CARAVAN SE  Bus Use	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way	Direction Of Travel WESTBOUND on With	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNC	Total T 0 Speed 45	AUTOMO Operating  railers  Limit  Emergenc NOT APF	As Endorsements  Total HazMat Types 0  Total Lanes 2  y Motor Vehicle Use PLICABLE			
No   Vehicle	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way TWO-WAY, NOT DIVID	Direction Of Travel WESTBOUND on With	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNC	Total T 0 Speed 45	AUTOMO Operating railers Limit Emergenc NOT APF Traffic Cor NO	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE attrol Inoperative/Missing			
Vehicle  License Plate Number ADF8716  Vehicle Identification Number 1B4GP25352B543549  Color SIL - SILVER (ALUMINUM)  Plate Type AUT - AUTOMOBILE WI UNITED STATES Wi UNITED STATES  Make Year DODGE 2002  CARAVAN SE  Bus Use	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way TWO-WAY, NOT DIVIDI Surface Type	Direction Of Travel WESTBOUND on With	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature	Total T 0 Speed 45	AUTOMO Operating  railers  Limit  Emergenc NOT APF  Traffic Cor NO Road Grad	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE htrol Inoperative/Missing			
License Plate Number ADF8716  Plate Type AUT - AUTOMOBILE  WI UNITED STATES  Vehicle Identification Number 1B4GP25352B543549  Color SIL - SILVER (ALUMINUM)  Plate Type AUT - AUTOMOBILE  WI UNITED STATES  Wodel CARAVAN SE  Bus Use  Bus Use	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat	Direction Of Travel WESTBOUND on With	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature	Total T 0 Speed 45	AUTOMO Operating  railers  Limit  Emergenc NOT APF  Traffic Cor NO Road Grad	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE htrol Inoperative/Missing			
ADF8716 AUT - AUTOMOBILE WI UNITED STATES  Vehicle Identification Number Make Year 184GP25352B543549 DODGE 2002 CARAVAN SE  Color Body Style Bus Use  VN - VAN  Bus Use	07	Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat	Direction Of Travel WESTBOUND on With	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature	Total T 0 Speed 45	AUTOMO Operating  railers  Limit  Emergenc NOT APF  Traffic Cor NO Road Grad	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE htrol Inoperative/Missing			
Vehicle Identification Number 1B4GP25352B543549 DODGE 1Body Style VN - VAN  Vehicle Identification Number 2002 CARAVAN SE  Bus Use  Bus Use	07	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH  Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle	Direction Of Travel WESTBOUND on With  ED  DUS)	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNCTION Traffic Control NO CONTROL Road Curvature	re Speed 45	AUTOMO Operating  railers  Limit  Emergenc NOT APF  Traffic Cor NO Road Grad	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE htrol Inoperative/Missing			
Telephone	07	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH  Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Numbe	Direction Of Travel WESTBOUND on With  ED  DUS)	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature CURVE RIGHT	re Speed 45  CTION	AUTOMO Operating  railers  Limit  Emergenc NOT APF  Traffic Con NO Road Grac DOWNHI	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE Introl Inoperative/Missing de LL			
Color	07	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Numbe ADF8716	Direction Of Travel WESTBOUND on With  ED  DUS)	Total # Citations Issue 1 Pre CrashTir Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOB	od TotalT 0 Speed 45 CTION St WI	AUTOMO Operating  railers  Limit  Emergence NOT APF  Traffic Core NO Road Grace DOWNHI  Country of I UNITED S	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE Introl Inoperative/Missing de LL			
SIL - SILVER (ALUMINUM) VN - VAN	UNIT 01	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO  Most Harmful Event: Collisi DITCH  Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Numbe ADF8716  Vehicle Identification	Direction Of Travel WESTBOUND on With  ED  DUS)	Total#Citations Issue 1 Pre CrashTin Mark Special Function NO SPECIAL FUNCTION NO CONTROL Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOB Make	Total T 0 Speed 45 CTION  St WI Year	AUTOMO Operating  railers  Limit  Emergence NOT APF Traffic Con NO Road Grace DOWNHI  Country of i UNITED S Model	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE atrol Inoperative/Missing de LL			
Initial Contact Point  On - NON-COLLISION  Extent Of Damage  MINOR DAMAGE  Vehicle Damage  14 - UNDERCARRIAGE	UNIT 01	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO  Vehicle License Plate Numbe ADF8716 Vehicle Identification 184GP25352B543	Direction Of Travel WESTBOUND on With  ED  DUS)	Total#Citations Issue 1 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOB Make DODGE	Total T 0 Speed 45 CTION  St WI Year	AUTOMO Operating  Trailers  Emergence NOT APF Traffic Core NO Road Grace DOWNHI  Country of I UNITED S  Model CARAVAN	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE atrol Inoperative/Missing de LL			
O0 - NON-COLLISION   Extent Of Damage   MINOR DAMAGE   14 - UNDERCARRIAGE	UNIT 01	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO Most Harmful Event: Collisi DITCH Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO  Vehicle License Plate Numbe ADF8716 Vehicle Identification 184GP25352B543 Color	Direction Of Travel WESTBOUND on With  ED  DUS)  T  Number 1:549	Total # Citations Issue 1 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOB Make DODGE Body Style	Total T 0 Speed 45 CTION  St WI Year	AUTOMO Operating  Trailers  Emergence NOT APF Traffic Core NO Road Grace DOWNHI  Country of I UNITED S  Model CARAVAN	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE atrol Inoperative/Missing de LL			
5 Extent Of Damage MINOR DAMAGE 14 - UNDERCARRIAGE	01 UNIT 01	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO  Most Harmful Event: Collisi DITCH  Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Numbe ADF8716  Vehicle Identification 1B4GP25352B543  Color SiL - SiLVER (ALL)	Direction Of Travel WESTBOUND on With  ED  DUS)  T  Number 1:549	Total # Citations Issue 1 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOB Make DODGE Body Style VN - VAN	Total T 0 Speed 45 CTION  St WI Year	AUTOMO Operating  Trailers  Emergence NOT APF Traffic Core NO Road Grace DOWNHI  Country of I UNITED S  Model CARAVAN	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE atrol Inoperative/Missing de LL			
MINOR DAMAGE	01 UNIT 01	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO  Most Harmful Event: Collisi DITCH  Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Numbe ADF8716  Vehicle Identification 1B4GP25352B543  Color SiL - SiLVER (ALL)	Direction Of Travel WESTBOUND on With  ED  DUS)  T  Number 1549  JMINUM)	Total # Citations Issue 1 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOB Make DODGE Body Style VN - VAN	Total T 0 Speed 45 CTION  St WI Year	AUTOMO Operating  Trailers  Emergence NOT APF Traffic Core NO Road Grace DOWNHI  Country of I UNITED S  Model CARAVAN	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE atrol Inoperative/Missing de LL			
	01 UNIT 01	Unit Status IN TRANSIT  Vehicle Type PASSENGER VAN  Total Occs 1 Insurance? NO  Most Harmful Event: Collisi DITCH  Traffic Way TWO-WAY, NOT DIVIDI Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Numbe ADF8716  Vehicle Identification 1B4GP25352B543  Color SiL - SiLVER (ALL)	Direction Of Travel WESTBOUND on With  ED  DUS)  T  Number 1549  JMINUM)	Total # Citations Issue 1 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature CURVE RIGHT  Plate Type AUT - AUTOMOB Make DODGE Body Style VN - VAN Vehicle Damage	Total T 0 Speed 45 CTION  St WI Year 2002	AUTOMO Operating  Trailers  Emergence NOT APF Traffic Core NO Road Grace DOWNHI  Country of I UNITED S  Model CARAVAN	As Endorsements  Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE atrol Inoperative/Missing de LL			

## 6TL0B4X4P8

20-13974

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/12/2020

Crash Time 01:51 PM

		Towed Due To Damage	NC DA84A	I	Vehicle Removed By					
		TOWED DUE TO DISABLING DAMAGE What Driver Was Doing		STEVES AUTO SERVICE  Vehicle Factors						
		NEGOTIATING CURVE			venicle raciois					
		Driver Prior Action Other			BRAKES					
		Driver Actions	CTION	•						
_		OTHER CONTRIBUTING ACTION								
IND	VEHICLE									
$\neg$										
		Owner Name			Owner Address					
2	5	SHAYNA LEIGH MILLER (608) 479-2247			110 N BROOKLYN AVE ELROY, WI 53929 , US					
_					LENG 1, 191 00020 , 00					
		Secuence Of Events								
		Event								
	5	DITCH								
	8	Event								
	03	Event								
		F								
	3	Event								
		ndividual								
		Driver			Citations issued		Sex			
		SHAYNA LEIGH MILLER			1		FEMALE			
	4	(608) 479-2247			Date of Birth		Race			
<b>=</b>	INDIVIDUA						WHITE			
Ž	á	Address 110 N BROOKLYN AVE			Driver License Number					
	2	ELROY, WI 53929 , US		STATE: WISCONSIN COUNTRY: UNITED STATES						
		On Duty ety Equipment	Crash		Safety Equipment					
	341									
		Row 01 - FRONT ROW	Seat Po		SHOULDER & LAP BELT					
		HelmetUse	101 - 22		Helmet Compliance					
		7.54.110.100.0			Tint Compliance					
		Eye Protection								
2	8	Injury Se	venty CTED MIN	OR INJURY	Airbag NON DEPLOYED					
		SUSPECTED MINOR INJURY    Ejected   Ejection Path			Trapped/Extricated					
				CTED/NOT APP	LICABLE		NOT TRAPPED			
		Medical Transport			EMS Agency Identifier		EMS Run#			
		NOT TRANSPORTED								
		Hospital			Date of Death Time of Death					
		Distracte	d By Source	) 						
		Distracted By NOT A	PPLICABL	E (NOT DISTRA	CTED)					
		Distracted By Action NOT DISTRACTED								
		Non Motorist	Jnit#	Location						
	MINNE STREET									

### 6TL0B4X4P8 20-13974

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/12/2020

Crash Time 01:51 PM

	Prior Action						
	Action						
Y							
UNIT							
UNIT							
Ź							
	Action Other						To/From School
	Action Other						10/10/11001
		Suspected Alco	phol Use	Suspected Drug Use			
	Drug & Alcohol	NO		NO			
	Alcohol Test Given		Alcohol Test Type			Alcohol Test Results	
	TEST NOT GIVEN  Drug Test Given		Drug Test Type		Drug Test Results		
	TEST NOT GIVEN		Sing root type		Ding restricesum		
<u>ال</u> ا	Drug Type				I .		
0 2							
	Individual Condition						
	NOT OBSERVED						
	NOT OBSERVED						
	Violations	STAR STAR STAR STAR					
5	UTC Number	Issue To?	Statute Number 344.62(1)	Description OPERATE MOTOR \	/EHICLE W/O IN	SURANCE	
•	BB955350	001	344.02(1)	OI EIGHTE MOTOR	VEHICLE W/O III	OUNTIOL	