6TL0B7D6TK 21-00746

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO**, WI 53913 (608) 356-4895

Document Number Override	21-00746 DEPU1 ash Date Crash Time Date Arrived Time Ar			tting Officer/Deputy Y S. ELLICKSON		
Crash Date 01/26/2021				Time Arrived 12:21 PM		
O1/26/2021 Date Notified O1/26/2021 On Emergency Hit Government Property	Time Notified 12:07 PM	Total U	nits	Total Injured 01	Total Kille	d
On Emergency Hit	and Run La	ine Closure	☐ Work Zone	Trailer or	Towed	Reporting Threshold
Government Property	Active School Zo	one School	Bus Related	Tags		•
▼ Reportable	Crash Type DT4000 (STANDARE	D CRASH)		Amended		Secondary Crash
Description Diagram					construction	
\$	School BusStop ahead sign	Churchill Road		Ph	notos By Iditional Info	
I, a sworn law enforcement unit 1 was eastbound on chuf damaged to where it could in	RCHILL ROAD. UNIT 1 LC	I have not adde	THE VEHICLE ON A SNO	his report.		

6TL0B7D6TK 21-00746

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/26/2021

Crash Time 12:00 PM

I	Location —								
·	ON CHURCHILL RD			Latitud	е		Longitude		
	0.96 MI W	43.57	6703463		-90.019027881				
	OF CTHF EB	Y Coor	X Coordinate		Y Coordinate				
	IN THE TOWN OF WINFI		32.15625		4829289				
	IN SAUK COUNTY						4020200		
					Structure Type				
Ĺ				NO S	NO STRUCTURE				
(Crash Scene 🗨								
ī	First Harmful Event			First H	armful Event l	ocation			
	TRAFFIC SIGN POST				LDER LEF				
ŀ	Manner of Collision			1	Light Condition				
	00 - NO COLLISION W/VI	EURCE E IN TRANSPORT	-	1 -					
ļ		ERICLE IN TRANSFOR			DAYLIGHT				
	Road Surface Condition(s)			Roadw	vay Factor(s)				
	SNOW								
ŀ	Environment Factor(s)				†				
	, ,			ROAD	ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH,				
	NONE			ETC)			((, , , , , , , , , , , , , , , , , ,		
ŀ	Weather Condition(s)								
	, ,								
	CLEAR								
ŀ	Animal Type			Relation To Trafficway					
					FICWAY - N	n			
-	Overla Classification in the								
	Crash Classification - Location	n			Crash Classification - Jurisdiction				
ļ	PUBLIC PROPERTY		NO SPECIAL JURISDICTION						
	Tribal Land				s Control		Special Study		
Į				NO CO	NO CONTROL				
ſ	Within Interchange Area	Junction Location	Intersection Type	tion Type					
	NO	NOT AN INTER	NINTERSECTION						
		NON-JUNCTION		NOT AN INTER	SECTION				
į				NOT AN INTER	SECTION				
į T	Unit Summary =		Vehicle Ope			UnitType			
Ţ	Unit Summary Unit Status		1	erating As Classifica		Unit Type	BII F		
į	Unit Summary Unit Status IN TRANSIT		Vehicle Ope			AUTOMO			
	Unit Summary Unit Status IN TRANSIT Vehicle Type		1			AUTOMO	BILE s Endorsements		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC	ELE	D CLASS	erating As Classifica	tion	AUTOMO Operating A	s Endorsements		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs		D CLASS Total#Citat	erating As Classifica	tion Total Tra	AUTOMO Operating A	s Endorsements Total HazMat Types		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC	ELE	D CLASS	erating As Classifica	tion	AUTOMO Operating A	s Endorsements Total HazMat Types 0		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs	:LE	D CLASS Total#Citat 2	erating As Classifica	tion Total Tra	AUTOMO Operating A	s Endorsements Total HazMat Types		
5	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1	CLE Train/Bus#Recorded	Total#Citat 2 Pre	erating As Classifica	Total Tra	AUTOMO Operating A	s Endorsements Total HazMat Types 0		
•	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance?	Train/Bus#Recorded Direction Of Travel EASTBOUND	Total#Citat 2 Pre	erating As Classifications Issued CrashTire Mark	TotalTra 0 Speed L	AUTOMOI Operating A illers mit Emergency	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
5	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO	Train/Bus#Recorded Direction Of Travel EASTBOUND	Total#Citat 2 Pre 6 SpecialFun	erating As Classifications Issued CrashTire Mark	TotalTra 0 Speed L	AUTOMOI Operating A	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE	Train/Bus#Recorded Direction Of Travel EASTBOUND	Total#Citat 2 Pre 6 SpecialFun NO SPECI	erating As Classifications issued CrashTire Mark ction	TotalTra 0 Speed L	AUTOMOI Operating A illers imit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way	Train/Bus#Recorded Direction Of Travel EASTBOUND	Total#Citat 2 Pre 6 Special Fun NO SPECI	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol	TotalTra 0 Speed L	AUTOMO Operating A illers imit Emergency NOT APP Traffic Conf	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED	Train/Bus#Recorded Direction Of Travel EASTBOUND	D CLASS Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL	TotalTra 0 Speed L	AUTOMOI Operating A illers mit Emergency NOT APP Traffic Cont	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type	Train/Bus#Recorded Direction Of Travel EASTBOUND Direction Of Travel	D CLASS Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Cont NO CONT	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL	TotalTra 0 Speed L	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL	Train/Bus#Recorded Direction Of Travel EASTBOUND Direction Of Travel	D CLASS Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL	TotalTra 0 Speed L	AUTOMOI Operating A illers mit Emergency NOT APP Traffic Cont	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL) Truck Bus or HazMat	Train/Bus#Recorded Direction Of Travel EASTBOUND Direction Of Travel	D CLASS Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Cont NO CONT	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL	TotalTra 0 Speed L	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL	Train/Bus#Recorded Direction Of Travel EASTBOUND Direction Of Travel	D CLASS Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Cont NO CONT	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL	TotalTra 0 Speed L	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
5	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL) Truck Bus or HazMat	Train/Bus#Recorded Direction Of Travel EASTBOUND Direction Of Travel	D CLASS Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Cont NO CONT	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL	TotalTra 0 Speed L	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE rol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL Truck Bus or HazMat NO Vehicle	Train/Bus#Recorded Direction Of Travel EASTBOUND Direction Of Travel	D CLASS Total#Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT Road Curva STRAIGH	erating As Classifications Issued CrashTire Mark ection rol ROL eture T	TotalTra 0 Speed L	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL Truck Bus or HazMat NO Vehicle License Plate Number	Train/Bus#Recorded Direction Of Travel EASTBOUND Direction Of Travel	D CLASS Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT Road Curva STRAIGH	erating As Classifications Issued CrashTire Mark ection IAL FUNCTION rol ROL eture T	Total Tra 0 Speed L 45	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOU Truck Bus or HazMat NO Vehicle License Plate Number AFW3832	Train/Bus#Recorded Direction Of Travel EASTBOUND DIRECTION OF TRAVEL	Total # Citat 2 Pre 0 Special Fun NO SPECI Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU	erating As Classifications Issued CrashTire Mark ection rol ROL eture T	Total Tra 0 Speed L 45	AUTOMO Operating A illers illers Emergency NOT APP Traffic Conf NO Road Grade DOWNHIL Country of Is UNITED S	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOU) Truck Bus or HazMat NO Vehicle License Plate Number AFW3832 Vehicle Identification No	Train/Bus#Recorded Direction Of Travel EASTBOUND DUITE OF TRAVEL DUITE	D CLASS Total#Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make	erating As Classifications Issued CrashTire Mark ection IAL FUNCTION rol ROL eture T	Total Tra 0 Speed L 45 St Wi Year	AUTOMO Operating A illers illers Emergency NOT APP Traffic Conf NO Road Grade DOWNHIL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL Truck Bus or HazMat NO Vehicle License Plate Number AFW3832 Vehicle Identification Not 1J4GL48K43W6346	Train/Bus#Recorded Direction Of Travel EASTBOUND DUITE OF TRAVEL DUITE	Total#Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONTI Road Curva STRAIGH Plate Type AUT - AU Make JEEP	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL Iture T	Total Tra 0 Speed L 45	AUTOMO Operating A illers illers illers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model LIBERTY	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL Truck Bus or HazMat NO Vehicle License Plate Number AFW3832 Vehicle Identification Not 1J4GL48K43W6346 Color	Train/Bus#Recorded Direction Of Travel EASTBOUND DUBY DU	Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT! Road Curva STRAIGH Plate Type AUT - AU Make JEEP Body Style	erating As Classifications Issued CrashTire Mark Ction IAL FUNCTION rol ROL Iture T	St Wi Year 2003	AUTOMO Operating A illers illers Emergency NOT APP Traffic Conf NO Road Grade DOWNHIL Country of Is UNITED ST	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL Truck Bus or HazMat NO Vehicle License Plate Number AFW3832 Vehicle Identification Not 1J4GL48K43W6346	Train/Bus#Recorded Direction Of Travel EASTBOUND DUBY DU	Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT! Road Curva STRAIGH Plate Type AUT - AU Make JEEP Body Style	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL Iture T	St Wi Year 2003	AUTOMO Operating A illers illers illers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model LIBERTY	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOU Truck Bus or HazMat NO Vehicle License Plate Number AFW3832 Vehicle Identification No 1J4GL48K43W6346 Color SiL - SiLVER (ALUM	Train/Bus#Recorded Direction Of Travel EASTBOUND DUBY DU	Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT! Road Curva STRAIGH Plate Type AUT - AU Make JEEP Body Style	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL Iture T	St Wi Year 2003	AUTOMO Operating A illers illers illers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model LIBERTY	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOU Truck Bus or HazMat NO Vehicle License Plate Number AFW3832 Vehicle Identification No 1J4GL48K43W6346 Color SiL - SiLVER (ALUM	Train/Bus#Recorded Direction Of Travel EASTBOUND DUBY DU	Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT Road Curva STRAIGH* Plate Type AUT - AU Make JEEP Body Style UT - SPO	erating As Classifications Issued CrashTire Mark ction IAL FUNCTION rol ROL Iture T	St Wi Year 2003	AUTOMO Operating A illers illers illers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model LIBERTY	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		
	Unit Summary Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHIC Total Occs 1 Insurance? NO Most Harmful Event: Collision TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOL Truck Bus or HazMat NO Vehicle License Plate Number AFW3832 Vehicle Identification Not 1J4GL48K43W6346 Color SIL - SILVER (ALUM Initial Contact Point	Train/Bus#Recorded Direction Of Travel EASTBOUND DUBY DU	Total # Citat 2 Pre 6 Special Fun NO SPECI Traffic Cont NO CONT Road Curva STRAIGH* Plate Type AUT - AU Make JEEP Body Style UT - SPO Vehicle Da	erating As Classifications Issued CrashTire Mark ction rol ROL iture T	St Wi Year 2003	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S Model LIBERTY Bus Use	Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use LICABLE crol Inoperative/Missing		

6TL0B7D6TK 21-00746

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/26/2021

Crash Time 12:00 PM

		Towed Due To Damage TOWED DUE TO DISABLE	NG DAMA		/ehicle Removed By REEDSBURG SALVAGE	=			
GOING STRAIGHT					Vehicle Factors				
		Driver Prior Action Other		1	NOT APPLICABLE				
UNIT	VEHICLE	Driver Actions SPEED TOO FAST/COND, WIND, SLIPPERY SURFAC	FAILURE CE, MOTO	TO CONTROL, F R VEHICLE, OBJ	FAILED TO KEEP IN DE IECT, NON-MOTORIST	SIGNATED LAN IN ROADWAY, E	NE, SWERVED OR AVOIDED DUE TO ETC.		
9	ы	OwnerName ALANA CLAIRE BERGQUIST (608) 393-4132			Owner Address 120 RIVER ST LA VALLE, WI 53941 , US				
		Sequence Of Events							
	ā	Event TRAFFIC SIGN POST							
	05	Event TREE							
	03	Event							
	94	Event							
		Individual							
		Driver ALANA CLAIRE BERGQU	ANA CLAIRE BERGQUIST				Sex FEMALE		
⊢	DUA	(608) 393-4132			Date of Birth		Race WHITE		
IN	INDMIDUAL	Address 120 RIVER ST LA VALLE, WI 53941, US			Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES				
	Sar	On Duty ety Equipment	Crash		Safety Equipment				
		Row 01 - FRONT ROW	Seat Po		SHOULDER & LAP B	ELT			
		HelmetUse			Helmet Compliance				
		Eye Protection			Tint Compliance				
٤	8	Injury Severity Injury SUSPECTED MINOR INJURY			Airbag DEPLOYED-FRONT				
		Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT AP					Trapped/Extricated NOT TRAPPED		
		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run#		
		Hospital			Date of Death Time of Death				
		Distracted By NOT A	ed By Source PPLICABL	E (NOT DISTRA	CTED)				
		Distracted By Action NOT DISTRACTED							
		Non Motorist	Unit#	Location					

6TL0B7D6TK 21-00746

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/26/2021

Crash Time 12:00 PM

		Prior Action							
TIND	INDIVIDUAL	Action							
		Action Other							To/From School
	Į	Drug & Alcoh	Suspected Alc	ohol Use	Suspected Dru NO	ug Use			•
		Alcohol Test Giver		Alcohol Test Ty	ре			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Type Drug Test Re		Drug Test Results	I	
0	001	Drug Type							
		Individual Conditio	n						
		APPEARED NO	RMAL						
	•	Violations	an ka	go g					
	0.1	UTC Number BC938434	Issue To? 001	Statute Number 343.43(1)(d)	Description LICENSE RE	ESTRICT	ION VIOLATION	-CLASS D OR M VEI	HICLE
	05	UTC Number BC938435	Issue To? 001	Statute Number 344.62(1)	Description OPERATE M	OTOR \	/EHICLE W/O IN	SURANCE	
	Pro _l	perty Ownei	r ====						
PROP 01		ernment VNSHIP OF WINI I) 524-6654	FIELD		Address E6274 BASS F REEDSBURG,		59 , US		
	Fixe	ed Objects St	ruck	######################################		·vvvvvvvv		ra era era era era era era era era era e	
	5		Struck Object TRAFFIC SIGN	POST					Damage Tag Number 337908
							ns.	THE PARTY OF THE P	