# **6TL0D0GSGK** 21-01293

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	Primary Crash Document#		Agency Crash Number 21-01293		Investigating Officer/Deputy DEPUTY S. FINNEGAN			
Crash Date 02/13/2021	Crash Time 01:55 PM			rived 2021	Time Arrived 02:17 PM			
Crash Date 02/13/2021  Date Notified 02/13/2021  On Emergency  Government Property	Time Notified 02:00 PM		Total Ui	nits	Total Injured	Total Kille	ed	
On Emergency	lît and Run	Lane Close		☐ Work Zone	ł	or Towed	Reporting Threshold	
Government Property	J	hool Zone	School NO	Bus Related	Tags			
Reportable	Crash Type DT4000 (STA	NDARD CRASH	ł)		Amend	ed	Secondary  Crash	
Diagram Diagram						Reconstruction	n Dv	
						Photos By		
						Additional Info	prmation	
	DAMAGE NOI PORTABLE	1						
The government of the second	ant officer are	oo that I have a	O+ = d-1 = -	ł any C IIO dośc in 4	hic roport			
I, a sworn law enforcer	N DRIVER CAUGHT	THE EDGE OF TH	E BLACK	TOP WITH HIS PASSEN	GER SIDE TIRES			
DITCH WHICH IS FILLED WITH S	NOW. HE BECAME	STUCK IN THE SN	IOW AND	BILLS TOWING WAS CA	ALLED TO REMOVE	: THE VEHICLE	FROM THE DITCH.	

# **6TL0D0GSGK** 21-01293

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/13/2021

Crash Time 01:55 PM

	Location <b>=</b>										
-	ON CTHT NB					Latitude			Longitud		
	46 FT S OF HILLMAN RD IN THE TOWN OF DELTON IN SAUK COUNTY					43.583331979		-89.746799539			
						X Coordin			Y Coord		
						278238.15625			4829262.5		
						Structure Type NO STRUCTURE					
(	Crash Scene										
1	First Harmful Event					FirstHarm	nful Event Lo	ocation			
	OTHER NON-COLLISIO	ON					ER RIGH				
	Manner of Collision					Light Condition					
	00 - NO COLLISION W/	/VEHIC	CLE IN TRANSPORT			DAYLIG	HT				
	00 - NO COLLISION W/VEHICLE IN TRANSPORT  Road Surface Condition(s)  SNOW					Roadway Factor(s)					
ŀ	Environment Factor(s)					1					
	NONE					NONE					
ŀ	Weather Condition(s)						-				
	CLEAR										
	Animal Type						Relation To Trafficway				
	 					TRAFFICWAY - ON ROAD					
	Crash Classification - Loca	ation				Crash Classification - Jurisdiction					
	PUBLIC PROPERTY						NO SPECIAL JURISDICTION				
	Tribal Land						Access Control NO CONTROL			Special Study	
	Within Interchange Area	- 1	inction Location ON-JUNCTION		Intersection	on Type INTERSE	CTION				
	110	140	011-0011011011		INO I AIN	114 1 21/02	011011				
l Į		147			NOT AN	IN I LIVOL	011011				
 	Unit Summary Unit Status	140		Vehicle Ope				UnitType			
 	Unit Summary Unit Status IN TRANSIT			Vehicle Ope				TRUCK			
	Unit Summary Unit Status IN TRANSIT Vehicle Type			1				1	s Endorse	ments	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU	UP TR	RUCK	D CLASS	erating As C	Classification	1	TRUCK Operating A			
	Unit Summary Unit Status IN TRANSIT Vehicle Type	UP TR		1	erating As C	Classification		TRUCK Operating A		ments Mat Types	
	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance?	UP TR	RUCK Train/Bus#Recorded Direction Of Travel	Total#Citat	erating As C	classification	Total Trail 0 Speed Lin	TRUCK Operating A	Total Haz  0  Total Lane	Mat Types	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES	UP TR	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total#Citat 0 Pre	erating As C tions Issued CrashTire Mark	classification	Total Trail	TRUCK Operating A ers	Total Haz  0  Total Lance	MatTypes es	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance?	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total#Citat	erating As C tions Issued CrashTire Mark	Classification	Total Trail 0 Speed Lin	TRUCK Operating A	Total Haz  0 Total Lane 2 Motor Veh	MatTypes es	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total#Citat 0 Pre Special Fun	erating As C tions Issued CrashTire Mark notion IAL FUNC	Classification	Total Trail 0 Speed Lin	TRUCK Operating A ers nit Emergency	Total Haz  0  Total Land  2  Motor Veh	MatTypes es icle Use	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total#Citat 0 Pre SpecialFur NO SPEC	erating As C tions Issued CrashTire Mark Action IAL FUNC	Classification	Total Trail 0 Speed Lin	TRUCK Operating A ers  nit Emergency NOT APPI Traffic Cont	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
5	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As C  tions Issued  CrashTire Mark nection IAL FUNC	Classification	Total Trail 0 Speed Lin	TRUCK Operating A  ers  nit  Emergency NOT APP  Traffic Cont NO Road Grade	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	erating As C  tions Issued  CrashTire Mark nection IAL FUNC	Classification	Total Trail 0 Speed Lin	TRUCK Operating A ers  nit Emergency NOT APPI Traffic Cont	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
5	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As C  tions Issued  CrashTire Mark nection IAL FUNC	Classification	Total Trail 0 Speed Lin	TRUCK Operating A  ers  nit  Emergency NOT APP  Traffic Cont NO Road Grade	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As C  tions Issued  CrashTire Mark nection IAL FUNC	Classification	Total Trail 0 Speed Lin	TRUCK Operating A  ers  nit  Emergency NOT APP  Traffic Cont NO Road Grade	Total Haz  0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
5	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As C  tions Issued  CrashTire Mark  nction IAL FUNC  trol  ROL  ature T	Classification	Total Trail  0 Speed Lin  55	TRUCK Operating A  ers  nit  Emergency NOT APP  Traffic Cont NO Road Grade	Total Haz  0  Total Lane 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
5	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO Vehicle	UP TRI	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	erating As C  tions Issued  CrashTire Mark  nction IAL FUNC  trol  ROL  ature T	Classification	Total Trail  0 Speed Lin  55	TRUCK Operating A ers  nit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz  0  Total Lane 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
5	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO  Vehicle License Plate Numbe 2863200B Vehicle Identification	UP TRI  I ion With ON  DED  OUS)	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND h	Total# Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LiG Make	erating As C  tions Issued  CrashTire Mark  nation IAL FUNC  trol ROL  ature T	Classification	Total Trail 0 Speed Lin 55	TRUCK Operating A ers  it  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is	Total Haz  0  Total Lane 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
5	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisis OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO  Vehicle License Plate Numbe 2863200B Vehicle Identification 5TFAY5F18LX900	UP TRI  I ion With ON  DED  OUS)	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND h	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LIC Make TOYOTA	erating As C  tions Issued  CrashTire Mark nection IAL FUNC  trol ROL ature T	Classification	Total Trail 0 Speed Lin 55	TRUCK Operating A  ers  nit  Emergency NOT APP  Traffic Cont NO  Road Grade LEVEL  Country of is UNITED ST	Total Haz  0  Total Lane 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
10	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO  Vehicle License Plate Numbe 2863200B Vehicle Identification	UP TRI  I ion With ON  DED  OUS)	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND h	Total# Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LiG Make	erating As C  tions Issued  CrashTire Mark nection IAL FUNC  trol ROL ature T	Classification	Total Trail 0 Speed Lin 55	TRUCK Operating A ers  it  Emergency NOT APP Traffic Conf NO Road Grade LEVEL  Country of is UNITED ST	Total Haz  0  Total Lane 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO  Vehicle License Plate Numbe 2863200B Vehicle Identification 5TFAY5F18LX900 Color Initial Contact Point	UP TRI  I ion With  ON  DED  OUS)	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND h	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LIC Make TOYOTA	erating As Continued and the continued at the continued a	Classification	Total Trail 0 Speed Lin 55	TRUCK Operating A  ers  nit  Emergency NOT APP  Traffic Cont NO  Road Grade LEVEL  Country of is UNITED ST	Total Haz  0  Total Lane 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs Insurance? YES Most Harmful Event: Collisi OTHER NON-COLLISIO Traffic Way TWO-WAY, NOT DIVID Surface Type BLACKTOP (BITUMING Truck Bus or HazMat NO  Vehicle License Plate Numbe 2863200B Vehicle Identification 5TFAY5F18LX900 Color	UP TRI  I ion With  ON  DED  OUS)	RUCK Train/Bus#Recorded Direction Of Travel NORTHBOUND h	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH  Plate Type LTK - LIG Make TOYOTA Body Style	erating As C  tions Issued  CrashTire Mark nction IAL FUNC  trol ROL ature T	Classification	Total Trail 0 Speed Lin 55	TRUCK Operating A  ers  nit  Emergency NOT APP  Traffic Cont NO  Road Grade LEVEL  Country of is UNITED ST	Total Haz  0  Total Lane 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use	

### 6TL0D0GSGK 21-01293

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/13/2021

Crash Time 01:55 PM

		Towed Due To Damage NOT TOWED		Vehicle Removed By BiLLS TOWING				
		What Driver Was Doing		Vehicle Factors				
		GOING STRAIGHT		Versione i decors				
		Driver Prior Action Other		NOT APPLICABLE				
LIND	VEHICLE	DriverActions FAILURE TO CONTROL						
	ь	OwnerName KRZYSZTOF KARLESZKO (224) 717-1124	ı	Owner Address 708 AUTUMN DR BOLINGBROOK, IL 60490 , US				
		Sequence Of Events						
	10	Event OTHER NON-COLLISION						
	8	Event						
	63	Event						
	75	Event						
_		Policy Holder						
UNIT		Insurance Company		Individual				
_		ILLINOIS-FARMERS-INS-C	; <b>o</b>	KRZYSZTOF KARLESZKO				
	200 M							
		ESPERANCE AND A CONTRACT OF THE PROPERTY OF TH		I Charles and				
		Driver KRZYSZTOF KARLESZKO		Citations issued	Sex MALE			
		Driver		Citations issued	Sex			
NIT		Driver KRZYSZTOF KARLESZKO		Citations Issued  0  Date of Birth	Sex MALE			
TINO	INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124	)	Citations issued 0	Sex MALE Race			
LIND	INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490	, US	Citations Issued  0  Date of Birth  Driver License Number	Sex MALE Race			
TINO	INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  fety Equipment	, <b>US</b> Crash	Citations Issued  0  Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment	Sex MALE Race			
FINO	INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  Fety Equipment  Row 01 - FRONT ROW	, US	Citations issued  0  Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT	Sex MALE Race			
FIND	INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  Fety Equipment Row 01 - FRONT ROW  Helmet Use	, <b>US</b> Crash  Seat Position	Citations issued  0  Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance	Sex MALE Race			
	E INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  On Duty Control of the	, US  Crash  Seat Position 07 - LEFT	Citations Issued  0  Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Helmet Compliance  Tint Compliance	Sex MALE Race			
	INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  On Duty C  Pety Equipment  Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Sev NO APP	, US  Crash  Seat Position 07 - LEFT  verity PARENT INJURY	Citations issued  0  Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance	Sex MALE Race  ED STATES			
	E INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  On Duty C  ety Equipment  Row 01 - FRONT ROW  Helmet Use  Eye Protection  Injury Sev NO APP	, US  Crash  Seat Position 07 - LEFT	Citations Issued  0 Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYED	Sex MALE Race  PED STATES  Trapped/Extricated			
	E INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection  Injury Set NO APP Ejected NOT EJECTED Medical Transport	, US  Crash  Seat Position 07 - LEFT  verity  PARENT INJURY Ejection Path	Citations Issued  0 Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYED	Sex MALE Race  ED STATES			
	E INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  Fety Equipment Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Set NO APP Ejected NOT EJECTED	, US  Crash  Seat Position 07 - LEFT  verity  PARENT INJURY Ejection Path	Citations issued  0 Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Helmet Compliance  Tint Compliance  Airbag  NON DEPLOYED	Sex MALE Race FED STATES  Trapped/Extricated NOT TRAPPED			
	E INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  Fety Equipment Row 01 - FRONT ROW Helmet Use  Eye Protection  Injury Set NO APP Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	, US  Crash  Seat Position 07 - LEFT  Verity  PARENT INJURY  Ejection Path NOT EJECTED/NOT API	Citations Issued  0 Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance  Tint Compliance  Airbag NON DEPLOYED  PLICABLE  EMS Agency Identifier	Sex MALE Race  FED STATES  Trapped/Extricated NOT TRAPPED EMS Run#			
	E INDIVIDUAL	Driver KRZYSZTOF KARLESZKO (224) 717-1124  Address 708 AUTUMN DR BOLINGBROOK, IL 60490  Fety Equipment Row 01 - FRONT ROW HelmetUse  Eye Protection  Injury Sev NO APP Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	, US  Crash  Seat Position 07 - LEFT  verity  PARENT INJURY Ejection Path	Citations Issued  0 Date of Birth  Driver License Number  STATE: ILLINOIS COUNTRY: UNIT  Safety Equipment  SHOULDER & LAP BELT  Heimet Compliance  Tint Compliance  Airbag NON DEPLOYED  PLICABLE  EMS Agency Identifier	Sex MALE Race  FED STATES  Trapped/Extricated NOT TRAPPED EMS Run#			

# **6TL0D0GSGK** 21-01293

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/13/2021

Crash Time 01:55 PM

	Non Motorist Striking Unit#	Location				
	Prior Action					
TIND	Action					
	Action Other					To/From School
	Drug & Alcohol NO	Jse	Suspected Drug Use NO			
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type			Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results		
01	Drug Type					
	Individual Condition					
	APPEARED NORMAL					