WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document# Crash Time 08:21 AM Time Notified 08:21 AM		Agency 21-045	Crash Number 571		Investigating Officer/Deputy DEPUTY B. STODDARD Time Arrived 08:56 AM				
2	Crash Date 05/26/2021			Date Ar 05/26/2		1					
TL0D6N018	Date Notified 05/26/2021			Total Ui	nits	Total Injure	Total Injured 00 Total Killed 00				
0	On Emergency Hit	t and Run Lane Close				☐ Trailer or Towed			Reporting Threshold		
119	Government Property	Active Sc	hool Zone	School NO	Bus Related	Tags					
	▼ Reportable	Crash Type DT4000 (STA	NDARD CRASH	H)		Amer	nded		Secondary Crash		
ĺ	Description Diagram							onstruction			
	Overhead Railro Bridge		Saraboo St				Add	tos By TODDAF itional Info			
		en e			Not to Sca	ıle					
	I, a sworn law enforceme						G UNDE	R THE RA	ILROAD BRIDGE. THE		
	RAILROAD BRIDGE IS MARKED WI UNDER THE BRIDGE WHEN THE T TRUCK WAS UNDER 11'6" BUT HE	TH ROAD SIGNS OP AND BACK OI	AT 11'6"NORTH AN THE TRUCK STR	ND SOUTH	I OF THE BRIDGE. UNIT UNDERSIDE OF THE RAI	1 OPERATOR	TRAVEL	ED ABOU	T HALF TO TWO-THIRDS		

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/26/2021

Crash Time 08:21 AM

	ON BARABOO ST 132 FT S				Latitude 43.374606933			Longitude -89.630506041		
	OF CHURCH ST (BRIDGE)	X Coordin				Y Coordinate				
	,		286894.5625 4805776.5							
	N THE VILLAGE OF ME N SAUK COUNTY	I	Structure Type BRIDGE							
C	rash Scene 💻			•						
П	First Harmful Event			FirstHarn	nful Event	Location				
	BRIDGE OVERHEAD ST	TRUCTURE		ON ROA						
	Manner of Collision	/EHICLE IN TRANSPORT		Light Con DAYLIG						
⊢	Road Surface Condition(s)	VEHICLE IN TRANSPORT			Factor(s)					
	DRY									
Ļ	Environment Factor(s)									
	NONE			NONE						
L										
	Weather Condition(s)									
	CLEAR									
'	Animal Type			II	To Traffico CWAY - (vay ON ROAD	•			
	Crash Classification - Location	on				n - Jurisdiction	Jurisdiction			
	PUBLIC PROPERTY Tribal Land				NO SPECIAL JURISDICTI			I		
	Iripai Land			Access Control NO CONTROL				Special Study		
	Within Interchange Area	Junction Location		Intersection Type			·			
L	NO	NON-JUNCTION	NOT	AN INTERSE	CTION					
	nit Cummanı =									
	Init Summary =		L Vahiala Onaratina	An Classification		1 1 14 7				
1	Jnit Status IN TRANSIT		Vehicle Operating B CLASS	As Classification	3	Unit Type TRUCK				
_ [Jnit Status N TRANSIT Vehicle Type			As Classification	1	1	As Endorse	ments		
I.n	JnitStatus N TRANSIT /ehicleType STRAIGHT TRUCK (INS		B CLASS			TRUCK Operating A				
I.O :	UnitStatus IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS	SERT TRUCK) Train/Bus#Recorded	B CLASS Total#Citations is		TotalTra	TRUCK Operating A	TotalHaz	ments Mat Types		
I.O	JnitStatus N TRANSIT /ehicleType STRAIGHT TRUCK (INS		B CLASS Total#Citations Is 0	ssued		TRUCK Operating A		Mat Types		
I.O	UnitStatus IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Fotal Occs	Train/Bus#Recorded	B CLASS Total#Citations is	ssued	Total Tr	TRUCK Operating A ailers	TotalHaz 0 TotalLan 2	Mat Types es		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs I nsurance?	Train/Bus#Recorded Direction Of Travel SOUTHBOUND on With	B CLASS Total#Citations Is 0 Pre Crash	ssued	TotalTra 0 Speed L	TRUCK Operating A	TotalHaz 0 TotalLan 2 MotorVeh	Mat Types es		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Fotal Occs Insurance? YES Wost Harmful Event: Collisio BRIDGE OVERHEAD ST	Direction Of Travel SOUTHBOUND on With	Total#Citations is 0 Pre Crash Mark Special Function NO SPECIAL FI	ssued	TotalTra 0 Speed L	TRUCK Operating A ailers Limit Emergency	Total Haz 0 Total Land 2 Motor Veh	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Fotal Occs Insurance? YES Wost Harmful Event: Collision BRIDGE OVERHEAD ST Fraffic Way FWO-WAY, NOT DIVIDE	Direction Of Travel SOUTHBOUND on With	Total # Citations is 0 Pre Crash Mark Special Function NO SPECIAL Fit Traffic Control NO CONTROL	ssued	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO	Total Haz 0 Total Land 2 Motor Veh LICABLE	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Fotal Occs Insurance? YES Wost Harmful Event: Collisio BRIDGE OVERHEAD ST Fraffic Way FWO-WAY, NOT DIVIDE Surface Type	Direction Of Travel SOUTHBOUND on With FRUCTURE	Total # Citations is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature	ssued	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO Road Grade	Total Haz 0 Total Land 2 / Motor Veh LICABLE	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs Insurance? YES Most Harmful Event: Collisio BRIDGE OVERHEAD ST Traffic Way TWO-WAY, NOT DIVIDE Burface Type BLACKTOP (BITUMINO Truck Bus or HazMat	Direction Of Travel SOUTHBOUND on With FRUCTURE ED	B CLASS Total # Citations is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT	ssued	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO	Total Haz 0 Total Land 2 / Motor Veh LICABLE	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs Insurance? YES Wost Harmful Event: Collisio BRIDGE OVERHEAD ST Traffic Way FWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat TRUCK OR TRUCK COM	Direction Of Travel SOUTHBOUND on With FRUCTURE	B CLASS Total # Citations is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT	ssued	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO Road Grade	Total Haz 0 Total Land 2 / Motor Veh LICABLE	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INSTOTAL COLLING) Total Occs Insurance? YES Wost Harmful Event: Collision BRIDGE OVERHEAD ST Fraffic Way FWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Fruck Bus or HazMat TRUCK OR TRUCK COLLING Vehicle	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations Is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT VWR/GCWR	ssued	TotalTra 0 Speed L 25	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Land 2 Motor Veh LICABLE trol Inopera	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs Insurance? YES Wost Harmful Event: Collisio BRIDGE OVERHEAD ST Traffic Way FWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat TRUCK OR TRUCK COM	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT	nTire	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO Road Grade	Total Haz 0 Total Land 2 Motor Veh LICABLE trol Inopera	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INSTOTAL COMPANY) TOTAL COCS INSURANCE WOST HARMFUL EVENT: COLLISION BRIDGE OVERHEAD ST TRAFFIC WAY TWO-WAY, NOT DIVIDE SURFACE Type BLACKTOP (BITUMINO) TRUCK OR TRUCK COMPANY VEHICLE License Plate Number 71265X Vehicle Identification	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations Is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT VWR/GCWR	nTire	TotalTra 0 Speed L 25	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade DOWNHIL	Total Haz 0 Total Land 2 Motor Veh LICABLE trol Inopera	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs Insurance? YES Most Harmful Event: Collisio BRIDGE OVERHEAD ST Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat TRUCK OR TRUCK COI Vehicle License Plate Number 71265X Vehicle Identification N 1HTGSSJT8EH792	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations Is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT VWR/GCWR Plate Type APO - APPORT Make INTERNATION	TIONED	Total Tr. 0 Speed L 25	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade DOWNHIL Country of Is UNITED S' Model STRAIGHT	Total Haz 0 Total Land 2 Motor Veh LICABLE trol Inopera	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INSTOTAL COMPANY) TOTAL COCS INSURANCE WOST HARMFUL EVENT: COLLISION BRIDGE OVERHEAD ST TRAFFIC WAY TWO-WAY, NOT DIVIDE SURFACE Type BLACKTOP (BITUMINO) TRUCK OR TRUCK COMPANY VEHICLE License Plate Number 71265X Vehicle Identification	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations Is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT VWR/GCWR Plate Type APO - APPORT	TIONED	Total Tr. 0 Speed L 25 St Wi Year	TRUCK Operating A ailers Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S:	Total Haz 0 Total Land 2 Motor Veh LICABLE trol Inopera	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs Insurance? YES Most Harmful Event: Collisio BRIDGE OVERHEAD ST Traffic Way FWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat TRUCK OR TRUCK COI Vehicle License Plate Number 71265X Vehicle Identification N 1HTGSSJT8EH792 Color BLK - BLACK	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations Is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT VWR/GCWR Plate Type APO - APPORT Make INTERNATION Body Style	TIONED	Total Tr. 0 Speed L 25 St Wi Year	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade DOWNHIL Country of Is UNITED S' Model STRAIGHT	Total Haz 0 Total Land 2 Motor Veh LICABLE trol Inopera	Mat Types es icle Use		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs Insurance? YES Most Harmful Event: Collisio BRIDGE OVERHEAD ST Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat TRUCK OR TRUCK COI Vehicle License Plate Number 71265X Vehicle Identification N 1HTGSSJT8EH792 Color BLK - BLACK Initial Contact Point 13 - TOP	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations Is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT WWR/GCWR Plate Type APO - APPORT Make INTERNATION Body Style OT - OTHER Vehicle Damage	TIONED	TotalTra 0 Speed L 25 St WI Year 2014	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con- NO Road Grade DOWNHIL Country of is UNITED S' Model STRAIGHT Bus Use	Total Haz 0 Total Land 2 / Motor Veh LICABLE trol Inopera e LL suance TATES	Mat Types es icle Use tive/Missing		
	Unit Status IN TRANSIT Vehicle Type STRAIGHT TRUCK (INS Total Occs Insurance? YES Most Harmful Event: Collisio BRIDGE OVERHEAD ST Traffic Way FWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat TRUCK OR TRUCK COI Vehicle License Plate Number 71265X Vehicle Identification N 1HTGSSJT8EH792 Color BLK - BLACK	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FRUCTURE DUS) MBINATION > 10,000LBS G	B CLASS Total # Citations Is 0 Pre Crash Mark Special Function NO SPECIAL FI Traffic Control NO CONTROL Road Curvature STRAIGHT WWR/GCWR Plate Type APO - APPORT Make INTERNATION Body Style OT - OTHER Vehicle Damage	TIONED	TotalTra 0 Speed L 25 St WI Year 2014	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con- NO Road Grade DOWNHIL Country of is UNITED S' Model STRAIGHT Bus Use	Total Haz 0 Total Land 2 / Motor Veh LICABLE trol Inopera e LL suance TATES	Mat Types es icle Use		

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/26/2021

Crash Time 08:21 AM

		Towed Due To Damage		Vehicle Removed By				
		NOT TOWED		OPERATOR				
		What Driver Was Doing		Vehicle Factors				
		GOING STRAIGHT		NOT APPLICABLE				
		Driver Prior Action Other		as i accession				
LINI	VEHICLE	Driver Actions NO CONTRIBUTING ACTI	ON					
5	5	Owner Name LUBETECH & PARTNERS	LLC	Owner Address 4033 W CUSTER AVE MILWAUKEE, WI 53209 , US				
		Sequence Of Events		averes very exercise and a second control of the co				
	5	Event BRIDGE OVERHEAD STR						
		Event						
	8							
	03	Event						
	3	Event						
_		Policy Holder						
INN		Insurance Company ZURICH-AMERICAN-INS-0		Organization/Company LUBETECH & PARTNERS LLC				
		Individual						
		Driver		Citations ssued	Sex			
		BRIAN ALLEN SIMCAKOS	KI	0	MALE			
_	MIN	(715) 340-5508		Date of Birth	Race WHITE			
TINO	INDIVIDUAL	Address 2130 BIRCH DR PLOVER, WI 54467, US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES				
		On Duty	Crash	Safety Equipment				
	04	fety Equipment	T	CHOSH DED & LAB DELT				
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT				
		Helmet Use		Helmet Compliance				
		Eye Protection		TintCompliance				
2	8	Injury Se	PARENT INJURY	Airbag NON DEPLOYED				
		Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT APP		PI ICARI E	Trapped/Extricated NOT TRAPPED			
		Medical Transport		EMS Agency Identifier	EMS Run#			
		NOT TRANSPORTED						
		Hospital		Date of Death	Time of Death			
		Hospital	ed By Source PPLICABLE (NOT DISTR		Time of Death			

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/26/2021

Crash Time 08:21 AM

		Non Motorist Striking	Jnit#	Location							
		Prior Action		•							
		Action									
E	DUAL										
UNIT	INDIVIDUAL										
	=										
		Action Other									To/From School
	Drug & Alcohol Alcohol Test Given TEST NOT GIVEN Suspected Alcohol Use NO Alcohol Test Type				Suspected Drug Use NO						
					L je			Alcohol Test Results			
				Drug Test Type	Drug Test Resu			Results	alts		
01	Drug Type										
	Individual Condition										
		APPEARED NORMAL									
		Carrier	renerenenenenen ortortortortortortortorto	rananananananananananananananananananan	rarararara edeletetetet	Source	rs is	erererere Terererer	ananananananananananananananananananan		ilararararararararararararararararararar
		Use Vehicle C	Owner San	ne as Carrier		DRIVER Address					
01	5	LUBETECH & PARTNERS LLC USDOT# 185609				4033 W CUSTER AVE MILWAUKEE, WI 53209 , US					
	GVWR Vehicle Configuration					Caro			o Body Type		
TINO	8	MORE THAN 26,000 LB SINGLE UNIT TRUCK (3			3 OR MORE AXLES) VAN			N/ENCLOSED BOX mitted Load			
5	RUCK	US DOT# Carrier Type 185609									
	H	OS/OW Load WJ Permit Number		Permitted Veh		Route		Permit Land		scort Vehicle Present	
		Measured Height	Measu	ired Length		Measured Widt	h		Measured Weight		
		perty Owner			A -1-1						
, a	Wr:	anization/Company SOUTHERN RAILROAD			Address						
PROP OWNER											
		ed Objects Struck Striking Unit Struck Object	:t						Structure Number	a	amage Tag Number
	5			STRUCTURE							