6TL097RB6B 21-09957

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/17/2021

Crash Time 04:16 AM

	Document Number Override		Primary Crash Document#		Agency Crash Number 21-09957		Investigating Officer/Deputy DEPUTY C. BRATZ			
eB 9	Crash Date 10/17/2021		Crash Time 04:16 AM		Date Arrived 10/17/2021		Time Arrived 04:35 AM			
'RB	Date Notified 10/17/2021		Time Notified 04:16 AM		Total Units 01		Total Injured 00	njured Total Killed 00		
.097	On Emergency Hit		and Run Lane Closu		were Work Zone		Trailer or 1	Trailer or Towerd " '		Reporting Threshold
6TL	Government Property		Active School Zone		School Bus Related NO		Tags			
	▼ Reportable		Crash Type DT4000 (STANDARD CRASH))		Amended	Amended		Secondary Crash
	Description -									

Photos By Additional Information NONE East Lane South Ave. Picture not to Scale

, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON OCTOBER 17, 2021, AT 4:18 A.M., I RESPONDED TO A ONE VEHICLE TRAFFIC ACCIDENT ON SOUTH AVE./HORKAN RD. I ARRIVED AT LOCATION AND MADE CONTACT WITH DRIVER IDENTIFIED THROUGH WI DL. DRIVER STATED THAT HE WAS DRIVING EAST ON SOUTH AVENUE. A DEER CAME INTO ROADWAY AND HE STEERED TO THE RIGHT TO AVOID COLLIDING WITH IT. HE STATED THAT HE OVER STEERED AND COLLIDED WITH GUARD RAIL ON SOUTH SHOULDER, DAMAGING THREE WOOD PILLARS. VEHICLE SUSTAINED DISABLING DAMAGE AND WAS NOT ABLE TO BE DRIVEN AWAY WITH ALL DAMAGE BEING IN THE UNDERBODY. DRIVER STATED HE WAS NOT INJURED. VEHICLE TOWED BY CRAIGS.

6TL097RB6B 21-09957

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Crash Time 04:16 AM

	_ocation ====								
Ī	ON SOUTH AVE			Latitude			Longitud	łe	
	226 FT E			43.581124508		08		-89.946151604	
	OF HORKAN RD			X Coordir	X Coordinate		Y Coord	inate	
	IN THE TOWN OF DELLON	I A		262134.140625 Structure Type			4829569		
	IN SAUK COUNTY					I			
				I	NO STRUCTURE				
(Crash Scene								
Ī	First Harmful Event			FirstHarn	nful Event L	ocation			
	NON DOMESTICATED ANI	MAL (ALIVE)	ON ROA	DWAY					
ı	Manner of Collision			Light Con	Light Condition DARK/UNLIT Roadway Factor(s)				
	00 - NO COLLISION W/VEH	HICLE IN TRANSPORT		DARK/U					
	Road Surface Condition(s)			Roadway					
	DRY								
	Environment Factor(s)								
	ANIMAL (S) IN ROADWAY			NONE					
ŀ	Weather Condition(s)								
	CLEAR	· ·							
ŀ	Animal Type			Relation	To Trafficwa	ау			
	DEER				CWAY - C				
	Crash Classification - Location					-Jurisdiction			
	PUBLIC PROPERTY			NO SPE	NO SPECIAL JURISDICTION				
	Tribal Land			1	Access Control NO CONTROL			Special Study	
				NO CON					
	Within Interchange Area	Junction Location	Inte	Intersection Type		Туре			
	NO	NON-JUNCTION	NC	OT AN INTERSE	CTION				
į	Jnit Summary								
j	Jnit Summary Unit Status		Vehicle Operatir	ng As Classification	3	Unit Type			
	Unit Status IN TRANSIT		Vehicle Operatir D CLASS	ng As Classification	3	Unit Type TRUCK			
	Unit Status IN TRANSIT Vehicle Type			ng As Classification	3	1	s Endorse	ments	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP 1			ng As Classification		TRUCK Operating A			
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP 1 Total Occs	FRUCK	D CLASS Total#Citations		TotalTra	TRUCK Operating A	TotalHaz	ments Mat Types	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1	Train/Bus#Recorded	D CLASS		Total Tra	TRUCK Operating A	Total Haz	Mat Types	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance?	Train/Bus#Recorded Direction Of Travel	Total#Citations 0 Pre Cras	Issued	TotalTra 0 Speed Li	TRUCK Operating A	Total Haz O Total Lane	Mat Types	
10	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP 1 Total Occs 1 Insurance? YES	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total#Citations 0 Pre Cras	lssued shTire rk	Total Tra	TRUCK Operating A ilers	Total Haz 0 Total Lance	Mat Types es	
10	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP 1 Total Occs 1 Insurance? YES Most Harmful Event: Collision W	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total # Citations 0 Pre Cras Mai	Issued ShTire rk	TotalTra 0 Speed Li	TRUCK Operating A illers mit Emergency	Total Haz 0 Total Lanc 2 Motor Veh	Mat Types es	
10	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total#Citations 0 Pre Cras Mai Special Function	Issued ShTire rk	TotalTra 0 Speed Li	TRUCK Operating A ilers mit Emergency NOT APPI	Total Haz 0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
10	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control	Issued shTire rk FUNCTION	TotalTra 0 Speed Li	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont	Total Haz 0 Total Lane 2 Motor Veh LICABLE	MatTypes es icle Use	
10	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL	Issued ShTire rk FUNCTION	TotalTra 0 Speed Li	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont	Total Haz 0 Total Lane 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type	Train/Bus#Recorded Direction Of Travel WESTBOUND //ith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature	Issued ShTire rk FUNCTION	TotalTra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lane 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS	Train/Bus#Recorded Direction Of Travel WESTBOUND //ith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL	Issued ShTire rk FUNCTION	TotalTra 0 Speed Li	TRUCK Operating A ilers mit Emergency NOT APPI Traffic Cont	Total Haz 0 Total Lane 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type	Train/Bus#Recorded Direction Of Travel WESTBOUND //ith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature	Issued ShTire rk FUNCTION	TotalTra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lane 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO	Train/Bus#Recorded Direction Of Travel WESTBOUND //ith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature	Issued ShTire rk FUNCTION	TotalTra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lane 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use	
10	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle	Train/Bus#Recorded Direction Of Travel WESTBOUND //ith	Total # Citations 0 Pre Cras Mai Special Functior NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT	Issued ShTire rk FUNCTION	Total Tra 0 Speed Li 55	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	MatTypes es icle Use	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number	Train/Bus#Recorded Direction Of Travel WESTBOUND //ith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT	Issued ShTire rk FUNCTION	Total Tra 0 Speed Li 55	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	MatTypes es icle Use	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT	Issued ShTire rk FUNCTION	TotalTra 0 Speed Li 55	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of is UNITED ST	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	MatTypes es icle Use	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LiGHT Make	shTire rk FUNCTION	TotalTra 0 Speed Li 55 St Wi Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	MatTypes es icle Use	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num 1GCHK34J1WZ26059	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT Make CHEVROLET	shTire rk FUNCTION	TotalTra 0 Speed Li 55	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model GMT	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	MatTypes es icle Use	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num 1GCHK34J1WZ26059 Color	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT Make CHEVROLET Body Style	shTire rk FUNCTION	TotalTra 0 Speed Li 55 St Wi Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	MatTypes es icle Use	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num 1GCHK34J1WZ26059 Color GRN - GREEN	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT Make CHEVROLET Body Style 2D - 2DR	Issued ShTire rk FUNCTION TRUCK	TotalTra 0 Speed Li 55 St Wi Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model GMT	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	Mat Types es icle Use tive/Missing	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num 1GCHK34J1WZ26059 Color GRN - GREEN Initial Contact Point	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT Make CHEVROLET Body Style	Issued ShTire rk FUNCTION TRUCK	TotalTra 0 Speed Li 55 St Wi Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model GMT	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	Mat Types es icle Use tive/Missing	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num 1GCHK34J1WZ26059 Color GRN - GREEN Initial Contact Point	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT Make CHEVROLET Body Style 2D - 2DR	Issued shTire rk FUNCTION -	TotalTra 0 Speed Li 55 St Wi Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model GMT	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	Mat Types es icle Use tive/Missing 7 8 9 10 11 6 12	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num 1GCHK34J1WZ26059 Color GRN - GREEN Initial Contact Point	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith S) ORNER	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT Make CHEVROLET Body Style 2D - 2DR Vehicle Damag	Issued shTire rk FUNCTION -	TotalTra 0 Speed Li 55 St Wi Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model GMT	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	Mat Types es icle Use tive/Missing	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W GUARDRAIL FACE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number PL6914 Vehicle Identification Num 1GCHK34J1WZ26059 Color GRN - GREEN Initial Contact Point 01 - RIGHT FRONT COL Extent Of Damage	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith S) ORNER	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type LTK - LIGHT Make CHEVROLET Body Style 2D - 2DR Vehicle Damag	Issued shTire rk FUNCTION -	TotalTra 0 Speed Li 55 St Wi Year	TRUCK Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model GMT	Total Haz 0 Total Lane 2 Motor Veh LiCABLE rol Inopera	Mat Types es icle Use tive/Missing 7 8 9 10 11 6 12	

6TL097RB6B

21-09957

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/17/2021

Crash Time 04:16 AM

		Towed Due To Damage	NG DAMAGE	Vehicle Removed By CRAIGS TOWING						
		TOWED DUE TO DISABLING DAMAGE		Vehicle Factors						
		What Driver Was Doing GOING STRAIGHT		versicle Factors						
		Driver Prior Action Other		NOT APPLICABLE						
		Bitter Herricken Gunar								
NNI	VEHICLE	Driver Actions NO CONTRIBUTING ACTION								
2	5	OwnerName JAKOB M KRAYER (608) 434-8003		Owner Address S2485 HORKAN REEDSBURG, W						
		 Seguence Of Events								
		Sequence Of Events Event								
	5	NON DOMESTICATED ANIMAL (ALIVE)								
	8	Event GUARDRAIL FACE								
	8	Event								
	3	Event								
_		l Policy Hölder								
N		Insurance Company		Individual Individual						
_		RURAL-COMMUNITY-INS	URANCE-COMPANY	JAKOB KRAYER						
		Individual								
		Driver		Citations Issued	Sex	_				
	_	JAKOB M KRAYER (608) 434-8003		0	MALE					
-	3	,		Date of Birth	Race WHITE					
TINO	INDIVIDUAL	Address S2485 HORKAN RD REEDSBURG, WI 53959	us	Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES						
	Sai	L On Duty 'ety Equipment	Crash	Safety Equipment						
		Row	SeatPosition	SHOULDER & LA	PBELT					
		01 - FRONT ROW		Helmet Compliance						
		Eye Protection		TietCompliance						
				Tint Compliance						
2	8	Injury Severity NO APPARENT INJURY Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT APP		Airbag NON DEPLOYED						
						Trapped/Extricated				
						NOT TRAPPED				
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier EMS Run#						
		Hospital		Date of Death Time of Death		Time of Death				
		I Distract	ed By Source							
		Distracted By NOT A	PPLICABLE (NOT DISTR	ACTED)						
		Distracted By Action NOT DISTRACTED								

6TL097RB6B 21-09957

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/17/2021

Crash Time 04:16 AM

			Striking Unit#	Location				
		Non Motor	(St					
		Prior Action						
UNIT	INDIVIDUAL	Action						
		Action Other						To/From School
	L	Drug & Alcol	Suspected Alcohol to NO	Jse	Suspected Drug Use NO			
		AlcoholTestGiven AlcoholTestTy TEST NOT GIVEN		Alcohol Test Type	9		Alcohol Test Results	
		Drug Test Given Drug Test Type TEST NOT GIVEN		Drug Test Type		Drug Test Results	5	
01	001	Drug Type		•		•		
		Individual Conditi	on					
		APPEARED NO	DRMAL					
ĺ	Pro	perty Owne	er 💮 💮					
PROP 01	Government TOWNSHIP OF DELLONA (608) 524-0800				Address E8062 CTH H REEDSBURG, WI 539	59 , US		
	Fixe S	ed Objects S Striking Unit 01	truck Struck Object GUARDRAIL FACE	TENERRERERERERERE				Damage Tag Number 337840
l			********************************					