6TL0BGSFGR 21-11368

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

œ
G
ш
S
O
Ď
0
_
F

	Document Number Override		Primary Crash Document#		Agency Crash Number 21-11368		Investigating Officer/Deputy DEPUTY D. KROLIKOWSKI		
GR	Crash Date 11/26/2021		Crash Time 10:30 AM		Date Arrived 11/26/2021		Time Arrived 11:19 AM		
GSF	Date Notified 11/26/2021		Time Notified 10:52 AM		Total Units 01		Total Injured 00	'	
080	On Emergency Hi		and Run Lane Closu		ure Work Zone		Trailer or Towed Reporting Threshold		
eTL	Government Property		Active School Zone		School Bus Related NO		Tags		
_	▼ Reportable		Crash Type DT4000 (STANDARD CRASH))		Amended		Secondary Crash

Description



I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

DRIVER WAS TRAVELING EAST BOUND ON MILLER RD WHEN THE VEHICLE BEGAN TO INEXPLICABLY RAPIDLY BEEP, AT WHICH TIME THE DRIVER LOST ALL CONTROL OF STEERING AND BRAKING. THE VEHICLE CROSSED THE CENTERLINE IN FRONT OF E1839 MILLER RD AND STRUCK 2 MAILBOXES. THE DRIVER THEN OPENED THE DOOR AND JUMPED OUT. THE VEHICLE CROSSED THE CENTERLINE IN FRONT OF E1839 MILLER RD AND STRUCK 2 MAILBOXES. THE DRIVER THEN OPENED THE DOOR AND JUMPED OUT. THE VEHICLE CONTINUED ACROSS AN OPEN FIELD BEFORE CRASHING INTO A TREE AT THE EDGE OF THE FIELD.

Crash Date 11/26/2021 Crash Time 10:30 AM

6TL0BGSFGR 21-11368

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/26/2021

Crash Time 10:30 AM

	ON MILLER RD 468 FT E OF EQUESTRIAN DR	NO		43.594146705 - X Coordinate		Longitud -90.223 Y Coord	3216463	
	IN THE TOWN OF WOODLA IN SAUK COUNTY	IND		239819.5 Structure			483184	16.5
				I	UCTURE			
	Crash Scene							
	FirstHarmful Event MAILBOX			First Harm ROADSI	nful Event L DE	ocation		
	Manner of Collision 00 - NO COLLISION W/VEHI	CLE IN TRANSPORT		Light Con-				
	Road Surface Condition(s) DRY			Roadway	Factor(s)			
	Environment Factor(s)			-				
	NONE			NONE				
	Weather Condition(s)							
	CLOUDY							
	Animal Type			I	o Trafficwa CWAY - O	•		
	Crash Classification - Location PUBLIC PROPERTY				sh Classification - Jurisdiction			
	Tribal Land			NO SPECIAL JURISDICTION Access Control NO CONTROL				Special Study
	· · · · · · · · · · · · · · · · · · ·	unction Location	I	tion Type N INTERSE	CTION			I
	Unit Summary		'					
	Unit Status IN TRANSIT		Vehicle Operating As D CLASS	Classification	l	Unit Type AUTOMOR	BILE	
	Unit Status IN TRANSIT Vehicle Type			Classification		1		ments
-0	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR	Train/Rus#Recorded	D CLASS			AUTOMOI Operating A	s Endorse	
2	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1	Train/Bus#Recorded			TotalTrai	AUTOMOI Operating A	s Endorse Total Haz 0	:MatTypes
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs	Train/Bus#Recorded Direction OfTravel EASTBOUND	D CLASS Total # Citations Issue	ed	TotalTrai	AUTOMOR Operating A	s Endorse Total Haz 0 Total Lan 2	MatTypes es
UNI 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance?	Direction Of Travel EASTBOUND	Total # Citations Issue 0 Pre CrashTii	ed re	TotalTrai 0 Speed Lir	AUTOMOI Operating A	Total Haz Total Lan Total Lan Motor Veh	MatTypes es sicle Use
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED	Direction Of Travel EASTBOUND	Total # Citations Issue 0 Pre CrashTil Mark Special Function	ed re	TotalTrai 0 Speed Lir	AUTOMOS Operating A lers nit	Total Haz 0 Total Lan 2 Motor Veh ICABLE	es icle Use
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control	ed re	TotalTrai 0 Speed Lir	AUTOMOS Operating A lers mit Emergency NOT APPI Traffic Cont	Total Haz 0 Total Lan 2 Motor Veh LICABLE	es icle Use
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature	ed re	TotalTrai 0 Speed Lir	AUTOMOS Operating A ers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE	es icle Use
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature	ed re	TotalTrai 0 Speed Lir	AUTOMOS Operating A ers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE	es icle Use
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature	ed re CTION	TotalTrai 0 Speed Lir	AUTOMOS Operating A ers mit Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	es icle Use
ONI 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AKT6008 Vehicle Identification Number	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB Make	ed re CTION	Total Trai 0 Speed Lir 55 St WI Year	AUTOMOS Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	es icle Use
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AKT6008 Vehicle Identification Numb 1NXBU4EE9AZ295159	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB Make TOYOTA	ed re CTION	Total Trai 0 Speed Lir 55 St WI	AUTOMOS Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model COROLLA	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	es icle Use
ONI 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AKT6008 Vehicle Identification Number	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB Make	ed re CTION	Total Trai 0 Speed Lir 55 St WI Year	AUTOMOS Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	es icle Use
01 ONI 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AKT6008 Vehicle Identification Numb 1NXBU4EE9AZ295159 Color RED - RED Initial Contact Point	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTil Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB Make TOYOTA Body Style	ed re CTION	Total Trai 0 Speed Lir 55 St WI Year	AUTOMOS Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model COROLLA	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	es icle Use
ONI 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? YES Most Harmful Event: Collision Wit TREE Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number AKT6008 Vehicle Identification Numb 1NXBU4EE9AZ295159 Color RED - RED	Direction Of Travel EASTBOUND th	Total # Citations Issue 0 Pre CrashTill Mark Special Function NO SPECIAL FUN Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB Make TOYOTA Body Style SD - SEDAN	ed CTION	St WI Year 2010	AUTOMOS Operating A lers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of is UNITED ST Model COROLLA Bus Use	Total Haz 0 Total Lan 2 Motor Veh ICABLE rol Inopera	es sicle Use stive/Missing

6TL0BGSFGR

21-11368

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/26/2021

Crash Time 10:30 AM

		Towed Due To Damage		Vehicle Removed By					
		TOWED DUE TO DISABLIN	IG DAMAGE	STEVES AUTO SERVICE					
		What Driver Was Doing GOING STRAIGHT		Vehicle Factors					
		Driver Prior Action Other		BRAKES, STEERING					
				· 					
		Driver Actions							
	8	NO CONTRIBUTING ACTIO	JN .						
N	유								
\supset	VEHICLE								
		Owner Name		Owner Address					
5	5	GEAPZA L CAMACHO (608) 415-8025		613 VINE ST WISCONSIN DEL	.S. WI 53965 . US	3			
_		, , , , , , , , , , , , , , , , , , , ,			,				
		l Sequencei⊘fEvents:		l					
		Event							
	5	CROSS CENTERLINE							
	8	Event MAILBOX							
		Event							
	S	DITCH							
	8	Event TREE							
_		Policy Holder							
N		Insurance Company	ue co	Individual	3				
		DAIRYLAND-AMERICAN-IN	15-00	GEAPZA CAMACHO					
_									
_		Individual				<u>ninaninaninaninaninaninaninan</u>			
		Individual Driver GEAPZA L CAMACHO		Citations Issued	Sex FEMALE	ntanan atau kananan atau kananan atau kana			
		Individual Driver		Citations Issued	Sex FEMALE Race				
		Individual Driver GEAPZA L CAMACHO (608) 415-8025		Citations issued 0 Date of Birth	Sex FEMALE Race HISPANIC				
LIND		Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST		Citations Issued 0 Date of Birth Driver License Numbe	Sex FEMALE Race HISPANIC				
	INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address		Citations issued 0 Date of Birth	Sex FEMALE Race HISPANIC				
		Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53:	965 , US	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI	Sex FEMALE Race HISPANIC				
	INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST	965 , US	Citations Issued 0 Date of Birth Driver License Numbe	Sex FEMALE Race HISPANIC				
	INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53:	965 , US	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI	Sex FEMALE Race HISPANIC				
	INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53:	965 , US Crash	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment	Sex FEMALE Race HISPANIC				
	INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Fety Equipment Row	965 , US Crash Seat Position	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment	Sex FEMALE Race HISPANIC				
	INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Cety Equipment Row 01 - FRONT ROW	965 , US Crash Seat Position	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP	Sex FEMALE Race HISPANIC				
HND	g INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Fety Equipment Row 01 - FRONT ROW HelmetUse	965 , US Crash Seat Position 07 - LEFT	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP Helmet Compliance Tint Compliance	Sex FEMALE Race HISPANIC				
HND	g INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection	965 , US Crash Seat Position 07 - LEFT	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP Helmet Compliance Tint Compliance Airbag	Sex FEMALE Race HISPANIC				
HND	INDIVIDUAL	Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Fety Equipment Row 01 - FRONT ROW HelmetUse Eye Protection Injury Sev NO APP	965 , US Crash Seat Position 07 - LEFT	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP Helmet Compliance Tint Compliance	Sex FEMALE Race HISPANIC				
HND	g INDIVIDUAL	Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Fety Equipment Row 01 - FRONT ROW HelmetUse Eye Protection Injury Sev NO APP Ejected	965 , US Crash Seat Position 07 - LEFT	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP Helmet Compliance Tint Compliance Airbag DEPLOYED-FRON	Sex FEMALE Race HISPANIC	TED STATES			
HND	g INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Cety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Sex NO APP Ejected NOT EJECTED Medical Transport	965 , US Crash Seat Position 07 - LEFT Verity PARENT INJURY Ejection Path	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP Helmet Compliance Tint Compliance Airbag DEPLOYED-FRON	Sex FEMALE Race HISPANIC	Trapped/Extricated			
HND	g INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO APP Ejected NOT EJECTED Medical Transport NOT TRANSPORTED	965 , US Crash Seat Position 07 - LEFT Verity PARENT INJURY Ejection Path	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP Heimet Compliance Tint Compliance Airbag DEPLOYED-FRON* PLICABLE EMS Agency Identifier	Sex FEMALE Race HISPANIC	Trapped/Extricated NOT TRAPPED EMS Run#			
HND	g INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Cety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Sex NO APP Ejected NOT EJECTED Medical Transport	965 , US Crash Seat Position 07 - LEFT Verity PARENT INJURY Ejection Path	Citations issued 0 Date of Birth Driver License Numbe STATE: WISCONSI Safety Equipment SHOULDER & LAP Helmet Compliance Tint Compliance Airbag DEPLOYED-FRONT	Sex FEMALE Race HISPANIC	Trapped/Extricated			
HND	g INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Cety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Sex NO APP Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	965 , US Crash Seat Position 07 - LEFT Verity PARENT INJURY Ejection Path NOT EJECTED/NOT APP	Citations issued 0 Date of Birth Driver License Number STATE: WISCONSI Safety Equipment SHOULDER & LAP Heimet Compliance Tint Compliance Airbag DEPLOYED-FRONT PLICABLE EMS Agency Identifier Date of Death	Sex FEMALE Race HISPANIC	Trapped/Extricated NOT TRAPPED EMS Run#			
HND	g INDIVIDUAL	Individual Driver GEAPZA L CAMACHO (608) 415-8025 Address 613 VINE ST WISCONSIN DELLS, WI 53: Ety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury Sev NO APP Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	965 , US Crash Seat Position 07 - LEFT Verity PARENT INJURY Ejection Path NOT EJECTED/NOT APP	Citations issued 0 Date of Birth Driver License Number STATE: WISCONSI Safety Equipment SHOULDER & LAP Heimet Compliance Tint Compliance Airbag DEPLOYED-FRONT PLICABLE EMS Agency Identifier Date of Death	Sex FEMALE Race HISPANIC	Trapped/Extricated NOT TRAPPED EMS Run#			

6TL0BGSFGR 21-11368

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/26/2021

Crash Time 10:30 AM

		Non Motor	Striking Unit#	Location				
		Prior Action		1				
		Action						
	AL							
TINO	INDIVIDUAL							
5	20							
	2							
		Action Other						To/From School
				11	10 110			
	l	Drug & Alcol	Suspected Alcohol NO	Use	Suspected Drug Use NO			
		Alcohol Test Give		Alcohol Test Typ	e		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
01	Ξ	Drug Type						
0	Drug Type							
		Individual Conditi	on					
		APPEARED NO	ORMAL					
'		perty Owne	r					
10		ridual N J BOTH 3) 464-3511			Address E1980 EQUESTRIAN			
PROP OWNER	(000	9 404-3311			LAVALLE, WI 53941 ,	US		
	Fixe	ed Objects S	truck	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				
	6	Striking Unit	Struck Object MAILBOX	ISMAAIISMEAIIAMAMATISMEAIISMEAIISMEAIIISMEAIII			Structure Number	Damage Tag Number
		perty Owne						
05		ridual ARENCE P SCHI			Address 31839 MILLER RD			
PROP OWNER (3) 464-5525	WO OKEK		LAVALLE, WI 53941 ,	US		
		ed Objects S Striking Unit	Struck Object				Structure Number	Damage Tag Number
	8	01	MAILBOX					J - · · · J · · · · · · · · · · · · · · · · · · ·