WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Overri	de Primary Crash		gency Crash Number 1-12540	Investigating Of DEPUTY K. N			
Crash Date 12/30/2021	Crash Time 99:99		ate Arrived 2/31/2021	Time Arrived 12:30 AM			
Date Notified 12/30/2021	Time Notified 11:58 PM	T 0	otal Units 1	Total Injured 00	Total Kille	illed	
On Emergency	Hit and Run	Lane Closure		Trailer or	Towed	Reporting Threshold	
Government Property	Active So	shoot Zono	chool Bus Related O	Tags			
Reportable	Crash Type DT4000 (STA	Crash Type DT4000 (STANDARD CRASH)			Amended Secondary		
Description ■ Diagram				l a	o o o o o tra cotio	n Dv	
Diagram				**	econstructio	n By	
				Pł	notos By		
					1 122 11 6		
				N N	iditional Info ONE	ormation	
🔽 l, a sworn law enf	orcement officer, agr	ee that I have not a	idded any CJIS data in	this report.			
INIT 1 MAS DOWNE SOL	JTH ON THE OFF RAMP T	O COUNTY RD BD FRO	MALUMAN 12 THE DOMED A	E LIMIT 1 STOLICK AND	1 1811/81/01/8/81	OBJECT ANDONIO LIED	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/30/2021

Crash Time 99:99

L	_ocation ===									
ſ	ON RAMP USH12 WB				Latitude			Longitue	de	
	493 FT S				43.56007704		-89.779	-89.779595569		
	OF MOON RD IN THE TOWN OF DELTON IN SAUK COUNTY				X Coordinate 275503.84375		Y Coord	linate		
							482670			
					Structure Type					
						Outdood is type				
(Crash Scene 💻									
Ī	First Harmful Event				FirstHarm	ful Event L	ocation			
	OTHER OBJECT - NOT	FIXED			ON ROA	DWAY				
ŀ	Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT				Light Condition					
					DARK/LIGHTED					
ŀ					Roadway	Factor(s)				
					,	, ,				
-										
	NONE				OTHER	DEBRIS				
ļ	Weather Condition(s)				1					
	CLEAR									
ŀ	AnimalType			Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Jurisdiction NO SPECIAL JURISDICTION Access Control NO CONTROL Special Study						
-	Crash Classification - Location PUBLIC PROPERTY Tribal Land Within Interchange Area YES Junction Location EXIT RAMP									
									Special Study	
Ī				Intersection Type NOT AN INTERSECTION						
	=	EXIT RAMP		NOT AN	INTERSE	CTION				
Į	YES	EXIT RAMP		NOT AN	INTERSE	CTION				
 	=	EXIT RAMP	Vehicle Ope	NOT AN erating As C			UnitType			
 	YES Unit Summary ■	EXIT RAMP	Vehicle Ope	erating As C			UnitType AUTOMO	BILE		
	YES Jnit Summary Unit Status	EXIT RAMP	1	erating As C			1		ments	
	YES Jnit Summary Unit Status IN TRANSIT	EXIT RAMP	1	erating As C			AUTOMO		ments	
	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type	EXIT RAMP Train/Bus#Recorded	D CLASS	erating As C	lassification		AUTOMO Operating A	s Endorse	ments zMatTypes	
	Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN		D CLASS	erating As C	lassification		AUTOMO Operating A	s Endorse		
	Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs		Total#Cital	erating As C	lassification	Total Trai	AUTOMO Operating A	s Endorse Total Haz	zMat Types	
•	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1	Train/Bus#Recorded	Total#Cital	erating As C	lassification	Total Trai	AUTOMO Operating A	s Endorse Total Haz	zMat Types	
•	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance?	Train/Bus#Recorded Direction Of Travel SOUTHBOUND	Total#Cital	erating As C tions Issued CrashTire Mark	lassification	Total Trai 0 Speed Lir	AUTOMO Operating A	Total Haz Total Lan Total Lan	MatTypes es	
•	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT	Train/Bus#Recorded Direction Of Travel SOUTHBOUND	Total#Citat 0 Pre SpecialFur NO SPEC	erating As C tions Issued CrashTire Mark nction	lassification	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP	Total Haz O Total Lan 4 Motor Veh	es nicle Use	
•	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way	Train/Bus#Recorded Direction Of Travel SOUTHBOUND on With FIXED	Total# Cital 0 Pre Special Fur NO SPEC	erating As C tions Issued CrashTire Mark notion EIAL FUNC	lassification	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Conf	Total Haz O Total Lan 4 Motor Veh	es nicle Use	
-	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA	Train/Bus#Recorded Direction Of Travel SOUTHBOUND on With FIXED	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	erating As C tions issued CrashTire Mark nction HAL FUNC	lassification	Total Trai 0 Speed Lir	AUTOMO Operating A lers mit Emergency NOT APP Traffic Conti	Total Haz 0 Total Lan 4 Motor Veh LICABLE	es nicle Use	
-	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type	Train/Bus#Recorded Direction Of Travel SOUTHBOUND On With FIXED	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As C tions Issued CrashTire Mark nction HAL FUNC trol ROL ature	lassification	Total Trai 0 Speed Lir	ers Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE	es nicle Use	
-	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO	Train/Bus#Recorded Direction Of Travel SOUTHBOUND On With FIXED	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	erating As C tions Issued CrashTire Mark nction HAL FUNC trol ROL ature	lassification	Total Trai 0 Speed Lir	AUTOMO Operating A lers mit Emergency NOT APP Traffic Conti	Total Haz 0 Total Lan 4 Motor Veh LICABLE	es nicle Use	
•	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type	Train/Bus#Recorded Direction Of Travel SOUTHBOUND On With FIXED	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As C tions Issued CrashTire Mark nction HAL FUNC trol ROL ature	lassification	Total Trai 0 Speed Lir	ers Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE	es nicle Use	
-	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO	Train/Bus#Recorded Direction Of Travel SOUTHBOUND On With FIXED	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva	erating As C tions Issued CrashTire Mark nction HAL FUNC trol ROL ature	lassification	Total Trai 0 Speed Lir	ers Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 4 Motor Veh LICABLE	es nicle Use	
-	YES Jnit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO) Truck Bus or HazMat NO Vehicle	Train/Bus#Recorded Direction Of Travel SOUTHBOUND on With FIXED DIFFIC BARRIER US)	Total# Cital 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve STRAIGH	erating As C tions Issued Crash Tire Mark nction IIAL FUNC trol ROL ature	lassification	Total Trai 0 Speed Lir 65	AUTOMO Operating A Bers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz O Total Lan 4 Motor Ver LICABLE crol Inopera	es nicle Use	
-	Truck Bus or HazMat NO Vehicle License Plate Number	Train/Bus#Recorded Direction Of Travel SOUTHBOUND on With FIXED DIFFIC BARRIER US)	Total# Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve STRAIGH	erating As C tions Issued Crash Tire Mark nction IIAL FUNC trol ROL ature	TION	Total Trai 0 Speed Lir 65	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Lan 4 Motor Ver LICABLE roll Inopera	es nicle Use	
-	Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO Vehicle License Plate Number 736PKV	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FIXED AFFIC BARRIER	Total # Citar 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve STRAIGH Plate Type AUT - AU	erating As C tions Issued Crash Tire Mark nction IIAL FUNC trol ROL ature	TION	Total Trai 0 Speed Lir 65	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S	Total Haz 0 Total Lan 4 Motor Ver LICABLE roll Inopera	es nicle Use	
-	Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO Vehicle License Plate Number 736PKV Vehicle Identification N	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FIXED AFFIC BARRIER BUS)	Total# Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curve STRAIGH	erating As C tions Issued Crash Tire Mark nction IIAL FUNC trol ROL ature	TION	Total Trai 0 Speed Lir 65	AUTOMOI Operating A lers mit Emergency NOT APP Traffic Confi NO Road Grade DOWNHIL Country of Is UNITED ST	Total Haz 0 Total Lan 4 Motor Veh LICABLE crol Inopera	es nicle Use	
-	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO Vehicle License Plate Number 736PKV Vehicle Identification N 2C4RDGC68GR334	Train/Bus#Recorded Direction Of Travel SOUTHBOUND ON With FIXED AFFIC BARRIER BUS)	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con NO CONT Road Curve STRAIGH Plate Type AUT - AL Make DODGE	erating As C tions issued CrashTire Mark nction HAL FUNC trol ROL ature IT	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model GRAND CA	Total Haz 0 Total Lan 4 Motor Veh LICABLE crol Inopera	es nicle Use	
•	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO Vehicle License Plate Number 736PKV Vehicle Identification N 2C4RDGC88GR334 Color SIL - SILVER (ALUI	Train/Bus#Recorded Direction Of Travel SOUTHBOUND IN With FIXED IFFIC BARRIER IUS) Number 4760	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con NO CONT Road Curva STRAIGH Plate Type AUT - AL Make DODGE Body Style VN - VAN	erating As C tions Issued CrashTire Mark nction HAL FUNC trol PROL ature T	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMOI Operating A lers mit Emergency NOT APP Traffic Confi NO Road Grade DOWNHIL Country of Is UNITED ST	Total Haz 0 Total Lan 4 Motor Veh LICABLE crol Inopera	es nicle Use	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO Vehicle License Plate Number 736PKV Vehicle Identification N 2C4RDGC88GR334 Color StL - StLVER (ALUI Initial Contact Point	Train/Bus#Recorded Direction Of Travel SOUTHBOUND IN With FIXED IFFIC BARRIER IUS) Vumber 4760 MINUM)	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con NO CONT Road Curva STRAIGH Plate Type AUT - AL Make DODGE Body Style	erating As C tions Issued CrashTire Mark nction HAL FUNC trol PROL ature T	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model GRAND CA	Total Haz 0 Total Lan 4 Motor Veh LICABLE crol Inopera	es nicle Use ative/Missing	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO Vehicle License Plate Number 736PKV Vehicle Identification N 2C4RDGC88GR334 Color StL - StLVER (ALUI Initial Contact Point	Train/Bus#Recorded Direction Of Travel SOUTHBOUND IN With FIXED IFFIC BARRIER IUS) Vumber 4760 MINUM)	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con NO CONT Road Curva STRAIGH Plate Type AUT - AU Make DODGE Body Style VN - VAN Vehicle Da	erating As C tions Issued CrashTire Mark nction EIAL FUNC trol ROL ature IT	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model GRAND CA	Total Haz 0 Total Lan 4 Motor Veh LICABLE crol Inopera	MatTypes les ative/Missing	
	Unit Summary Unit Status IN TRANSIT Vehicle Type PASSENGER VAN Total Occs 1 Insurance? YES Most Harmful Event: Collisio OTHER OBJECT - NOT Traffic Way DIVIDED HWY W/O TRA Surface Type BLACKTOP (BITUMINO Truck Bus or HazMat NO Vehicle License Plate Number 736PKV Vehicle Identification № 2C4RDGC88GR334 Color StL - StLVER (ALUI Initial Contact Point	Train/Bus#Recorded Direction Of Travel SOUTHBOUND IN With FIXED IFFIC BARRIER IUS) Vumber 4760 MINUM)	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con NO CONT Road Curva STRAIGH Plate Type AUT - AU Make DODGE Body Style VN - VAN Vehicle Da	erating As C tions Issued CrashTire Mark nction HAL FUNC trol PROL ature T	TION	Total Trai 0 Speed Lir 65 St WI Year	AUTOMO Operating A lers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED ST Model GRAND CA	Total Haz 0 Total Lan 4 Motor Veh LICABLE crol Inopera	es nicle Use ative/Missing	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/30/2021

Crash Time 99:99

		Towed Due To Damage		Vehicle Removed By						
		NOT TOWED		OPERATOR Vahida Fastan						
		What Driver Was Doing GOING STRAIGHT		Vehicle Factors						
		Driver Prior Action Other		NOT APPLICABLE						
⊢	Щ	Driver Actions NO CONTRIBUTING ACTION								
IND	VEHICLE									
	5	Owner Name ESTELLE RAE WHITE WIN (608) 393-5608	e G	Owner Address S2849 DECOR BARABOO, WI						
			250505050500000000000000000000000000000	l						
	10	Event OTHER OBJECT - NOT FIX	(ED							
	8	Event								
	8	Event								
	3	Event								
		 Policy Holder								
N		Insurance Company		Individual						
⋾		STATE-FARM-GENERAL-INS-CO		ESTELLE WHITE WING						
		Individual								
		Driver ESTELLE RAE WHITE WING		Citations Issued Sex						
	4	ESTELL NAL WITTE WA		0 FEMALE Date of Birth Race						
⊨	NDIVIDUAL				AMERICAN IN	AN INDIAN OR ALASKAN NATIVE				
FIND	2	Address S2849 DECORAH RD # 123	1	Driver License Number						
	Z	BARABOO, WI 53913 , US		STATE: WISCONSIN COUNTRY: UNITED STATES						
	Sai	fety Equipment On Duty C	Crash	Safety Equipment						
		Row	Seat Position	SHOULDER & LAP BELT						
		01 - FRONT ROW								
	A32500000		07 - LEFT	111 18 5						
		HelmetUse	07 - LEFT	Helmet Compliance	+					
			07 - LEFT	Heimet Compliance	,					
М	100	Helmet Use Eye Protection	verity							
10	100	Eye Protection Injury Seventh No APP	verity ARENT INJURY Ejection Path	Tint Compliance Airbag NON DEPLOYEE		Frapped/Extricated				
9	100	Eye Protection Injury Sevent September 1	verity ARENT INJURY	TintCompliance Airbag NON DEPLOYED)	NOT TRAPPED				
2	001	Eye Protection Injury Seventh No APP	verity ARENT INJURY Ejection Path	Tint Compliance Airbag NON DEPLOYEE)					
10	100	Eye Protection Injury Sevent September 1	verity ARENT INJURY Ejection Path	TintCompliance Airbag NON DEPLOYED)	NOT TRAPPED				
01	F00	Eye Protection Injury Second	verity PARENT INJURY Ejection Path NOT EJECTED/NOT AP	Airbag NON DEPLOYEE PLICABLE EMS Agency Identi)	NOT TRAPPED EMS Run#				
10	100	Eye Protection Injury Section Injury No APP Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	verity PARENT INJURY Ejection Path NOT EJECTED/NOT AP	Airbag NON DEPLOYEE PLICABLE EMS Agency Identi)	NOT TRAPPED EMS Run#				

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/30/2021

Crash Time 99:99

	Non Motorist Striking Unit	# Location				
	Prior Action					
UNIT	Action					
ANGNI						
	Action Other					To/From School
	Drug & Alcohol NO	licohol Use	Suspected Drug Use NO			
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	9		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	3	
90 100	Drug Type					
	Individual Condition					
	APPEARED NORMAL					