22-00062

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Ovenide	Primary Crash Document#	Agency Crash Number 22-00062		Investigating Officer/Deputy DEPUTY C. BRATZ			
<u>א</u>	Crash Date 01/03/2022	Crash Time 09:25 PM	Date Ar 01/03/		Time Arrived 09:32 PM			
LUY/ KBOK	Date Notified 01/03/2022	Time Notified 09:25 PM	TotalUnits 02		Total Injured     Total Killed       00     00			
180	On Emergency	and Run	re Work Zone				Reporting Threshold	
ם ם	Government Property	Active School Zone		·				
	Reportable	Crash Type DT4000 (STANDARD CRASH	)		Amend	ed	Secondary Crash	
	Description							
	Diagram					Reconstructio Photos By Additional Info NONE		
		STH 23 near		IMAGE NOT SCALE	то			
ð		Open View Rd. nt officer, agree that I have no	)	t any CIIS data in this	report			
	hand	nt officer, agree that I have no						
	VEHICLE ACCIDENT INVOLVING A THROUGH WI DL'S. UNIT ONE DRI	DEER, I ARRIVED AT THE LOCATION VER STATED THAT HE WAS TRAVE /ELING ON NORTH ON STH 23, FOLI	n i Mad Ling No Lowing	E CONTACT WITH BOTH DE RTH ON STH 23 WHEN A DE BEHIND UNIT ONE, STRUCH	Rivers. Unit Eer came in ( the back r	one and unit Front of his Ear of unit (	TWO DRIVERS ID VEHICLE WHICH HE DNES VEHICLE, AFTER	

Wisconsin Motor Vehicle Crash Form DT4000

CITED AND EXPLAINED.

AND BACK. UNIT ONE DRIVER ABLE TO DRIVE VEHICLE AWAY. UNIT TWO VEHICLE HAD DISABLING DAMAGE AND TOWED BY CRAIGS. UNIT TWO DRIVER

Crash Date 01/03/2022 Crash Time 09:25 PM 22-00062

### WISCONSIN MOTOR VEHICLE **CRASH REPORT**

	Loc	ation 🛛 🗖									
	ON	STH23 WB				Latitude			Longi	tude	
	745	FT W				43.46647	2775			21471605	
		OPEN VIEW RD			÷.	X Coordin	ato		Y Cor	rdinate	
		HE TOWN OF WEST	FIELD			255589.8				053.5	
	INS	AUK COUNTY	-								
				Structure							
	Cra	sh Scene 🛛 💻									
		HarmfulEvent				Eirst Harm	fulEventLo	cation			
		DOMESTICATED AI				ON ROA		Jeauon			
						Light Con					
	Manner of Collision 03 - FRONT TO REAR						altion NLIT				
	Roa	d Surface Condition(s)				Roadway	Factor(s)				
	DR	1									
	Envi	ronment Factor(s)			-						
		MAL (S) IN ROADWA	Y			NONE					
	Wea	ther Condition(s)									
	CLE										
	Anin	nalType				Relation T	o Trafficway	y			
	DEE	R				TRAFFIC	CWAY - OI	N ROAD			
	Cras	h Classification - Location	n			Crash Cla	ssification -	Jurisdiction			
	PUE	BLIC PROPERTY				NO SPECIAL JURISDICTION					
	Triba	alLand				Access Control Special Study				Special Study	
						NO CONTROL					
	With	in Interchange Area	Junction Location		Intersection	n Type					
	NO	-	NON-JUNCTION		NOT AN I	NTERSE	CTION				
	lini	t Summary 🗖									
-	-			Vehicle Op	orating As Cl	assification		UnitType			
		Unit Status Vehicle Operating As C									
	IN TRANSIT D Vehicle Type							Operating As Endorsements			
5		ORT) UTILITY VEHIC									
Ū	· ·		T . 1805					T . 4 . 11 1			
		Total Occs Train/Bus # Recorded			tions issued			ers		azMatTypes	
	1			0			0		0		
		rance?	Direction Of Travel	FIEC		CrashTire Speed Lin				anes	
E	YES		NORTHBOUND	lun	Mark	55		2			
LIND		tHarmfulEvent: Collision		Special Fur		TION		Emergency Motor Vehicle Use			
	MO.	MOTOR VEH IN TRANSPORT NO SPECIAL FU									
		fic Way		Traffic Cont				Traffic Control Inoperative/Missing NO Road Grade LEVEL		rative/Missing	
		D-WAY, NOT DIVIDED	)	NO CONT	ROL						
		асе Туре		Road Curva							
	BLA	CKTOP (BITUMINOU	IS)	STRAIGH	IT						
		k Bus or HazMat									
	NO										
	-	Vehicle				1400.4445.					
		License Plate Number		Plate Type	5 Selected and a selected and a s	ententerterterterterterter	St	Country of Is	suance		
	- 10 10	AFW3718		JTOMOBIL	E	WI	UNITED STATES				
		Vehicle Identification Nu	Make		Year		Model				
5	8	IGNDT13W1Y2239630			LET	2000		BLAZER Bus Use			
					2						
		BLK - BLACK	Body Style				240 000				
	щ	Initial Contact Point	-	Vehicle Da					1		
F	U U	11 - LEFT FRONT C	ORNER		•					7 8 9 10 11	
LIND	Ť	Extent Of Damage			HT REAR O	CORNER,	11 - LEFT	FRONT		6 12	
2	Extent Of Damage			CORNER	र					5 4 3 2 1	

22-00062

### WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage NOT TOWED		Vel	nicle Removed By					
		What Driver Was Doing		Vel	nicle Factors					
		GOING STRAIGHT			NOT APPLICABLE					
	r Hasir Hasir d									
	ш	Driver Actions NO CONTRIBUTING ACTIO	N	-						
UNIT	ICL									
5	VEHICLE									
		OwnerName CLETUS R BASS			Owner Address S1643 COUNTY R	OAD WD				
9	01			REEDSBURG, WI 53959, US						
		Sequence Of Events								
	5	Event			an a					
		NON DOMESTICATED ANI	MAL (ALIVE)							
	02	MOTOR VEH IN TRANSPOR	रा							
	03	Event								
	MAN N	Event								
		Policy Holder								
UNIT	-	Insurance Company		CONTRACTOR OF	ndividual			. TARAHAN MANANANAN		
כ		PROGRESSIVE-CLASSIC-IN	NS-CO		CLETUS BASS			11		
		Driver	\$		LA A A MA A A ATAIN Citations Issued	Sex	$\mathbf{x} \stackrel{\mathrm{def}}{\rightarrow} \mathbf{x} \mathrm{d$	N N N N N N N N N N		
		CLETUS R BASS			)	MALE				
L	TENDINION			Ε	Date of Birth	Race WHITE				
LINIT	INC	Addres s S1643 COUNTY ROAD WD		-+ī	Driver Licens eNumber	<u> </u>				
	IN	REEDSBURG, WI 53959, U	IS	5	STATE: WISCONSIN	COUNTRY: UNI	TED STATES			
	Saf	ety Equipment	14511		Safety Equipment					
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	1	SHOULDER & LAP I	BELT				
		H emet Use		-	Helmet Compliance		·			
		Eye Protection		Tint Compliance						
	j,	Injury Sev	erity		Airbag			_		
5	Bo	Injury NO APP	ARENT INJURY		NON DEPLOYED		-			
			Jection Path NOT EJECTED/NOT AF	PLIC	ABLE		Trapped/Extricated			
		Medical Transport			EMSAgency Identifier		EMS Run #			
		NOT TRANSPORTED Hospital			Date of Death		Time of Death			
		Distracted By NOT AP	l By Source PLICABLE (NOT DISTI	RACI	ED)					
		Distracted By Action NOT DISTRACTED								
		NOT DIGHNAGTED								

22-00062

### WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	* * * * * *	Non Motorist	king Unit#	Location						
	U.F.	Prior Action								
		Action								
UNIT										
	NDIVIDUA									
Action Other To										
	Ĺ		pected Alcohol U	se	Suspected Drug Use					
		Alcohol Test Given		Alcohol Test Type	e		AlcoholTest	Results		
		Drug Test Given		Drug Test Type		Drug Test Resul	ts			
6	001	Drug Type								
	Ō									
	like Second	Individual Condition								
		t Summary 🛛 💻								
	Units	Status			ehicle Operating As Class	ification	Hnit Type			
		Status <b>FRANSIT</b>			/ehicleOperatingAsClass CLASS	ification	Unit Type AUTOMOE	NLE		
02	<b>IN T</b> Vehi					ification	AUTOMOE	BILE Endorsements		
02	IN T Vehi PAS	<b>RANS!T</b>	Train/Bus#Red	C	OCLASS	Total Tra	AUTOMOE Operating As ilers			
	IN T Vehi PAS Total 1	TRANSIT icle Type SSENGER CAR Il Occs rance?	Train/Bus#Red Direction Of Tra NORTHBOUN	corded T 1	oclass	TotalTra	AUTOMOE Operating As ilers mit	s Endorsements Total HazMat Types		
UNIT 02	IN T Vehir PAS Tota 1 Insur YES Most	TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision W	Direction Of Tra NORTHBOUN	corded T 1 ivel ND [ S	otal # Citations Issued	TotalTra 0 Speed Li 55	AUTOMOE Operating As illers mit	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	IN T Vehic PAS Tota 1 Insur YES Most MOT Traff	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision W TOR VEH IN TRANSPOI fic Way	Direction Of Tra NORTHBOUN	corded T 1 ivel ND [ ND T	O CLASS	TotalTra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
	IN T Vehic PAS Tota 1 Insur YES Most MOT Traff	TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision W TOR VEH IN TRANSPOR	Direction Of Tra NORTHBOUN	conded T 1 1 ND [ ND ] ND ] ND ] ND ] ND ] ND ] ND ] ND ]	O CLASS	TotalTra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE		
	IN T Vehic PAS Tota 1 Insur YES Most MOT Traff TWC Surfa BLA	TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision W TOR VEH IN TRANSPOR fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS)	Direction Of Tra NORTHBOUM ith RT	Corded T 1 NVEl ND E T ND R	O CLASS	TotalTra 0 Speed Li 55	AUTOMOE Operating As ilers mit Emergency I NOT APPL Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE		
	IN T Vehic PAS Tota 1 Insur YES Most MOT Traff TWC Surfa BLA	TRANSIT icle Type SSENGER CAR Il Occs rance? S t Harmful Event: Collision W TOR VEH IN TRANSPOI fic Way O-WAY, NOT DIVIDED ace Type	Direction Of Tra NORTHBOUM ith RT	Corded T 1 NVEl ND E T ND R	O CLASS	TotalTra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE		
	IN T Vehi PAS Tota 1 Insur YES Most MOT Traff BLA Truc NO	TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision W TOR VEH IN TRANSPOR fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ik Bus or HazMat	Direction Of Tra NORTHBOUN ith RT	corded T ivel ND [ R S R S	O CLASS Total # Citations Issued The Crash Tire Mark Special Function NO SPECIAL FUNCTIO Traffic Control NO CONTROL Road Curvature STRAIGHT	TotalTra 0 SpeedLi 55 N	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most MOT Traff BLA Truc NO	TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision W TOR VEH IN TRANSPOI fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ik Bus or HazMat	Direction Of Tra NORTHBOUN ith RT	corded T ivel ND [ R S S	O CLASS Total # Citations Issued The Crash Tire Mark Decial Function NO SPECIAL FUNCTIO Traffic Control NO CONTROL Coad Curvature STRAIGHT	TotalTra 0 SpeedLi 55 N	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
	IN T Vehi PAS Tota 1 Insur YES Most MOT Traff BLA Truc NO	TRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision W TOR VEH IN TRANSPOR fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ik Bus or HazMat Vehicle License Plate Number	Direction Of Tra NORTHBOUN ith RT	Corded T ivel ND [ R R S S S	O CLASS  Total # Citations Issued  Pre CrashTire Mark  Special Function NO SPECIAL FUNCTIO  Traffic Control NO CONTROL  Road Curvature  STRAIGHT  Plate Type	TotalTra 0 SpeedLi 55 N	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
UNIT	IN T Vehin PAS Tota 1 Insur YES Most MOT Traff BLA NO	TRANSIT icle Type SSENGER CAR Il Occs rance? THARMFULEvent: Collision W TOR VEH IN TRANSPOI fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) ik Bus or HazMat Vehicle License Plate Number AFS7960 Vehicle Identification Numit 1G1ZB5ST9KF146587 Color	Direction Of Tra NORTHBOUN ith RT	corded T ivel ND [ ND S N N S S S S S S S S S S S S S S S S S	O CLASS Otal # Citations Issued Pre CrashTire Mark Special Function NO SPECIAL FUNCTIO Fraffic Control O CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBILE Make	Total Tra 0 Speed Li 55 N St Wi Year	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
02 UNIT	IN T Vehin PAS Tota 1 Insur YES Most MOT Traff BLA NO	TRANSIT         icle Type         SSENGER CAR         il Occs         rance?         t Harmful Event: Collision W         TOR VEH IN TRANSPOI         fic Way         O-WAY, NOT DIVIDED         ace Type         ACKTOP (BITUMINOUS)         ick Bus or HazMat         Vehicle         License Plate Number         AFS7960         Vehicle Identification Numited         1G1ZB5ST9KF146587         Color         WHI - WHITE         Initial Contact Point	Direction Of Tra NORTHBOUM ith RT	corded T ivel ND [ ND S N N S S S	O CLASS         Fotal # Citations Issued         Pre CrashTire         Mark         Special Function         NO SPECIAL FUNCTIO         NO CONTROL         Road Curvature         STRAIGHT         Plate Type         AUT - AUTOMOBILE         Make         CHEVROLET         Body Style	Total Tra 0 Speed Li 55 N St Wi Year	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model MALIBU	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use CABLE ol Inoperative/Missing Uance ATES		
UNIT	IN T Vehin PAS Tota 1 Insur YES Most MOT Traff TWC Surfa BLA NO	TRANSIT         icle Type         SSENGER CAR         il Occs         il Occs         t Harmful Event: Collision W         TOR VEH IN TRANSPOI         fic Way         O-WAY, NOT DIVIDED         ace Type         ACKTOP (BITUMINOUS)         kk Bus or HazMat         Vehicle         License Plate Number         AFS7960         Vehicle Identification Numil         1G1ZB5ST9KF146587         Color         WHI - WHITE         Initial Contact Point         11 - LEFT FRONT COF         Extent Of Damage	Direction Of Tra NORTHBOUM ith RT	corded T ivel ND [ ND R R S	O CLASS         Fotal # Citations Issued         Pre CrashTire         Mark         Special Function         NO SPECIAL FUNCTIO         Traffic Control         NO CONTROL         Road Curvature         STRAIGHT         Plate Type         AUT - AUTOMOBILE         Make         CHEVROLET         Body Style         SD - SEDAN	TotalTra 0 Speed Li 55 N St Wi Year 2019	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model MALIBU Bus Use	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing Uance ATES 7 8 9 10 11 6 12		
02 UNIT	IN T Vehi PAS Tota 1 Insur YES Most MOT Traff BLA Truc NO	TRANSIT         icle Type         SSENGER CAR         il Occs         rance?         t Harmful Event: Collision W         TOR VEH IN TRANSPOI         fic Way         D-WAY, NOT DIVIDED         ace Type         ACKTOP (BITUMINOUS)         ik Bus or HazMat         Vehicle         License Plate Number         AFS7960         Vehicle Identification Numited         1G1ZB5ST9KF146587         Color         WHI - WHITE         Initial Contact Point         11 - LEFT FRONT COF	Direction Of Tra NORTHBOUN ith RT	corded T ivel ND [ ND ] R S S I I I I I I I I I I I I I I I I I	O CLASS         Fotal # Citations Issued         Pre CrashTire Mark         Decial Function         NO SPECIAL FUNCTIO         Traffic Control         NO CONTROL         Road Curvature         STRAIGHT         Plate Type         AUT - AUTOMOBILE         Make         CHEVROLET         Body Style         SD - SEDAN         Vehicle Damage	TotalTra 0 Speed Li 55 N St Wi Year 2019	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss UNITED ST Model MALIBU Bus Use	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing  Funce ATES 7 8 9 10 11		

22-00062

### WISCONSIN MOTOR VEHICLE CRASH REPORT

	5	What Driver Was Doing		Vehicle	e Factors			
	in las	GOING STRAIGHT		NOT				
		Driver Prior Action Other			APPLICABLE			
UNIT	<b>EHICLE</b>	DriverActions FAILURE TO CONTROL						
	<b>, X</b>							
02	<b>62</b>	Owner Name TRACY M KARLL		31	wner Address 16 N UNION ST AUSTON, WI 5394	48 , US		
	(	Sequence Of Events		l. Na serie a serie				
	8	Event MOTOR VEH IN TRANSPOR	T					
	8		. 1					
	02	Event						
	4	Event						
	03	Event						
⊢		Policy Holder					and the approximation of the second	
UNIT		Insurance Company		Indi	vidual			
-		WISCONSIN-MUTUAL-INS-C	0	TRACY KARLL				
		<b>ndividual</b>		o [6] o [6] -		namannan		
		Driver TRACY M KARLL				Sex		
	UAL			1 Date	∋ of Birth	FEMALE Race		
⊢						WHITE		
UNIT		Address		Driver License Number				
_	Ľ	316 N UNION ST MAUSTON, WI 53948 , US		STATE: WISCONSIN COUNTRY: UNITED STATES				
		On Duty Cr	ash	Safe	ety Equipment			
	Sai	ety Equipment						
		Row 01 - FRONT ROW	SeatPosition 07 - LEFT	SH	OULDER & LAP B	ELT		
		HelmetUse		Helr	metCompliance			
		Eye Protection		Tint	Compliance			
8	2	I Injury Seve	rity	Airb	ag			
02	002	INJURY NO APPA	RENT INJURY	DEI	PLOYED-FRONT			
			ection Path				Trapped/Extricated NOT TRAPPED	
		NOT EJECTED No Medical Transport	OT EJECTED/NOT APF		SAgency Identifier		EMS Run#	
		NOT TRANSPORTED			shigeney laentiller			
	2	Hospital		Date	e of Death		Time of Death	
		Distracted By NOT APP	BySource LICABLE (NOT DISTRA	ACTED	))			
		Distracted By Action NOT DISTRACTED						
	je je	Striking Un	it # Location					
		Non Motorist						

#### 22-00062

### WISCONSIN MOTOR VEHICLE CRASH REPORT

	6	UTC Number BB957699	Issue To? 002	Statute Number 346.57(2)	Description FAILURE TO KEEP	VEHICLE UNDER		
		APPEARED NORM	IAL					
		Individual Condition						
03	002	Drug Type						
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug TestResults		
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			AlcoholTestResults	
	× C	Drug & Alcohol	Suspected Alco		Suspected Drug Use NO			
		Action Other						To/From School
UNIT	INDIVIDUAL	Action						
		Prior Action						