# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash E	ocument#	Agency 22-009	Crash Number	Investigating DEPUTY I.	g Officer/Deput . <b>HANSON</b>	у		
000	Crash Date 01/29/2022	Crash Time 10:52 AM		Date Ar 01/29/		Time Arrived				
グへく	Date Notified 01/29/2022	Time Notified 10:54 AM		Total Ui	nits	Total Injured	Total Kil	Total Killed		
)	On Emergency Hit	and Run	Lane Closs	ure	Work Zone	Trailer	or Towed	Reporting  Threshold		
0150	Government Property	Active Sc	hool Zone	School NO	Bus Related	Tags		'		
	Reportable Crash Type DT4000 (STANDARD CRASH)						led	Secondary  Crash		
ĺ	Description Diagram						Reconstructi	_		
		NON	REPORTABLE				Photos By I HANSON  Additional Interpretation	formation		
		nt officer, agre	e that I have no	ot added	I any CJIS data in t	his report.	l			
	I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.  UNIT 2 WAS EXITING THE SOUTH END OF THE WALGREENS PARKING LOT ONTO STH 136. UNIT 1 FELT HIS FRONT END WAS OUT TO FAR AND PUT THE SUV IN REVERSE TO BACK AWAY FROM THE ROADWAY. UNIT 1 BACKED INTO UNIT 2. UNT 2 WAS STATIONARY WAITING TO EXIT THE LOT AS WELL. 9109									

### **WISCONSIN MOTOR VEHICLE CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

Loc	ation <b></b>							
	STH33 EB			Latitude			Longitud	le
295	FT W			43.4748	322893			014417
OF	STH136 EB			X Coordi	nato		Y Coord	
	HE VILLAGE OF WEST	BARABOO		275962			481727	
IN S	AUK COUNTY			Structure			101121	
				Structure	: rype			
Cra	sh Scene			'				
First	Harmful Event			FirstHan	mful Event L	_ocation		
MO.	OR VEH IN TRANSPO	RT		ON ROA	ADWAY			
Man	ner of Collision			Light Cor	ndition			
03 -	FRONT TO REAR			DAWN	1 -			
Road	d Surface Condition(s)			Roadwa	y Factor(s)			
	• • •			///	, , , , ,			
DRY								
Envi	ronment Factor(s)							
NON	IF			NONE				
Wea	ther Condition(s)							
CLE	AR							
A mirror	alType			D-1-6	T. T. 60 -			
Anim	iai i ype			I	To Trafficwa	ay XY - PARKINO	SLOT	
	1.01 20 0 1 0						3 LUI	
	h Classification - Location				Crash Classification - Jurisdiction PRIVATE PROPERTY			
	/ATE PROPERTY					RIY		T =
Inba	lLand			Access				Special Study
					ONTROL			
With	٠ ا	Junction Location		ersection Type				
		NON HINCTION	INC	T AN INTERSI	ECTION			
		NON-JUNCTION		71 Att 1117 Ette.				
Unit	Summary ===	NON-JUNC HON		7 744 114 7 21404	2011011			
		NON-JUNC HON		ng As Classificatio		Unit Type		
Unit	Summary =	NON-SONC FROM				Unit Type AUTOMOI	BILE	
Unit	Summary Status	NON-SONC FROM	Vehicle Operatir			1		ments
Unit IN T Vehi	Summary Status		Vehicle Operatir			AUTOMO		ments
Unit	Summary Status RANSIT cle Type		Vehicle Operatir	ng As Classificatio		AUTOMOI Operating A	s Endorse	ments MatTypes
Unit IN T Vehi (SP	Summary  Status  RANSIT  cle Type  DRT) UTILITY VEHICLE	<b>.</b>	Vehicle Operatir D CLASS	ng As Classificatio	n	AUTOMOI Operating A	s Endorse	
Unitation Vehicus (SPC) Tota 3	E Summary Status RANSIT CIE Type DRT) UTILITY VEHICLE	<b>.</b>	Vehicle Operation D CLASS  Total # Citations 0	ng As Classificatio	n TotalTra 0	AUTOMOI Operating A	s Endorse Total Haz	Mat Types
Unit IN T Vehi (SPC Tota 3	E Summary  Status  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Coccs	E Train/Bus#Recorded	Vehicle Operation D CLASS  Total # Citations 0 Pre Cras	ng As Classificatio	n   Total Tra	AUTOMOI Operating A	s Endorse Total Haz 0	Mat Types
Unit. IN T Vehi (SP) Tota 3 Insur YES	E Summary  Status  RANSIT  cle Type  DRT) UTILITY VEHICLE  Cocs  rance?	Train/Bus#Recorded  Direction Of Travel  EASTBOUND	Vehicle Operation D CLASS  Total # Citations 0	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOBI Operating A illers	s Endorsei Total Haz 0 Total Land 2	Mat Types es
Unit IN T Vehi (SPC Tota 3 Insur YES Most	E Summary  Status  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Coccs	Train/Bus#Recorded  Direction Of Travel  EASTBOUND	Vehicle Operation D CLASS  Total # Citations 0  Pre Cras	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOI Operating A	Total Haz  Total Land  Total Land  Motor Veh	Mat Types es
Unit. IN T Vehi (SPC Tota 3 Insur YES	Summary  Status  RANSIT  cle Type  DRT) UTILITY VEHICLE  Occs  rance?  Harmful Event: Collision W	Train/Bus#Recorded  Direction Of Travel  EASTBOUND	Vehicle Operatin D CLASS  Total # Citations 0  Pre Cras Mai Special Functior NO SPECIAL	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOLI Operating A illers	Total Haz  0  Total Land  2  Motor Veh  ICABLE	MatTypes es icle Use
Unit. IN T Vehi (SPC Tota 3 Insui YES Most	Esummary  Status  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  CHarmful Event: Collision W  FOR VEH IN TRANSPORT	Train/Bus#Recorded  Direction Of Travel  EASTBOUND	Vehicle Operatin D CLASS  Total # Citations 0  Pre Crass Mai Special Function NO SPECIAL Traffic Control	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOS Operating A illers imit  Emergency NOT APPI	Total Haz  0  Total Land  2  Motor Veh  ICABLE	MatTypes es icle Use
Unit. IN T Vehi (SPC Tota 3 Insur YES Mos: MO Traff TWC	Esummary  Estatus  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  CHarmful Event: Collision W  FOR VEH IN TRANSPOLIC  CWay  D-WAY, NOT DIVIDED	Train/Bus#Recorded  Direction Of Travel  EASTBOUND	Vehicle Operatin D CLASS  Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control STOP SIGN	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOS Operating A illers init Emergency NOT APPI Traffic Cont NO	Total Haz  0 Total Land  2 Motor Veh LICABLE  rol Inopera	MatTypes es icle Use
Unit. IN T Vehi (SP) Tota 3 Insui YES Mos: MO Traff TWO	Esummary  Estatus  RANSIT  cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  Harmful Event: Collision W  FOR VEH IN TRANSPOLIC  ic Way  D-WAY, NOT DIVIDED  ace Type	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  iith	Total # Citations  O  Pre Cras  Mai  Special Function  NO SPECIAL  Traffic Control  STOP SIGN  Road Curvature	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOL Operating A illers  mit  Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz  0 Total Land  2 Motor Veh LICABLE  rol Inopera	MatTypes es icle Use
Unit- IN T Vehi (SP) Tota 3 Insur YES Most MO Traff TWO Surfa BLA	ESUMMARY  Estatus  RANSIT  cle Type  DRT) UTILITY VEHICLE  Cocs  Fance?  CHArmful Event: Collision W  FOR VEH IN TRANSPO  ic Way  D-WAY, NOT DIVIDED  ace Type  CKTOP (BITUMINOUS)	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  iith	Vehicle Operatin D CLASS  Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control STOP SIGN	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOS Operating A illers init Emergency NOT APPI Traffic Cont NO	Total Haz  0 Total Land  2 Motor Veh LICABLE  rol Inopera	MatTypes es icle Use
Unit- IN T Vehi (SP) Tota 3 Insur YES Most MO Traff TWO Surfa BLA	Esummary  Estatus  RANSIT  cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  Harmful Event: Collision W  FOR VEH IN TRANSPOLIC  ic Way  D-WAY, NOT DIVIDED  ace Type	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  iith	Total # Citations  O  Pre Cras  Mai  Special Function  NO SPECIAL  Traffic Control  STOP SIGN  Road Curvature	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOL Operating A illers  mit  Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz  0 Total Land  2 Motor Veh LICABLE  rol Inopera	MatTypes es icle Use
Unit- IN T Vehi (SPC) Tota 3 Insur YES MOS MOS Traff TWC Surfa BLA	ESUMMARY  Status  RANSIT  cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  CHarmful Event: Collision W  FOR VEH IN TRANSPOLIC  ic Way  D-WAY, NOT DIVIDED  ace Type  CKTOP (BITUMINOUS)  k Bus or HazMat	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  iith	Total # Citations  O  Pre Cras  Mai  Special Function  NO SPECIAL  Traffic Control  STOP SIGN  Road Curvature	ng As Classificatio	TotalTra 0 SpeedLi	AUTOMOL Operating A illers  mit  Emergency NOT APPI Traffic Cont NO Road Grade	Total Haz  0 Total Land  2 Motor Veh LICABLE  rol Inopera	MatTypes es icle Use
Unit- IN T Vehi (SPC) Tota 3 Insur YES MOS MOS Traff TWC Surfa BLA	Esummary  Estatus  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Charmful Event: Collision W  FOR VEH IN TRANSPOLIC  CWay  D-WAY, NOT DIVIDED  ace Type  CKTOP (BITUMINOUS)  K Bus or HazMat	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  iith	Vehicle Operatin D CLASS  Total # Citations 0  Pre Crass Mail Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT	ng As Classificatio	TotalTra 0 Speed Li 05	AUTOMOR Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO Road Grade LEVEL	Total Haz 0 Total Land 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use
Unit- IN T Vehi (SPC) Tota 3 Insur YES MOS MOS Traff TWC Surfa BLA	Esummary  Estatus  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Charmful Event: Collision W  FOR VEH IN TRANSPOLIC  CWay  D-WAY, NOT DIVIDED  ace Type  CKTOP (BITUMINOUS)  K Bus or HazMat  Vehicle  License Plate Number	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  iith	Vehicle Operatin D CLASS  Total # Citations 0  Pre Crass Mail Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT	g As Classification	TotalTra 0 Speed Li 05	AUTOMOR Operating A illers imit  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of Is	Total Haz 0 Total Lang 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use
Unit- IN T Vehi (SPC Tota 3 Insur YES MOS MOS Traff TWC Surfa BLA Truc NO	Esummary  Estatus  RANSIT  cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  Harmful Event: Collision W  FOR VEH IN TRANSPOLIC  ic Way  D-WAY, NOT DIVIDED  ace Type  CKTOP (BITUMINOUS)  K Bus or HazMat  Vehicle  License Plate Number  185PHV	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  With  RT	Vehicle Operatin D CLASS  Total # Citations 0 Pre Cras Mai Special Functor NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTOI	g As Classification	TotalTra 0 Speed Li 05	AUTOMOS Operating A silers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of is UNITED ST	Total Haz 0 Total Lang 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use
Unit: IN T Vehi (SPC Tota 3 Insui YES MOS MO Traff TWC Surfa BLA	Estatus RANSIT cle Type DRT) UTILITY VEHICLE Occs Fance?  CHARMful Event: Collision W FOR VEH IN TRANSPOLIC CWAY D-WAY, NOT DIVIDED ace Type CKTOP (BITUMINOUS) K Bus or HazMat  Vehicle License Plate Number 185PHV  Vehicle Identification Num	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Vehicle Operatin D CLASS  Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTO	g As Classification	TotalTra 0 Speed Li 05	AUTOMOS Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO Road Grade LEVEL  Country of is UNITED ST Model	Total Haz  Total Land  Total Land  Motor Veh  ICABLE  roll Inopera	MatTypes es icle Use
Unit- IN T Vehi (SPC) Tota 3 Insur YES MOS MOS Traff TWC Surfa BLA Truc NO	Estatus RANSIT cle Type DRT) UTILITY VEHICLE Occs Fance? CHarmful Event: Collision W FOR VEH IN TRANSPOLIC CWAY D-WAY, NOT DIVIDED ACE Type CKTOP (BITUMINOUS) K Bus or HazMat  Vehicle License Plate Number 185PHV Vehicle Identification Num 5TDJZRFH2JS892875	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTO Make TOYOTA	g As Classification	TotalTra 0 Speed Li 05	AUTOMOR Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model HIGHLAND	Total Haz  Total Land  Total Land  Motor Veh  ICABLE  roll Inopera	MatTypes es icle Use
Unit: IN T Vehi (SPC Tota 3 Insur YES MOS MO Traff TWC Surfa BLA Truc NO	Estatus RANSIT cle Type DRT) UTILITY VEHICLE Occs Fance? CHarmful Event: Collision W FOR VEH IN TRANSPOLIC CWAY D-WAY, NOT DIVIDED ace Type CKTOP (BITUMINOUS) K Bus or HazMat  Vehicle License Plate Number 185PHV Vehicle Identification Num 5TDJZRFH2JS892875 Color	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTO Make TOYOTA Body Style	ng As Classification Issued ShTire Tk FUNCTION	TotalTra 0 SpeedLi 05  St WI Year 2018	AUTOMOS Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO Road Grade LEVEL  Country of is UNITED ST Model	Total Haz  Total Land  Total Land  Motor Veh  ICABLE  roll Inopera	MatTypes es icle Use
Unit IN T Vehi (SPC) Tota 3 Insur YES MOO Traff TWC Surfa BLA Truc NO	Estatus RANSIT cle Type DRT) UTILITY VEHICLE Occs Fance?  Harmful Event: Collision W FOR VEH IN TRANSPOLIC IC Way D-WAY, NOT DIVIDED ACE Type CKTOP (BITUMINOUS) IK Bus or HazMat  Vehicle License Plate Number 185PHV Vehicle Identification Num 5TDJZRFH2JS892875 Color BLU - BLUE	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Total # Citations 0 Pre Cras Mail Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTO Make TOYOTA Body Style UT - SPORT	Issued Issued ShTire Isk FUNCTION	TotalTra 0 SpeedLi 05  St WI Year 2018	AUTOMOR Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model HIGHLAND	Total Haz  0 Total Land 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use
Unit: IN T Vehi (SPC Tota 3 Insui YES Mos: MO: Traff TWC Surfa BLA Truc NO	Estatus RANSIT cle Type DRT) UTILITY VEHICLE Occs Fance?  Harmful Event: Collision W FOR VEH IN TRANSPOLIC IC Way D-WAY, NOT DIVIDED ACE Type CKTOP (BITUMINOUS) IK Bus or HazMat  Vehicle License Plate Number 185PHV Vehicle Identification Num 5TDJZRFH2JS892875 Color BLU - BLUE Initial Contact Point	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Total # Citations 0 Pre Cras Mai Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTO Make TOYOTA Body Style	Issued Issued ShTire Isk FUNCTION	TotalTra 0 SpeedLi 05  St WI Year 2018	AUTOMOR Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST Model HIGHLAND	Total Haz  0 Total Land 2 Motor Veh LICABLE rol Inopera	Mat Types  es  icle Use  tive/Missing
Unit: IN T Vehi (SPC Tota 3 Insui YES Mos: MO: Traff TWC Surfa BLA Truc NO	Esummary  Status  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  CHarmful Event: Collision W  FOR VEH IN TRANSPO  CIC Way  D-WAY, NOT DIVIDED  ACE Type  CKTOP (BITUMINOUS)  K Bus or HazMat  Vehicle  License Plate Number  185PHV  Vehicle Identification Num  5TDJZRFH2JS892875  Color  BLU - BLUE  Initial Contact Point  06 - REAR	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Vehicle Operating D CLASS  Total # Citations 0  Pre Crass Mail Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTOI Make TOYOTA Body Style UT - SPORT Vehicle Damag	Issued Issued ShTire Isk FUNCTION	TotalTra 0 SpeedLi 05  St WI Year 2018	AUTOMOR Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO  Road Grade LEVEL  Country of Is UNITED ST  Model HIGHLAND	Total Haz  0 Total Land 2 Motor Veh LICABLE rol Inopera	Mat Types  es  icle Use  tive/Missing
Unit: IN T Vehi (SPI Tota 3 Insui YES Mos: MO: Traff TWC Surfa BLA Truc NO	Esummary  Status  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Cance?  CHarmful Event: Collision W  FOR VEH IN TRANSPO  Cic Way  D-WAY, NOT DIVIDED  CACE Type  CKTOP (BITUMINOUS)  K Bus or HazMat  Vehicle  License Plate Number  185PHV  Vehicle Identification Num  5TDJZRFH2JS892875  Color  BLU - BLUE  Initial Contact Point  06 - REAR  Extent Of Damage	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Total # Citations 0 Pre Cras Mail Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTO Make TOYOTA Body Style UT - SPORT	Issued Issued ShTire Isk FUNCTION	TotalTra 0 SpeedLi 05  St WI Year 2018	AUTOMOR Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO  Road Grade LEVEL  Country of Is UNITED ST  Model HIGHLAND	Total Haz  0 Total Land 2 Motor Veh LICABLE rol Inopera	Mat Types  es  icle Use  tive/Missing  7 8 9 10 11  6 12
Unit IN T Vehi (SPC) Tota 3 Insur YES MOS MOS Surfa BLA Truc NO	Esummary  Status  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Fance?  CHarmful Event: Collision W  FOR VEH IN TRANSPO  CIC Way  D-WAY, NOT DIVIDED  ACE Type  CKTOP (BITUMINOUS)  K Bus or HazMat  Vehicle  License Plate Number  185PHV  Vehicle Identification Num  5TDJZRFH2JS892875  Color  BLU - BLUE  Initial Contact Point  06 - REAR	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  Ditth  RT	Vehicle Operating D CLASS  Total # Citations 0  Pre Crass Mail Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTOI Make TOYOTA Body Style UT - SPORT Vehicle Damag	Issued Issued ShTire Isk FUNCTION	TotalTra 0 SpeedLi 05  St WI Year 2018	AUTOMOR Operating A illers  mit  Emergency NOT APPI  Traffic Cont NO  Road Grade LEVEL  Country of Is UNITED ST  Model HIGHLAND	Total Haz  0 Total Land 2 Motor Veh LICABLE rol Inopera	Mat Types  es  icle Use  tive/Missing
Unit: IN T Vehi (SPI Tota 3 Insui YES Mos: MO: Traff TWC Surfa BLA Truc NO	Esummary  Status  RANSIT  Cle Type  DRT) UTILITY VEHICLE  Occs  Cance?  CHarmful Event: Collision W  FOR VEH IN TRANSPO  Cic Way  D-WAY, NOT DIVIDED  CACE Type  CKTOP (BITUMINOUS)  K Bus or HazMat  Vehicle  License Plate Number  185PHV  Vehicle Identification Num  5TDJZRFH2JS892875  Color  BLU - BLUE  Initial Contact Point  06 - REAR  Extent Of Damage	Train/Bus#Recorded  Direction Of Travel  EASTBOUND  //ith RT	Vehicle Operating D CLASS  Total # Citations 0  Pre Crass Mail Special Function NO SPECIAL Traffic Control STOP SIGN Road Curvature STRAIGHT  Plate Type AUT - AUTOI Make TOYOTA Body Style UT - SPORT Vehicle Damag	MOBILE  UTILITY VEHICE	TotalTra 0 Speed Li 05	AUTOMOR Operating A illers imit  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of is UNITED ST Model HIGHLAND Bus Use	Total Haz 0 Total Land 2 Motor Veh ICABLE rol Inopera	Mat Types  es  icle Use  tive/Missing  7 8 9 10 11  6 12

22-00906

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage NOT TOWED		Vehicle Removed By OWNER							
		What Driver Was Doing		Vehicle Factors							
		BACKING									
		Driver Prior Action Other		NOT APPLICABLE							
LINI	VEHICLE	Driver Actions UNSAFE BACKING									
	5	Owner Name MICHELLE MAE ZUELKE (608) 393-3892		Owner Address 1882 8TH ST REEDSBURG, W	/ł 53959 , <b>US</b>						
		Sequence Of Events		l							
	5	Event MOTOR VEH IN TRANSPO	RT								
	8	Event Event									
	8										
	75	Event									
_		Policy Holder									
IN		insurance Company RURAL-TRUST-INSURANG	CE-COMPANY	Individual MICHELLE ZUEL	(E						
		Individual		·							
		Driver JEFFERY PETER ZUELKE	Citations Issued	Sex FEMALE							
_	NDIVIDUAL	(608) 393-3892		Date of Birth	Race						
E S	3	Address		Drivert icense Number							
_	Z	1882 8TH ST REEDSBURG, WI 53959 ,	US	STATE: WISCONSIN COUNTRY: UNITED STATES							
		On Duty	Crash	Safety Equipment							
	Sai	fety Equipment	Ia .a	SHOULDER & LAI	9 8E: T						
		Row 01 - FRONT ROW	Seat Position 07 - LEFT		PELI						
		HelmetUse		Helmet Compliance							
		Eye Protection		Tint Compliance							
5	8	STREET, STREET	PARENT INJURY	Airbag NON DEPLOYED							
		1	Ejection Path NOT EJECTED/NOT API	PLICABLE		Trapped/Extricated NOT TRAPPED					
		Medical Transport NOT TRANSPORTED		EMS Agency Identifie	er .	EMS Run#					
		Hospital		Date of Death		Time of Death					
		Distracte	ed By Source								
		Distracted By NOT A	PPLICABLE (NOT DISTR	ACTED)							
		Distracted By Action NOT DISTRACTED									

Crash Date 01/29/2022 Crash Time 10:52 AM

WISCONSIN MOTOR VEHICLE CRASH REPORT SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Striking Non Motorist	Unit#	Location							
		Prior Action		1							
		Action	Action								
	J										
UNIT	9										
<b> </b>	INDIVIDUAL										
		Action Other						To/From School			
		I Drug & Alcohol NO	ted Alcohol U	jse	Suspected Drug Use						
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results				
		TEST NOT GIVEN Drug Test Given		Drug Test Type		Drug Test Results					
		TEST NOT GIVEN		Diog restryps		Diug restresuis	•				
9	8	Drug Type									
		individual Condition									
		APPEARED NORMAL									
		Individual									
		Passenger MICHELLE MAE ZUELKE			Citations Issued  0	Sex FEMALE					
	MAL	(608) 393-3892			Date of Birth	Race WHITE					
N	INDIVIDUA	Address 1882 8TH ST									
	Z	REEDSBURG, WI 53959	, US		STATE: WISCONSIN COUNTRY: UNITED STATES						
		On Duty	On Duty Crash			Safety Equipment					
	Sal	ety Equipment	SeatPo	osition	SHOULDER & LAP BELT						
		01 - FRONT ROW HelmetUse	09 - RI		Halmat Campliance						
					Helmet Compliance						
		Eye Protection			Tint Compliance						
۶	902	Injury So	everity <b>PARENT</b> II	NJURY	Airbag NON DEPLOYED						
		Ejected NOT EJECTED	Ejection Pa	ith CTED/NOT APPI	LICABLE		Trapped/Extricated NOT TRAPPED				
		Medical Transport  NOT TRANSPORTED		EMS Agency Identifier		EMS Run#					
		Hospital			Date of Death		Time of Death				
		Distracted By	ed By Source	•							
		Distracted By Action									
		Striking	Unit#	Location							
		Non Motorist	- man								

Crash Date 01/29/2022 Crash Time 10:52 AM

22-00906

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/29/2022

		Prior Action								
		Action								
	NDIVIDUAL									
<b>L</b> NN	8									
5	ã									
	Z									
		Action Other						To/From School		
	,	Suspec	ted Alcohol t	Jse	Suspected Drug Use			1		
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results			
		TEST NOT GIVEN				I =				
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	3			
2	8	Drug Type								
	•									
		Individual Condition								
		APPEARED NORMAL								
		1								
		Passenger KELAN J ZUELKE (608) 393-3892  Address 1882 8TH ST REEDSBURG, WI 53959 , US			Citations Issued  0	Sex MALE				
	INDIVIDUAL				Date of Birth	Race WHITE				
Ę	2				Driver License Number					
-	2				COUNTRY: UNITED STATES					
	Sai	ety Equipment On Duty	Crash		Safety Equipment					
		Row	ow Seat Position		SHOULDER & LAP BELT					
		02 - SECOND ROW Helmet Use	07 - LE	EFT	Helmet Compliance					
		Eye Protection			Tint Compliance					
2	8	Injury Se	everity	N.II IRV	Airbag NON DEPLOYED	PI OVED				
		Ejected	Ejection Pa	<b>it</b> h			Trapped/Extricated			
		NOT EJECTED  Medical Transport	NOT EJE	CTED/NOT APP	LICABLE EMS Agency Identifier		NOT TRAPPED EMS Run#			
		NOT TRANSPORTED			EWO Agency Identine		EWS Run			
		Hospital			Date of Death		Time of Death			
		Distract	ed By Source	<del>0</del>	1		1			
		Distracted By  Distracted By Action								
		Non Motorist	Unit#	Location						
		Prior Action		1						

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/29/2022

UNIT	INDIVIDUAL	Action								
		Action Other								To/From School
	1	Susp Drug & Alcohol NO	pected Alcohol U	se	Suspected Drug Use NO					
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test T				A	Alcohol Test	Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type			Drug Test F	Results			
5	883	Drug Type								
		Individual Condition  APPEARED NORMAL								
	I I m i	t Summanı								
	Unit	t Summary Status			ehicle Operating As Class	ification		Jnit Type		
	IN TRANSIT  Vehicle Type				CLASS			AUTOMOE  Operating A		ements
02		PORT) UTILITY VEHICLE								
	Tota 2	lOccs	Train/Bus#Recorded		otal#Citations Issued	Tota	al Trailers	0		zMat Types
╘	YES		Direction Of Travel  EASTBOUND		Pre CrashTire Mark	Speed Limi		mit Total Lanes 2 Emergency Motor Vehicle Use		
	MO.	st Harmful Event: Collision With DTOR VEH IN TRANSPORT			Special Function NO SPECIAL FUNCTION			NOT APPL	ICABLE	
		fic Way D-WAY, NOT DIVIDED			Traffic Control NO CONTROL			Traffic Control Inoperative/Missing  NO		
		ace Type			oad Curvature		1.	Road Grade		
	Truc	<b>k Bus or HazMat</b>			TRAIGHT			.EVEL		
	NO.									
		Vehicle License Plate Number		T F	Plate Type	St	Tc	ountry of lss	suance	
		804XTT			AUT - AUTOMOBILE	WI		NITED ST		
	8	Vehicle Identification Numb 3C4PDCGGXFT543732			Make DODGE	Year 201		odel OURNEY (	CR	
		Color		£	Body Style			JOURNEY CR Bus Use		
⊨	Ш O	Initial Contact Point 12 - FRONT		\	/ehicle Damage		I			7 8 9 10 11
L N	VEHICLE	Extent Of Damage MINOR DAMAGE			12 - FRONT					6 12 12 5 4 3 2 1
		Towed Due To Damage NOT TOWED			Vehicle Removed By DWNER					
		What Driver Was Doing STOP IN TRAFFIC								

22-00906

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/29/2022

					/ehicle Factors						
		Driver Prior Action Other			NOT APPLICABLE						
		Birrar Harriston Guidi									
LINI	VEHICLE	Driver Actions NO CONTRIBUTING ACT	ION								
		Owner Name			Owner Address						
	02	MISTY ROSE SMELCER (608) 393-3683			914 JUSTIN CIR REEDSBURG, WI	53959 , US					
		Sequence Of Events			I .						
	10	Event MOTOR VEH IN TRANSPORT									
	Event										
	03	Event									
	8	Event									
_		Policy Holder									
IN		Insurance Company SECURA-INS-CO		Individual							
		ndisidual			MISTY SMELCER						
		Driver MISTY ROSE SMELCER (608) 393-3683			Citations Issued	Sex					
	4			0							
⊨	3			Date of Birth	Race WHITE						
TINO	INDIVIDUA	Address 914 JUSTIN CIR REEDSBURG, WI 53959 , US		STATE: WISCONSIN COUNTRY: UNITED STATES							
	Sai	On Duty Crash  ety Equipment			Safety Equipment						
		Row 01 - FRONT ROW	Row Seat Position		SHOULDER & LAP BELT						
		HelmetUse			Helmet Compliance						
		Eye Protection			TintCompliance						
05	8	Injury S Injury NO AF	everity PARENT II	·JURY	Airbag NON DEPLOYED						
		Ejected NOT EJECTED	Ejection Pa		ICABLE		Trapped/Extricated NOT TRAPPED				
		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run#				
		Hospital		Date of Death		Time of Death					
		Distracted By NOT A	ed By Source	E (NOT DISTRAC	I		I				
		Distracted By Action NOT DISTRACTED			<u> </u>						
		Non Motorist	Unit#	Location							

22-00906

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/29/2022

		Prior Action									
	j	Action	Action								
LIND	NDIVIDUAL										
<b>-</b>	á										
		_									
		Action Other						To/From School			
	1										
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results				
		TEŠT NOT GIVEN		Drug TestType		Drug Test Results					
05	8	Drug Type									
		Individual Condition									
		APPEARED NORMAL									
		Individual Passenger JENNIFER LYNNE DUNSE (608) 415-8578			Citations Issued	T Sex					
	<u>i</u>				0	FEMALE					
⊨	INDIVIDUAL				Date of Birth	Race WHITE					
LNN	ă	Address E10042 SHADY LANE RD			Driver License Numbe	r					
	R	REEDSBURG, WI 53959 , US			STATE: WISCONSIN COUNTRY: UNITED STATES						
	Sai	On Duty Crash afety Equipment			Safety Equipment						
		Row 01 - FRONT ROW	Seat Po 09 - Ri		SHOULDER & LAP	BELT					
		HelmetUse			Helmet Compliance						
		Eye Protection			TintCompliance						
05	8	Injury NO A	Severity PPARENT II	NJURY	Airbag NON DEPLOYED						
		Ejected	Ejection Pa	th			Trapped/Extricated				
		NOT EJECTED  Medical Transport	MOLETE	CTED/NOT APPL	.ICABLE  EMS Agency Identifier		NOT TRAPPED EMS Run#				
		NOT TRANSPORTED									
		Hospital			Date of Death Time of Death						
		Distracted By	cted By Source	•							
		Distracted By Action									
		Non Motorist	ig Unit#	Location							
		Prior Action									

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 01/29/2022

LIND	INDIVIDUAL	Action					
		Action Other					To/From School
	Ĺ	Drug & Alcohol NO	Alcohol Use	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	3	
02	002	Drug Type	·				
		Individual Condition					
		APPEARED NORMAL					