

6TL0CX0Q9L
22-03073

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0CX0Q9L

Document Number Override		Primary Crash Document#	Agency Crash Number 22-03073	Investigating Officer/Deputy DEPUTY I. HANSON	
Crash Date 04/04/2022		Crash Time 07:58 AM	Date Arrived 04/04/2022	Time Arrived 08:34 AM	
Date Notified 04/04/2022		Time Notified 08:00 AM	Total Units 01	Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p> <p>NotScale</p>	Reconstruction By
	Photos By
	Additional Information NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS WEST ON CTH H WHEN IT STRUCK A TURKEY. THE TURKEY HIT THE HOOD AND STRUCK THE WINDSHIELD AND ROOF AREA AS WELL. THE ENTIRE WINDSHIELD WAS BROKEN AND PARTIALLY INSIDE THE DRIVERS FRONT PORTION OF THE SUV. UNIT 1 STATED SHE HAD INHALED SOME OF THE GLASS FROM THE WINDSHIELD AND HAD GLASS IN HER HAIR. UNIT 1 STATED SHE DID NOT WANT AMBULANCE BUT WOULD MONITOR AND GO TO THE HOSPITAL IF NEED BE. 9109

6TL0CX0Q9L

22-03073

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON CTHH WB 936 FT N OF SOUTH AVE IN THE TOWN OF DELLONA IN SAUK COUNTY	Latitude 43.583764665	Longitude -89.954751294
	X Coordinate 261450.234375	Y Coordinate 4829886.5
	Structure Type	

Crash Scene

First Harmful Event NON DOMESTICATED ANIMAL (ALIVE)	First Harmful Event Location ON ROADWAY	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DAYLIGHT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type TURKEY	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE	Operating As Endorsements			
	Total Occs 3	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With NON DOMESTICATED ANIMAL (ALIVE)	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade DOWNHILL	
	Truck Bus or HazMat NO				

Vehicle

UNIT VEHICLE 01	License Plate Number DK7177	Plate Type LTK - LIGHT TRUCK	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number JTEBU5JR8H5443675	Make TOYOTA	Year 2017	Model 4RUNNER
	Color BLK - BLACK	Body Style UT - SPORT UTILITY VEHICLE		Bus Use
	Initial Contact Point 00 - NON-COLLISION	Vehicle Damage		
	Extent Of Damage FUNCTIONAL DAMAGE	12 - FRONT, 13 - TOP		



6TL0CX0Q9L

22-03073

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By STEVES AUTO SERVICE		
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
01	Owner Name VANDANA DHANDA RICH (608) 477-2779		Owner Address 340 BOWMAN RD WISCONSIN DELLS, WI 53965 , US		
	Sequence Of Events				
01	01	Event NON DOMESTICATED ANIMAL (ALIVE)			
	02	Event			
	03	Event			
	04	Event			
UNIT	Policy Holder				
	Insurance Company STATE-FARM-GENERAL-INS-CO		Individual VANDANA RICH		
UNIT INDIVIDUAL	Individual				
	Driver VANDANA DHANDA RICH (608) 477-2779		Citations Issued 0	Sex FEMALE	
	Address 340 BOWMAN RD WISCONSIN DELLS, WI 53965 , US		Date of Birth [REDACTED]	Race ASIAN OR NATIVE HAWAIIAN OR OTHER PACIFIC ISLAN	
			Driver License Number [REDACTED]	STATE: WISCONSIN COUNTRY: UNITED STATES	
01	001	Safety Equipment		On Duty Crash	
				Safety Equipment SHOULDER & LAP BELT	
	Row 01 - FRONT ROW		Seat Position 07 - LEFT		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
	Injury		Injury Severity SUSPECTED MINOR INJURY	Airbag NON DEPLOYED	
	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action		NOT DISTRACTED			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT INDIVIDUAL	Non Motorist		Striking Unit #	Location
	Prior Action			
	Action			
	Action Other			To/From School
01 001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results
	Drug Type			
	Individual Condition APPEARED NORMAL			
	Individual			
UNIT INDIVIDUAL	Passenger LOGAN R RICH (608) 477-2779		Citations Issued 0	Sex MALE
			Date of Birth [REDACTED]	Race WHITE
	Address 340 BOWMAN RD WISCONSIN DELLS, WI 53965 , US		Driver License Number	
01 002	Safety Equipment		On Duty Crash	Safety Equipment
	Row 02 - SECOND ROW	Seat Position 09 - RIGHT	SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	
Distracted By		Distracted By Source		
Distracted By Action				
Non Motorist		Striking Unit #	Location	

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Prior Action	
		Action	
		Action Other	To/From School
01	002	Drug & Alcohol	
		Suspected Alcohol Use NO	Suspected Drug Use NO
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type
		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type
		Drug Test Results	
Drug Type			
Individual Condition APPEARED NORMAL			
UNIT	INDIVIDUAL	Individual	
		Passenger GERTRUDE O RICH (608) 477-2779	Citations Issued 0
			Sex FEMALE
			Date of Birth [REDACTED]
			Race WHITE
		Address 340 BOWMAN RD WISCONSIN DELLS, WI 53965 , US	Driver License Number
01	003	Safety Equipment	
		On Duty Crash	Safety Equipment
		Row 02 - SECOND ROW	Seat Position 07 - LEFT
		CHILD RESTRAINT SYSTEM - FORWARD FACING	
		Helmet Use	Helmet Compliance
		Eye Protection	Tint Compliance
01	003	Injury	
		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE
		Trapped/Extricated NOT TRAPPED	
		Medical Transport NOT TRANSPORTED	EMS Agency Identifier
		EMS Run #	
Hospital	Date of Death		
Time of Death			
Distracted By	Distracted By Source		
	Distracted By Action		
Non Motorist	Striking Unit #	Location	
	Prior Action		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT INDIVIDUAL	Action			
	Action Other		To/From School	
	Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
	Drug Type			
	Individual Condition APPEARED NORMAL			
	01 003			