6TL097RB7D 22-03799

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Overrid	le Primary Crash	Primary Crash Document# Crash Time 07:10 PM Time Notified 07:18 PM		Agency Crash Number 22-03799 Date Arrived 04/26/2022		Investigating Officer/Deputy DEPUTY C. BRATZ Time Arrived 07:31 PM		
2	Crash Date 04/26/2022								
6TL097RB7D	Date Notified 04/26/2022				Inits	Total Injured Total K		Killed	
097	On Emergency	Hit and Run	Lane Clos	ure	Work Zone	Trailer	or Towed	Reporting Threshold	
3T	Government Property	Active So	chool Zone	Schoo NO	IBus Related	Tags		-	
_		Crash Type DT4000 (STA	ANDARD CRASI	H)		Amend	ed .	Secondary Crash	
	Description —								
	Su	Cul ınrise Rd.	vert		Field Driveway		Photos By Additional Inf	formation	
				STOP	Image not to So	cale			

| I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

Summit Dr.

ON THE ABOVE DATE AND TIME, I HEARD THE SAUK COUNTY DISPATCH NOTIFY VIA RADIO, OF A ONE VEHICLE ACCIDENT, LOCATED NEAR THE ADDRESS OF S6205 SUNRISE RD, LOGANVILLE, WI 53943. WHILE ENROUTE, DISPATCH ADVISED, THAT THEIR WAS A MALE INSIDE THE VEHICLE SLUMPED OVER DISPATCH FURTHER ADVISED, THAT IT WAS UNKNOWN IF THE MALE WAS BREATHING, OR HAD A PULSE. I ARRIVED AT THE LOCATION WHERE I OBSERVED A TRUCK, MAROON IN COLOR, WITH WI LICENSE PLATE SU1000, LOCATED IN THE WESTERN SIDE OF THE DITCH, FROM THE COURSE OF THE INVESTIGATION, AND LOCATION OF THE VEHICLE, IT APPEARED THAT THE VEHICLE (UNIT ONE) TRAVELED WEST ON SUMMIT DR. UNIT ONE APPROACHED THE STOP SIGN AT INTERSECTION OF SUMMIT DRIVE/SUNRISE RD, AND CONTINUED THROUGH INTERSECTION. UNIT ONE THEN ENTERED THE DITCH, AND WENT OVER A CULVERT, UNIT ONE THEN STRUCK THE SIDE BERM OF DITCH, AS LARGE PATCHES OF GRASS, APPEARED TO HAVE BEEN UPROOTED. UNIT ONE CAME TO A REST IN THE DITCH APPROXIMATELY 60 YARDS OFF ROADWAY. I OBSERVED THAT UNIT ONE HAD SUSTAINED SUBSTANTIAL DAMAGE TO NUMEROUS PARTS OF VEHICLE, UNIT ONE, HAD ONE LONE OCCUPANT, SITTING IN THE DRIVER'S SEAT. I WAS ABLE RECOGNIZE UNIT ONE DRIVER FROM PREVIOUS LAW ENFORCEMENT CONTACTS, UNIT ONE DRIVER ALSO WAS ABLE TO VERBALLY, IDENTIFY HIMSELF. UNIT ONE DRIVER STATED HE HAD NO INJURIES, UNIT ONE DRIVER REFUSED EMS. UNIT ONE DRIVER WAS TAKEN INTO CUSTODY, AND ARRESTED FOR OWI. VEHICLE WAS REMOVED FROM DITCH AND TOWED BY STEVES AUTO.

1 of 4

Crash Date 04/26/2022
Crash Time 07:10 PM

6TL097RB7D 22-03799

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 04/26/2022

Crash Time 07:10 PM

•	ON SUNRISE RD 38 FT N OF SUMMIT RD			Latitude 43.4203				3566181		
	IN THE TOWN OF WESTFI	ELD					Y Coord			
				Structure NO STR	Type RUCTURE	•				
	Crash Scene			•						
	First Harmful Event			FirstHarr	mful Event	Location				
	DITCH			ON ROA	ADWAY					
	Manner of Collision			Light Cor	ndition					
	00 - NO COLLISION W/VEH	HICLE IN TRANSPORT		DAYLIG	DAYLIGHT					
	Road Surface Condition(s)			Roadway	Roadway Factor(s)					
	DRY	DRY								
	Environment Factor(s)									
	NONE			NONE	NONE					
	Weather Condition(s)									
	CLEAR									
	Animal Type	Animal Type				Relation To Trafficway				
					TRAFFICWAY - ON ROAD					
	Crash Classification - Location PUBLIC PROPERTY				Crash Classification - Jurisdiction NO SPECIAL JURISDICTION					
	Tribal Land							Special Study		
				NO COM	NO CONTROL					
	,	Junction Location		Intersection Type	CTION					
		NON-JUNCTION		NOT AN INTERSE	ECHON					
	Unit Summary		Vehicle Oper	atina As Classificatio	n	1 1 m is T				
	Unit Summary Unit Status IN TRANSIT		Vehicle Opera	ating As Classificatio	n	Unit Type TRUCK				
	Unit Status			ating As Classificatio	n	1	As Endorse	ements		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP 1		D CLASS			TRUCK Operating A				
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs	FRUCK Train/Bus#Recorded	D CLASS Total # Citatio		TotalTra	TRUCK Operating A	TotalHa	ements zMat Types		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1	Train/Bus#Recorded	D CLASS Total # Citatio 1	ns Issued	Total Tra	TRUCK Operating A	Total Ha:	zMatTypes		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs		Total#Citatio	ns ssued	TotalTra	TRUCK Operating A	TotalHa	zMatTypes		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance?	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total # Citation Pre C Special Func	rashTire Mark	TotalTra 0 Speed L	TRUCK Operating A ailers Limit Emergency	Total Ha: 0 Total Lar 2 / Motor Vel	zMat Types nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total#Citatio 1 Pre C N Special Funct NO SPECIA	rashTire Mark tion AL FUNCTION	TotalTra 0 Speed L	TRUCK Operating A ailers Limit Emergency NOT APP	Total Ha: 0 Total Lar 2 Motor Vel	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total # Citation 1 Pre C. N. Special Function NO SPECIA	rashTire Mark tion AL FUNCTION	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con	Total Ha: 0 Total Lar 2 Motor Vel	zMat Types nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total#Citatio 1 Pre C N Special Funct NO SPECIA	rashTire flark tion AL FUNCTION	TotalTra 0 Speed L	TRUCK Operating A ailers Limit Emergency NOT APP	Total Ha: 0 Total Lar 2 / Motor Vel LICABLE	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citation Pre C Special Funct NO SPECIA Traffic Contro NO CONTR	rashTire flark tion AL FUNCTION OL	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO	Total Ha: 0 Total Lar 2 / Motor Vel LICABLE	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citation Pre C Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatu	rashTire flark tion AL FUNCTION OL	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO Road Grade	Total Ha: 0 Total Lar 2 / Motor Vel LICABLE	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision W DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citation Pre C Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatu	rashTire flark tion AL FUNCTION OL	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO Road Grade	Total Ha: 0 Total Lar 2 / Motor Vel LICABLE	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total#Citatio 1 Pre C. Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatt STRAIGHT	rashTire flark tion AL FUNCTION OL	TotalTra 0 Speed L	TRUCK Operating A ailers Emergency NOT APP Traffic Con NO Road Grade	Total Haz 0 Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citation Pre C Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatu	rashTire Mark tion AL FUNCTION OL	Total Tra 0 Speed L 55	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade LEVEL	Total Haz O Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number SU1300 Vehicle Identification Num	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citatio 1 Pre C N Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatt STRAIGHT Plate Type LTK - LIGH Make	rashTire Mark tion AL FUNCTION OL LIFE	Total Tra 0 Speed L 55	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade LEVEL Country of Is UNITED S Model	Total Haz 0 Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number SU1300 Vehicle Identification Num 1GCHK23U02F21545	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citatio 1 Pre Ci No Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatt STRAIGHT Plate Type LTK - LiGH Make CHEVROL	rashTire Mark tion AL FUNCTION OL LIFE	Total Tra 0 Speed L 55	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD	Total Haz 0 Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number SU1300 Vehicle Identification Num	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citatio 1 Pre C N Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatt STRAIGHT Plate Type LTK - LIGH Make	rashTire Mark tion AL FUNCTION OL LIRE	Total Tra 0 Speed L 55	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade LEVEL Country of Is UNITED S Model	Total Haz 0 Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number SU1300 Vehicle Identification Num 1GCHK23U02F21545: Color MAR - MAROON (BUF Initial Contact Point	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citatio 1 Pre Ci N Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatt STRAIGHT Plate Type LTK - LiGH Make CHEVROLi Body Style	rashTire Mark tion AL FUNCTION OL JIP HT TRUCK ET	Total Tra 0 Speed L 55	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD	Total Haz 0 Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use Eative/Missing		
10 INO 110	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number SU1300 Vehicle Identification Num 1GCHK23U02F21545: Color MAR - MAROON (BUF Initial Contact Point	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith	Total # Citatio 1 Pre Ci No Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatu STRAIGHT Plate Type LTK - LiGH Make CHEVROLi Body Style PK - PICKU Vehicle Dam	rashTire Mark tion AL FUNCTION OL ure HT TRUCK ET UP	Total Tra 0 Speed L 55	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD	Total Haz 0 Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use Eative/Missing		
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP Total Occs 1 Insurance? UNKNOWN Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number SU1300 Vehicle Identification Num 1GCHK23U02F215456 Color MAR - MAROON (BUF Initial Contact Point	Train/Bus#Recorded Direction Of Travel WESTBOUND Vith S) Aber 1 RGUNDY)	Total # Citatio 1 Pre Ci No Special Funct NO SPECIA Traffic Contro NO CONTR Road Curvatu STRAIGHT Plate Type LTK - LiGH Make CHEVROL Body Style PK - PICKU	rashTire Mark tion AL FUNCTION OL ure HT TRUCK ET UP	Total Tra 0 Speed L 55	TRUCK Operating A ailers Limit Emergency NOT APP Traffic Con NO Road Grade LEVEL Country of Is UNITED S' Model SILVERAD	Total Haz 0 Total Lar 2 Motor Vel LICABLE trol Inopera	zMatTypes nes hicle Use thative/Missing		

6TL097RB7D

22-03799

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 04/26/2022

Crash Time 07:10 PM

		Towed Due To Damage TOWED DUE TO DISA	ABLING DAMA		ehicle Removed By TEVES AUTO SERVI	ICE			
		What Driver Was Doing			Vehicle Factors				
		GOING STRAIGHT Driver Prior Action Other		N	NOT APPLICABLE				
	ш	Driver Actions OTHER CONTRIBUTION	NG ACTION						
UNIT	ō								
5	VEHICLE								
_	OwnerName ANN MARIE HELM				Owner Address S5932 COUNTY ROAD PF				
2	8				NORTH FREEDOM	1, WI 53951 , US			
	Sequence Of Events								
	5	Event DITCH							
		Event							
	8								
	8	Event							
	2	Event							
		Driver			Citations Issued	Sex			
		KEVIN LEROY HELM			1 MALE				
_	3	Address S5932 COUNTY ROAD PF NORTH FREEDOM. W: 53951 . US			Date of Birth	Race WHITE			
N					Driver License Number				
	S5932 COUNTY ROAD PF NORTH FREEDOM, WI 53951 , US				STATE: WISCONSIN COUNTRY: UNITED STATES				
		0-	Duti Creek		Defeat Freedoment				
	Sai	ety Equipment	Duty Crash		Safety Equipment				
	Row Seat Position 01 - FRONT ROW 07 - LEFT				SHOULDER & LAP BELT				
		HelmetUse	101-2	L t 1	HelmetCompliance				
		Eve Protection			TintCompliance				
	Eye Protection								
2	8	Injury NO	rry Severity O APPARENT I	INJURY	Airbag NON DEPLOYED				
		Ejected	Ejection P	ath			Trapped/Extricated		
	NOT EJECTED NOT EJECTED/NOT APPLIC					NOT TRAPPED			
		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run#		
		Hospital			Date of Death Time of Death				
		Distracted By UN	tracted By Sourc	¢e			L		
		Distracted By Action UNKNOWN							
		Non Motorist	iking Unit#	Location					
		(TOT MOTORISE							

6TL097RB7D 22-03799

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 04/26/2022

Crash Time 07:10 PM

		Prior Action						
		Action						
	4							
⊨	à							
LIND	INDIVIDUAL							
		Action Other						To/From School
	l		Suspected Alco	shollies	Suspected Drug Use			
	L	Drug & Alcohol	YES	onor ose	YES			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given		Drug Test Type		Drug Test Results		
		TEST NOT GIVEN		Diag restrype		Diug restricesum		
10	8	Drug Type		•		•		
		Individual Condition						
		UNDER THE INFLU	UENCE OF ME	EDICATIONS/DRUGS/	ALCOHOL			
		65 X 45						
	1	With a 158 (198 (198 (198 (198 (198 (198 (198 (19						
	9	UTC Number BE611809	Issue To?	Statute Number 346.63(1)(a)	Description OPERATING WHILE	UNDER THE IN	FLUENCE	