WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override Crash Date 05/21/2022		Primary Crash Document# Crash Time 12:32 PM		Agency Crash Number 22-04619 Date Arrived 05/21/2022		Investigating Officer/Deputy DEPUTY B. STODDARD Time Arrived 12:52 PM				
7//											
O I LUDONUZW	Date Notified 05/21/2022		Time Notified 12:32 PM		Total Units 01		Total Injured	Total Injured Total Kille		1	
טוט.	On Emergency Hit		t and Run Lane Closu				☐ Trailer or Towed		wed	Reporting Threshold	
0 I L	Government Property			hool Zone	School NO	Bus Related	Tags				
	Reportable		Crash Type DT4000 (STANDARD CRASH)							Secondary Crash	
	Description Diagram					•		Reco	nstruction	Ву	
	0		Mar	shal Rd				Photo	os By		
						Not to Scale		Additi	ional Infor I E	mation	
	↓ I, a sworn law enfo	rceme	nt officer. agre	ee that I have no	ot added	d any CJIS data in this	report.				
	UNIT 1 WAS WESTBOUND WIRE FENCE. UNIT 1 CAM	ON MAR	SHAL RD. UNIT	1 OPERATOR FELL	ASLEEP			UNIT 1	1 STRUCK	BRUSH AND A BARBED	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/21/2022

Crash Time 12:32 PM

DN MASSHALL RD Longitude		Location —								
OF CTHON B IN THE TOWN OF IRONTON IN SAUK COUNTY X Conditionals X Conditional X Condit		ON MARSHALL RD					Latitude		Longitude	
IN THE TOWN OF IRONTON IN SAUK COUNTY 2X3978.28125 Structure Type Crash Scene First-Hammful Event Location First-Hammful Event Location On No Collision WivEHICLE IN TRANSPORT Read Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Annual Type TRAFFICWAY - ON ROAD Cash Classification - Jurisdiction NO SPECIAL JURISDICTION Width Interchange Area NO NON-JUNCTION Unit Summary Vehicle Operating As Classification IN TRANSIT Unit Summary Vehicle Operating As Classification Insurance? Unit Type Trausification - Jurisdiction NO SPECIAL Jurisdiction NO TAN INTERSECTION Unit Summary Vehicle Operating As Classification Insurance? Unit Summary Vehicle Operating As Classification Insurance? Unit Type Traffic Control Insurance? Unit Type Traffic Control Insurance? Insurance? Insurance Control Insurance Insura							43.533040804		-90.1	68491651
IN SAUK COUNTY Crash Scene First Harmful Event Location SHOULDER RICHT Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT Road downer of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT Road downer of Collision DRY Environment Factor(s) NONE NONE NONE NONE NONE NONE Relation To Trafficway TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY The Land NO CONTROL With Interchange Assa NO CONTROL With Interchange Assa NO NON-JUNCTION Unit Summary Unit Summary IN Salvis IN TRANSIT D CLASS Vehicle Operating As Classification NO Train Classification Intersection Type NOT An INTERSECTION Unit Summary Unit Summary Vehicle Operating As Classification IN TRANSIT D CLASS TRUCK Total Occs Train Base Recorded Intersection Type Unit Summary Unit Summary In Train Control NO SPECIAL JURIS O D O O O O O O O O O O O O O O O O O			.∪N				X Coordinate		Y Coordinate	
Crash Scene First Harmful Event TREE SHOULDER RICHT Manner of Collision 00 - NO COLLISION WVEHICLE IN TRANSPORT Road Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Relation To Treffloway TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY No SPECIAL JURISDICTION Tribal Land Access Control NO SPECIAL JURISDICTION Within interchange Area No NON-JUNCTION Unit Summary Unit Summa						243978.28125		4824	889.5 	
First Hamful Event TREE SHOULDER RIGHT Menner of Collision Do - NO COLLISION WIVEHICLE IN TRANSPORT DAYLIGHT Read Surface Gondition(s) DRY Environment Factor(s) NONE NONE CLEAR Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD Cresh Classification - Location Public Property Tribal Land No SPECIAL JURISDICTION NO CONTROL Within Interchange Area NO NOT AN INTERSECTION Unit Summary Property Unit Summary Unit Summ				Structure Type						
TREE SHOULDER RIGHT		Crash Scene				I				
Mainter of Collision WiveHicLE in TransPort DaYLIGHT		FirstHarmfulEvent				FirstHarm	ful Event L	ocation.		
DAYLIGHT Road Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Trans Classification - Location PUBLIC PROPERTY Tribal Land NO - Junction Location NON-JUNCTION NON-JUNCTION NON-JUNCTION NON-JUNCTION NOT AN INTERSECTION Unit Summary In I TRANSIT D CLASS Vehicla Type UTILITY TRUCK/PICKUP TRUCK Tribal Cocs Train/Bus # Recorded Train/Cocs		TREE								
Road Surface Condition(s) Roadway Factor(s)		Manner of Collision			Light Condition					
DRY Environment Factor(s) NONE Weather Condition(s) CLEAR Animal Type Traffic Control PUBLIC PROPERTY Tibal Land Within Interchange Area NoN-JUNCTION Unit Summary Unit Status NoN-JUNCTION Unit Status NoN-JUNCTION Unit Status No Control Unit Traffic Control No Special Study NoT An INTERSECTION Unit Traffic Control No Special Study NoT An Interchange Area NoN-JUNCTION Unit Status Vehicle Operating As Classification Unit Type Traffic Control No Special Study NoT An Interchange Area No Unit Type NoT An Interchange Area No Unit Type Unit Status No Control Unit Status No Special Study NoT An Interchange Area No Unit Type Unit Status No Special Study NoT An Interchange Area No Unit Type Traffic Control No Special Function No Specia			EHICLE IN TRANSPORT							
NONE Weather Condition(s)		, ,				Roadway Factor(s)				
NONE Weather Condition(s)		[[]								
Weather Condition(s) CLEAR		1								
CLEAR Animal Type Crash Classification - Location PUBLIC PROPERTY Tribal Land Access Control NO SPECIAL JURISDICTION Tribal Land Access Control NO SPECIAL JURISDICTION Tribal Land Access Control NO CONTROL Within interchange Area NO NON-JUNCTION Unit Summary Unit Status IN TRANSIT Vehicle Operating As Classification Unit Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0						NONE				
Animal Type Relation To Trafficway TRAFFICWAY - ON ROAD		Weather Condition(s)								
TRAFFICWAY - ON ROAD Crash Classification - Location PUBLIC PROPERTY Tribal Land Access Control NO SPECIAL JURISDICTION Access Control NO CONTROL Within Interchange Area Junction Location NO HON-JUNCTION NO CONTROL Within Interchange Area Junction Location NO HON-JUNCTION NO CONTROL Unit Summary Unit Summary Unit Transition Unit Summary Unit Transition Unit Transition Vehicle Operating As Classification Unit Type NOT AN INTERSECTION Unit Summary Vehicle Type Operating As Classification Unit Type TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total Haz/Mat Types 1		CLEAR								
PUBLIC PROPERTY Tribal Land Access Control NO CONTROL Within Interchange Area NO NON-JUNCTION Unit Summary Unit Status IN TRANSIT Vehicle Operating As Classification Unit TYPE TRUCK/PICKUP TRUCK Total Cocs Intain/Bus #Recorded O		Animal Type				ı		-		
Tribal Land Access Control NO CONTROL		Crash Classification - Location	n			Crash Cla	ssification	- Jurisdiction		
Within Interchange Area NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Summary Unit Status Vehicle Type D CLASS TRUCK Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded O O O O O O O O O O O O O O O O O O										
Unit Summary Vehicle Operating As Classification Unit Type TRUCK		TribalLand					Spec		Special Study	
Unit Summary Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded Insurance? Vehicle Septendum Vehicle Vehicle Septendum Vehicle Use No Special Function No SPECIAL FUNCTION Most Harmful Event Collision With TREE Traffic Way TWO-WAY, NOT DIVIDED NO CONTROL NO Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number PL6952 LTK - Light Truck PRA PLORE Vehicle Islance Vehicle Color Body Style BLK - BLACK PK - PICKUP Make Vehicle Vehicle Jeenstrication Number CHEVROLET Color Body Style BLK - BLACK PK - PICKUP Well black Color Body Style BLK - BLACK PK - PICKUP Vehicle Damage			1			••				
Unit Status Vehicle Operating As Classification Unit Type TRUCK Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total # Citations Issued O O O Insurance? Direction Of Travel EASTBOUND Mark 45 2 Treatific Way Traffic Control NO SPECIAL FUNCTION Traffic Control Inoperative/Missing NO CONTROL NO CO			non concrete		1101741					
IN TRANSIT				Vehicle One	erating As C	lassification		I Init Typo		
Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded 1				1	_					
Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total HazMat Types	_									
Truck Bus or HazMat NO	ò	T								
YES						.			azMatTypes	
Most Harmful Event: Collision With TREE Special Function NO SPECIAL FUNCTION Emergency Motor Vehicle Use NOT APPLICABLE Traffic Way Traffic Control Traffic Control Inoperative/Missing NO CONTROL NO Surface Type Road Curvature Road Grade LEVEL Truck Bus or HazMat NO Vehicle License Plate Number Plate Type St Country of Issuance PL6952 LTK - LIGHT TRUCK WI UNITED STATES Vehicle Identification Number Make Year Model SILVERADO Color Body Style PK - PICKUP BILK - BLACK PK - PICKUP Wehicle Damage		Insurance?	Direction Of Travel Pre		Pre CrashTire		Speed Limit		TotalLanes	
Traffic Way Traffic Control Traffic Control NO Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number PL6952 Vehicle Identification Number 2GCEK19T411117721 Color BLK - BLACK Initial Contact Point Traffic Control NO Traffic Control NO Road Curvature Road Grade LEVEL Truck Bus or HazMat NO Vehicle License Plate Number PL6952 Vehicle Identification Number Body Style Bus Use Bus Use Initial Contact Point Vehicle Damage	⊨	YES	EASTBOUND				45		2	
TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number PL6952 Vehicle Identification Number 2GCEK19T411117721 Color BLK - BLACK PK - PICKUP Initial Contact Point No Road Curvature Road Grade LEVEL Road Grade LEVEL Road Grade LEVEL Country of Issuance UNITED STATES Will UNITED STATES Bus Use Bus Use Initial Contact Point Vehicle Damage	5		1 '							
Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number PL6952 Vehicle Identification Number 2GCEK19T411117721 Color BLK - BLACK PK - PICKUP Initial Contact Point Road Grade LEVEL Road Grade LEVEL Road Grade LEVEL Country of Issuance UNITED STATES Road Grade LEVEL Bus Use Road Grade LEVEL LEVEL Country of Issuance UNITED STATES Bus Use Bus Use Road Grade LEVEL By Country of Issuance UNITED STATES Bus Use Bus Use					Traffic Control				Traffic Control Inoperative/Missing	
BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number PL6952 Vehicle Identification Number 2GCEK19T411117721 Color BLK - BLACK Initial Contact Point Plate Type LTK - LIGHT TRUCK WI UNITED STATES Make Year Model CHEVROLET Body Style PK - PICKUP Initial Contact Point Vehicle Damage			NO CONT	NO CONTROL			l .			
Truck Bus or HazMat NO Vehicle License Plate Number PL6952 LTK - LIGHT TRUCK Vehicle Identification Number 2GCEK19T411117721 CHEVROLET BLK - BLACK PK - PICKUP Initial Contact Point Vehicle Damage		= :	10)					1		
Vehicle License Plate Number PL6952 Vehicle Identification Number Added Vehicle Id			JS)	STRAIGH				LEVEL		
License Plate Number PL6952 Vehicle Identification Number 2GCEK19T411117721 Color BLK - BLACK PK - PICKUP Initial Contact Point Plate Type LTK - LIGHT TRUCK WI UNITED STATES Whodel UNITED STATES Whodel UNITED STATES Wodel SILVERADO Bus Use Bus Use										
License Plate Number PL6952 Vehicle Identification Number 2GCEK19T411117721 Color BLK - BLACK PK - PICKUP Initial Contact Point Plate Type LTK - LIGHT TRUCK WI UNITED STATES Whodel UNITED STATES Whodel UNITED STATES Wodel SILVERADO Bus Use Bus Use										· CRISTO
Vehicle Identification Number 2GCEK19T411117721 CHEVROLET 2001 SILVERADO Body Style BLK - BLACK PK - PICKUP Initial Contact Point Vehicle Identification Number 2001 SILVERADO Bus Use		License Plate Number	Plate Type	LTK - LIGHT TRUCK Make				Country of Issuance		
Color Body Style Bus Use BLK - BLACK PK - PICKUP Initial Contact Point Vehicle Damage		PL6952	LTK - LIC			WI	UNITED ST	el		
Color Body Style Bus Use BLK - BLACK PK - PICKUP Initial Contact Point Vehicle Damage							1			
BLK - BLACK PK - PICKUP Initial Contact Point Vehicle Damage		Color BLK - BLACK Initial Contact Point							<u> </u>	
Ш Initial Contact Point Vehicle Damage					1			□ □ US USE		
									T	
Extent Of Damage CORNER, 12 - FRONT CORNER, 11 - LEFT FRONT CORNER, 12 - FRONT 5.4.3.2.1	╘									
MINOR DAMAGE	5	Extent Of Damage MINOR DAMAGE			LAGRIER AG FRONT			6 12 5 4 3 2 1		

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/21/2022

Crash Time 12:32 PM

		Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR							
		What Driver Was Doing		Vehicle Factors							
		GOING STRAIGHT		venicle Factors							
		Driver Prior Action Other		NOT APPLICABLE							
	411	Driver Actions RAN OFF ROADWAY									
l⊨	VEHICLE										
	Ħ										
	5										
		Owner Name		Owner Address							
	5	LEONARD LEE GASSER (608) 434-7569		S3007 COUNTY ROAD G LA VALLE, WI 53941 , US							
	T	(,			,						
		l Sequence Of Events		I							
	5	Event TREE			***************************************						
	ឧ	FENCE	Event FENCE								
	8	Event									
		Event									
	Z										
l⊨		Policy Holder									
IN N	Insurance Company ALLSTATE-INS-CO			Individual LEONARD GASSER							
		individual									
		Driver		Citations ssued Sex							
		LEONARD LEE GASSER (608) 434-7569		0							
<u>_</u>	NDIVIDUA	, ,		Date of Birth	Race WHITE						
FNS	2	Address		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES							
-	Z	S3007 COUNTY ROAD G LA VALLE, WI 53941 , US									
	Sai	On Dut fety Equipment	y Crash	Safety Equipment							
	Ŭ.,	Row	Seat Position	SHOULDER & LAP BELT							
		01 - FRONT ROW	07 - LEFT								
		HelmetUse		Helmet Compliance							
		Eye Protection		Tint Compliance							
				·							
2	8	Injury Severity NO APPARENT INJURY Ejected Ejection Path		Airbag NON DEPLOYED							
						Trapped/Extricated					
		NOT EJECTED NOT EJECTED/NOT AF				NOT TRAPPED					
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run#					
		Hospital		Date of Death		Time of Death					
		_,									
		Distracted By NOT A	ted By Source IPPLICABLE (NOT DISTR	ACTED)							
		Distracted By Action NOT DISTRACTED									
ı	51110000	1									

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/21/2022

Crash Time 12:32 PM

	Striking Unit	# Location				
	Non Motorist	# Location				
	Prior Action					
UNIT	Action					
	Action Other					To/From School
	Drug & Alcohol NO	Alcohol Use	Suspected Drug Use NO			
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	e		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results		3	
<u>8</u>	Drug Type					
	Individual Condition					
	ASLEEP OR FATIGUED					