WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/29/2022

Crash Time 05/29/2022 10:05 PM 05/30/2022 06:04 AM 05/29/2022 10:15 PM 05/30/2022 07:04 AM 05/29/2022 10:15 PM 01 01 00 00 00 00 00 00 00 00 00 00 00	Document Number Override	Primary Crash I	Document #	Agency 22-09	/ Crash Number 76	Investigating Of DEPUTY J. G			
On Emergency									
Government Property Active School Zone NO School Bus Related NO Tags Reportable Crash Types C					Inits			ed	
Property Reportable Dradou (STANDARD CRASH) Description Reconstruction By	On Emergency	lit and Run	Lane Clos	osure Work Zone		Trailer or Towed		Reporting Threshold	
Description Diagram Reconstruction By Photos By Not to scale Not to scale I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.		Active Sc	hool Zone		Bus Related	Tags			
Diagram Reconstruction By Photos By Additional Information NONE Not to scale I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.	 ⊘ Reportable	Crash Type DT4000 (STA	NDARD CRASI	H)		Amended	l		
Photos By Additional Information NonE Not to scale I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.									
						A	dditional Info	ormation	
UNIT I TRAVELING NORTH ON 3TH 30 BT REDSTONE MARINA AND HIT A COW IN THE ROADWAT.						is report.			

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/29/2022

	Loc	ation								
		STH58 NB			I Li	atitude			Longitue	de
	902	FT N			4	3.60731	4288		_	3461776
		WILKE RD			X	X Coordinate		Y Coord	dinate	
		THE TOWN OF LA VAL SAUK COUNTY	.LE			247927.265625		483300		
	IIN S	SAUR COUNTY			S	Structure T	уре			
					N	NO STRU	JCTURE			
	Cra	sh Scene								
	First	: Harmful Event			F	irst Harm	ful Event Lo	cation		
	DOI	MESTICATED ANIMAL	- ALIVE		C	ON ROAL	DWAY			
	Man	ner of Collision			L	ight Cond	ition			
	00 -	NO COLLISION W/VE	HICLE IN TRANSPORT		ם	DARK/UN	NLIT			
	Roa	d Surface Condition(s)			R	Roadway F	actor(s)			
	DR	Y								
	Envi	ronment Factor(s)								
	NOI	NE			N	NONE				
	Wea	ather Condition(s)								
	CLE	EAR								
	Anin	nal Type			R	Relation To	o Trafficway	/		
	ОТН	HER NON DOMESTICA	ATED				WAY - O			
		sh Classification - Location					sification -			
		BLIC PROPERTY al Land				NO SPECIAL JURISDICTION Access Control Special Study				Special Study
						NO CONTROL				
		in Interchange Area	Junction Location		Intersection 7	••				
	NO		NON-JUNCTION		NOT AN IN	HERSE	JIION			
					1					
		t Summary -		I Vahiala On	ereting As Clas	aification		Lust		
	Unit	Status			erating As Clas	ssification		Unit Type	RII F	
	Unit IN T	Status FRANSIT		Vehicle Ope		ssification		AUTOMOE		ments
01	Unit IN T Vehi	Status	.E			ssification				ments
	Unit IN T Vehi (SP	Status FRANSIT icle Type	.E Train/Bus # Recorded	D CLASS		ssification	Total Trail	AUTOMOE Operating As	s Endorse	ments zMat Types
	Unit IN T Vehi (SP Tota 2	Status FRANSIT icle Type ORT) UTILITY VEHICL	Train/Bus # Recorded	D CLASS		ssification	0	AUTOMOE Operating As	s Endorse Total Haz	zMat Types
10	Unit IN T Vehi (SP Tota 2	Status FRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance?	Train/Bus # Recorded Direction Of Travel	D CLASS Total # Cita 0	tions Issued CrashTire	ssification	0 Speed Lim	AUTOMOE Operating As	Total Haz O Total Lan	zMat Types
10	Unit IN T Vehi (SP Tota 2 Insu YES	Status RANSIT icle Type ORT) UTILITY VEHICL Il Occs rance?	Train/Bus # Recorded Direction Of Travel NORTHBOUND	Total # Cita 0	crashTire	ssification	0	AUTOMOE Operating Assers	Total Haz O Total Lan 2	zMat Types
	Unit IN T Vehi (SP Tota 2 Insu YES	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? S t Harmful Event: Collision V	Train/Bus # Recorded Direction Of Travel NORTHBOUND With	Total # Cita 0 Pre Special Fur	crashTire		0 Speed Lim	AUTOMOE Operating As	Total Haz 0 Total Lan 2 Motor Veh	Mat Types les
10	Unit IN T Vehi (SP Tota 2 Insu YES Mos DOI	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? S t Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With	Total # Cita 0 Pre Special Fur NO SPEC	CrashTire Mark notion		0 Speed Lim	AUTOMOE Operating As ers iit Emergency NOT APPL	Total Haz O Total Lan 2 Motor Veh	ees iicle Use
10	Unit IN T Vehi (SP Tota 2 Insu YES Mos DOI Traff	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE	Total # Cita 0 Pre Special Fur NO SPEC	CrashTire Mark notion CIAL FUNCTION		0 Speed Lim	AUTOMOE Operating Asserts Emergency	Total Haz O Total Lan 2 Motor Veh	ees iicle Use
10	Unit IN T Vehi (SP Tota 2 Insu YES Mos DOI Traff	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? S t Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE	Total # Cita 0 Pre Special Fur NO SPEC	CrashTire Mark notion CIAL FUNCTION TO THE T		0 Speed Lim	AUTOMOE Operating As ers it Emergency NOT APPL Traffic Contr	Total Haz 0 Total Lan 2 Motor Veh LICABLE ol Inopera	ees iicle Use
01	Unit IN T Vehi (SP Tota 2 Insu YES Mos: DOI Traff TWO Surfa	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With - ALIVE	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	CrashTire Mark nction CIAL FUNCTION TROL		0 Speed Lim	AUTOMOE Operating As ers Emergency NOT APPL Traffic Contr	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	ees iicle Use
01	Unit IN T Vehi (SP Tota 2 Insu YES Mos DOI Traff TWC Surf: BLA	Status TRANSIT icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With - ALIVE	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT	CrashTire Mark nction CIAL FUNCTION TROL		0 Speed Lim	AUTOMOE Operating As ers Emergency NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	ees iicle Use
10	Unit IN T Vehi (SP Tota 2 Insu YES DOI Traff TWO Surfa BLA Truck NO	Status TRANSIT TICLE Type ORT) UTILITY VEHICL TRANSIT TRANSIT TO THE TYPE ORT) UTILITY VEHICL TO THE TYPE TO THE TYPE TO THE TYPE ACKTOP (BITUMINOUS) TO THE TYPE	Train/Bus # Recorded Direction Of Travel NORTHBOUND With - ALIVE	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT	CrashTire Mark nction CIAL FUNCTION TROL		0 Speed Lim	AUTOMOE Operating As ers Emergency NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	ees nicle Use
10	Unit IN T Vehi (SP Tota 2 Insu YES DOI Traff TWO Surfa BLA Truck NO	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With - ALIVE	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark notion CIAL FUNCTION TROL ature	ON	Speed Lim	AUTOMOE Operating As ers Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	ees iicle Use
10	Unit IN T Vehi (SP Tota 2 Insu YES DOI Traff TWO Surfa BLA Truck NO	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With - ALIVE	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark notion CIAL FUNCTION TROL nature	ON	Speed Lim 55	AUTOMOE Operating As ers Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh ICABLE II Inopera	ees iicle Use
LINIU 01	Unit IN T Vehit (SP Tota 2 Insury YES DOI Traff TWG Surfa BLA Truck NO	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark notion CIAL FUNCTION TROL ature	ON	Speed Lim	AUTOMOE Operating As ers Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh ICABLE II Inopera	ees iicle Use
10	Unit IN T Vehi (SP Tota 2 Insu YES DOI Traff TWO Surfa BLA Truck NO	Status TRANSIT Icle Type ORT) UTILITY VEHICL II Occs rance? St Harmful Event: Collision of the collision	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE	Total # Cital 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AU Make CADILLA	CrashTire Mark Inction CIAL FUNCTION TROL STATE	ON	Speed Lim 55 St WI	AUTOMOE Operating As ers iit Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model XT5	Total Haz 0 Total Lan 2 Motor Veh ICABLE II Inopera	ees iicle Use
LIND 01	Unit IN T Vehit (SP Tota 2 Insury YES DOI Traff TWG Surfa BLA Truck NO	Status TRANSIT ICIDE Type ORT) UTILITY VEHICL II OCCS TRANCE? Status TRANCE? TRANCE? TRANCE? STATE TO THE TENT TO THE	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AL Make CADILLA Body Style	CrashTire Mark Inction CIAL FUNCTION TROL Sature STOMOBILE AC	ON	Speed Lim 55 St WI Year 2020	AUTOMOE Operating As ers iit Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE II Inopera	ees iicle Use
LIND 01	Unit IN T Vehi (SP Tota 2 Insu YES DOI Traff TWO Surfa NO	Status TRANSIT ICIDE Type ORT) UTILITY VEHICL II OCCS TRANCE? S THARMFUL EVENT: COLLISION N MESTICATED ANIMAL FIC Way O-WAY, NOT DIVIDED ACKTOP (BITUMINOUS ICK BUS OF HAZMAT Vehicle License Plate Number AKS8027 Vehicle Identification Num 1GYKNBR40LZ1766 Color SIL - SILVER (ALUMINOUS)	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AL Make CADILLA Body Style UT - SPC	CrashTire Mark Detion CIAL FUNCTION TROL Dature JTOMOBILE AC DRT UTILITY	ON	Speed Lim 55 St WI Year 2020	AUTOMOE Operating As ers iit Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model XT5	Total Haz 0 Total Lan 2 Motor Veh ICABLE II Inopera	ees iicle Use
10 UNIT 01	Unit IN T Vehi (SP Tota 2 Insury YES DOI Traff TWO Surfa BLA Truc NO	Status TRANSIT TICLE Type ORT) UTILITY VEHICL TRANSIT TICLE Type ORT) UTILITY VEHICL TRANSIT OCCS TRANSIT TRANSI	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AL Make CADILLA Body Style	CrashTire Mark Detion CIAL FUNCTION TROL Dature JTOMOBILE AC DRT UTILITY	ON	Speed Lim 55 St WI Year 2020	AUTOMOE Operating As ers iit Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model XT5	Total Haz 0 Total Lan 2 Motor Veh ICABLE II Inopera	ees iicle Use
LIND 01	Unit IN T Vehi (SP Tota 2 Insu YES DOI Traff TWO Surfa NO	Status TRANSIT ICIDE Type ORT) UTILITY VEHICL II OCCS TRANCE? S THARMFUL EVENT: COLLISION N MESTICATED ANIMAL FIC Way O-WAY, NOT DIVIDED ACKTOP (BITUMINOUS ICK BUS OF HAZMAT Vehicle License Plate Number AKS8027 Vehicle Identification Num 1GYKNBR40LZ1766 Color SIL - SILVER (ALUMINOUS)	Train/Bus # Recorded Direction Of Travel NORTHBOUND With ALIVE S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AL Make CADILLA Body Style UT - SPC	CrashTire Mark Inction CIAL FUNCTION TROL STATE	ON	Speed Lim 55 St WI Year 2020	AUTOMOE Operating As ers iit Emergency NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model XT5	Total Haz 0 Total Lan 2 Motor Veh ICABLE II Inopera	zMat Types les licle Use itive/Missing

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/29/2022

		Towed Due To Damage		Veh	icle Removed By					
		NOT TOWED		ow	NER					
		What Driver Was Doing		Veh	icle Factors					
		GOING STRAIGHT								
		Driver Prior Action Other		NO.	T APPLICABLE					
		Driver Actions								
	щ	NO CONTRIBUTING ACT	TION							
╘	VEHICLE									
LNO	ᇁ									
	VE									
		Owner Name GRETCHEN SMITH			Owner Address W5116 MORROS N	III E RD				
7	01	OKE TOTIEN OMITTI			NECEDAH, WI 546					
		Sequence Of Events								
		Event								
	01	DOMESTICATED ANIMAL	L - ALIVE							
	02	Event								
	03	Event								
		Event								
	04	Event								
⊢	ı	Policy Holder								
LIND		Insurance Company			dividual					
_		PROGRESSIVE-CLASSIC	C-INS-CO	G	RETCHEN SMITH					
	ļ	Individual								
		Driver SUSAN GUTTORMSEN			Citations Issued Sex					
	1	(262) 627-9319		0						
_	INDIVIDUAL	,		ا ا	Date of Birth Race WHITE					
	ĭ	Address		D	Driver License Number					
⊃	$\overline{\Box}$	S1154 DUTCH HOLLOW			STATE: WISCONSIN COUNTRY: UNITED STATES					
	_	LA VALLE, WI 53941 , US	5	5	IAIE: WISCONSIN	COUNTRY: UNI	IED STATES			
	Sat	On Duty fety Equipment	y Crash	S	afety Equipment					
	1	Row	Seat Position	s	HOULDER & LAP I	BFI T				
		01 - FRONT ROW	07 - LEFT		OHOGEDER & EAF BEET					
		Helmet Use		Н	Helmet Compliance					
					·					
		Eye Protection		Т	int Compliance					
	_	Injury S	Severity	A	irbag					
2	90	lan in annua	PPARENT INJURY		ON DEPLOYED					
		Ejected	Ejection Path				Trapped/Extricated			
		NOT EJECTED	NOT EJECTED/NOT A				NOT TRAPPED			
		Medical Transport		E	MS Agency Identifier		EMS Run #			
		NOT TRANSPORTED			ata of Dooth		Time of Dooth			
		Hospital		ا	ate of Death		Time of Death			
		Distracted By NOT A	ted By Source	RACTI	ED)					
		Distracted By Action	•		-					
		NOT DISTRACTED								

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		<u>_</u>							
		Non Motorist	Striking U	nit#	Location				
		Prior Action							
LINIT	INDIVIDUAL	Action							
		Action Other							To/From School
	L	Drug & Alcohol	Suspected NO	d Alcohol U	lse	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test Results	5	
٦	001	Drug Type							
		Individual Condition APPEARED NORM	1AL						
		 Individual							
		Passenger				Citations Issued	Sex		
	_	GRETCHEN SMITH	Н			0	FEMALE		
_	DUA					Date of Birth	Race WHITE		
LIND	INDIVIDUAL	Address W5116 MORROS M NECEDAH, WI 546				Driver License Numbe STATE: WISCONSI		ITED STATES	
	Sat	fety Equipment	On Duty C	Crash		Safety Equipment			
		Row 01 - FRONT ROW		Seat Po		SHOULDER & LAP	BELT		
		Helmet Use				Helmet Compliance			
		Eye Protection				Tint Compliance			
2	005	Injury	NO APP	ARENT II		Airbag NON DEPLOYED			
		NOT EJECTED		jection Pa	th CTED/NOT APPI	LICABLE		Trapped/Extricated NOT TRAPPED	
		Medical Transport NOT TRANSPORT	ED			EMS Agency Identifier		EMS Run #	
		Hospital				Date of Death		Time of Death	
		Distracted By	Distracted	By Source	9	•		•	
		Distracted By Action							
		Non Motorist	Striking U	nit#	Location				

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/29/2022

I		Prior Action								
		1 Hor 7 totion								
l		Action Action								
	Ţ									
ᆫ	۸U									
L	Π									
∣⋽	\leq									
	INDIVIDUAL									
		Action Other						To/From School		
1					T					
	,	Drug & Alcoh	Suspected Alcohol U	Jse	Suspected Drug Use NO					
	-	_			1		T			
		Alcohol Test Given Alcohol Test Ty			•		Alcohol Test Results			
l		TEST NOT GIVEN		D T4 T		In + . n				
		Drug Test Given TEST NOT GIVE	EN	Drug Test Type		Drug Test Results	•			
2	002	Drug Type		•						
0	0									
ł		Individual Condition								
		APPEARED NO	RMAL							
I	D									
		perty Owner								
0	Indiv KAF	idual REN GEITZ			Address S1078 HWY 58					
					LA VALLE, WI 53941 , US					
PROP OWNER										
	Five	ed Objects St	ruck							
							Ctrustura Number	Damas Tan Number		
	2		Struck Object DOMESTICATED AN	IIMAL - ALIVE			Structure Number	Damage Tag Number		
	_	VI	DOMESTICATED AN	IIIVIAL - ALIVE						