#### 6TL09XQZ48 22-06845

## **WISCONSIN MOTOR VEHICLE CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895


Crash Date 07/16/2022

Crash Time 04:58 AM

Crash

.09XQZ48	DocumentNumberOvemde		Primary Crash Document#		Agency Crash Number 22-06845		DEPUTY I. GALVAN			
	Crash Date 07/16/2022		Crash Time 04:58 AM		Date Arrived 07/16/2022		Time Arrived 05:14 AM			
	Date Notified 07/16/2022		Time Notified 05:00 AM		Total Units 01		Total Injured 00	·		
	On Emergency Hit		t and Run Lane Closu		ure Work Zone		Trailer or Towed   " '		Reporting Threshold	
6TL	Government Property		Active School Zone		School Bus Related NO		Tags			
		Crash Type DT4000 (STANDARD CRASH		)		Amended			Secondary Crash	

Description



, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING WESTBOUND ON CTH APPROACHING BIRCHWOOD ROAD. UNIT 1 CLAIMS HE WAS TIRED AND MAY HAVE DOSED OFF CAUSING HIM TO LEAVE THE ROADWAY. UNIT 1 STRUCK A STOP SIGN AND STRUCK A DITCH. UNIT 1 REPORTED NO INJURIES AND WAS REMOVED BY STEVES AUTO.

## 6TL09XQZ48 22-06845

Location

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 07/16/2022

Crash Time 04:58 AM

	ON CTHP WB 8 FT W		Latitude 43.59034		10606	Longitude -89.818661185 Y Coordinate 4830235		818661185	
	OF BIRCHWOOD RD IN THE TOWN OF DELTON IN SAUK COUNTY	I		X Coordinate 272462.625					
				Structure NO STR					
1	Crash Scene								
	First Harmful Event			FirstHarm	ıful Event Lo	cation			
	TRAFFIC SIGN POST	ROADSII	DE						
	Manner of Collision			Light Cond	dition				
	00 - NO COLLISION W/VEH	IICLE IN TRANSPORT		DAWN					
	Road Surface Condition(s)			Roadway	Factor(s)				
	DRY								
	Environment Factor(s)			†					
	WEATHER CONDITIONS			NONE					
	Weather Condition(s)			1					
	FOG								
	Animal Type			Relation T	o Trafficway	1			
	,. 			TRAFFICWAY - ON ROAD					
	Crash Classification - Location			Crash Classification - Jurisdiction					
	PUBLIC PROPERTY					SDICTION			
	Tribal Land			Access Co		Special Stu		Special Study	
	NAPAL N. L. A	1 2 1 2	Li e	NO CONTROL					
	•	Junction Location INTERSECTION-RELATED		ection Type TERSECTION					
	Unit Summary	MILITER OF THE TENTED	7	102071011					
	Omi Simulaly								
			Vehicle Operating As (	Classification		Hnit Type			
	Unit Status		Vehicle Operating As 0	Classification		Unit Type TRUCK			
				Classification			s Endorse	ements	
5	Unit Status IN TRANSIT	RUCK		Classification		TRUCK	s Endorse	ements	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs	RUCK	D CLASS  Total # Citations Issue		Total Traile	TRUCK Operating A	Total Ha:	ements zMat Types	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1	Train/Bus#Recorded	D CLASS		Total Traile	TRUCK Operating A	Total Ha:	zMat Types	
5	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance?	Train/Bus#Recorded Direction Of Travel	Total#Citations Issue  O  Pre CrashTire	d	Total Traile 0 Speed Lim	TRUCK Operating A	Total Ha.  0  Total Lar	zMat Types	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES	Train/Bus#Recorded  Direction Of Travel  WESTBOUND	Total#Citations Issue 0  Pre CrashTire Mark	d	Total Traile	TRUCK Operating A ers	Total Har 0 Total Lar 2	zMat Types nes	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance?	Train/Bus#Recorded  Direction Of Travel  WESTBOUND	Total#Citations Issue  O  Pre CrashTire	d Đ	Total Traile 0 Speed Lim	TRUCK Operating A	Total Ha: 0 Total Lar 2 Motor Vel	zMat Types nes hicle Use	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W	Train/Bus#Recorded  Direction Of Travel  WESTBOUND	Total # Citations Issue 0  Pre CrashTire Mark  Special Function	d Đ	Total Traile 0 Speed Lim	TRUCK Operating A  ers  iit  Emergency NOT APPI	Total Ha: 0 Total Lar 2 Motor Vel	zMat Types nes hicle Use	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W DITCH	Train/Bus#Recorded  Direction Of Travel  WESTBOUND	Total#Citations Issue  O  Pre CrashTire Mark  Special Function NO SPECIAL FUNC	d Đ	Total Traile 0 Speed Lim	TRUCK Operating A  ers  iit  Emergency NOT APPI	Total Ha: 0 Total Lar 2 Motor Vel	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature	d Đ	Total Traile 0 Speed Lim	TRUCK Operating A  ors  Emergency NOT APPI Traffic Cont NO Road Grade	Total Ha: 0 Total Lar 2 Motor Vel LICABLE	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL	d Đ	Total Traile 0 Speed Lim	TRUCK Operating A  ers  Emergency NOT APPI Traffic Cont NO	Total Ha: 0 Total Lar 2 Motor Vel LICABLE	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature	d Đ	Total Traile 0 Speed Lim	TRUCK Operating A  ors  Emergency NOT APPI Traffic Cont NO Road Grade	Total Ha: 0 Total Lar 2 Motor Vel LICABLE	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature	d Đ	Total Traile 0 Speed Lim	TRUCK Operating A  ors  Emergency NOT APPI Traffic Cont NO Road Grade	Total Ha: 0 Total Lar 2 Motor Vel LICABLE	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKUP T Total Occs 1 Insurance? YES Most Harmful Event: Collision W DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total#Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE LEFT	ction	Total Traile 0 Speed Lim 45	TRUCK Operating A  ors  iit  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of Is	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP T  Total Occs 1 Insurance? YES  Most Harmful Event: Collision W DITCH  Traffic Way TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle  License Plate Number TL5019	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE LEFT  Plate Type LTK - LiGHT TRUE	ction	Total Traile 0 Speed Lim 45 St	TRUCK Operating A  Operating A  iit  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of is UNITED ST	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP T  Total Occs 1 Insurance? YES  Most Harmful Event: Collision W DITCH  Traffic Way TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle  License Plate Number TL5019  Vehicle Identification Num	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function  NO SPECIAL FUNC  Traffic Control  NO CONTROL  Road Curvature  CURVE LEFT  Plate Type  LTK - LiGHT TRUE  Make	ction	Total Traile 0 Speed Lim 45 St WI Year	TRUCK Operating A  Operating A  In the series of the serie	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP T  Total Occs 1 Insurance? YES  Most Harmful Event: Collision W DITCH  Traffic Way TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO  Vehicle License Plate Number TL5019  Vehicle Identification Num 3B7HF13Z2XG233076	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total# Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE LEFT  Plate Type LTK - LIGHT TRUE  Make DODGE	ction	Total Traile 0 Speed Lim 45 St	TRUCK Operating A  Property A  Description  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST  Model RAM 1500	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP T  Total Occs 1 Insurance? YES  Most Harmful Event: Collision W DITCH  Traffic Way TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle  License Plate Number TL5019  Vehicle Identification Num	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function  NO SPECIAL FUNC  Traffic Control  NO CONTROL  Road Curvature  CURVE LEFT  Plate Type  LTK - LiGHT TRUE  Make	ction	Total Traile 0 Speed Lim 45 St WI Year	TRUCK Operating A  Operating A  In the series of the serie	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMat Types nes hicle Use E	
	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP T  Total Occs 1 Insurance? YES  Most Harmful Event: Collision W DITCH  Traffic Way TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS  Truck Bus or HazMat NO  Vehicle License Plate Number TL5019  Vehicle Identification Num 3B7HF13Z2XG233076  Color BLK - BLACK	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature  CURVE LEFT  Plate Type  LTK - LIGHT TRUE  Make  DODGE  Body Style	ction	Total Traile 0 Speed Lim 45 St WI Year	TRUCK Operating A  Property A  Description  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST  Model RAM 1500	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMatTypes  nes  hicle Use E ative/Missing	
	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP T  Total Occs 1 Insurance? YES  Most Harmful Event: Collision W DITCH  Traffic Way TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS  Truck Bus or HazMat NO  Vehicle License Plate Number TL5019  Vehicle Identification Num 3B7HF13Z2XG233076  Color BLK - BLACK	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE LEFT  Plate Type LTK - LIGHT TRUE Make DODGE  Body Style PK - PICKUP	ction	Total Traile 0 Speed Lim 45 St WI Year	TRUCK Operating A  Property A  Description  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST  Model RAM 1500	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMatTypes  nes  hicle Use E ative/Missing	
	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP T  Total Occs 1 Insurance? YES  Most Harmful Event: Collision W DITCH  Traffic Way TWO-WAY, NOT DIVIDED  Surface Type BLACKTOP (BITUMINOUS  Truck Bus or HazMat NO  Vehicle License Plate Number TL5019  Vehicle Identification Num 3B7HF13Z2XG233076  Color BLK - BLACK Initial Contact Point	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  //ith	Total # Citations Issue 0  Pre CrashTire Mark  Special Function NO SPECIAL FUNC  Traffic Control NO CONTROL  Road Curvature CURVE LEFT  Plate Type LTK - LIGHT TRUE Make DODGE  Body Style PK - PICKUP	ction	Total Traile 0 Speed Lim 45 St WI Year	TRUCK Operating A  Property A  Description  Emergency NOT APPI Traffic Cont NO Road Grade LEVEL  Country of Is UNITED ST  Model RAM 1500	Total Ha: 0 Total Lar 2 Motor Vel LICABLE rol Inopera	zMatTypes  nes  hicle Use E ative/Missing	

## 6TL09XQZ48

22-06845

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 07/16/2022

Crash Time 04:58 AM

		Towed Due To Damage		Vehicle Removed By						
		TOWED DUE TO DISABLI	NG DAMAGE	STEVES AUTO SERVICE						
		What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors						
		Driver Prior Action Other		NOT APPLICABLE						
		Diver Flior Action Caner								
UNIT	VEHICLE	Driver Actions FAILED TO KEEP IN DESIGNATED LANE, LOOKED BUT DID NOT SEE								
		OwnerName		Owner Address						
2	5	DANIEL G DREWS (608) 495-7119		S1439 W REDSTO						
		Sequence Of Events								
	5	Event TRAFFIC SIGN POST								
	S	Event DITCH								
	8	Event								
	75	Event								
		l Policy Hölder								
IN N		Insurance Company		Individu <b>al</b>						
_		SENTRY-INS-CO		DANIEL DREWS						
		Individual								
		Driver DANIEL G DREWS		Citations Issued Sex  0 MALE						
	INDIVIDUAL	(608) 495-7119		Date of Birth	Race					
LNN	₽	A distance		WHITE						
Ś	ā	Address S1439 W REDSTONE DR		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES						
	=	LA VALLE, WI 53941 , US								
	Sai	ety Equipment On Duty	Crash	Safety Equipment						
		Row Seat Position		SHOULDER & LAP BELT						
		01 - FRONT ROW	07 - LEFT							
		HelmetUse		Helmet Compliance						
		Eye Protection		Tint Compliance						
5	5	Injury Se	verity	Airbag						
_	0	Injury NO APPARENT INJURY  Ejected Ejection Path		NON DEPLOYED  Trapped/Extricated						
		NOT EJECTED NOT EJECTED/NOT A		PLICABLE		NOT TRAPPED				
		Medical Transport		EMS Agency Identifier		EMS Run#				
	NOT TRANSPORTED									
		Hospital		Date of Death	Date of Death Time of Death					
		Distracted By NOT AF	d By Source PLICABLE (NOT DISTR.	ACTED)		•				
		Distracted By Action NOT DISTRACTED								

## 6TL09XQZ48 22-06845

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 07/16/2022

Crash Time 04:58 AM

								,	
		Non Motor	Striking Unit#	Location					
		Prior Action							
		Action							
_	UAL								
UNIT	INDIVIDUAL								
	INC								
		Action Other						To/From School	
		Action Other						10/F10m School	
	1	Orug & Alcol	Suspected Alcohol L NO		Suspected Drug Use NO				
		Alcohol Test Give	coholTestGiven AlcoholTestType EST NOT GIVEN		)		Alcohol Test Results	est Results	
	Drug Test Given Drug Test Type TEST NOT GIVEN			Drug Test Type		Drug Test Results			
10	001	Drug Type			•				
		Individual Condition	on						
		ASLEEP OR FA	ATIGUED						
	Pro	perty Owne	r						
01	Gove	ernment JK COUNTY HW	Y DEPT		Address 620 STH 136				
PROP OWNER	(608) 356-3855			PO BOX 26 BARABOO, WI 53913	, US				
	Fixe	ed Objects S		**************************************		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	********		
	9	Striking Unit 01	Struck Object TRAFFIC SIGN POST	Г				Damage Tag Number 37888	