

6TL0B655TX
22-07347

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0B655TX

| | | | | | | | |
|--|--------------------------------------|---|------------------------------------|----------------------------------|---|--|--------------------|
| Document Number Override | | Primary Crash Document# | | Agency Crash Number 22-07347 | | Investigating Officer/Deputy DEPUTY W. NEUBAUER | |
| Crash Date 07/29/2022 | | Crash Time 05:55 AM | | Date Arrived 07/29/2022 | | Time Arrived 06:08 AM | |
| Date Notified 07/29/2022 | | Time Notified 06:00 AM | | Total Units 02 | | Total Injured 00 | Total Killed 00 |
| <input type="checkbox"/> On Emergency | <input type="checkbox"/> Hit and Run | <input type="checkbox"/> Lane Closure | <input type="checkbox"/> Work Zone | | <input type="checkbox"/> Trailer or Towed | <input type="checkbox"/> Reporting Threshold | |
| <input type="checkbox"/> Government Property | | <input type="checkbox"/> Active School Zone | | School Bus Related NO | | Tags | |
| <input type="checkbox"/> Reportable | | Crash Type DT4000 (STANDARD CRASH) | | <input type="checkbox"/> Amended | | <input type="checkbox"/> Secondary Crash | |

Description

| | |
|----------------|--------------------------------|
| <p>Diagram</p> | Reconstruction By |
| | Photos By |
| | Additional Information NONE |

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 DRIVER WAS BACKING UP AND HAD MATERIAL IN THE BED OF THE TRUC EXTENDING PAST THE TAILGATE. UNIT 1 BACKED INTO THE FRONT GRILL OF UNIT 2

6TL0B655TX
22-07347

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

| | | |
|---|--------------------------------|----------------------------|
| ON NACHREINER AVE 312 FT N OF OAK ST IN THE VILLAGE OF PLAIN IN SAUK COUNTY | Latitude 43.277769355 | Longitude -90.048862796 |
| | X Coordinate 252607.390625 | Y Coordinate 4796176 |
| | Structure Type NO STRUCTURE | |

Crash Scene

| | | |
|---|---|---|
| First Harmful Event MOTOR VEH IN TRANSPORT | First Harmful Event Location ON ROADWAY | |
| Manner of Collision 03 - FRONT TO REAR | Light Condition DAWN | |
| Road Surface Condition(s) DRY | Roadway Factor(s) NONE | |
| Environment Factor(s) NONE | | |
| Weather Condition(s) CLEAR | | |
| Animal Type | Relation To Trafficway TRAFFICWAY - ON ROAD | |
| Crash Classification - Location PUBLIC PROPERTY | Crash Classification - Jurisdiction NO SPECIAL JURISDICTION | |
| Tribal Land | Access Control NO CONTROL | Special Study |
| Within Interchange Area NO | Junction Location NON-JUNCTION | Intersection Type NOT AN INTERSECTION |

Unit Summary

| | | | | | |
|----------------|---|---|--|--|--------------------------------|
| UNIT 01 | Unit Status IN TRANSIT | Vehicle Operating As Classification D CLASS | Unit Type TRUCK | | |
| | Vehicle Type UTILITY TRUCK/PICKUP TRUCK | Operating As Endorsements | | | |
| | Total Occs 1 | Train/Bus # Recorded | Total # Citations Issued 0 | Total Trailers 0 | Total HazMat Types 0 |
| | Insurance? YES | Direction Of Travel SOUTHBOUND | <input type="checkbox"/> Pre Crash Tire Mark | Speed Limit 25 | Total Lanes 1 |
| | Most Harmful Event: Collision With PARKED MOTOR VEHICLE | Special Function NO SPECIAL FUNCTION | | Emergency Motor Vehicle Use NOT APPLICABLE | |
| | Traffic Way ONE-WAY TRAFFIC | Traffic Control NO CONTROL | | Traffic Control Inoperative/Missing NO | |
| | Surface Type BLACKTOP (BITUMINOUS) | Road Curvature STRAIGHT | | Road Grade LEVEL | |
| | Truck Bus or HazMat NO | | | | |

Vehicle

| | | | | |
|------------------------|---|--|---------------------|---|
| UNIT 02 VEHICLE | License Plate Number NU3976 | Plate Type LTK - LIGHT TRUCK | St WI | Country of Issuance UNITED STATES |
| | Vehicle Identification Number 1C6RR7FT8HS779288 | Make RAM | Year 2017 | Model |
| | Color SIL - SILVER (ALUMINUM) | Body Style PK - PICKUP | | Bus Use |
| | Initial Contact Point 06 - REAR | Vehicle Damage | | |
| | Extent Of Damage NO DAMAGE | 00 - NO DAMAGE | | |



6TL0B655TX

22-07347

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

| | | | | |
|---|--|--|--|--|
| UNIT VEHICLE | Towed Due To Damage NOT TOWED | | Vehicle Removed By OPERATOR | |
| | What Driver Was Doing BACKING | | Vehicle Factors | |
| | Driver Prior Action Other | | NOT APPLICABLE | |
| | Driver Actions LOOKED BUT DID NOT SEE | | | |
| 02 | Owner Name IVAN J MCGHEE (863) 228-2835 | | Owner Address 1135 NACHREINER AVE PLAIN, WI 53577 , US | |
| | Sequence Of Events | | | |
| 01 02 03 04 | Event MOTOR VEH IN TRANSPORT | | | |
| | Event PARKED MOTOR VEHICLE | | | |
| | Event | | | |
| | Event | | | |
| UNIT | Policy Holder | | | |
| | Insurance Company GEICO-CASUALTY-CO | | Individual IVAN MCGHEE | |
| UNIT INDIVIDUAL | Individual | | | |
| | Driver IVAN J MCGHEE (863) 228-2835 | | Citations Issued 0 | Sex MALE |
| | Address 1135 NACHREINER AVE PLAIN, WI 53577 , US | | Date of Birth [REDACTED] | Race WHITE |
| | | | Driver License Number [REDACTED] | STATE: WISCONSIN COUNTRY: UNITED STATES |
| 01 001 | Safety Equipment | | On Duty Crash | |
| | Row 01 - FRONT ROW | | Seat Position | SHOULDER & LAP BELT |
| | Helmet Use | | Safety Equipment | |
| | Eye Protection | | Helmet Compliance | |
| | | | Tint Compliance | |
| Injury | | Injury Severity NO APPARENT INJURY | Airbag NON DEPLOYED | |
| Ejected NOT EJECTED | | Ejection Path NOT EJECTED/NOT APPLICABLE | | Trapped/Extricated NOT TRAPPED |
| Medical Transport NOT TRANSPORTED | | EMS Agency Identifier | | EMS Run # |
| Hospital | | Date of Death | | Time of Death |
| Distracted By | | Distracted By Source NOT APPLICABLE (NOT DISTRACTED) | | |
| Distracted By Action NOT DISTRACTED | | | | |

6TL0B655TX
22-07347

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

| | | | | | |
|---|---|--|-----------------------------|--------------------------|--|
| UNIT INDIVIDUAL 01 001 | Non Motorist | | Striking Unit # | Location | |
| | Prior Action | | | | |
| | Action | | | | |
| | Action Other | | | To/From School | |
| | Drug & Alcohol | | Suspected Alcohol Use NO | Suspected Drug Use NO | |
| | Alcohol Test Given TEST NOT GIVEN | | Alcohol Test Type | Alcohol Test Results | |
| | Drug Test Given TEST NOT GIVEN | | Drug Test Type | Drug Test Results | |
| | Drug Type | | | | |
| | Individual Condition APPEARED NORMAL | | | | |

Unit Summary

| | | | | | | |
|------------|--|-----------------------------------|--|---------------------------|---|--|
| UNIT 02 | Unit Status LEGALLY PARKED | | Vehicle Operating As Classification D CLASS | | Unit Type TRUCK | |
| | Vehicle Type UTILITY TRUCK/PICKUP TRUCK | | | Operating As Endorsements | | |
| | Total Occs 0 | Train/Bus # Recorded | Total # Citations Issued 0 | Total Trailers 0 | Total HazMat Types 0 | |
| | Insurance? YES | Direction Of Travel NORTHBOUND | <input type="checkbox"/> Pre Crash Tire Mark | Speed Limit 25 | Total Lanes 1 | |
| | Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT | | Special Function NO SPECIAL FUNCTION | | Emergency Motor Vehicle Use NOT APPLICABLE | |
| | Traffic Way ONE-WAY TRAFFIC | | Traffic Control NO CONTROL | | Traffic Control Inoperative/Missing NO | |
| | Surface Type BLACKTOP (BITUMINOUS) | | Road Curvature STRAIGHT | | Road Grade LEVEL | |
| | Truck Bus or HazMat NO | | | | | |

| | | | | | | | | | | | | | | | | | | | | | |
|----------------------------------|--|-----------------------------|---------------------------------|--------------|--------------------------------------|---|---|----|----|----|----|---|--|--|--|----|---|---|---|---|---|
| UNIT VEHICLE 01 | Vehicle | | | | | | | | | | | | | | | | | | | | |
| | License Plate Number TD2778 | | Plate Type LTK - LIGHT TRUCK | St WI | Country of Issuance UNITED STATES | | | | | | | | | | | | | | | | |
| | Vehicle Identification Number 1FTPW14V69FB13096 | | Make FORD | Year 2009 | Model F150 | | | | | | | | | | | | | | | | |
| | Color SIL - SILVER (ALUMINUM) | | Body Style PK - PICKUP | | Bus Use NOT A BUS | | | | | | | | | | | | | | | | |
| | Initial Contact Point 12 - FRONT | | Vehicle Damage 12 - FRONT | | | <table border="1"> <tr> <td>7</td><td>8</td><td>9</td><td>10</td><td>11</td> </tr> <tr> <td>6</td><td></td><td></td><td></td><td>12</td> </tr> <tr> <td>5</td><td>4</td><td>3</td><td>2</td><td>1</td> </tr> </table> | 7 | 8 | 9 | 10 | 11 | 6 | | | | 12 | 5 | 4 | 3 | 2 | 1 |
| | 7 | 8 | | | | | 9 | 10 | 11 | | | | | | | | | | | | |
| | 6 | | | | 12 | | | | | | | | | | | | | | | | |
| 5 | 4 | 3 | 2 | 1 | | | | | | | | | | | | | | | | | |
| Extent Of Damage MINOR DAMAGE | | | | | | | | | | | | | | | | | | | | | |
| Towed Due To Damage NOT TOWED | | Vehicle Removed By OWNER | | | | | | | | | | | | | | | | | | | |

6TL0B655TX
22-07347

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

| | | |
|---|---|--|
| UNIT VEHICLE 01 | What Driver Was Doing LEGALLY PARKED | Vehicle Factors |
| | Driver Prior Action Other | NOT APPLICABLE |
| | Driver Actions NO CONTRIBUTING ACTION | |
| | Owner Name JOSE E DOPICO GUTIERREZ (608) 643-9401 | Owner Address 1110 NACHREINER AVE PLAIN, WI 53577 , US |
| UNIT VEHICLE 01 02 03 04 | Sequence Of Events | |
| | Event MOTOR VEH IN TRANSPORT | |
| | Event | |
| | Event | |
| UNIT VEHICLE 04 | Policy Holder | |
| | Insurance Company PROGRESSIVE-CASUALTY-INS-CO | Individual JOSE DOPICO GUTIERREZ |