6TL0B4X4QQ 22-09931

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Overrid	le Primary Crash	Document#	Agency	Crash Number					
			22-099						
Crash Date 10/05/2022	Crash Time 03:22 PM	I .		rived 2022					Time Arrived 03:30 PM
Date Notified 10/05/2022				nits	Total Injured 01	Total Kille	ed		
On Emergency	Hit and Run	Lane Clo	sure	☐ Work Zone	Trailer	or Towed	Reporting Threshold		
Government Property	Active S	chool Zone	School NO	Bus Related	Tags				
Reportable	Crash Type DT4000 (ST	ANDARD CRAS	SH)		Amend	ed	Secondary Crash		
Description =	,						1		
Diagram		i				Reconstructio	n By		
(®				Photos By POINTON			
02		NOT TO SCALE	_			Additional Info PHOTOS	ormation		
	2 (01	, s =							
\$	STH 33								
,,		***************************************							
, a sworn law enfo	orcement officer, agi	ee that I have	not added	l any CJIS data in ti	his report.				
UNIT 2 WB ON STH 33 AND	WAS SLOWING TO PU	L OVER. UNIT 1	WAS WB AN	ID WAS ON THE PHONE	AND DIDNT SEE				
THE REAR OF UNIT 2. UNIVEHICLE SUSTAINED DISA MEDICAL. UNIT 2 SUSTAIN INSURANCE	ABLING DAMAGE AND W	AS REMOVED BY	CRAIGS TO	WING. OPERATOR OF	UNIT 2 COMPLAIN	ED OF BACK F			

6TL0B4X4QQ 22-09931

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/05/2022

	ON STH33 WB 848 FT E	5		Latitude 43.524350916		Longitude -89.834304134	
	OF MIRROR LAKE R IN THE TOWN OF DE IN SAUK COUNTY			X Coordinate 270949.75		Y Coordinate 4822949	
				Structure Type NO STRUCTUR	E		
	Crash Scene						
•	First Harmful Event			First Harmful Ever	t Location		
	MOTOR VEH IN TRA	NSPORT		ON ROADWAY			
	Manner of Collision			Light Condition			
	03 - FRONT TO REAL	R		DAYLIGHT			
	Road Surface Condition((s)		Roadway Factor(s)		
	DRY						
	Environment Factor(s)			4			
	NONE			NONE			
	NONE			NONE			
	Weather Condition(s)						
	CLOUDY						
	Animal Type			Relation To Traffic	34/21/		
	,			TRAFFICWAY -	-		
	Crash Classification - Lo	cation		Crash Classification	n - Jurisdiction		
	PUBLIC PROPERTY			NO SPECIAL JU	JRISDICTION		
	Tribal Land			Access Control		Special Study	
				NO CONTROL			
	Within Interchange Area	Junction Location	Intersect	ion Type		<u>.</u>	
	NO	NON-JUNCTION	NOT AN	INTERSECTION			
	Unit Summary						
			Classification Unit Type				
	Unit Status		Vehicle Operating As 0	Classification	UnitType		
			Vehicle Operating As 0	Classification	Unit Type AUTOMO	BILE	
	Unit Status IN TRANSIT Vehicle Type			Classification	AUTOMO	PBILE As Endorsements	
2	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR		D CLASS		AUTOMO Operating	As Endorsements	
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs	Train/Bus#Recorded	D CLASS Total# Citations Issue	d Total T	AUTOMO Operating	As Endorsements Total HazMat Types	
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1		Total#Citations Issue	d Total T	AUTOMO Operating /	As Endorsements Total HazMat Types 0	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs Insurance?	Direction Of Travel	Total#Citations Issue 2 Pre CrashTin	d TotalT 0 e Speed	AUTOMO Operating /	As Endorsements Total HazMat Types 0 Total Lanes	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs I Insurance? NO	Direction Of Travel WESTBOUND	Total#Citations Issue 2 Pre CrashTire Mark	d Total T	AUTOMO Operating /	As Endorsements Total HazMat Types 0 Total Lanes 2	
	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs Insurance? NO Most Harmful Event: Coll	Direction Of Travel WESTBOUND lision With	Total#Citations Issue 2 Pre CrashTin	d TotalT 0 e Speed 55	AUTOMO Operating /	As Endorsements Total HazMat Types Total Lanes 2 y Motor Vehicle Use	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs I Insurance? NO	Direction Of Travel WESTBOUND lision With	Total#Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC	d TotalT 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP	As Endorsements Total HazMat Types Total Lanes 2 Motor Vehicle Use PLICABLE	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA	Direction Of Travel WESTBOUND lision With NSPORT	Total # Citations Issue 2 Pre CrashTin Mark Special Function	d TotalT 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP	As Endorsements Total HazMat Types Total Lanes 2 y Motor Vehicle Use	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way	Direction Of Travel WESTBOUND lision With NSPORT	D CLASS Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC	d TotalT 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP	Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use LICABLE strol Inoperative/Missing	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUME)	Direction Of Travel WESTBOUND lision With NSPORT	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL	d TotalT 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con	Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use LICABLE strol Inoperative/Missing	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat	Direction Of Travel WESTBOUND lision With NSPORT	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature	d Total T 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad	Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use LICABLE strol Inoperative/Missing	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUME)	Direction Of Travel WESTBOUND lision With NSPORT	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature	d Total T 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad	Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use LICABLE strol Inoperative/Missing	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat	Direction Of Travel WESTBOUND lision With NSPORT	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature	d Total T 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad	Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use LICABLE strol Inoperative/Missing	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat NO Vehicle License Plate Num	Direction Of Travel WESTBOUND lision With NSPORT DED NOUS)	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT	d TotalT 0 e Speed 55	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI Truck Bus or HazMat NO Vehicle License Plate Num AMT8047	Direction Of Travel WESTBOUND lision With NSPORT DED NOUS)	Total # Citations Issue 2 Pre Crash Tire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI	d TotalT 0 e Speed 55 CTION	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of is UNITED S	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing	
UNIT 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI: Truck Bus or HazMat NO Vehicle License Plate Num AMT8047 Vehicle Identificatif	Direction Of Travel WESTBOUND lision With NSPORT DED NOUS)	Total # Citations Issue 2 Pre Crash Tire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make	d TotalT 0 e Speed 55 CTION St WI Year	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of is UNITED S Model	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing	
10	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat NO Vehicle License Plate Num AMT8047 Vehicle Identificatic 2T1BURHE2JC0	Direction Of Travel WESTBOUND lision With NSPORT DED NOUS)	Total # Citations Issue 2 Pre CrashTim Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make TOYOTA	d TotalT 0 e Speed 55 CTION	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of is UNITED S Model COROLLA	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing	
UNIT 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat NO Vehicle License Plate Num AMT8047 Vehicle Identification 2T1BURHE2JC0 Color	Direction Of Travel WESTBOUND lision With NSPORT DED NOUS)	Total # Citations Issue 2 Pre CrashTim Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB! Make TOYOTA Body Style	d TotalT 0 e Speed 55 CTION St WI Year	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of is UNITED S Model	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing	
UNIT 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat NO Vehicle License Plate Num AMT8047 Vehicle Identificatic 2T1BURHE2JCC Color WHI - WHITE	Direction Of Travel WESTBOUND lision With NSPORT RDED NOUS) ber on Number 044106	Total # Citations Issue 2 Pre CrashTim Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB! Make TOYOTA Body Style SD - SEDAN	d TotalT 0 e Speed 55 CTION St WI Year	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of is UNITED S Model COROLLA	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing	
01 UNIT 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat NO Vehicle License Plate Num AMT8047 Vehicle Identificatic 2T1BURHE2JCC Color WHI - WHITE	Direction Of Travel WESTBOUND lision With NSPORT RDED NOUS) ber on Number 044106	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make TOYOTA Body Style SD - SEDAN Vehicle Damage	d TotalT 0 e Speed 55 CTION St WI Year 2018	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model COROLLA Bus Use	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing le TATES	
01 UNIT 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat NO Vehicle License Plate Num AMT8047 Vehicle Identificatic 2T1BURHE2JCC Color WHI - WHITE	Direction Of Travel WESTBOUND lision With NSPORT RDED NOUS) ber on Number 044106	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make TOYOTA Body Style SD - SEDAN Vehicle Damage 01 - RIGHT FRON	d Total T 0 e Speed 55 CTION St WI Year 2018	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model COROLLA Bus Use	Total HazMat Types 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing e 7 8 9 10 11 6 12	
UNIT 01	Unit Status IN TRANSIT Vehicle Type PASSENGER CAR Total Occs 1 Insurance? NO Most Harmful Event: Coll MOTOR VEH IN TRA Traffic Way TWO-WAY, NOT DIVI Surface Type BLACKTOP (BITUMI) Truck Bus or HazMat NO Vehicle License Plate Num AMT8047 Vehicle Identification 2T1BURHE2JCC Color WHI - WHITE Initial Contact Poin 12 - FRONT	Direction Of Travel WESTBOUND lision With NSPORT DED NOUS) ber on Number 044106	Total # Citations Issue 2 Pre CrashTire Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make TOYOTA Body Style SD - SEDAN Vehicle Damage	d Total T 0 e Speed 55 CTION St WI Year 2018	AUTOMO Operating / railers Limit Emergency NOT APP Traffic Con NO Road Grad LEVEL Country of Is UNITED S Model COROLLA Bus Use	Total HazMatTypes 0 Total Lanes 2 y Motor Vehicle Use PLICABLE strol Inoperative/Missing le TATES	

6TL0B4X4QQ

22-09931

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/05/2022

		Towed Due To Damage TOWED DUE TO DISABI	ING DAMA		ehicle Removed By RAIGS TOWING						
		What Driver Was Doing GOING STRAIGHT		V	ehicle Factors						
		Driver Prior Action Other		N	NOT APPLICABLE						
LIND	VEHICLE	Driver Actions OPERATED MOTOR VEI	HICLE IN IN	ATTENTIVE, CAR	RELESS OR ERRATIO	MANNER					
2	Б	OwnerName TAYSHALIZ ORTIZ FLOR (608) 415-2197	RES		Owner Address 1100 19TH ST #8 REEDSBURG, WI	53959 , US					
		Sequence Of Events									
	10	Event MOTOR VEH IN TRANSF									
	8	Event DITCH									
	8	Event									
	8	Event									
		ndividual									
	_	Driver TAYSHALIZ ORTIZ FLOR (608) 415-2197	RES		Citations issued Sex 2 FEMALE						
⊨	INDIMIDNA	(000) 413-2181			Date of Birth Race HISPANIC						
S	ă	Address 1100 19TH ST #8			Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES						
	4	REEDSBURG, WI 53959	, US								
	Sai	ety Equipment On Du	ty Crash		Safety Equipment						
		Row 01 - FRONT ROW	SeatPo 07 - LE		SHOULDER & LAP BELT						
		Helmet Use	•		Helmet Compliance						
		Eye Protection			Tint Compliance						
2	8	Injury S Injury NO Al	Severity PPARENT II	NJURY	Airbag DEPLOYED-COMBINATION						
		Ejected NOT EJECTED	Ejection Pa	ith CTED/NOT APPLI	ICABLE		Trapped/Extricated NOT TRAPPED				
		Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run#				
		Hospital			Date of Death		Time of Death				
		Distracted By HANG	ted By Source -HELD MOI	BILE PHONE							
		Distracted By Action MANUALLY OPERATING	E(TEXTING,	DIALING,PLAYIN	G GAME ETC)						
		Non Motorist	g Unit#	Location							

6TL0B4X4QQ

22-09931

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/05/2022

		Prior Action												
!		Action												
	4													
E	NDIVIDUAL													
UNIT														
	Z													
		Action Other											To/From School	
			Susi	pected Alco	hol U	se		Suspected Drug Use						
	<u>I</u>	Drug & Alcohol	NO					NO						
		Alcohol Test Given TEST NOT GIVEN				Alcohol Test T	ype				Alcohol Tes	t Results		
		Drug Test Given TEST NOT GIVEN				Drug Test Type	9		Drug	Test Results	l			
_	_	Drug Type												
9	001	2.09 1 7 20												
		Individual Condition												
		APPEARED NORM	IAL											
		Violations												
		UTC Number	Issu	⊭e To?	Stat	ute Number	argargarg	Description				<u> </u>		
	0.1	BB955416	001			.89(1)		INATTENTIVE DRIVI	NG					
	02	UTC Number BB955417	lsst 001	ŧe To? I		ute Number .62(1)		Description OPERATE MOTOR V	/EHIC	CLE W/O IN	SURANCE			
'	Unit	t Summary •												
	Unit	Status						ehicle Operating As Class	ificatio	n	UnitType			
		cle Type					D CLASS				AUTOMOBILE Operating As Endorsements			
02		SENGER VAN												
	Tota 1	lOccs		Train/Bus	#Red	corded	To	otal#Citations Issued		Total Traile	ers	Total Hazi	Mat Types	
		rance?		Direction ()f Tra	vel	ļ ,	_ Pre CrashTire		Speed Lim	it	TotalLane	98	
Ħ		YES WESTBOUND			G	Mark 55		55	Emergency	2 Motor\/ehi	cla I lea			
ź		tHarmfulEvent: Collision						NO SPECIAL FUNCTION			NOT APPLICABLE			
		ic Way D-WAY, NOT DIVIDI	=n				1	affic Control O CONTROL			Traffic Cont	rol inoperat	ive/Missing	
		ace Type					-	oad Curvature			Road Grade			
		CKTOP (BITUMING	OUS)				STRAIGHT LEVEL							
	NO	k Bus or HazMat												
	1	Vehicle					000 000							
		License Plate Number SZ 5735	r				Plate Type St LTK - LIGHT TRUCK WI		St WI	Country of Is				
02	7	Vehicle Identification		per			N	1ake		Year	Model			
0	02	2C4GP44R15R126 Color	455				_	CHRYSLER lody Style		2005	TOWN & C	OU		
		GLD - GOLD						/N - VAN						
		Initial Contact Point 06 - REAR												
		00 - KEAK												

6TL0B4X4QQ

22-09931

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/05/2022

	Ш			Vehicle Damage						
TIN O	VEHICLE	Extent Of Damage FUNCTIONAL DAMAGE		05 - RIGHT REAR C REAR CORNER	ORNER, 06 - REAF	R, 07 - LEFT	5 4 3 2 1			
		Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR						
		What Driver Was Doing SLOW/STOPPING Driver Prior Action Other		Vehicle Factors						
TINO	VEHICLE	Driver Actions NO CONTRIBUTING ACT	ON							
03	02	Owner Name GOTTA GUY & GIRL LLC (608) 393-0355		Owner Address 868 CTH A GRAND MARSH	, WI 53936 , US					
		Sequence Of Events				en e				
	5	Event MOTOR VEH IN TRANSPO								
	03	Event								
	8	Event								
	8	Event								
INN		Policy Holder Insurance Company ROOT-PROPERTY-&-CAS Individual Driver GREGORY GENE ALLEN (715) 403-0599	UALTY-INS-CO	Organization/Compa GOTTA GUY & Gi Citations issued	Sex MALE					
╘	IDINIDUA			Date of Birth	WHITE					
Ī	Î	Address 618 MINOR AVE WEST LADYSMITH, WI 54848 , US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES						
		On Duty	Crash	Safety Equipment						
	Ja.	Fety Equipment Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT						
		HelmetUse	•	Heimet Compliance						
		Eye Protection		Tint Compliance						
05	802	Injury Se	verity BLE INJURY	Airbag NON DEPLOYED						
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPL	LICABLE		Trapped/Extricated NOT TRAPPED				
		Medical Transport	avadymento i Atti	EMS Agency Identific	er e	EMS Run#				
		NOT TRANSPORTED Hospital		Date of Death		Time of Death				
		1 to share		Date of Death		THRE OF DEATH				

6TL0B4X4QQ 22-09931

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/05/2022

		Distracted By	Distracted By Source NOT APPLICABL	E (NOT DISTRAC	CTED)			
		Distracted By Action NOT DISTRACTED						
		Non Motorist	Striking Unit#	Location				
		Prior Action						
	L .	Action						
TINO	INDIWIDUAL							
٠	INDI							
		Action Other						To/From School
								10/210/1130/100/
	I	Drug & Alcohol	Suspected Alcohol U NO	se	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
05	002	Drug Type						
		Individual Condition						
		APPEARED NORM	AL					