6TL0D1PTMK

22-09956

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document # Crash Time 01:56 PM Time Notified 01:56 PM		22-09956 DEPUTY Date Arrived Time Arrive 10/06/2022 02:00 PM		g Officer/Deputy S. MESSNER			
6TL0D1PTMK	Crash Date 10/06/2022					Time Arrived			
	Date Notified 10/06/2022					Total Injured Total Killed		ed	
00,	On Emergency	t and Run		sure Work Zone		Trailer or Towe		ed Reporting Threshold	
JTC	Government Property	hool Zone	School Bus Related Tags						
9	✓ Reportable	led	Secondary Crash						
	Description						Reconstructio	-	
					Not to scale	Ø	Photos By DEP. S. ME Additional Info PHOTOS	SSNER #9134	
	Unit 1 in motion Unit 1 Unit 1 Unit 1 Unit 1 Unit 1 Unit 1	runs off road	STH 33	nit 1 roll		nes to rest upri			
	▶ I, a sworn law enforceme ON 10/06/2022, AT APPROXIMATEL OWNER, PAULA M. GEORGE. UNIT ROADWAY RIGHT, PAST THE DRIV OVER AND CAME TO REST ON UF SCENE, OBSERVING THE DRIVER EMS TO ST. CLARE HOSPITAL. TH	LY 1:56 PM, UNIT 1, PER WITNESS /EWAY MARKED I PRIGHT. A COMBI WAS NOT WEAR	1, a 2005 white J Ses, was going 1 E12499. Unit 1 CC Nation of Airba Ing her seat be	EEP LIBEI UNDER OI ONTINUED GS WERE	RTY BEARING WI PLAT THE SPEED OF THE IN THE DITCH LINE, S DEPLOYED. THE DRIV RIVER WAS REMOVED	e # Arg2113, WA Posted Speed L Triking Alliant /er Was Injured) From the Vehic	IMIT, 55 MPH. U ENERGY UTILIT AND BARABO CLE AND TRAN	JNIT 1 DRIFTED OFF THE IY POLE. UNIT 1 ROLLED O EMS ARRIVED ON SPORTED BY BARABOO	

22-09956

WISCONSIN MOTOR VEHICLE CRASH REPORT

L	.oc	ation									
		STH33 EB		Latitude			Longi	tude			
		I FT W	43.47446	60416		-89.6	99476744				
	OF ROCKY POINT RD IN THE TOWN OF GREENFIELD						X Coordinate		Y Coo	ordinate	
		AUK COUNTY	281666.21875		4817	045					
						Structure Type NO STRUCTURE					
C	ra	sh Scene									
-	-	Harmful Event				First Harm	nful Event Lo	ocation			
				DER RIGH							
		ner of Collision	Light Con	-	-						
	00 -	NO COLLISION W/VE	DAYLIG								
I	Road	Surface Condition(s)				Roadway	Factor(s)				
1	DR۱	,									
I	Envi	onment Factor(s)				-					
1	NOM	IE				NONE					
١	Wea	ther Condition(s)				1					
	CLC	DUDY									
	Anim	al Type				Relation T	o Trafficway	/			
						TRAFFIC	WAY - O	NROAD			
		h Classification - Location				Crash Cla	ssification -	Jurisdiction			
						NO SPECIAL JURISDICTION					
	Tribal Land					Access Control Special Study NO CONTROL					
		in Interchange Area	Junction Location		Intersectio						
	NO		NON-JUNCTION		NOT AN	INTERSE	CTION				
		t Summary 🛛 💻									
		Status				Classification Unit Type					
	IN TRANSIT D CLASS					AUTOMOBILE					
	Vehicle Type							Operating A	s Endor	sements	
'	•	ORT) UTILITY VEHICL	E Train/Bus # Recorded	Tatal # Oita	4 I		Total Trail	oro	Total L		
	1 ota 1	Occs	Train/Bus # Recorded	ed Total # Citations Issued		d Total Trail		ailers Total HazMat Types 0		laziviat Types	
		ance?	Direction Of Travel		Pre CrashTire						
			EASTBOUND	Pre Crash lire Mark		55		2			
	Most Harmful Event: Collision With			Special Fur	Special Function Em				Emergency Motor Vehicle Use		
					NO SPECIAL FUNCTION NOT A				APPLICABLE		
					Traffic Control				Traffic Control Inoperative/Missing		
		D-WAY, NOT DIVIDED		NO CONT				NO			
	Surface Type			Road Curva				Road Grade			
)	STRAIGH	1			LEVEL			
	NO	k Bus or HazMat									
		Vehicle									
	License Plate Number ARG2113 Vehicle Identification Number 1J4GL48K45W583965 Color WHI - WHITE			51	Plate Type St			Country of Issuance			
					AUT - AUTOMOBILE Make JEEP Body Style UT - SPORT UTILITY VEHIC		WI	UNITED STATES Model			
							Year				
							2005		LIBERTY		
									Bus Use		
	ш	Initial Contact Point	Vehicle Damage								
	12 - FRONT Extent Of Damage DISABLING DAMAGE				. oniolo Banago					7 8 9 10 11	
				15 - ALL	15 - ALL AREAS				6		
1					-					5 4 3 2 1	

22-09956

WISCONSIN MOTOR VEHICLE CRASH REPORT

					Vehicle Removed By CRAIGS TOWING					
		What Driver Was Doing			Vehicle Factors					
	GOING STRAIGHT									
				INKNOWN						
	ш	Driver Actions RAN OFF ROADWAY								
E	CLE									
UNIT	VEHICL									
	<									
		Owner Name PAULA GEORGE			Owner Address N8614 FENSKE RD					
2	01				PARDEEVILLE,					
		Sequence Of Events								
	01	Event RUN OFF ROADWAY RIG	нт							
	02	Event UTILITY POLE								
	03 (Event								
	0	OVERTURN/ROLLOVER								
	04	Event								
		ndividual								
		Driver			Citations Issued	Sex	Sex			
	INDIVIDUAL	Address N8614 FENSKE RD PARDEEVILLE, WI 53954 , US			1	FEMALE				
					Date of Birth	Race WHITE				
UNIT	/ID				Driver License Number					
5										
	Z				STATE: WISCONSIN COUNTRY: UNITED STATES					
	Saf				Safety Equipment					
	1	Row Seat Position		sition	NONE USED - VEHICLE OCCUPANT					
		01 - FRONT ROW	07 - LE							
		Helmet Use	elmet Use		Helmet Compliance					
		Eye Protection			Tint Compliance					
		,								
6	001	Injury Se	-		Airbag					
0	õ		Injury SUSPECTED SERIOUS INJUR DEPLOYED-COMBINATION							
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APP				Trapped/Extricated NOT TRAPPED			
		Medical Transport			EMS Agency Identifier		EMS Run #			
		EMS GROUND			6000368					
		Hospital			Date of Death		Time of Death			
ST CLARE HOSP Distracted By Source										
		Distracted By UNKNO)WN							
		Distracted By Action UNKNOWN								
		Non Motorist	Jnit#	Location						

6TL0D1PTMK

22-09956

Т

WISCONSIN MOTOR VEHICLE **CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Prior Action									
INDIVIDUAL	Action									
	Action Other						To/From School			
L	Drug & Alcohol NO			NO						
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	e		Alcohol Test Results				
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results					
001	Drug Type	Drug Type								
	Individual Condition									
		APPEARED NORMAL								
Ì										
01	BG024431			VEHICLE OPERATO	OR FAIL/WEAR S	EAT BELT				
	IANT ENERGY				1077, US					
Fixe	d Objects Stru	ck								
0	J -						Damage Tag Number NA			
Witı	ness									
KAT	RINA EDERER			715 5TH STREET	, US	D	ate of Birth			
THE	RESA HILL			S6241 DEVIL'S DELIG		ט	ate of Birth			
DEF	RICK MAYOLETH					D	ate of Birth			
	50 Fixee 50 Pro Organization Fixee 50 Witti Indivition Fixee Witti Indivition Fixee Witti Indivition Fixee Witti Indivition Fixee Witti Indivition Fixee Witti Indivition Fixee Witti Indivition Fixee Witti Indivition Fixee Witti Indivition Fixee Witti Fixee Fix	Action Action Action Other Action Other Drug & Alcohol Alcohol Test Given TEST NOT GIVEN Drug Test Given TEST NOT GIVEN Drug Type Individual Condition APPEARED NORI UTC Number BG024431 Property Owner Organization/Company ALLIANT ENERGY Striking Unit Striking Unit Striking Unit Striking Unit	Action Action Action Action Action Other Act	Action Action Other Drug & Alcohol Suspected Alcohol Use NO Alcohol Test Given TEST NOT GIVEN Drug Type Individual Condition APPEARED NORMAL Violations UTC Number B024431 Individual Condition APPEARED NORMAL Violations UTC Number B024431 Individual Company AtLIANT ENERGY Fixed Objects Struck S Striking Unit Struck Object UTLITY POLE Witness Individual KATRINA EDERER (608) 434-2149 Witness Individual Mitness Individual Witness Individual Witness Individual DesnelCk MAYOLETH	Action Action Other Drug & Alcohol Suspected Alcohol Use NO NO Action Other Drug & Alcohol No Action Test Given Alcohol Test Type TEST NOT GIVEN Drug Test Given Drug Test Given Drug Test Type Test NOT GIVEN Drug Test Type Drug Type Individual Condition APPEARED NORMAL Violations Violations Issue To? Statute Number Description Verification/Company Address Malison, wit 53707 Fixed Objects Struck Test Type Struck Object Individual Struck Object Mitness Tis Striker Struck Witness Address Individual Struck Object THERESA HILL (606) 434-2871 Address Mitness Merril Devil's DeLic Witness Merril Devil's OF FAIRFIELD RO Status Articles Status Articles Mitness Address Individual Status Articles Derekick MayoLETH State FAIRF	Action Action Other Action Other Suspected Alcohol Use Suspected Drug Use Prug & Alcohol No No Acton Test Given Drug Test Type Drug Test Results TEST NOT GIVEN Drug Test Type Drug Test Results Test NOT GIVEN Drug Test Type Drug Test Results Test NOT GIVEN Drug Test Type Drug Test Results Torug Test Store Drug Test Results Drug Test Results Torug Test Results Drug Test Results Drug Test Results Test NOT GIVEN Drug Test Results Drug Test Results Test NOT Given Drug Test Results Drug Test Results Test NOT Given Statute Number Description Test Results Statute Number Description Violations Vences YetHCLE OPERATOR FAIL/WEAR S Property Owner Address Statute Number Actions Statute Number Address Statute Number Statute Number Maddress Mathing Unit Struck Object UTILITY PoLe Witness Individual Address Statute Number Middedal Address Statute Number Theres Annual Statute Number Address Witnes	Action Action Action Other Suspected Alcohol Use NO NO Action Other Alcohol Test Type Drug Test Grown Drug Test Results Drug Test Grown Drug Test Results Drug Type Individual Condition APPEARED NORMAL Violations Violations UTC Number Bigg24431 Issue To? Statute Number Description Orgenization/Compare Orgenization/Compare Orgenization/Compare Orgenization Norgenization Address Transform Stricture Number Structure Number Dirug Tist Ko Object Structure Number Monitoria Structure Number Mail Son, Wi 53707 1077, US			