### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/10/2022

Crash Time 08:20 AM

	Document Number Override	Primary Crash Document #	Agency Crash Number 22-10080		Investigating Officer/Deputy			
4 Z	Crash Date 10/10/2022	Crash Time 08:20 AM	Date Arrived 10/10/2022	DEPUTY I. GALVAN  Time Arrived  09:24 AM				
Ď	Date Notified 10/10/2022	Time Notified 09:00 AM	Total Units <b>02</b>	Total Injured <b>00</b>	Total Killed <b>00</b>			
X60.	On Emergency	Hit and Run Lane Cl	osure Work Zone	Trailer or 1	Towed Reporting Threshold			
eTL	Government Property	Active School Zone	School Bus Related NO	Tags				
	<b>▼</b> Reportable	Crash Type DT4000 (STANDARD CRA	SH)	Amended	Secondary Crash			
	Description <b>——</b>							
	Diagram			Red	construction By			

✓ I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 2 WAS TRAVELING SOUTHBOUND ON STH 78 NEAR RUTHE BADGER LN. UNIT 1 WAS TRAVELING NORTHBOUND. UNIT 2 STATES UNIT 1 OPERATED LEFT OF CENTER AND SIDE SWIPED UNIT 2. BOTH STRUCK EACH OTHERS MIRROR. NO INJURIES REPORTED. BOTH PARTIES EXCHANGED INFORMATION AND CONTINUED ON THEIR WAY TO THEIR PLACE OF EMPLOYMENT.

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/10/2022

L	Location										
ſ	ON	STH78 SB				Latitude			Longitu	de	
	1066 FT S						43.360747102		-89.697979167		
		RUTHE BADGER LN HE TOWN OF MERRI	MAC						Y Coord	Y Coordinate	
		AUK COUNTY	WAO						48044	12	
							Type UCTURE				
L			NOSIK	OCTORE							
(	-	sh Scene									
		Harmful Event					nful Event Lo	ocation			
ļ		TOR VEH IN TRANSP	ORT			ON ROA					
		ner of Collision	TE DIDECTION			Light Cond					
ŀ		SIDESWIPE/OPPOSI	TE DIRECTION			DAYLIG					
	DRY	d Surface Condition(s)				Roadway	racior(s)				
-	Envir	ronment Factor(s)									
	GLA	RE				NONE					
ŀ	Wea	ther Condition(s)									
	CLE	AR									
-	Anim	al Type					o Trafficwa				
ļ	Cros	h Classification - Location					CWAY - OI				
		BLIC PROPERTY	I			Crash Classification - Jurisdiction NO SPECIAL JURISDICTION					
ŀ	Tribal Land					Access Control Special Study			Special Study		
-	\\/ith	in Interchange Area	Junction Location		Intersectio	NO CONTROL					
	NO	in interchange Area	NON-JUNCTION			INTERSECTION					
l	Jnii	Summary =									
		Status		Vehicle Op	erating As Cl	lassification	1	Unit Type			
	IN T	RANSIT		D CLASS		TRUCK					
_	Vehicle Type					Operating As Endorsements					
5	UTII	LITY TRUCK/PICKUP									
		Occs	Train/Bus # Recorded		ations Issued		Total Trail	ers		zMat Types	
ļ	1		Direction Of Travel	1	_	Speed Lim		imit Total L		100	
_	NO	ance?	NORTHBOUND	Pre	CrashTire Mark					anes	
	Most	Harmful Event: Collision	With		Special Function			Emergency			
L	MOTOR VEH IN TRANSPORT				NO SPECIAL FUNCTION			NOT APPL			
	Traffic Way TWO-WAY, NOT DIVIDED				Traffic Control NO CONTROL			Traffic Control Inoperative/Missing  NO			
		ace Type		Road Curvature			Road Grade				
		CKTOP (BITUMINOU	S)	CURVE L				LEVEL			
ſ	Trucl	k Bus or HazMat		ı							
$\dashv$		Vehicle									
		License Plate Number		Plate Type	e		St	Country of Iss	suance		
	SJ8396		LTK - LIC	LTK - LIGHT TRUCK		WI	UNITED STATES				
;	_	Vehicle Identification Nu	Make			Year	Model RAM 1500				
1	01	1B7HF13Z01J54992	3	DODGE		2001					
		Color BLK - BLACK		, ,	Body Style		•		Bus Use		
				4D - 4DR							
									П		
	CLE	Initial Contact Point  10 - LEFT SIDE FRO	NT	Vehicle Da						7 8 9 10 11	
	VEHICLE	Initial Contact Point	NT	Vehicle Da		ONT				7 8 9 10 11 6 2 12 5 4 3 2 1	

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/10/2022

		Towed Due To Damage		Vehicle Removed By				
		NOT TOWED		OWNER				
		What Driver Was Doing		Vehicle Factors				
		NEGOTIATING CURVE		NOT ARRIVE ARI				
		Driver Prior Action Other		NOT APPLICABLE				
		Driver Actions	NATEDIANE					
_	VEHICLE	FAILED TO KEEP IN DESIG	INATED LANE					
	우							
_	Œ							
		Owner Name		Owner Address	ND 440			
2	01	JOSEPH SWEENEY (608) 370-1961		S7351 STATE ROA MERRIMAC, WI 53				
٥		(000) 000		,	,			
		Sequence Of Events						
	01	Event MOTOR VEH IN TRANSPOR	RT					
	02	Event						
		Event						
	03	LVOIIC						
	04	Event						
		ndividual						
		Driver	Citations Issued	Sex				
	_	JOSEPH SWEENEY		1	MALE	MALE		
	INDIVIDUAL			Date of Birth	Race			
╘	Ī				WHITE			
		Address S7351 STATE ROAD 113	Driver License Number					
	Z	MERRIMAC, WI 53561 , US		STATE: WISCONSIN COUNTRY: UNITED STATES				
	Sat	On Duty C <b>fety Equipment</b>	rash	Safety Equipment				
	J	Row	Seat Position	SHOULDER & LAP	RFI T			
		01 - FRONT ROW	07 - LEFT	OHOOLDER & LAI	DEE!			
		Helmet Use	Helmet Compliance					
		Eye Protection	Tint Compliance					
5	90	Injury Seven	•	Airbag				
	0	2 2 11 <b>0</b> 7 u 1 7	ARENT INJURY jection Path	NON DEPLOYED		Trapped/Extricated		
			IOT EJECTED/NOT APP	LICABLE		NOT TRAPPED		
		Medical Transport		EMS Agency Identifier		EMS Run #		
	NOT TRANSPORTED							
		Hospital		Date of Death		Time of Death		
		Distracted By NOT APP	By Source PLICABLE (NOT DISTRA	ACTED)		1		
		Distracted By Action  NOT DISTRACTED	,	•				
			nit # Location					
	Non Motorist Striking Unit # Location							

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/10/2022

Action Other  Action Other  Action Other  Action Other  Drug & Alcohol No  Action Test Results  Drug & Alcohol No  Action Test Results  Test Not Given  Test Not Given  Drug Test Results  Drug Test Result													
Tour School   Suspected Alcohol Use   Suspected Purp Use   No   No   No   No   No   No   No   N			Prior Action										
Tour School   Suspected Alcohol Use   Suspected Purp Use   No   No   No   No   No   No   No   N			Action										
Action Other    Drug & Alcohol   No   No   No   No   No   No   No			Action										
Action Other    Drug & Alcohol   No   No   No   No   No   No   No		7											
Action Other    Drug & Alcohol   No   No   No   No   No   No   No	_	Ď											
Action Other    Drug & Alcohol   No   No   No   No   No   No   No	Ž												
Action Other    Drug & Alcohol   No   No   No   No   No   No   No	ר												
Alcohol Test Given   Alcohol Test Given   Alcohol Test Type   Alcohol Test Results		Z											
Alcohol Test Given   Alcohol Test Given   Alcohol Test Type   Alcohol Test Results													
Alcohol Test Gleven			Action Other										To/From School
Alcohol Test Gleven													
Alcohol Test Given TEST NOT GIVEN Drug Test Given TEST NOT GIVEN Drug Test Given TEST NOT GIVEN Drug Type  Drug Test Type  Drug Test Results  Drug		,	Drug & Alachal	Suspected A	Icohol L	Jse							
TEST NOT GIVEN  Drug Test Type  Drug Test Type  Drug Test Results  Dru				NO				10					
Total Transitor   Direction Of Travel   Direction Of Direction						Alcohol Test Ty	ype				Alcohol Test	t Results	
TEŜT NOT GIVEN    TUTO   Type   Tuto   Type   Tuto   Type   Tuto   Type   Type						Drug Test Type	2		Drug T	oet Posulte			
Individual Condition   APPEARED NORMAL   Violations   UTC Number   AE757847   001   344.62(1)   Description   OPERATE MOTOR VEHICLE W/O INSURANCE						Diag rest type	•		Drug 1	est ixesuits			
Individual Condition   APPEARED NORMAL   Violations   UTC Number   AE757847   001   344.62(1)   Description   OPERATE MOTOR VEHICLE W/O INSURANCE	1	_	Drug Type						l				
APPEARED NORMAL  Violations  UTC Number   Issue To?   Statute Number   344.62(1)   Description   OPERATE MOTOR VEHICLE W/O INSURANCE  Unit Summary  Unit Summary  Unit Status   Vehicle Operating As Classification   Unit Type   TRUCK   TRUCK   Operating As Classification   Unit Type   TRUCK   Operating As Endorsements   Unit Type   Unit Unit Unit Unit Unit Unit Unit Unit	Ó	00											
APPEARED NORMAL  Violations  UTC Number   Issue To?   Statute Number   344.62(1)   Description   OPERATE MOTOR VEHICLE W/O INSURANCE  Unit Summary  Unit Summary  Unit Status   Vehicle Operating As Classification   Unit Type   TRUCK   TRUCK   Operating As Classification   Unit Type   TRUCK   Operating As Endorsements   Unit Type   Unit Unit Unit Unit Unit Unit Unit Unit			Individual Condition										
Violations   UTC Number   AE757847   001   344.62(1)   Description   OPERATE MOTOR VEHICLE W/O INSURANCE			individual Condition										
Total Cumber and Statute Number on the Plate Type and Country Traffic Control Inoperative/Missing Two-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Total Cost Traffic Control Inoperative/Missing Two-WAY, NOT DIVIDED Curvature Curvature Type BLACKTOP (BITUMINOUS)  Total Cost Traffic Control Inoperative/Missing No Control Surface Type BLACKTOP (BITUMINOUS)  The Plate Type High Fight Number DeB89  Vehicle Operating As Classification Unit Type TRUCK  Vehicle Operating As Classification Unit Type TRUCK  Total Occs Train/Bus # Recorded O O O Total # Citations Issued O Total Trailers Total HazMat Types O O O O O O O O O O O O O O O O O O O			APPEARED NORM	IAL									
Total Cumber and Statute Number on the Plate Type and Country Traffic Control Inoperative/Missing Two-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Total Cost Traffic Control Inoperative/Missing Two-WAY, NOT DIVIDED Curvature Curvature Type BLACKTOP (BITUMINOUS)  Total Cost Traffic Control Inoperative/Missing No Control Surface Type BLACKTOP (BITUMINOUS)  The Plate Type High Fight Number DeB89  Vehicle Operating As Classification Unit Type TRUCK  Vehicle Operating As Classification Unit Type TRUCK  Total Occs Train/Bus # Recorded O O O Total # Citations Issued O Total Trailers Total HazMat Types O O O O O O O O O O O O O O O O O O O		ļ	Violations										
Unit Summary  Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP TRUCK  Total Occs Insurance? YES SOUTHBOUND  Most Harmful Event: Collision With MOTO Veh In IN TRANSPORT  Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle Type License Plate Number DEB89 Vehicle Identification Number 3GTUSDEDOLG101694 Color WHI - WHITE  Vehicle Damage Unit Type Insurance? Vehicle Type Description Unit Type TRUCK  Vehicle Operating As Classification TRUCK  Operating As Endorsements  Truck Bus or Inal HazMat Types Operating As Endorsements  Total PazMat Types Operating As Endorsements  Total HazMat Types Operating As Endorsements  Total PazMat Types Operating As Endor				Issue To?									
Unit Status   Vehicle Operating As Classification   Unit Type   TRUCK		9	AE757847	001	344	4.62(1)	C	PERATE MOTOR V	/EHICL	E W/O IN	SURANCE		
IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKUP TRUCK  Total Occs  Insurance? YES  Direction Of Travel YES  SOUTHBOUND  Motor Veh In TRANSPORT  Traffic Control NO SPECIAL FUNCTION  NO SPECIAL FUNCTION  NO CONTROL  Surface Type BLACKTOP (BITUMINOUS)  Truck Bus or HazMat NO  Vehicle  License Plate Number DEB89  Vehicle Identification Number JOHN JOHN JOHN JOHN JOHN JOHN JOHN JOHN		llnit	Cummany										
Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs 1 Total Occs 1 Insurance? YES SOUTHBOUND Mark Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT Traffic Way TWO-WAY, NOT DIVIDED NO CONTROL NO Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle Identification Number Again NO  Vehicle Identification Number Again Make  Vehicle Identification Number Again Again Again Make  Vehicle Identification Number Again Again Again Make  GENERAL MOTORS COR Vehicle Damage  Vehicle Damage  Vehicle Damage  Vehicle Damage  Total Trailers Total HazMat Types Total LareMat Types Total HazMat Types Total Lanes Total HazMat Types Total Lanes Total Lanes Total Lanes Total HazMat Types Total Lanes Total HazMat Types Total HazMat Types Total Lanes Total Lanes Total Control NoTotal Lanes Total Control NoTotal Lanes Total Control NoTotal Lanes Total Control NoT		Ullil	t Sullillial y 💻										
Total Occs									fication				
Total Occs 1		Unit :	Status RANSIT						ification		TRUCK		,
1		Unit :	Status <b>RANSIT</b> cle Type	ID TRIICK					ification		TRUCK	s Endorse	ements
YES   SOUTHBOUND   Mark   55   2		Unit S IN T Vehice UTIL	Status RANSIT cle Type LITY TRUCK/PICKU		Bus # Re	ecorded	D C	LASS	fication	Total Traile	TRUCK Operating A		
Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT  Traffic Way  Traffic Control  NO SPECIAL FUNCTION  Traffic Control  NO CONTROL  Surface Type  BLACKTOP (BITUMINOUS)  Truck Bus or HazMat  NO  Vehicle  License Plate Number  DEB89  Vehicle Identification Number  3GTU9DED0LG101694  Color  WHI - WHITE  AD - 4DR  Wehicle Damage  To LEFT SIDE FRONT  Extent Of Damage  Emergency Motor Vehicle Use  NOT APPLICABLE  Traffic Control  NO ROAD GATCH  NO ROAD GRANGE  NO ROAD GRANGE  NO APPLICABLE  Straffic Control Inoperative/Missing  NO CONTROL  NO  Surface Type  Road Grade  LEVEL  St Country of Issuance  UNITED STATES  Windel  STATUS Model  STATUS Model  STATUS Model  STATUS MODE  SIERRA  To LEFT SIDE FRONT  Or 18 9 10 11  To LEFT SIDE FRONT		Unit S IN T Vehic UTIL Total	Status RANSIT cle Type LITY TRUCK/PICKU		Bus # Re	ecorded	D C	LASS			TRUCK Operating A	Total Ha	
Traffic Way Traffic Control NO Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number DEB89 Vehicle Identification Number 3GTU9DED0LG101694 Color WHI - WHITE Initial Contact Point Initial Contact Point Left Side FRONT  More Initial Contact Point Initial Contact Point Extent Of Damage  Traffic Control Inoperative/Missing NO  Traffic Control NO  Traffic Control Inoperative/Missing NO  Road Curvature Curve Right Left Left Side FRONT  Traffic Control Inoperative/Missing NO  Souther State Control Inoperative/Missing NO  Vehicle Damage  Traffic Control Inoperative/Missing NO  Souther State Control Inoperative/Missing NO  Vehicle University Inoperative/Missing NO  Vehicle Damage  Traffic Control Inoperative/Missing NO  Vehicle Outher State Inoperative/Missing NO  Vehicle University Inoperative/Missing NO  Vehicle Damage  Traffic Control Inoperative/Missing NO  Vehicle Outher State Inoperative/Missing N		Unit S IN T Vehic UTIL Total 1	Status RANSIT cle Type LITY TRUCK/PICKU	Train/E			D C	LASS # Citations Issued		0	TRUCK Operating A	Total Ha	zMat Types
Traffic Way TWO-WAY, NOT DIVIDED NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number DEB89 Vehicle Identification Number 3GTU9DED0LG101694 Color WHI - WHITE Initial Contact Point 10 - LEFT SIDE FRONT  Traffic Control NO	02	Unit S IN T Vehic UTIL Total 1 Insur YES	Status  RANSIT  cle Type  LITY TRUCK/PICKU  I Occs  rance?	Train/E	on Of Tr	avel	Total 0	# Citations Issued  Pre CrashTire Mark		0 Speed Limit	TRUCK Operating A	Total Ha  0  Total Lar  2	zMat Types nes
TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number DEB89 Vehicle Identification Number 3GTU9DED0LG101694 Color WHI - WHITE Initial Contact Point 10 - LEFT SIDE FRONT Extent Of Damage  NO CONTROL NO  Road Curvature Road Grade LEVEL  Road Grade LEVEL  St Country of Issuance UNITED STATES  WI UNITED STATES  Windel Bus Use  7 8 9 10 11  10 - LEFT SIDE FRONT  Extent Of Damage  10 - LEFT SIDE FRONT	02	Unit s IN T Vehice UTIL Total I Insur YES	Status  RANSIT  cle Type  LITY TRUCK/PICKU  I Occs  rance?  It Harmful Event: Collision	Direction SOUT	on Of Tr	avel	Total 0	# Citations Issued  Pre CrashTire Mark  Sial Function		0 Speed Limit	TRUCK Operating A	Total Ha  0  Total Lar  2  Motor Vel	zMat Types nes
Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO  Vehicle License Plate Number DEB89 Vehicle Identification Number 3GTU9DED0LG101694 Color WHI - WHITE DITION TO Damage  NO  Road Curvature CURVE RIGHT  Road Grade LEVEL  Road Grade LEVEL  St Country of Issuance WI UNITED STATES  Make GENERAL MOTORS COR 2020 SIERRA  Sierra  Model Sierra  Body Style 4D - 4DR  Vehicle Damage  10 - LEFT SIDE FRONT  Extent Of Damage  10 - LEFT SIDE FRONT	02	Unit s IN T Vehice UTIL Total Insur YES Most	Status  RANSIT cle Type  LITY TRUCK/PICKU  I Occs  rance?  St Harmful Event: Collision	Direction SOUT	on Of Tr	avel	Total 0 Spec	# Citations Issued  Pre CrashTire Mark cial Function SPECIAL FUNCTIO		0 Speed Limit	TRUCK Operating A  ors  it  Emergency NOT APPI	Total Ha  0 Total Lai  2 Motor Vel	zMat Types nes nicle Use
Truck Bus or HazMat NO  Vehicle  License Plate Number DEB89 Vehicle Identification Number 3GTU9DED0LG101694 Color WHI - WHITE Initial Contact Point Initial Contact Point Extent Of Damage  Vehicle  Plate Type HEM - HIGHER EDUCATI WI UNITED STATES  Make Year Model 2020 SIERRA  Bus Use  Vehicle Damage  10 - LEFT SIDE FRONT  Fixent Of Damage  10 - LEFT SIDE FRONT	02	Unit : IN T Vehic UTIL Total 1 Insur YES Most MOT	Status  RANSIT  cle Type  LITY TRUCK/PICKU  I Occs  rance?  B  I Harmful Event: Collision  TOR VEH IN TRANS  ic Way	Direction SOUT	on Of Tr	avel	Total 0 Spec NO Traff	# Citations Issued  Pre CrashTire Mark cial Function SPECIAL FUNCTIO		0 Speed Limit	TRUCK Operating A  Trs  Emergency NOT APPL Traffic Control	Total Ha  0 Total Lai  2 Motor Vel	zMat Types nes nicle Use
NO  Vehicle  License Plate Number DEB89  Vehicle Identification Number 3GTU9DED0LG101694  Color WHI - WHITE  AD - 4DR  Initial Contact Point 10 - LEFT SIDE FRONT  Extent Of Damage  Vehicle  Vehicle Identification Number Body Style WHI - WHITE  AD - LEFT SIDE FRONT  Fixent Of Damage  Vehicle Damage  Plate Type Plate Type New Year WI UNITED STATES  Windel UNITED STATES  Model SIERRA  Bus Use  Vehicle Damage  10 - LEFT SIDE FRONT	02	Unit : IN T Vehic UTIL Total 1 Insur YES Most MO1 Traffi	Status FRANSIT Cle Type LITY TRUCK/PICKU I Occs  rance? B Harmful Event: Collision TOR VEH IN TRANS TIC Way D-WAY, NOT DIVIDE	Direction SOUT	on Of Tr	avel	Total 0 Spec NO Traff	# Citations Issued  Pre CrashTire Mark cial Function SPECIAL FUNCTIO ic Control CONTROL		0 Speed Limit	TRUCK Operating A  ors  Emergency NOT APPL Traffic Contr	Total Ha  0  Total Lan  2  Motor Vel LICABLE	zMat Types nes nicle Use
Vehicle License Plate Number DEB89 Vehicle Identification Number 3GTU9DED0LG101694 Color WHI - WHITE AD - 4DR  Initial Contact Point 10 - LEFT SIDE FRONT  Extent Of Damage  Plate Type HEM - HIGHER EDUCATI WI UNITED STATES UNITED STATES  Whodel GENERAL MOTORS COR 2020 SIERRA  Bus Use  7 8 9 10 11 6 7 8 9 10 11	02	Unit : IN T Vehic UTIL Total 1 Insur YES Most MO1 Traffi TWC Surfa	Status  RANSIT  cle Type  LITY TRUCK/PICKU  Cocs  rance?  Harmful Event: Collision  TOR VEH IN TRANS  ic Way  D-WAY, NOT DIVIDE  ace Type  ACKTOP (BITUMING	Direction With SPORT	on Of Tr	avel	Total 0 Spec NO Traff	# Citations Issued  Pre CrashTire Mark cial Function SPECIAL FUNCTIO ic Control CONTROL d Curvature		0 Speed Limit	TRUCK Operating A  Errs  Emergency NOT APPL Traffic Contr NO Road Grade	Total Ha  0  Total Lan  2  Motor Vel LICABLE	zMat Types nes nicle Use
License Plate Number DEB89  Vehicle Identification Number 3GTU9DED0LG101694  Color WHI - WHITE  Initial Contact Point Inc. LEFT SIDE FRONT  Extent Of Damage  Plate Type HEM - HIGHER EDUCATI WI UNITED STATES  Windel UNITED STATES  Model SIERRA  Bus Use  Vehicle Damage  10 - LEFT SIDE FRONT	02	Unit: IN T Vehicle UTIL Total 1 Insur YES Most MO Trafff TWC Surfa BLA Truck	Status  RANSIT  cle Type  LITY TRUCK/PICKU  Cocs  rance?  Harmful Event: Collision  TOR VEH IN TRANS  ic Way  D-WAY, NOT DIVIDE  ace Type  ACKTOP (BITUMING	Direction With SPORT	on Of Tr	avel	Total 0 Spec NO Traff	# Citations Issued  Pre CrashTire Mark cial Function SPECIAL FUNCTIO ic Control CONTROL d Curvature		0 Speed Limit	TRUCK Operating A  Errs  Emergency NOT APPL Traffic Contr NO Road Grade	Total Ha  0  Total Lan  2  Motor Vel LICABLE	zMat Types nes nicle Use
DEB89 Vehicle Identification Number 3GTU9DED0LG101694 Color WHI - WHITE Initial Contact Point 10 - LEFT SIDE FRONT  Extent Of Damage  HEM - HIGHER EDUCATI WI UNITED STATES  Make Year Model SIERRA  Bus Use  Vehicle Damage  10 - LEFT SIDE FRONT	02	Unit: IN T Vehic UTII Total 1 Insur YES Most MOT Traffi TWC Surfa BLA Trucl	Status  RANSIT  cle Type  LITY TRUCK/PICKU  I Occs  rance?  St Harmful Event: Collision  TOR VEH IN TRANS  ic Way  D-WAY, NOT DIVIDE  ace Type  ACKTOP (BITUMING)  k Bus or HazMat	Direction With SPORT	on Of Tr	avel	Total 0 Spec NO Traff NO	# Citations Issued  Pre CrashTire Mark cial Function SPECIAL FUNCTIO ic Control CONTROL d Curvature		0 Speed Limit	TRUCK Operating A  Errs  Emergency NOT APPL Traffic Contr NO Road Grade	Total Ha  0  Total Lan  2  Motor Vel LICABLE	zMat Types nes nicle Use
Vehicle Identification Number 3GTU9DED0LG101694 GENERAL MOTORS COR Color WHI - WHITE 4D - 4DR Initial Contact Point 10 - LEFT SIDE FRONT Extent Of Damage  Make GENERAL MOTORS COR 2020 SIERRA Bus Use  Vehicle Damage  10 - LEFT SIDE FRONT  10 - LEFT SIDE FRONT	02	Unit: IN T Vehic UTII Total 1 Insur YES Most MOT Traffi TWC Surfa BLA Trucl	Status  RANSIT  Cle Type  LITY TRUCK/PICKU  I Occs  rance?  St Harmful Event: Collision  TOR VEH IN TRANS  TOR WAY, NOT DIVIDE  TOR TYPE  ACKTOP (BITUMING)  K Bus or HazMat	Directic SOUT SOUTH	on Of Tr	avel	Total 0 Spec NO Traff NO CUF	Pre CrashTire Mark Sial Function SPECIAL FUNCTIO Ic Control CONTROL Id Curvature RVE RIGHT	DN	Speed Limi	TRUCK Operating A  ors  Emergency NOT APPI Traffic Contr NO Road Grade LEVEL	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Color Body Style Bus Use  WHI - WHITE 4D - 4DR  Initial Contact Point Vehicle Damage  10 - LEFT SIDE FRONT  Extent Of Damage 10 - LEFT SIDE FRONT	02	Unit: IN T Vehic UTII Total 1 Insur YES Most MOT Traffi TWC Surfa BLA Trucl	Status  RANSIT  cle Type  LITY TRUCK/PICKU  I Occs  rance?  St Harmful Event: Collision  TOR VEH IN TRANS  ic Way  D-WAY, NOT DIVIDE  ace Type  ACKTOP (BITUMINC  k Bus or HazMat  Vehicle  License Plate Number	Directic SOUT SOUTH	on Of Tr	avel	Total 0 Spec NO Trafff NO CUF	Pre CrashTire Mark Sial Function SPECIAL FUNCTIO Ic Control CONTROL Id Curvature RVE RIGHT	PN	Speed Limi	TRUCK Operating A  ors  it  Emergency NOT APPI Traffic Contr NO Road Grade LEVEL  Country of Is:	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
WHI - WHITE 4D - 4DR  Initial Contact Point Vehicle Damage  10 - LEFT SIDE FRONT  Extent Of Damage  10 - LEFT SIDE FRONT	UNIT 02	Unit: IN T Vehic UTIL Total 1 Insur YES Most MOT Trafff TWC SurfaBLA NO	Status  RANSIT cle Type  LITY TRUCK/PICKU  I Occs  rance?  B Harmful Event: Collision  TOR VEH IN TRANS  TOWAY, NOT DIVIDE  TOR TOP (BITUMING  K Bus or HazMat  Vehicle  License Plate Number  DEB89	Directic SOUT On With SPORT	on Of Tr	avel	Total 0 Spec NO Traff NO Roac CUR	Pre CrashTire Mark Sial Function SPECIAL FUNCTIO IC CONTROL IT CURVATURE RVE RIGHT  The Type M - HIGHER EDUCA	DN ATI	Speed Limi	TRUCK Operating A  Tris  Emergency NOT APPL Traffic Contri NO Road Grade LEVEL  Country of Is:	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Initial Contact Point 10 - LEFT SIDE FRONT Extent Of Damage  Vehicle Damage  7 8 9 10 11 6 7 8 9 10 11 6 7 8 9 10 11	UNIT 02	Unit: IN T Vehic UTIL Total 1 Insur YES Most MOT Trafff TWC SurfaBLA NO	Status  RANSIT cle Type  LITY TRUCK/PICKU  I Occs  rance?  B Harmful Event: Collision  TOR VEH IN TRANS  TOWAY, NOT DIVIDE  TOR TOP (BITUMING)  K Bus or HazMat  Vehicle  License Plate Number  DEB89  Vehicle Identification	Directic SOUT SOUT SPORT	on Of Tr	avel	Total 0 Spec NO Traff NO Roac CUF	Pre CrashTire Mark Cial Function SPECIAL FUNCTIO CONTROL CONTROL CUrvature RVE RIGHT	DN ATI	St WI	TRUCK Operating A  ors  it  Emergency NOT APPL Traffic Contr NO Road Grade LEVEL  Country of Is: UNITED ST Model	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
10 - LEFT SIDE FRONT Extent Of Damage  10 - LEFT SIDE FRONT  10 - LEFT SIDE FRONT	UNIT 02	Unit: IN T Vehic UTIL Total 1 Insur YES Most MOT Trafff TWC SurfaBLA NO	Status  RANSIT  cle Type  LITY TRUCK/PICKU  I Occs  rance?  I Harmful Event: Collision  TOR VEH IN TRANS  ic Way  D-WAY, NOT DIVIDE  ace Type  ACKTOP (BITUMINO  k Bus or HazMat  Vehicle  License Plate Number  DEB89  Vehicle Identification N  3GTU9DEDOLG10	Directic SOUT SOUT SPORT	on Of Tr	avel	Total 0 Speck NO Trafff NO CUF	# Citations Issued  Pre CrashTire Mark  Sial Function SPECIAL FUNCTIO  IC CONTROL  IC CONTROL  IC CURVATURE  RVE RIGHT  TO THE TOPE  M - HIGHER EDUCA  SEE  NERAL MOTORS C  Type  NERAL MOTORS C	DN ATI	Steed Limits  St WI Year 2020	TRUCK Operating A  Trs  Emergency NOT APPL Traffic Contr NO Road Grade LEVEL  Country of Is: UNITED ST Model SIERRA	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
Extent Of Damage FUNCTIONAL DAMAGE  10 - LEFT SIDE FRONT  5 4 3 2 1	UNIT 02	Unit: IN T Vehic UTIL Total 1 Insur YES Most MOT Traffi TWC Surfa BLA NO	Status  RANSIT  Cle Type  LITY TRUCK/PICKU  I Occs  rance?  B  I Harmful Event: Collision  TOR VEH IN TRANS  TOR VEH IN	Directic SOUT SOUT SPORT	on Of Tr	avel	Total 0 Spec NO Traff NO CUF	# Citations Issued  Pre CrashTire Mark  cial Function  SPECIAL FUNCTIO  ic Control  CONTROL  d Curvature  RVE RIGHT  e Type  M - HIGHER EDUCA  (e)  NERAL MOTORS C  ly Style  - 4DR	DN ATI	Steed Limits  St WI Year 2020	TRUCK Operating A  Trs  Emergency NOT APPL Traffic Contr NO Road Grade LEVEL  Country of Is: UNITED ST Model SIERRA	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types nes nicle Use
FUNCTIONAL DAMAGE	02 UNIT 02	Unit: IN T Vehic UTII Total 1 Insur YES Most MO Traffi TWC Surfa BLA Trucl NO	Status  RANSIT  Cle Type  LITY TRUCK/PICKU  I Occs  rance?  B  I Harmful Event: Collision  TOR VEH IN TRANS  TOR VEH IN	Directing SOUT SOUTH SOU	on Of Tr	avel	Total 0 Spec NO Traff NO CUF	# Citations Issued  Pre CrashTire Mark  cial Function  SPECIAL FUNCTIO  ic Control  CONTROL  d Curvature  RVE RIGHT  e Type  M - HIGHER EDUCA  (e)  NERAL MOTORS C  ly Style  - 4DR	DN ATI	Steed Limits  St WI Year 2020	TRUCK Operating A  Trs  Emergency NOT APPL Traffic Contr NO Road Grade LEVEL  Country of Is: UNITED ST Model SIERRA	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types  nes  nicle Use E attive/Missing
	02 UNIT 02	Unit: IN T Vehic UTII Total 1 Insur YES Most MO Traffi TWC Surfa BLA Trucl NO	Status  RANSIT  Cle Type  LITY TRUCK/PICKU  I Occs  rance?  B  I Harmful Event: Collision  TOR VEH IN TRANS  TOR VEH IN	Directing SOUT SOUTH SOU	on Of Tr	avel	Total 0 Spece NO Traff NO Roace CUF Plat HE Bod 4D Veh	# Citations Issued  Pre CrashTire Mark  Cial Function SPECIAL FUNCTIO  Ic Control CONTROL Id Curvature RVE RIGHT  The Type M - HIGHER EDUCA  THE TYPE  NERAL MOTORS C  Ty Style - 4DR  Ty Style  Language	ATI COR	Steed Limits  St WI Year 2020	TRUCK Operating A  Trs  Emergency NOT APPL Traffic Contr NO Road Grade LEVEL  Country of Is: UNITED ST Model SIERRA	Total Ha  0 Total Lai  2 Motor Vel LICABLE rol Inopera	zMat Types  nes  nicle Use Eative/Missing  7 8 9 10 11 6 2 12

### 6TL09XQZ4N

22-10080

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/10/2022

		Towed Due To Damage  NOT TOWED		Vehicle Removed By  OWNER					
		What Driver Was Doing		Vehicle Factors					
		NEGOTIATING CURVE							
		Driver Prior Action Other		NOT APPLICABLE					
		Driver Actions							
_	LE	NO CONTRIBUTING ACTIO	ON						
LIND	VEHICLE								
_	ΛĒ								
		Owner Name DEBORAH TALLAFUSS		Owner Address E13196 STATE RO	)AD 33				
02	02	(715) 340-8005		BARABOO, WI 53					
		Sequence Of Events  Event							
	01	MOTOR VEH IN TRANSPO	RT						
	02	Event							
	03	Event							
		Event							
	04								
UNIT	ļ	Policy Holder Insurance Company		Trest i					
5		LICHTE INSURANCE		Individual  DEBORAH TALLAF	DEBORAH TALLAFUSS				
	i	Individual							
		Driver DEBORAH TALLAFUSS		Citations Issued					
	AL	(715) 340-8005		<b>0</b> Date of Birth	FEMALE Race				
⊨	INDIVIDUAL			Date of Birth	WHITE				
UNI	<u> </u>	Address E13196 STATE ROAD 33		Driver License Number					
	Ξ	BARABOO, WI 53913 , US		STATE: WISCONSIN COUNTRY: UNITED STATES					
	Sat	On Duty C	Crash	Safety Equipment					
	ا	Row	Seat Position	SHOULDER & LAP	BELT				
		01 - FRONT ROW	07 - LEFT						
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
		Linium Co.	(orib)	Airbox					
05	002	Injury Sev	PARENT INJURY	Airbag NON DEPLOYED					
		Ejected	Ejection Path	L		Trapped/Extricated			
			NOT EJECTED/NOT APP			NOT TRAPPED			
		Medical Transport  NOT TRANSPORTED		EMS Agency Identifier		EMS Run #			
		Hospital		Date of Death		Time of Death			
		Distractor	d By Source						
		Distracted By NOT AP	PLICABLE (NOT DISTRA	ACTED)					
		Distracted By Action NOT DISTRACTED							

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 10/10/2022

		Non Motorist	Striking Unit#	Location				
		Prior Action						
TIND	INDIVIDUAL	Action						
		Action Other						To/From School
	I	Drug & Alcohol	Suspected Alcohol U NO	Jse	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
05	002	Drug Type						
		Individual Condition  APPEARED NORM	IAL					