WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document #	Agency 22-117	Crash Number 75	DEPUTY I.	Officer/Deputy GALVAN	
≩ົ	Crash Date 11/23/2022	Crash Time 08:30 PM	Date Arrived 11/24/2022		Time Arrived 11:04 AM		
Ž	Date Notified 11/24/2022	Time Notified 11:03 AM	Total Un	Total Units 02		Total Kille	ed
6 0-		and Run Lane Clos		Work Zone		or Towed	Reporting Threshold
9 <u>1</u>	Government Property	Active School Zone	NO	Bus Related	Tags		
	▼ Reportable	Crash Type DT4000 (STANDARD CRASH	H)		Amend	led	Secondary Crash
	Diagram					Reconstructio	-
			630 ST TO SO	W PINE ST		Photos By DEPUTY IS. Additional Info PHOTOS	AAC GALVAN
-	I, a sworn law enforceme UNIT 2 WAS LEGALLY PARKED IN EAST IN THE PARKING LOT. UNIT	nt officer, agree that I have n A PARKING STALL AT 630 W PINE 1 STRUCK UNIT 2. MINOR DAMAGE	ST BARABO	OO WI. UNIT 1 CAME INTO	PARKING LOT	CONDUCTED UNIT 2 DID NO	A WIDE TURN TO TRAVEL T SEE DAMAGE UNTIL

Crash Date 11/23/2022
Crash Time 08:30 PM

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/23/2022

Crash Time 08:30 PM

Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Plate Type Vehicle Identification Number Make Plate Type St Country of Issuance Vehicle Damage Initial Contact Point Vehicle Damage		Loc	alion								
IN THE VILLAGE OF WEST BARABOO IN SAUK COUNTY Crash Scene First Harmful Event Unknown Motor Verth Intransport Monare of Collision 03 - FRONT TO REAR Road Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CCrash Classification - Location PRIVATE PROPERTY Animal Type Relation To Trafficway NON TRAFFICWAY - PARKING LOT Crash Classification - Jurisdiction PRIVATE PROPERTY PRIVATE PROPERTY PRIVATE PROPERTY PRIVATE PROPERTY PRIVATE PROPERTY Unit Summary Unit Su		PAR	RKING LOT			La	atitude		Longitud	de	
IN THE VILLAGE OF WEST BARABOO IN SAUK COUNTY THE VILLAGE OF WEST BARABOO IN SAUK COUNTY IN SAUK COUNTY THE VILLAGE OF WEST BARABOO IN SAUK COUNTY IN SAUK COUNTY THE VILLAGE OF WEST BARABOO IN SAUK COUNTY IN SAUK							43.476518377 -8			89.768110552	
NTEVILLACE OF WEST BARABOO N SAUK COUNTY THE VILLACE OF WEST BARABOO N SAUK COUNTY PRIVATE TYPE HOUSE/BUILDING Crash Scene First Harmful Event MOTOR VEH IN TRANSPORT UNKNOWN HArmer of Collision 03 - FRONT TO REAR TOAS Surface Condition(s) DRY Enronment Factor(s) NONE NONE NONE NONE NONE NONE Readway Factor(s) Crash Classification - Location NONE NONE NONE NONE NONE Readway Factor(s) NONE NONE NONE NONE NONE NONE NONE Readway Factor(s) NONE NONE		, ,					X Coordinate		Y Coord	Y Coordinate	
N SAUK COUNTY											
Crash Scene First Harmful Event First Harmful Event Location Unknown				I BARABOO		Str	ructure Type		1		
Crash Scene First Harmful Event Motor Verb In Transport Motor Verb In Motor In		IIN 3	AUK COUNTY				• • •	G			
First Harmful Event Location UNKNOWN Unk							0002/20/22//				
Motor Vehi in Transport Marmer of Collision 03 - FRONT TO REAR Road Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CLOUDY Animal Type Relation To Trafficway NON TRAFFICWAY - PARKING LOT Cresh Clessification - Location PRIVATE PROPERTY Tribal Land Access Control NON CONTROL William interchange Area NON-JUNCTION Unit Summary Unit Status HTAND RUN D CLASS TRUCK Vehicle Type UNITION D TRUCK Total Occes Transbus # Recorded Total # Citations Issued Total Hazhart Types UNKNOWN Mark PROPERTY Traffic Control NOT AN INTERSECTION Unit Type Unit Status PROPERTY TRUCK/PICKUP TRUCK Total Occes Transbus # Recorded Total # Citations Issued Total Hazhart Types UNKNOWN PARKED MOTOR VEHICLE Traffic Way PARKEN DOTOR VEHICLE Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL NO APPLICABLE Traffic Control Traffic	(Cra	sh Scene								
Minner of Collision Dark/LightTeD		First	Harmful Event			Fir	rst Harmful Event	Location			
03 - FRONT TO REAR Road Surface Condition(s) DRY Environment Factor(s) NONE Weather Condition(s) CLOUDY Animal Type Crash Classification - Location PRIVATE PROPERTY Tribal Land NO NONE William Interchange Area Junction Location NON NONE William Interchange Area Junction Location NON NONE William Interchange Area Junction Location NO NON NON NON-JUNCTION Unit Summary Unit Summary Unit Summary Vehicle Operating As Classification Unit Type Tribula Crash Classification Unit Type Unit Ty		MO	TOR VEH IN TRANSPO	ORT		UI	NKNOWN				
Basilian DarkillichtED		Man	ner of Collision			Lic	ght Condition				
Road Surface Condition(s) Roadway Factor(s)		03 -	FRONT TO REAR			_	~				
DRY Environment Factor(s) NONE Weather Condition(s) CLOUDY Animal Type Relation To Trafficway Animal Type Access Control No Traffic Control No CONTROL Within Interchange Area Junction Location NON-JUNCTION NO CONTROL Within Interchange Area Junction Location NON-JUNCTION NOT AN INTERSECTION Unit Summary Vehicle Operating As Classification Unit Type TRUCK Total Trailer Operating As Endorsements TRUCK Operating As Endorsements TRUCK Operating As Endorsements TRUCK Operating As Endorsements Unit Type Unit Traffic Control O											
Environment Factor(s) NONE Weather Condition(s) CLOUDY Animal Type Relation To Trafficway NON TRAFFICWAY - PARKING LOT Crash Classification - Location PRIVATE PROPERTY Tribal Land Access Centrol NON-JUNCTION Within Interchange Area Junction Location NON-JUNCTION Unit Summary Unit Status HIT AND RUN Unit Status HIT AND RUN Vehicle Operating As Classification Type Unit Status HIT AND RUN TRUCK Total Occs TrainBus # Recorded 1 Total # Citations Issued 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK Total Occs TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY TRUCK/PICKUP TRUCK TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY Truck Unit TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY Truck Unit TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY Truck Unit TrainBus # Recorded 0 0 0 0 1 Insurance? UnitRUTY Truck Unit TrainBus # Recorded 0 0 0 0 1 Insurance? Unit Truck Unit TrainBus # Recorded 0 0 0 0 1 Insurance? Unit Truck Unit TrainBus # Recorded 0 0 0 0 1 Insurance? Unit Truck Unit TrainBus # Recorded 0 0 0 0 1 Insurance? Unit Truck Unit TrainBus # Recorded 0 0 0 0 1						110	badway r actor(3)				
NONE Weather Condition(s) CLOUPY		DRY	<i>(</i>								
Weather Condition(s) CLOUDY		Envi	ronment Factor(s)								
Weather Condition(s) CLOUDY		NON	NE			NO	ONE				
CLOUDY Animal Type Relation To Trafficway NON TRAFFICWAY - PARKING LOT Crash Classification - Location PRIVATE PROPERTY Tribal Land Access Control NO CONTROL Within Interchange Area Junction Location NO NON-JUNCTION NOT AN INTERSECTION Unit Summary Vehicle Operating As Classification Unit Type HIT AND RUN D CLASS TRUCK Operating As Endorsements Truck Collection of Travel UNITITY TRUCK/PICKUP TRUCK Total Ocos Train/Bus # Recorded 1 Total # Citations Issued O 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0						140	ONE				
Animal Type Trash Classification - Location PRIVATE PROPERTY Tribal Land Access Centrol NO CONTROL Within Interchange Area NO ANIMAL Type An		Wea	ther Condition(s)								
Crash Classification - Location PRIVATE PROPERTY PRIVATE PROPERT		CLC	DUDY								
Crash Classification - Location PRIVATE PROPERTY PRIVATE PROPERTY PRIVATE PROPERTY Access Control NO CONTROL NO CONTROL NO CONTROL NOT AN INTERSECTION Unit Type NOT AN INTERSECTION Unit Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total HazMat Types UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total HazMat Types UNKNOWN Mark NIA NIA Emergency Motor Vehicle Use NO SPECIAL Function Not APPLICABLE Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL NO SPECIAL FUNCTION NOT APPLICABLE Traffic Control Traffic Control Inoperative/Missing No CONTROL NO SPECIAL FUNCTION NO CONTROL NO SPECIAL FUNCTION NOT APPLICABLE Traffic Control Inoperative/Missing No CONTROL NO SPECIAL FUNCTION NOT APPLICABLE Traffic Control Inoperative/Missing No CONTROL NO CONTR											
Crash Classification - Location PRIVATE PROPERTY Tribal Land Access Control NO CONTROL Within Interchange Area NO NON-JUNCTION Unit Summary Unit Status HIT AND RUN Vehicle Type UNITLITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded 1 nursurance? UNKNOWN Most Harmful Event: Collision With PARKED MOTOR VEHICLE Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL NO SPECIAL FUNCTION Train Bus Occorred NO Control NO C		Anım	nal Type					,			
PRIVATE PROPERTY Tribia Land Access Control NO CONTROL Within Interchange Area NO NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Summary Unit Status HIT AND RUN Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded Insurance? UNKNOWN Insurance? Insurance? Insurance? UNKNOWN Insurance? Insurance Insurance? Insurance									3 LOT		
Tribal Land Access Control NO CONTROL Within Interchange Area Junction Location NO											
Within Interchange Area NON-JUNCTION Intersection Type Unit Status HIT AND RUN Vehicle Operating As Classification Unit Type TRUCK Operating As Endorsements Unit Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded 1								RTY			
Within Interchange Area NO NON-JUNCTION Intersection Type NOT AN INTERSECTION Unit Summary Unit Status Vehicle Operating As Classification Unit Type TRUCK Vehicle Type Operating As Classification Unit Type TRUCK Vehicle Unit Intersection Unit Type Operating As Classification Unit Type TRUCK Vehicle Limit Vehicle Unit Intersection Unit Type Operating As Classification Unit Type TRUCK Vehicle Unit Intersection Unit Type Operating As Classification Uni		Triba	al Land			Ac	Access Control Special Study				
Unit Summary Vehicle Operating As Classification						NO	NO CONTROL				
Unit Summary Unit Status Vehicle Operating As Classification Unit Type TRUCK Unit Status Vehicle Type TRUCK Unit Status Vehicle Type Train/Bus # Recorded Total # Citations Issued Operating As Endorsements Unit Truck/PICKUP TRUCK Total Occs Train/Bus # Recorded Total # Citations Issued Operating As Endorsements Unit Truck/PICKUP TRUCK Total Trailers Total HazMat Types Unit Traince? Direction Of Travel Pre CrashTire Speed Limit Total Lanes UNKNOWN UNKNOWN Mark N/A 2 UNKNOWN UNKNOWN Mark N/A 2 UNKNOWN Mark N/A 2 PARKED MOTOR VEHICLE NO SPECIAL FUNCTION NOT APPLICABLE Traffic Control Traffic Control Inoperative/Missing NO CONTROL N		With	in Interchange Area	terchange Area Junction Location Interse			tion Type				
Unit Status Vehicle Type		NO		NON-JUNCTION NOT A			N INTERSECTION				
Unit Status Vehicle Type											
HIT AND RUN Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs Train/Bus # Recorded 0		IInit	t Summary								
Vehicle Type UTILITY TRUCK/PICKUP TRUCK Total Occs 1					Vehicle Ope	erating As Class	sification	Unit Type			
Total Occs Train/Bus # Recorded Total # Citations Issued Total Trailers Total HazMat Types		Unit	Status		· ·	erating As Class	sification				
Total Occs		Unit HIT	Status AND RUN		· ·	erating As Class	sification	TRUCK	s Endorsei	ments	
Total Lanes Direction Of Travel Direction Of Direction		Unit HIT Vehi	Status AND RUN cle Type	TRUCK	· ·	erating As Class	sification	TRUCK	s Endorsei	ments	
Insurance? UNKNOWN Insurance? UNKNOWN Most Harmful Event: Collision With PARKED MOTOR VEHICLE Traffic Way PARKING LOT OR PRIVATE PROPERTY Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Vehicle Identification Number Make Pre CrashTire Mark N/A Special Function NO SPECIAL FUNCTION Traffic Control NO SPECIAL FUNCTION Traffic Control NO CONTROL NO Road Curvature Road Grade LEVEL Vehicle License Plate Number Vehicle Vehicle Identification Number Make Vehicle Damage 16 - VEHICLE NOT AT SCENE		Unit HIT Vehi	Status AND RUN cle Type LITY TRUCK/PICKUP		D CLASS			TRUCK Operating As			
UNKNOWN UNKNOWN Special Function Most Harmful Event: Collision With PARKED MOTOR VEHICLE Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Vehicle Identification Number No Make Vehicle Identification Number Vehicle Identification Number Vehicle Color Body Style Bus Use 16 - VEHICLE NOT AT SCENE		Unit HIT Vehi UTII Tota	Status AND RUN cle Type LITY TRUCK/PICKUP		D CLASS		Total Tra	TRUCK Operating As	Total Haz		
Most Harmful Event: Collision With PARKED MOTOR VEHICLE Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Plate Type Vehicle Identification Number Make Plate Type St Country of Issuance Vehicle Initial Contact Point O1 - RIGHT FRONT CORNER Extent Of Damage Most Harmful Event: Collision With PARKED MOTOR VEHICLE NO SPECIAL FUNCTION NO SPECIAL FUNCTION NO Traffic Control Inoperative/Missing NO NO Surface Type Road Grade LEVEL St Country of Issuance Vehicle Identification Number Vehicle Damage 16 - VEHICLE NOT AT SCENE		Unit HIT Vehi UTII Tota 1	Status AND RUN cle Type LITY TRUCK/PICKUP	Train/Bus # Recorded	D CLASS Total # Cita 0	tions Issued	Total Tra	TRUCK Operating As	Total Haz	Mat Types	
Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Plate Type Vehicle Identification Number Make Plate Type St Country of Issuance Vehicle Identification Number Make Vehicle Damage Vehicle Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehic UTII Tota 1	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs	Train/Bus # Recorded Direction Of Travel	D CLASS Total # Cita 0	tions Issued CrashTire	Total Tra 0 Speed L	TRUCK Operating As	Total Haz 0 Total Lan	Mat Types	
Traffic Way PARKING LOT OR PRIVATE PROPERTY NO CONTROL Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Plate Type Vehicle Identification Number Make Plate Type St Country of Issuance Vehicle Identification Number Make Vehicle Damage Vehicle Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehic UTII Tota 1 Insur	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN	Train/Bus # Recorded Direction Of Travel UNKNOWN	Total # Cita 0 Pre	tions Issued CrashTire Mark	Total Tra 0 Speed L	TRUCK Operating As	Total Haz 0 Total Lan 2	Mat Types es	
PARKING LOT OR PRIVATE PROPERTY Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Plate Type License Plate Number Vehicle Identification Number Make Plate Type Vehicle Identification Number No No Vehicle Damage Initial Contact Point O1 - RIGHT FRONT CORNER Extent Of Damage NO Road Curvature Road Grade LEVEL Road Grade LEVEL Country of Issuance NO Road Curvature Road Grade LEVEL Vehicle Bus Use	01	Unit HIT Vehic UTII Tota 1 Insur UNIP	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN t Harmful Event: Collision N	Train/Bus # Recorded Direction Of Travel UNKNOWN With	Total # Cita 0 Pre Special Fur	CrashTire Mark	Total Tra 0 Speed L N/A	TRUCK Operating As ailers mit Emergency	Total Haz 0 Total Lan 2 Wotor Veh	es icle Use	
Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Vehicle Identification Number Make Vehicle Identification Number Vehicle Initial Contact Point 01 - RIGHT FRONT CORNER Extent Of Damage Road Curvature Road Grade LEVEL Road Grade LEVEL Road Grade LEVEL Truck Bus or HazMat NO Vehicle St Country of Issuance Make Year Model Vehicle Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehi UTII Tota 1 Insur UNI Most	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN t Harmful Event: Collision V	Train/Bus # Recorded Direction Of Travel UNKNOWN With	Total # Cita 0 Pre Special Fur NO SPEC	crashTire Mark Action	Total Tra 0 Speed L N/A	TRUCK Operating Astallars mit Emergency I	Total Haz 0 Total Lan 2 Motor Veh	es icle Use	
BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Vehicle Identification Number Vehicle Identification Number Vehicle Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehi UTII Tota 1 Insui UNI Most PAR	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN t Harmful Event: Collision N RKED MOTOR VEHICL ic Way	Train/Bus # Recorded Direction Of Travel UNKNOWN With	Total # Cita 0 Pre Special Fur NO SPEC	CrashTire Mark nection	Total Tra 0 Speed L N/A	TRUCK Operating Astallars mit Emergency I NOT APPL Traffic Contr	Total Haz 0 Total Lan 2 Motor Veh	es icle Use	
Truck Bus or HazMat NO Vehicle License Plate Number Vehicle Identification Number Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Damage Initial Contact Point O1 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehic UTII Tota 1 Insur UNIP Most PAR Traff	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision N RKED MOTOR VEHICL ic Way RKING LOT OR PRIVA	Train/Bus # Recorded Direction Of Travel UNKNOWN With	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont	CrashTire Mark Inction CrashTire Mark CrashTire Mark CrashTire Mark CrashTire CrashTir	Total Tra 0 Speed L N/A	TRUCK Operating As ailers mit Emergency INOT APPL Traffic Contr	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Vehicle License Plate Number Vehicle Identification Number Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Damage Initial Contact Point O1 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehi UTII Tota 1 Insui UNI Most PAR Traff PAR	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision N RKED MOTOR VEHICL fic Way RKING LOT OR PRIVA ace Type	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT	CrashTire Mark action EIAL FUNCTIO	Total Tra 0 Speed L N/A	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Vehicle License Plate Number Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Make Vehicle Identification Number Model Color Body Style Initial Contact Point 01 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehi UTII Tota 1 Insui UNI Most PAR Traff PAR	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision N RKED MOTOR VEHICL fic Way RKING LOT OR PRIVA ace Type	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT	CrashTire Mark action EIAL FUNCTIO	Total Tra 0 Speed L N/A	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
License Plate Number Plate Type St Country of Issuance Vehicle Identification Number Make Year Model Color Body Style Initial Contact Point O1 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehi UTII Tota 1 Insur UNIP Most PAR Traff PAR Surfa BLA Truc	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision Now RKED MOTOR VEHICL ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS) k Bus or HazMat	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT	CrashTire Mark action EIAL FUNCTIO	Total Tra 0 Speed L N/A	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
License Plate Number Plate Type St Country of Issuance Vehicle Identification Number Make Year Model Color Body Style Initial Contact Point O1 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	01	Unit HIT Vehi UTII Tota 1 Insur UNIP Most PAR Traff PAR Surfa BLA Truc	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision Now RKED MOTOR VEHICL ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS) k Bus or HazMat	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT	CrashTire Mark action EIAL FUNCTIO	Total Tra 0 Speed L N/A	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Color Body Style Bus Use Initial Contact Point Vehicle Damage	01	Unit HIT Vehi UTII Tota 1 Insur UNIP Most PAR Surfa BLA Truc NO	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision N RKED MOTOR VEHICL fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT	CrashTire Mark action EIAL FUNCTIO	Total Tra 0 Speed L N/A	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Color Body Style Bus Use Initial Contact Point Vehicle Damage	01	Unit HIT Vehi UTII Tota 1 Insur UNIP Most PAR Surfa BLA Truc NO	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision N RKED MOTOR VEHICL ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Inction BIAL FUNCTION BIAL TON BI	Total Tra 0 Speed L N/A	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Color Body Style Bus Use Initial Contact Point Vehicle Damage	01	Unit HIT Vehi UTII Tota 1 Insur UNIP Most PAR Surfa BLA Truc NO	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision N RKED MOTOR VEHICL ic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Inction BIAL FUNCTION BIAL TON BI	Total Tra 0 Speed L N/A	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Color Body Style Bus Use Initial Contact Point Vehicle Damage	UNIT 01	Unit HIT Vehi UTII Tota 1 Insur UNIP Most PAR Surfa BLA Truc NO	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision V RKED MOTOR VEHICL Tic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Inction BIAL FUNCTION BIAL TON BI	Total Tra 0 Speed L N/A DN	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Initial Contact Point O1 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	UNIT 01	Unit HIT Vehical Vehic	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision V RKED MOTOR VEHICL Tic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH	CrashTire Mark Inction BIAL FUNCTION BIAL TON BI	Total Tra 0 Speed L N/A DN	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
O1 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	UNIT 01	Unit HIT Vehical Vehic	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision Name RKED MOTOR VEHICL fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type	CrashTire Mark Inction EIAL FUNCTIO TROL atture T	Total Tra 0 Speed L N/A DN	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
O1 - RIGHT FRONT CORNER Extent Of Damage 16 - VEHICLE NOT AT SCENE	UNIT 01	Unit HIT Vehical Vehic	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision Name RKED MOTOR VEHICL fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type	CrashTire Mark Inction EIAL FUNCTIO TROL atture T	Total Tra 0 Speed L N/A DN	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
Extent Of Damage Victorial Property 16 - Vehicle NOT AT SCENE 16 - Vehicle NOT AT SCENE 17 18 19 19 19 19 19 19 19	UNIT 01	Unit HIT Vehi- Vehi- UTIII Tota 1 Insur Most PAR Trafff PAR Surfa BLA Truc NO	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision Na RKED MOTOR VEHICL fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number Vehicle Identification Nur Color	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type Make Body Style	CrashTire Mark Detion EIAL FUNCTION Brother T	Total Tra 0 Speed L N/A DN	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use	
THE VEHICLE NOT AT SCENE	01 UNIT 01	Unit HIT Vehic UTIII Total 1 Insuru UNIF Most PAR Trafff PAR Surfa BLA Truc	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN t Harmful Event: Collision Na KKED MOTOR VEHICL fic Way KKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number Vehicle Identification Nur Color Initial Contact Point	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type Make Body Style	CrashTire Mark Detion EIAL FUNCTION Brother T	Total Tra 0 Speed L N/A DN	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use tive/Missing	
I VERICLE NOT AT SCENE	01 UNIT 01	Unit HIT Vehic UTIII Total 1 Insuru UNIF Most PAR Trafff PAR Surfa BLA Truc	Status AND RUN cle Type LITY TRUCK/PICKUP I Occs rance? KNOWN I Harmful Event: Collision Na RKED MOTOR VEHICL fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOUS IK Bus or HazMat Vehicle License Plate Number Vehicle Identification Nur Color Initial Contact Point 01 - RIGHT FRONT C	Train/Bus # Recorded Direction Of Travel UNKNOWN With E TE PROPERTY S)	Total # Cita 0 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type Make Body Style	CrashTire Mark Inction IIAL FUNCTIO ITROL	Total Tra 0 Speed L N/A DN St Year	TRUCK Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade LEVEL Country of Iss Model	Total Haz 0 Total Lan 2 Motor Veh ICABLE ol Inopera	es icle Use tive/Missing	

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/23/2022

Crash Time 08:30 PM

		Towed Due To Damage		Vehicle Removed By					
		NOT TOWED		OPERATOR					
		What Driver Was Doing	Vehicle Factors						
		UNKNOWN							
	Driver Prior Action Other			UNKNOWN					
		Driver Actions							
	щ	UNKNOWN							
L	VEHICLE								
5	ᇤ								
	>								
		Owner Name		Owner Address					
		Owner Name		Owner Address					
6	2			, ,					
		Sequence Of Events							
	01	Event PARKED MOTOR VEHICLE							
	0								
	02	Event							
	03	Event							
		Event							
	04								
	Ì	ndividual							
	Ī	Driver UNKNOWN UNKNOWN		Citations Issued	Sex	Sex			
	INDIMIDNAL			0					
			Date of Birth	Race					
		A 1.1		D: 1: N: 1					
5		Address		Driver License Number					
	Z	, ,							
	Sat	On Duty Co	rash	Safety Equipment					
		Row	Seat Position	RESTRAINT USE UNKNOWN					
		01 - FRONT ROW	07 - LEFT	NEONO MINI GOL ON MICHIGAN					
		Helmet Use	Helmet Compliance						
		Eye Protection		Tint Compliance					
		-							
5	001	Injury Seve		Airbag					
•	ŏ		ARENT INJURY	NOT APPLICABLE					
		Ejection Path		DI ICARI E		Trapped/Extricated NOT APPLICABLE			
		NOT APPLICABLE NOT EJECTED/NOT APP Medical Transport		EMS Agency Identifier		EMS Run #			
		NOT TRANSPORTED	Livio Agency Identifier		LIVIO I CUIT #				
		Hospital		Date of Death Time of Death					
		Distracted Distracted	By Source	1					
		Distracted By Distracted By Action							
		Non Motorist Striking Un	it # Location						

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Prior Action								
		Action								
		Action								
	Ļ									
_	INDIVIDUAL									
LNU	9									
>										
	Z									
		Action Other								To/From School
	,	Susp	pected Alcohol U	se	Suspected Drug	Use				I
	L	Orug & Alcohol								
		Alcohol Test Given		Alcohol Test Ty	/ре			Alcohol Tes	t Results	
		TEST NOT GIVEN Drug Test Given		Drug Test Type	<u> </u>	Drug	Test Results			
		TEST NOT GIVEN		Drug Test Type	•	Drug	rest Results			
_	_	Drug Type								
2	001									
		Individual Condition								
		individual Condition								
		NOT OBSERVED								
-		t Summary Status			Vehicle Operating A	e Classification	<u> </u>	Unit Type		
		ALLY PARKED			Vehicle Operating As Classification D CLASS			AUTOMOBILE		
	Vehicle Type			D GEAGG			Operating As Endorsements			
05	PASSENGER CAR									
	Total	Occs	Train/Bus # Recorded		Total # Citations Issued		Total Trailers		Total HazMat Types	
	0		D: // 0/7		0		0		0	
	Insurance? Direction Of Travel YES NOT ON ROADWAY		Pre CrashTire N/A		Speed Lim	Limit Total Lanes		es		
L			Special Function			Emergency Motor Vehicle Use				
⊃	most ramma zvena cometen vita			NO SPECIAL FUNCTION			NOT APP			
	Traffic Way PARKING LOT OR PRIVATE PROPERTY			Traffic Control			Traffic Control Inoperative/Missing			
				NO CONTROL			NO			
		ace Type			Road Curvature			Road Grade		
		CKTOP (BITUMINOUS) k Bus or HazMat			STRAIGHT		LEVEL			
	NO	N Dus of Flaziviat								
		Vehicle								
		License Plate Number		Plate Type St		St	Country of Issuance			
		ANY2357			AUT - AUTOMO	BILE	1	UNITED STATES		
~	~ 1	Vehicle Identification Number				Model				
05	02	WDDKJ8JB0DF204990		MERCEDES BENZ 2013		E				
		Color		* *			Bus Use			
		SIL - SILVER (ALUMIN Initial Contact Point	IUM)		CP - COUPE Vehicle Damage					
<u>⊢</u>	VEHICLE	05 - RIGHT REAR COR	RNER		vollide Dallage					7 8 9 10 11
LIND	\exists	Extent Of Damage			05 - RIGHT REAR CORNER					
_ ر	VE	MINOR DAMAGE								5 4 3 2 1
		Towed Due To Damage		Vehicle Removed By						
		NOT TOWED		OWNER						
	What Driver Was Doing LEGALLY PARKED									
		LEGALLI PARNED								

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/23/2022

Crash Time 08:30 PM

		-	
			Vehicle Factors
		Driver Prior Action Other	NOT APPLICABLE
ł		Driver Actions	
	111	NO CONTRIBUTING ACTION	
⊢	<u> </u>		
LIND	\cong		
∣∍	VEHICLE		
	>		
Ī		Owner Name	Owner Address
١,,,	01	WENDY VAN DINTER	504 8TH AVE
05	02	(608) 963-3627	BARABOO, WI 53913 , US
		Comunica Of Frants	
	•	Sequence Of Events	
	2	Event MOTOR VEH IN TRANSPORT	
		MOTOR VEHTIN TRANSPORT	
	02	Event	
	0		
İ		Event	
	03		
		Event	
	9	LVEIII	
⊢	- 1	Policy Holder	
LIND		Insurance Company	Individual
⊃		PROGRESSIVE-UNIVERSAL-INSURANCE-COMP	WENDY VAN DINTER
ı			1