6TL0B4X4QX

22-12257

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Ove	erride Primary Crash		gency Crash Number 2-12257	-	g Officer/Deputy IT E. KNULL			
Crash Date 12/09/2022	Crash Time 08:44 AM		ate Arrived 2/09/2022	Time Arrive 08:57 AN	ïme Arrived 18:57 AM			
Crash Date 12/09/2022 Date Notified 12/09/2022 On Emergency Governmen Property	Time Notified 08:44 AM	Tc 02	otal Units 2	Total Injure 00	ed Total Kille	ed		
On Emergency	Hit and Run	Lane Closure	Work Zone		er or Towed	Reporting		
Governmer Property	nt Active S	School Zone N	chool Bus Related O	Tags				
Reportable	Crash Type DT4000 (ST	ANDARD CRASH)		Amer	nded	Secondary Crash		
Description					Reconstructio			
STH	NOT SCA				Photos By Additional Info	prmation		
	nforcement officer, ag							
ON SNOW COVERED S	TH 23-33. UNIT 1 STARTED SNOW AND ALSO TRIED AV SABLING DAMAGE AND WA	OIDING COLLISION BY S	STEERING RIGHT. UNIT:	2 STRUCK THE REA	R OF UNIT 1. NO	INJURIES REPORTED.		

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data. $1 \quad \text{of} \quad 6$

22-12257

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

L	UC	ation									
C	ΟN	STH23 EB				Latitude			Longitu	Longitude	
		FT W		43.532644844 -8			-89.95	89.95595539			
		STH136 WB				X Coordinate			Y Coord	dinate	
		HE TOWN OF REEDS	BURG			261150.9			48242		
	N 5	SAUK COUNTY				Structure Type					
						NO STR					
С	ra	sh Scene									
F	First	Harmful Event				First Harm	nful Event L	_ocation			
Ν	NO	TOR VEH IN TRANSPO	ORT	ON ROA	DWAY						
Ν	Manı	ner of Collision		Light Cond	dition						
0)3 -	FRONT TO REAR		DAYLIG	HT						
F	Road	d Surface Condition(s)				Roadway	Factor(s)				
v	NE	T, SNOW, SLUSH									
E	nvi	ronment Factor(s)				POADS		CONDITION	(WET 14	V SNOW SI LISH	
۷	NE	ATHER CONDITIONS				ETC)	UNFACE	CONDITION	i (₩EI, IC	CY, SNOW, SLUSH,	
V	Nea	ther Condition(s)				,					
		.,									
1	SNC	JVV									
A	۱nim	nal Type				Relation T	o Trafficwa	ау			
						TRAFFIC	CWAY - C	ON ROAD			
C	Cras	h Classification - Location				Crash Clas	ssification	- Jurisdiction			
F	PUE	BLIC PROPERTY				NO SPE	CIAL JUF	RISDICTION			
Т	Friba	al Land				Access Co	ontrol			Special Study	
						NO CON	TROL				
V	Nithi	in Interchange Area	Junction Location		Intersectio	on Type					
N	٥V	°	NON-JUNCTION		NOT AN	INTERSE	CTION				
	-	t Summary									
				Vehicle One	arating Δe C	lassification					
l	Jnit	Status		Vehicle Ope	erating As C	lassification	1	Unit Type	BII F		
L I	Jnit N T	Status RANSIT		Vehicle Ope D CLASS	erating As C	lassification	I	AUTOMO		ments	
י ו - ^ע	Jnit N T /ehi	Status RANSIT cle Type			erating As C	lassification	1			ments	
נ ו א ק	Jnit NT /ehi PAS	Status RANSIT cle Type SSENGER CAR	Train/Rus # Decorded	D CLASS				AUTOMO Operating A	s Endorse		
ו ע ק ק ל	Jnit NT /ehi PAS	Status RANSIT cle Type	Train/Bus # Recorded	D CLASS			Total Tra	AUTOMO Operating A	s Endorse	ments zMat Types	
ι Ι Γ Γ	Jnit N T /ehi PAS Fotal	Status TRANSIT Cle Type SSENGER CAR I Occs		D CLASS	tions Issued	1	Total Tra 0	AUTOMO Operating A	is Endorse Total Haz 0	zMat Types	
ע ו ד 1	Jnit N T /ehi PAS Fotal I nsur	Status TRANSIT Cle Type SSENGER CAR I Occs rance?	Direction Of Travel	D CLASS	tions Issued	1	Total Tra 0 Speed Li	AUTOMO Operating A	s Endorse Total Haz 0 Total Lan	zMat Types	
	Jnit /ehi PAS Fotal I nsur YES	Status (RANSIT Cle Type SSENGER CAR I Occs rance? S	Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark	1	Total Tra 0	AUTOMO Operating A illers mit	s Endorse Total Haz 0 Total Lan 2	zMat Types ies	
	Jnit NT /ehi PAS Fotal I nsur YES	Status TRANSIT Cle Type SSENGER CAR I Occs rance? Harmful Event: Collision V	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency	s Endorse Total Haz 0 Total Lan 2 Motor Veh	zMat Types les icle Use	
	Jnit NT /ehi PAS Fotal I nsur YES Most	Status RANSIT cle Type SSENGER CAR I Occs rance? t Harmful Event: Collision V TOR VEH IN TRANSPO	Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction IAL FUNC	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP	IN Endorse	zMat Types ies icle Use :	
	Jnit NT /ehid PAS Total I msur YES Most Most	Status RANSIT Cle Type SSENGER CAR I Occs rance? Harmful Event: Collision V TOR VEH IN TRANSPO ic Way	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont	IN Endorse	zMat Types les icle Use	
U I F I I I I I I I I I I I I I I I I I	Jnit NT /ehi PAS Total I msur YES Most Traff	Status RANSIT Cle Type SSENGER CAR I Occs rance? CHarmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO	IN Endorse	zMat Types ies icle Use :	
U II T 1 II N T T S	Unit NT /ehi PAS Fotal I Most VES MO Traff	Status RANSIT Cle Type SSENGER CAR I Occs rance? Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	In Sendorse Total Haz O Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
U II F 1 II M T T T E E	Unit NT Vehin PAS Total I Most VES Most Traff TWC Surfa	Status RANSIT Cle Type SSENGER CAR I Occs rance? CHarmful Event: Collision V TOR VEH IN TRANSPO TOR VEH IN TRANSPO COWAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
U II T 1 II N T T T E E T	Unit NT Vehin PAS Total I Most VES Most Traff Gurfa Burfa BLA	Status RANSIT Cle Type SSENGER CAR I Occs rance? CHarmful Event: Collision V TOR VEH IN TRANSPO TOR VEH IN TRANSPO CONTRACTOR TOR VEH IN TRANSPO CONTRACTOR CONTRACTOR K Bus or HazMat	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
U II T 1 II N T T T E E T	Unit NT Vehic PAS Total I Most YES Most YES Most Traff Traff Traff Traff Traff NO	Status RANSIT Cle Type SSENGER CAR I Occs I Occs I dece I dece I dece Cocs Cocs I dece I d	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι	Unit NT Vehic PAS Total I Most YES Most YES Most Traff Traff Traff Traff Traff NO	Status RANSIT Cle Type SSENGER CAR I Occs rance? CHarmful Event: Collision V TOR VEH IN TRANSPO TOR VEH IN TRANSPO CONTRACTOR TOR VEH IN TRANSPO CONTRACTOR CONTRACTOR K Bus or HazMat	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Tra 0 Speed Li	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι	Unit NT Vehic PAS Total I Most YES Most YES Most Traff Traff Traff Traff Traff NO	Status RANSIT Cle Type SSENGER CAR I Occs I Occs I dece I dece I dece Cocs Cocs I dece I d	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark iction IAL FUNC rol ROL iture T		Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι	Unit NT Vehic PAS Total I Most YES Most YES Most Traff Traff Traff Traff Traff NO	Status RANSIT Cle Type SSENGER CAR I Occs I Occs I Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle	Direction Of Travel EASTBOUND With DRT	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T		Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
U I I I I I I I I I I I I I	Jnit N T Jehiu PAS Fotal I nsur YES Most Y Most Fraff Fruc Surfa BLA Fruc NO	Status RANSIT Cle Type SSENGER CAR I Occs I Occs I Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number	Direction Of Travel EASTBOUND With DRT S)	D CLASS	tions Issued CrashTire Mark iction IAL FUNC rol ROL iture T		Total Tra 0 Speed Li 55	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
U I I I I I I I I I I I I I	Unit NT Vehic PAS Total I Most YES Most YES Most Traff Traff Traff Traff Traff NO	Status RANSIT Cle Type SENGER CAR I Occs I ance? Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AKL6894	Direction Of Travel EASTBOUND With DRT S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T		Total Tra 0 Speed Li 55 St WI	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
U U U U U U U U U U U U U U	Jnit N T Jehiu PAS Fotal I nsur YES Most Y Most Fraff Fruc Surfa BLA Fruc NO	Status RANSIT Cle Type SENGER CAR I Occs I Occs I Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AKL6894 Vehicle Identification Num	Direction Of Travel EASTBOUND With DRT S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T ITOMOBII		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S [*] Model	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
U U U U U U U U U U U U U U	Jnit N T Jehiu PAS Fotal I nsur YES Most Y Most Fraff Fruc Surfa BLA Fruc NO	Status RANSIT Cle Type SENGER CAR I Occs I Occs I Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AKL6894 Vehicle Identification Num 1G1ND52J33M59995	Direction Of Travel EASTBOUND With DRT S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T ITOMOBII		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model MALIBU	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types ies icle Use :	
	Jnit N T Vehic PAS Fotal I msur YES Most Traff Surfa SLA Frucc Surfa SLA	Status RANSIT Cle Type SENGER CAR I Occs I Occs I Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AKL6894 Vehicle Identification Num 1G1ND52J33M59995 Color	Direction Of Travel EASTBOUND With DRT S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T ITOMOBII LET PAN		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model MALIBU	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	2Mat Types les licle Use tive/Missing	
	Jnit N T Vehic PAS Fotal I msur YES Most Traff Surfa SLA Frucc Surfa SLA	Status RANSIT Cle Type SENGER CAR I Occs rance? Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AKL6894 Vehicle Identification Num 1G1ND52J33M59995 Color DGR - GREEN, DARH	Direction Of Travel EASTBOUND With DRT S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T ITOMOBII LET PAN		Total Tra 0 Speed Li 55 St WI Year	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model MALIBU	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	2Mat Types les licle Use tive/Missing	
	Jnit N T Vehic PAS Fotal I msur YES Most Traff Surfa SLA Frucc Surfa SLA	Status RANSIT Cle Type SENGER CAR I Occs rance? Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AKL6894 Vehicle Identification Num 1G1ND52J33M59995 Color DGR - GREEN, DARM Initial Contact Point	Direction Of Travel EASTBOUND With DRT S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T ITOMOBII DLET DAN mage		Total Tra 0 Speed Li 55 St WI Year 2003	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S ^T Model MALIBU Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	2Mat Types les licle Use tive/Missing	
	Jnit N T Vehic PAS Fotal I msurf YES Most Traff Two Surfa BLA NO	Status RANSIT Cle Type SENGER CAR I Occs I Occs I ance? Harmful Event: Collision V TOR VEH IN TRANSPO ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AKL6894 Vehicle Identification Num 1G1ND52J33M59995 Color DGR - GREEN, DARM Initial Contact Point 05 - RIGHT REAR CC	Direction Of Travel EASTBOUND With DRT S) s)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T ITOMOBII DLET DAN mage	TION	Total Tra 0 Speed Li 55 St WI Year 2003	AUTOMO Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade DOWNHIL Country of Is UNITED S ^T Model MALIBU Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	2Mat Types les licle Use tive/Missing	

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data.



22-12257

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damag	-	DAMAGE		hicle Removed By	10E					
		TOWED DUE TO D What Driver Was Doin		5 DAMAGE		EVES AUTO SERV hicle Factors	ICE					
		SLOW/STOPPING	9									
		Driver Prior Action Other			NC	OT APPLICABLE						
UNIT	VEHICLE	Driver Actions SPEED TOO FAST	COND									
	>											
01	01	Owner Name AMBER ADE (608) 844-0860	E			Owner Address 138 SILVER DR REEDSBURG, WI	1 53959 , US					
	:	Sequence Of Ev	/ents									
	2	Event MOTOR VEH IN TR	RANSPOR	т								
	02	Event										
	03	Event										
	8	Event										
F	I	Policy Holder										
UNIT		Insurance Company FARMERS-INS-CO)-INC			Individual AMBER ADEE						
		Individual										
		Driver				Citations Issued						
	AL	AMBER ADE (608) 844-0860	= E			0 FEMALE Date of Birth Race						
⊢	D					Date of Birtin	WHITE					
UNIT	INDIVIDUAL	Address 138 SILVER DR REEDSBURG, WI 53959 , US			1	Driver License Number	r					
	_		On Duty Cr	ash		Safety Equipment						
	Sat	fety Equipment										
		Row 01 - FRONT ROW	ROW Seat Position		:	SHOULDER & LAP						
		Helmet Use			,	Helmet Compliance						
		Eye Protection				Tint Compliance						
01	001		Injury Seve			Airbag						
	•	Ejected		RENT INJURY		NON DEPLOYED						
		NOT EJECTED		OT EJECTED/NO		CABLE		Trapped/Extricated NOT TRAPPED				
		Medical Transport				EMS Agency Identifier		EMS Run #				
		NOT TRANSPORT	ED			Date of Death		Time of Death				
		Hospital										
		Distracted By	Distracted NOT APP	By Source	DISTRACT	ſED)						
		Distracted By Action NOT DISTRACTED)									
				_				Crach Data	10/00/0000			

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 3 of 6

6TL0B4X4QX

22-12257

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Non Motorist	king Unit #	Location						
		Prior Action								
		Action								
	IAL									
UNIT	INDIVIDUAL									
	-									
		Action Other								To/From School
			spected Alcohol L	Jse	Suspected Drug Use					
		Drug & Alcohol)	Alcohol Test Type	NO			Alcohol Test	Results	
		TEST NOT GIVEN							Trobulto	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug T	est Results			
5	001	Drug Type				•				
		Individual Condition								
		APPEARED NORMAL								
	Unit	t Summary								
		Status		Ve	ehicle Operating As Classi	fication		Unit Type		
		RANSIT cle Type		D	D CLASS			AUTOMOBILE Operating As Endorsements		
03	PAS	SENGER CAR								
	Total Occs Train/Bus # Recorded 1		ecorded To	Total # Citations Issued 0		Total Traile	0		Mat Types	
Ŀ	Insur YES	ance?	Direction Of Tr		Pre CrashTire Speed Lin Mark 55			2		
UNIT		Harmful Event: Collision W		Special Function NO SPECIAL FUNCTION			Emergency I NOT APPL			
		ic Way D-WAY, NOT DIVIDED			affic Control O CONTROL		Traffic Control Inoperative/Missing NO			
		ace Type			Road Curvature			Road Grade		
	BLA	CKTOP (BITUMINOUS	S	STRAIGHT				DOWNHILL		
	Truck Bus or HazMat NO									
	1	Vehicle								
		License Plate Number 425XVH			Plate Type AUT - AUTOMOBILE	St WI		Country of Issuance UNITED STATES		
03	02	Vehicle Identification Num	N	/lake		Year	Model			
	0	3VW3L7AJ2CM331598			VOLKSWAGEN 2012		2012	JETTA Bus Use		
		Color BLK - BLACK			Body Style Bus U SD - SEDAN			Dus Ose		
⊢	CLE	Initial Contact Point 12 - FRONT		V	/ehicle Damage					7 8 9 10 11
UNIT	VEHICLE	Extent Of Damage			12 - FRONT					6 5 4 3 2 1
	>	Towed Due To Damage			Vehicle Removed By OPERATOR					
I										

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

4 of 6

22-12257

WISCONSIN MOTOR VEHICLE CRASH REPORT

		5			Vehicle Factors							
		GOING STRAIGHT										
		Driver Prior Action Other				NOT APPLICABLE						
		Driver Actions										
		Driver Actions SPEED TOO FAST/COND										
⊢	ĽE											
UNIT	₽											
∍	VEHICL											
	~											
		Owner Name					Owner Address					
2	2	ZACHARY DOROW					537 BABB AVE					
02	02	(608) 963-1622					REEDSBURG, WI	3959,05				
		Sequence Of Events	s									
	01	Event MOTOR VEH IN TRANS	POR	т								
	02	Event										
	3	Event										
	03											
	04	Event										
		Policy Holder										
UNIT		Insurance Company					ndividual					
5		PROGRESSIVE-CLASS	IC-IN	s-co			ACHARY DOROW					
		Individual										
		Driver				Т	Citations Issued	Sex				
		ZACHARY DOR	ow				0 MALE					
	INDIVIDUAL	(608) 963-1622				C	Date of Birth	Race				
F	Ď					WHITE						
UNIT	<u>S</u>	Address 537 BABB AVE				1	river License Number					
	N.	REEDSBURG, WI 53959	. U	s								
		On Duty Crash					Safety Equipment					
	Saf	fety Equipment										
		Row		Seat Po	sition	SHOULDER & LAP BELT						
		01 - FRONT ROW		07 - LE	FT							
		Helmet Use		-		Helmet Compliance						
		Eye Protection				Tint Compliance						
~	8	Injury	Seve	rity		Airbag						
02	002			RENT II	NJURY	NON DEPLOYED						
		Ejected	Ej	ection Pa	th				Trapped/Extricated			
		NOT EJECTED NOT EJECTED/NOT APPI			-			NOT TRAPPED				
		Medical Transport				E	MS Agency Identifier		EMS Run #			
		NOT TRANSPORTED										
		Hospital					Date of Death		Time of Death			
		Distracted By NOT	cted E	By Source	E (NOT DISTRA	кст	ED)		:			
		Distracted By Action					-					
		NOT DISTRACTED										
		Non Motorist	ng Uni	t #	Location							
		Non Motorist										
					This second	-	and not include any CIII	O data	Crash Date	12/00/2022		

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 5 of 6

6TL0B4X4QX

22-12257

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action					
		Action					
	JAL						
UNIT	INDIVIDUAL						
ر	NDI						
	-						
		Action Other					To/From School
	L	Drug & Alcohol NO	lse	Suspected Drug Use			
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results		
02	002	Drug Type			I		
	•						
		Individual Condition					
		APPEARED NORMAL					