### 6TL0DDT5MN

22-12263

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document#	Agency Crash Number 22-12263	Investigating Officer/Deputy DETECTIVE I. HANSON		
Z S	Crash Date 12/09/2022	Crash Time 09:25 AM	Date Arrived 12/09/2022	Time Arrived 10:05 AM		
015	Date Notified 12/09/2022	Time Notified 09:26 AM	Total Units 01	Total Injured 00	Total Killed 00	
	On Emergency Hit	t and Run Lane Closu	re Work Zone	Trailer or Towed Reporting Threshold		
91F	Government Property Active School Zone		School Bus Related NO	Tags		
	<b>▼</b> Reportable	Crash Type DT4000 (STANDARD CRASH)	)	Amended	Secondary Crash	

<b>Description</b>		
Diagram	B	Reconstruction By
	Cth K	Photos By
		Additional Information NONE
	STOP 1 Meyer Road 01	
Alliant Energy Pole		

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS WEST ON MEYER ROAD WHICH WAS SLIGHTLY DOWNHILL. UNIT 1 STATED HE WAS SLOWING DOWN TO STOP AT THE STOP SIGN AND SLID THROUGH THE INTERSECTION. UNIT 1 BEGAN TO FISH TAIL AND ENTERED THE WEST DITCHLINE. UNIT 1 STRUCK THE ALLIANT UTILITY POLE WITH THE PASSENGER SIDE OF HIS TRUCK. 9109

1 of 4

Crash Date 12/09/2022
Crash Time 09:25 AM

## **6TL0DDT5MN** 22-12263

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/09/2022

Crash Time 09:25 AM

	Location <b>—</b>								
	ON CTHK WB		Latitude		Longitude				
	7 FT S	43.496570696		-90.103289921					
	OF MEYER RD IN THE TOWN OF IRONTON IN SAUK COUNTY					X Coordinate Y Coordinate		linate	
						249095.796875 4820640			
		Structure Type							
	Crash Scene								
	First Harmful Event				First Harm	ful Event l	ocation		
	UTILITY POLE				SHOULD				
	Manner of Collision				Light Condition				
	00 - NO COLLISION W/	VEHICLE IN TRANSPORT			DAYLIG	ΗT			
	Road Surface Condition(s)				Roadway	Factor(s)			
	SNOW								
	Environment Factor(s)								
	WEATHER CONDITION	s			NONE				
	Weather Condition(s)			Relation To Trafficway					
	SNOW								
	Animal Type								
	Crash Classification - Locat					Y - ON ROAD ation - Jurisdiction			
	PUBLIC PROPERTY				NO SPECIAL JURISDICTION				
	Tribal Land	TribalLand				Access Control Special Study FULL CONTROL			
	Within Interchange Area NO	Junction Location INTERSECTION		Intersection	ion Type RSECTION				
	Unit Summary								
	Unit Summary ■ Unit Status		Vehicle Ope	erating As Cl	lassification		Unit Type		
			Vehicle Ope	erating As Cl	lassification		Unit Type TRUCK		
	Unit Status IN TRANSIT Vehicle Type		1	erating As Cl	lassification		1	ks Endorse	ments
2	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU		D CLASS				TRUCK Operating A		
	Unit Status IN TRANSIT Vehicle Type	P TRUCK  Train/Bus#Recorded	D CLASS	erating As Cl		Total Trai	TRUCK Operating A		ments Mat Types
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance?	Train/Bus#Recorded  Direction Of Travel	D CLASS  Total # Citat 0			TotalTrai 0 Speed Lii	TRUCK Operating A	TotalHaz  0  TotalLan	MatTypes
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES	Direction Of Travel WESTBOUND	Total#Citate 0	tions Issued CrashTire Mark		Total Trai	TRUCK Operating A	TotalHaz  0  TotalLan  2	Mat Types es
	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance?	Direction Of Travel WESTBOUND	Total#Citat 0 Pre SpecialFur	tions Issued CrashTire Mark		TotalTrai 0 Speed Lii	TRUCK Operating A	TotalHaz  0 TotalLan  2 MotorVeh	Mat Types es
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collision	Direction Of Travel WESTBOUND	Total#Citat 0 Pre SpecialFur	crashTire Mark nction		TotalTrai 0 Speed Lii	TRUCK Operating A	Total Haz  0  Total Lan  2  Motor Veh  LICABLE	MatTypes es icle Use
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisio UTILITY POLE Traffic Way TWO-WAY, NOT DIVIDE	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  on With	Total # Citat 0 Pre Special Fur NO SPEC	CrashTire Mark netion IAL FUNC		TotalTrai 0 Speed Lii	TRUCK Operating A lers mit Emergency NOT APP	Total Haz  0  Total Lan  2  Motor Veh  LICABLE	es icle Use
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collision UTILITY POLE Traffic Way TWO-WAY, NOT DIVIDE Surface Type	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  on With	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont STOP SIG	CrashTire Mark nction IAL FUNC		TotalTrai 0 Speed Lii	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Con NO  Road Grade	Total Haz  0 Total Lan- 2 Motor Veh LICABLE	MatTypes es icle Use
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs Insurance? YES Most Harmful Event: Collisio UTILITY POLE Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  on With	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont	CrashTire Mark nction IAL FUNC		TotalTrai 0 Speed Lii	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Cont NO	Total Haz  0 Total Lan- 2 Motor Veh LICABLE	MatTypes es icle Use
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collision UTILITY POLE Traffic Way TWO-WAY, NOT DIVIDE Surface Type	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  on With	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont STOP SIG	CrashTire Mark nction IAL FUNC		TotalTrai 0 Speed Lii	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Con NO  Road Grade	Total Haz  0 Total Lan- 2 Motor Veh LICABLE	MatTypes es icle Use
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisio UTILITY POLE Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  on With	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont STOP SIG	CrashTire Mark nction IAL FUNC		TotalTrai 0 Speed Lii	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Cont NO  Road Grade DOWNHIL	Total Haz  0  Total Lan- 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use
07	Unit Status IN TRANSIT Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisio UTILITY POLE Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO Vehicle License Plate Number	Train/Bus#Recorded  Direction OfTravel  WESTBOUND  on With  ED	Total# Cital 0 Pre Special Fur NO SPEC Traffic ConsTOP SIG Road Curve STRAIGH	CrashTire Mark netion IIAL FUNC trol GN ature T	TION	Total Trai 0 Speed Lii 45	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Cont NO  Road Grade DOWNHIL  Country of is	Total Haz  0  Total Lan- 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use
07	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKU  Total Occs 1 Insurance? YES  Most Harmful Event: Collisio UTILITY POLE  Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMINO  Truck Bus or HazMat NO  Vehicle  License Plate Number NFFD36	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  On With  ED  DUS)	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont STOP SIG Road Curve STRAIGH	CrashTire Mark netion IAL FUNC trol GN ature T	TION	Total Trai 0 Speed Lii 45 St	TRUCK Operating A  lers  mit  Emergency NOT APP Traffic Con NO Road Grade DOWNHIL  Country of Is UNITED S:	Total Haz  0  Total Lan- 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use
UNIT 01	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES  Most Harmful Event: Collision UTILITY POLE  Traffic Way TWO-WAY, NOT DIVIDE  Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Number NFFD36  Vehicle Identification	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  On With  ED  DUS)	Total# Cita 0 Pre Special Fur NO SPEC Traffic Cons STOP SIG Road Curve STRAIGH  Plate Type LTK - LIC Make	CrashTire Mark netion IIAL FUNC trol GN ature T	TION	Total Trai  Speed Lii  45  St  WI  Year	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Con NO Road Grade DOWNHIL  Country of is UNITED S	Total Haz  0  Total Lan- 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use
07	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKU  Total Occs 1 Insurance? YES  Most Harmful Event: Collisio UTILITY POLE  Traffic Way TWO-WAY, NOT DIVIDE  Surface Type BLACKTOP (BITUMINO  Truck Bus or HazMat NO  Vehicle License Plate Number NFFD36  Vehicle Identification I 1FT7W2BN2BNEE	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  On With  ED  DUS)	Total # Citat 0 Pre Special Fur NO SPEC Traffic Cont STOP SIG Road Curve STRAIGH  Plate Type LTK - LIC Make FORD	CrashTire Mark nction IAL FUNC trol GN ature T	TION	Total Trai 0 Speed Lii 45 St	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Cont NO Road Grade DOWNHIL  Country of is UNITED S' Model F250	Total Haz  0  Total Lan- 2  Motor Veh LICABLE trol Inopera	MatTypes es icle Use
UNIT 01	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES  Most Harmful Event: Collision UTILITY POLE  Traffic Way TWO-WAY, NOT DIVIDE  Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Number NFFD36  Vehicle Identification	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  On With  ED  DUS)	Total# Cita 0 Pre Special Fur NO SPEC Traffic Cons STOP SIG Road Curve STRAIGH  Plate Type LTK - LIC Make	CrashTire Mark notion IAL FUNC trol GN ature T	TION	Total Trai  Speed Lii  45  St  WI  Year	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Con NO Road Grade DOWNHIL  Country of is UNITED S	Total Haz  0  Total Lan- 2  Motor Veh LICABLE trol Inopera	es icle Use
01 UNIT 01	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKU  Total Occs 1 Insurance? YES  Most Harmful Event: Collisio UTILITY POLE  Traffic Way TWO-WAY, NOT DIVIDE  Surface Type BLACKTOP (BITUMINO)  Truck Bus or HazMat NO  Vehicle License Plate Number NFFD36  Vehicle Identification I 1FT7W2BN2BNEE Color BLU - BLUE Initial Contact Point	Train/Bus # Recorded  Direction Of Travel  WESTBOUND  On With  ED  DUS)	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con: STOP SIG Road Curva STRAIGH  Plate Type LTK - LIC Make FORD Body Style	CrashTire Mark nction IAL FUNC trol GN ature T	TION	Total Trai  Speed Lii  45  St  WI  Year	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Cont NO Road Grade DOWNHIL  Country of is UNITED S' Model F250	Total Haz  0  Total Lan- 2  Motor Veh LICABLE trol Inopera	es icle Use tive/Missing
01 UNIT 01	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKU  Total Occs 1 Insurance? YES  Most Harmful Event: Collisio UTILITY POLE  Traffic Way TWO-WAY, NOT DIVIDE  Surface Type BLACKTOP (BITUMINO)  Truck Bus or HazMat NO  Vehicle License Plate Number NFFD36  Vehicle Identification I 1FT7W2BN2BNEE Color BLU - BLUE Initial Contact Point	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  On With  ED  Number  34559	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con STOP SIG Road Curva STRAIGH  Plate Type LTK - LIC Make FORD Body Style TK - TRU Vehicle Da 01 - RIGI	CrashTire Mark netion IAL FUNC trol SN ature T GHT TRUC	TION K	TotalTrai 0 Speed Lii 45 St WI Year 2022	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Con NO  Road Grade DOWNHIL  Country of Is UNITED S' Model F250  Bus Use	Total Haz  0 Total Lan- 2 Motor Veh LICABLE trol Inopera	es icle Use tive/Missing
UNIT 01	Unit Status IN TRANSIT  Vehicle Type UTILITY TRUCK/PICKU Total Occs 1 Insurance? YES Most Harmful Event: Collisio UTILITY POLE  Traffic Way TWO-WAY, NOT DIVIDE Surface Type BLACKTOP (BITUMING) Truck Bus or HazMat NO  Vehicle License Plate Number NFFD36 Vehicle Identification II 1FT7W2BN2BNEE Color BLU - BLUE Initial Contact Point	Train/Bus#Recorded  Direction Of Travel  WESTBOUND  On With  ED  Number 34559	Total # Citar 0 Pre Special Fur NO SPEC Traffic Con STOP SIG Road Curva STRAIGH  Plate Type LTK - LIC Make FORD Body Style TK - TRU Vehicle Da 01 - RIGI	CrashTire Mark netion IAL FUNC trol SN ature T GHT TRUC	TION K	TotalTrai 0 Speed Lii 45 St WI Year 2022	TRUCK Operating A  lers  mit  Emergency NOT APP  Traffic Con NO  Road Grade DOWNHIL  Country of Is UNITED S: Model F250  Bus Use	Total Haz  0 Total Lan- 2 Motor Veh LICABLE trol Inopera	es icle Use tive/Missing

### 6TL0DDT5MN

22-12263

#### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/09/2022

Crash Time 09:25 AM

		Towed Due To Damage TOWED BUT NOT DUE TO	DISABLING DAMAG		nicle Removed By EVES AUTO SERVI	CE			
	What Driver Was Doing		Vehicle Factors						
	SLOW/STOPPING  Driver Prior Action Other			NOT APPLICABLE					
	ш	Driver Actions FAILURE TO CONTROL							
≒	VEHICLE								
IND	Ŧ								
	•								
		OwnerName MARK CHARLES WEIHING	1		Owner Address S4139 STH 136				
2	5	(608) 524-2816			ROCK SPRINGS, V	VI 53961 , US			
		Sequence Of Events							
	5	UTILITY POLE							
	8	Event							
		Event							
	03	_							
	4	Event							
_		Policy Holder							
IN		Insurance Company GENERAL-CASUALTY-INS-CO		Individual MARK WEIHING					
		in altrigues							
		Driver		Citations sued Sex					
	4	MARK CHARLES WEIHING (608) 524-2816		0 MALE					
_	INDIVIDUAL				Date of Birth	Race WHITE	E		
EN D	፷	Address S4139 STH 136		Driver License Number					
	Z	ROCK SPRINGS, WI 53961	, us	STATE: WISCONSIN COUNTRY: UNITED STATES					
	Sat	ety Equipment	Crash	8	Safety Equipment				
		Row Seat Position		SHOULDER & LAP BELT					
		01 - FRONT ROW HelmetUse	07 - LEFT	Helmet Compliance					
		Eye Protection							
				TintCompliance					
5	=	Injury Sev	verity	Airbag					
0	TO ALLANEAL MOOK!			NON DEPLOYED  Trapped/Extricated					
	Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT APF		PLICABLE			NOT TRAPPED			
	Medical Transport		E	EMS Agency Identifier		EMS Run#			
		NOT TRANSPORTED Hospital		1	Date of Death Time of Death		Time of Death		
	Distracted By Source NOT APPLICABLE (NOT DISTRACTED)								
	Distracted By Action NOT DISTRACTED								
	Distracted By Action NOT DISTRACTED								

## **6TL0DDT5MN** 22-12263

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 12/09/2022

Crash Time 09:25 AM

								,
		Non Motor	Striking Unit#	Location				
		Prior Action						
		Action						
	UAL							
UNIT	INDIVIDUAL							
	INC							
		Action Other						To/From School
		Action Other						TON TOTAL CONSON
	L	Drug & Alcol			Suspected Drug Use NO			
		Alcohol Test Give		Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIV	/EN	Drug Test Type	Drug Test Resu		L	
6	001	Drug Type						
		Individual Conditi	on					
		APPEARED NO	ORMAL					
ı	Pro	perty Owne	er 💻					
01	Orga <b>ALL</b>	nization/Company IANT ENERGY			Address 4902 N BILTMORE			
PROP OWNER					MADISON, WI 53707	1077, US		
	Fixe	ed Objects S				***********	************	STATES STATES AND
	۵	Striking Unit 01	Struck Object UTILITY POLE				Structure Number	)amage Tag Number