

6TL0BGSFJ2  
22-12674

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

6TL0BGSFJ2

Document Number Override		Primary Crash Document#		Agency Crash Number 22-12674		Investigating Officer/Deputy DEPUTY D. KROLIKOWSKI	
Crash Date 12/19/2022		Crash Time 11:57 AM		Date Arrived 12/19/2022		Time Arrived 12:17 PM	
Date Notified 12/19/2022		Time Notified 11:57 AM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input checked="" type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type PRIVATE PROPERTY/PARKING LOT				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram



Reconstruction By

Photos By

Additional Information  
NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 2 WAS PARKED IN THE PARKING LOT WHEN UNIT 1, A SEMI WITH FULL LENGTH SEMI TRAILER, WAS BACKING BEHIND UNIT 1 IN AN ATTEMPT TO POSITION CORRECTLY TO DEPART THE PARKING LOT. DURING THIS BACKING THE RIGHT SIDE OF THE SEMI TRAILER MADE CONTACT WITH THE REAR LEFT CORNER OF UNIT 2, CAUSING DAMAGE TO THE TAIL LIGHT ASSEMBLY & HATCH.

6TL0BGSFJ2  
22-12674

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

Location

ON VALLEY VIEW RD 831 FT N OF MILL RD IN THE TOWN OF FRANKLIN IN SAUK COUNTY	Latitude 43.283181736	Longitude -90.024246463
	X Coordinate 254626.703125	Y Coordinate 4796704.5
	Structure Type NO STRUCTURE	


Crash Scene

First Harmful Event <b>PARKED MOTOR VEHICLE</b>	First Harmful Event Location <b>OUTSIDE RIGHT-OF-WAY (TRAFFICWAY)</b>	
Manner of Collision <b>05 - REAR TO SIDE</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>SNOW</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>NON TRAFFICWAY - PARKING LOT</b>	
Crash Classification - Location <b>PRIVATE PROPERTY</b>	Crash Classification - Jurisdiction <b>PRIVATE PROPERTY</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

Unit Summary

UNIT 01	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>C CLASS</b>	Unit Type <b>TRUCK</b>		
	Vehicle Type <b>UTILITY TRUCK/PICKUP TRUCK</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>1</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>NOT ON ROADWAY</b>	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit <b>N/A</b>	Total Lanes <b>1</b>
	Most Harmful Event: Collision With <b>PARKED MOTOR VEHICLE</b>	Special Function <b>NO SPECIAL FUNCTION</b>	Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>		
	Traffic Way <b>PARKING LOT OR PRIVATE PROPERTY</b>	Traffic Control <b>NO CONTROL</b>	Traffic Control Inoperative/Missing <b>NO</b>		
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>	Road Grade <b>LEVEL</b>		
	Truck Bus or HazMat <b>TRUCK OR TRUCK COMBINATION &gt; 10,000LBS GVWR/GCWR</b>				

UNIT VEHICLE 01	<b>Vehicle</b>			
	License Plate Number <b>33948Z</b>	Plate Type <b>LTK - LIGHT TRUCK</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
	Vehicle Identification Number <b>3AKJGEDV1ESFJ6070</b>	Make <b>FREIGHTLINER CORP</b>	Year <b>2014</b>	Model <b>CASCADIA</b>
	Color <b>WHI - WHITE</b>	Body Style <b>SE - SEMI-TRAILER</b>	Bus Use	
	Initial Contact Point <b>03 - RIGHT SIDE MIDDLE</b>	Vehicle Damage  <b>03 - RIGHT SIDE MIDDLE</b>		
Extent Of Damage <b>MINOR DAMAGE</b>				



6TL0BGSFJ2

22-12674

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By		
	What Driver Was Doing <b>BACKING</b>		Vehicle Factors		
	Driver Prior Action Other		<b>NOT APPLICABLE</b>		
	Driver Actions <b>NO CONTRIBUTING ACTION</b>				
01	01	Owner Name <b>LTL SERVICE INC (414) 571-9988</b>		Owner Address <b>330 E MAHN CT #200 OAK CREEK, WI 53154 , US</b>	
<b>Sequence Of Events</b>					
01	01	Event <b>PARKED MOTOR VEHICLE</b>			
02	02	Event			
03	03	Event			
04	04	Event			
<b>Policy Holder</b>					
UNIT	01	Insurance Company <b>NORTHLAND-INS-CO</b>		Organization/Company <b>LTL SERVICE INC</b>	
<b>Trailer/Towed</b>					
UNIT	01	Trailer Plate # <b>107695T</b>	Plate Type	Make <b>UTIL</b>	State <b>TN</b>
UNIT	TRAILER	Unit Type <b>SEMI TRAILER</b>	Organization/Company <b>LTL SERVICE INC (414) 571-9988</b>		Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>1UYVS2532M6335411</b>		Address <b>330 E MAHN CT #200 OAK CREEK, WI 53134 , US</b>	
<b>Individual</b>					
UNIT	INDIVIDUAL	Driver <b>LUIS JULIO GUZMAN (562) 467-3065</b>		Citations Issued <b>0</b>	Sex <b>MALE</b>
		Address <b>4595 S KANSAS AVE SAINT FRANCIS, WI 53235 , US</b>		Date of Birth [REDACTED]	Race <b>HISPANIC</b>
		Driver License Number <b>STATE: WISCONSIN COUNTRY: UNITED STATES</b>			
<b>Safety Equipment</b>					
01	001	On Duty Crash		Safety Equipment	
		Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		Injury Severity <b>Injury NO APPARENT INJURY</b>		Airbag <b>NON DEPLOYED</b>	
		Ejected <b>NOT EJECTED</b>	Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	Trapped/Extricated <b>NOT TRAPPED</b>	



6TL0BGSFJ2

22-12674

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT Insurance? YES Direction Of Travel NOT ON ROADWAY Pre Crash Tire Mark Speed Limit N/A Total Lanes 0
Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT Special Function NO SPECIAL FUNCTION Emergency Motor Vehicle Use NOT APPLICABLE
Traffic Way PARKING LOT OR PRIVATE PROPERTY Traffic Control NO CONTROL Traffic Control Inoperative/Missing NO
Surface Type BLACKTOP (BITUMINOUS) Road Curvature STRAIGHT Road Grade LEVEL
Truck Bus or HazMat NO

02 02 Vehicle License Plate Number 808GLP Plate Type AUT - AUTOMOBILE St WI Country of Issuance UNITED STATES
Vehicle Identification Number 4T3BK11A19U015017 Make TOYOTA Year 2009 Model VENZA
Color GRN - GREEN Body Style UT - SPORT UTILITY VEHICLE Bus Use
Initial Contact Point 06 - REAR Vehicle Damage 06 - REAR, 07 - LEFT REAR CORNER
Extent Of Damage MINOR DAMAGE Towed Due To Damage NOT TOWED Vehicle Removed By
What Driver Was Doing LEGALLY PARKED Vehicle Factors NOT APPLICABLE
Driver Prior Action Other
Driver Actions NO CONTRIBUTING ACTION
Owner Name HOPE R WHITE (608) 588-5777 Owner Address 1280 PLAINVIEW RD APT 14 PLAIN, WI 53577 , US

02 02 Sequence Of Events Event 01 MOTOR VEH IN TRANSPORT
Event 02
Event 03
Event 04

UNIT Policy Holder Insurance Company GEICO-GENERAL-INS-CO Individual HOPE WHITE