6TL0DBC3FK

22-12950

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Override	e Primary Crash I	Primary Crash Document #		y Crash Number 950	Investigating Officer/Deputy DEPUTY B. TRAGER			
Crash Date 12/28/2022	Crash Time 03:27 PM	Crash Time 03:27 PM Time Notified 03:27 PM		rrived /2022	Time Arrived 03:44 PM			
Crash Date 12/28/2022 Date Notified 12/28/2022 On Emergency Government Property	Time Notified			Inits	Total Injured Total Killed 00 00		ed	
On Emergency	Hit and Run	it and Run		Work Zone	Trailer or Towed		Reporting Threshold	
Government Property		hool Zone	School NO	Bus Related	Tags			
Reportable	Crash Type DT4000 (STA	NDARD CRAS	H)				Secondary Crash	
Description								
	CTY Hwy Ch (1) Pin	he Bluff Rd.		Not to Scale	Ac N	Iditional Info	ormation	

This report does not include any CJIS data. $1 \quad \text{of} \quad 4$

22-12950

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Loc	ation									
ł		CTHCH EB			1	Latitude			Longitue	de	
		FT N				43.47125	4512		-90.004	4004558	
	OF PINE BLUFF RD IN THE TOWN OF REEDSBURG						X Coordinate		Y Coordinate		
		AUK COUNTY	BUNG		:	257021.984375 4817533.5		33.5			
			:	Structure T	уре		•				
	Cra	sh Scene 💻									
1		Harmful Event				First Harm		ocation			
			ROADSI								
	DITCH Manner of Collision						Light Condition				
	00 -	NO COLLISION W/VE	HICLE IN TRANSPORT			DAYLIGH					
	Road	d Surface Condition(s)				Roadway Factor(s)					
	WE	т									
	Envi	ronment Factor(s)									
	NO	NE			1	NONE					
	Wea	ther Condition(s)									
		DUDY			Relation To Trafficway TRAFFICWAY - NOT Crash Classification - Juri NO SPECIAL JURISE						
	Anim	nal Type									
		sh Classification - Location BLIC PROPERTY									
	Triba	al Land			Access Control NO CONTROL			Special Study		Special Study	
					Intersection Type						
					NOT AN U	AN INTERSECTION					
					NOT AN I	NIEKSE					
l	-	t Summary				NIERSE					
	Uni	t Summary			erating As Cla			Unit Type			
	Unit Unit IN T	Status RANSIT		Vehicle Ope	erating As Cla			TRUCK			
	Unit Unit IN T Vehi	Status RANSIT cle Type			erating As Cla				s Endorse	ments	
	Unit Unit IN T Vehi UTI	Status RANSIT cle Type LITY TRUCK/PICKUP	TRUCK	D CLASS	erating As Cla			TRUCK Operating A			
	Unit Unit IN T Vehi UTI	Status RANSIT cle Type		D CLASS	erating As Cla		Total Tra 0	TRUCK Operating A		ments zMat Types	
	Unit Unit IN T Vehi UTII Tota 1	Status RANSIT cle Type LITY TRUCK/PICKUP	TRUCK Train/Bus # Recorded Direction Of Travel	D CLASS	erating As Cla		Total Tra	TRUCK Operating A illers	Total Haz	zMat Types	
01	Unit Unit IN T Vehi UTII Tota 1 Insu	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark		Total Tra 0	TRUCK Operating A illers	Total Haz 0 Total Lan 2	zMat Types nes	
01	Unit Unit IN T Vehi UTII Tota 1 Insu YES Most	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision \	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark	assification	Total Tra 0 Speed Li	TRUCK Operating A illers	Total Haz 0 Total Lan 2 Motor Veh	zMat Types nes nicle Use	
01	Unit Unit IN T Vehi UTII Tota 1 Insu YES Most	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision \	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark Iction CIAL FUNCT	assification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes nicle Use	
01	Unit Unit IN T Vehi UTII Tota 1 Insu YES Most DIT Traff	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction cliAL FUNCT	assification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP	Total Haz 0 Total Lan 2 Motor Veh LICABLE	zMat Types nes nicle Use	
01	Unit Unit IN T Vehi UTII Tota 1 Insuu YES DIT Traff TW0 Surfa	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction CIAL FUNCT Trol ROL ature	assification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use	
01	Unii Unit IN T Vehi UTII Tota 1 Insuu YES Moss DITO Traff TWO Surfa	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH CH CH CWay D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU:	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction CIAL FUNCT Trol ROL ature	assification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use	
01	Unii Unit IN T Vehi UTII Tota 1 Insuu YES Moss DITO Traff TWO Surfa	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction CIAL FUNCT Trol ROL ature	assification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use	
01	Unii Unit IN T Vehi UTII Tota 1 Insuu YES Mosi DIT Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH CH CH CWay D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU:	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction CIAL FUNCT Trol ROL ature	assification	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use	
01	Unii Unit IN T Vehi UTII Tota 1 Insuu YES Mosi DIT Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH CH CH Source Type ACKTOP (BITUMINOU) k Bus or HazMat	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCT TROL ature EFT	rion	Total Tra 0 Speed Li	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	zMat Types nes nicle Use	
01	Unii Unit IN T Vehi UTII Tota 1 Insuu YES Mosi DIT Traff TWO Surfa BLA Truc NO	Status RANSIT cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNCT TROL ature EFT	Elon	Total Tra 0 Speed Li 55	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera 3 suance	zMat Types nes nicle Use	
UNIT 01	Unit Unit Unit Vehi UTII Tota 1 Insuu YES DIT Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Tharmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number MR9729 Vehicle Identification Nur	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction IAL FUNCT Trol TROL ature EFT GHT TRUCK	rion	Total Tra 0 Speed Li 55 St St WI Year	TRUCK Operating A ilers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance rATES	zMat Types nes nicle Use	
UNIT 01	Unii Unit IN T Vehi UTII Tota 1 Insuu YES Mosi DIT Traff TWO Surfa BLA Truc NO	Status TRANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number MR9729 Vehicle Identification Nur 3GCPKSE75DG3513	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark CrashTire Mark Class CrashTire CrashTire CrashTire CrashTire CrashTire CrashTire CrashTire CrashTire CrashTire CrashTire CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire Mark CrashTire CrashTire Mark CrashTire CrashTire Mark CrashTire CrashTire Mark CrashTire CrashTire Mark CrashTire CrashTire Mark CrashTire CrashTire Mark CrashTire Cr	rion	Total Tra 0 Speed Li 55	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model SILVERAD	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance rATES	zMat Types nes nicle Use	
UNIT 01	Unit Unit Unit Vehi UTII Tota 1 Insuu YES DIT Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Tharmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number MR9729 Vehicle Identification Nur	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction CrashTire Mark IAL FUNCT Trol TROL ature EFT GHT TRUCK DLET	rion	Total Tra 0 Speed Li 55 St St WI Year	TRUCK Operating A ilers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance rATES	zMat Types nes nicle Use	
UNIT 01	Unit Unit Unit IN T Vehi Tota 1 Insuu YES DIT Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number MR9729 Vehicle Identification Nur 3GCPKSE75DG3513 Color	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark CrashTire Mark Clal FUNCT TROL TROL EFT GHT TRUCK	rion	Total Tra 0 Speed Li 55 St St WI Year	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model SILVERAD	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance rATES	zMat Types nes nicle Use titive/Missing	
01 UNIT 01	Unit Unit Unit IN T Vehi Tota 1 Insuu YES DIT Traff TWO Surfa BLA Truc NO	Status TRANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? S t Harmful Event: Collision N CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number MR9729 Vehicle Identification Nur 3GCPKSE75DG3513 Color BLK - BLACK Initial Contact Point 12 - FRONT	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued tions Issued CrashTire Mark CrashTire Mark Crol ROL ature EFT SHT TRUCK SHT TRUCK SHT TRUCK SHT TRUCK	rion	Total Tra 0 Speed Li 55 St WI Year 2013	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Output Output Intersector Model SILVERAD Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance rATES	zMat Types nes nicle Use titive/Missing	
UNIT 01 UNIT 01	Unit Unit Unit IN T Vehi UTII Tota 1 Insuu YES DITO Traff TWO Surfa BLA Truc NO	Status RANSIT Cle Type LITY TRUCK/PICKUP I Occs rance? Tharmful Event: Collision N CH Tic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU: k Bus or HazMat Vehicle License Plate Number MR9729 Vehicle Identification Nur 3GCPKSE75DG3513 Color BLK - BLACK Initial Contact Point	TRUCK Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS Total # Cita 1 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type LTK - LIC Make CHEVRO Body Style PK - PICI Vehicle Da 01 - RIGI	tions Issued CrashTire Mark Inction CrashTire Mark IAL FUNCT TROL Ature EFT GHT TRUCK DLET KUP	rion Corner	Total Tra 0 Speed Li 55 St WI Year 2013	TRUCK Operating A illers mit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Output Output Intersector Model SILVERAD Bus Use	Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera suance rATES	zMat Types nes nicle Use titive/Missing	

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data.

2 of 4

6TL0DBC3FK

22-12950

WISCONSIN MOTOR VEHICLE CRASH REPORT

									(,	
		Towed Due To Damag	-	DISABLING DAMAG		hicle Removed By EVES AUTO SERVI	CE.			
		What Driver Was Doin		JISABLING DAMAG		hicle Factors	CE			
		NEGOTIATING CU	•		ve					
		Driver Prior Action Oth			NC	T APPLICABLE				
		Driver Actions								
	щ	RAN OFF ROADW	AY							
UNIT	ŭ									
5	VEHICLE									
	5									
		Ourse News				Ourses Address				
		Owner Name KERRY GULSRU	D			Owner Address 1494 N PEARL ST				
2	2	(608) 604-3332				RICHLAND CENTE	ER, WI 53581, U	JS		
	5	Sequence Of Ev	vents			1				
		Event DITCH								
	5	DITCH								
	8	Event								
	0	E vert								
	03	Event								
		Event								
	8	Lyon								
		Policy Holder								
UNIT						Individual				
5		ERIE-INS-CO			KERRY GULSRUD					
		Individual								
		Driver				Citations Issued	Sex			
	_	KERRY GULSRUD (608) 604-3332			1 MALE					
	M				Date of Birth Race					
F	NDIVIDUAL				WHITE					
UNIT	≥	Address			Driver License Number					
-	ž	1494 N PEARL ST RICHLAND CENTER, WI 53581 , US								
	_		,,	,						
			On Duty Cr	ash		Safety Equipment				
	Sat	afety Equipment								
		Row Seat Position		-	SHOULDER & LAP I					
		01 - FRONT ROW		07 - LEFT						
		Helmet Use			Helmet Compliance					
		Eye Protection			Tint Compliance Airbag					
	-									
6	00	Les la com a		RENT INJURY						
		Ejected	Ej	ection Path				Trapped/Extricated		
		NOT EJECTED NOT EJECTED/NOT AP		PLIC	CABLE		NOT TRAPPED			
		Medical Transport			I	EMS Agency Identifier		EMS Run #		
		NOT TRANSPORTED								
		Hospital				Date of Death Time of Death				
		L	Distracted 8	SV Source						
		Distracted By	OTHER D	ISTRACTION (ANIMA	L, F	DOD, GROOMING)				
		Distracted By Action			-					
			OOKING	AWAY FROM TASK E	ETC)					
				T 1 ·				Crash Data	10/00/0000	

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 3 of 4

6TL0DBC3FK

22-12950

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motorist	Striking Unit #	Location					
		Prior Action							
UNIT	INDIVIDUAL	Action							
		Action Other						To/From School	
	L	Drug & Alcohol	Suspected Alco		Suspected Drug Use				
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results		
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results			
0	001	Drug Type							
		Individual Condition	/ Δ1						
		Violations	1						
	6	UTC Number BG112956	Issue To? 001	Statute Number 346.89(1)	Description INATTENTIVE DRIV	ING			