6TL0D1PTMZ

22-12709

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Primary Crash D Crash Time 09:30 PM	Document #	Agency 22-127 Date Ar	Crash Number 7 09		Officer/Deputy			
09:30 PM		Date Ar						
+		12/20/2		Time Arrived 02:50 PM				
Time Notified 02:19 PM		Total Units 01		Total Injured Total Killed 00 00		ed		
t and Run	and Run 🛛 Lane Closu		Work Zone	Trailer or Towed		Reporting Threshold		
Crash Date Crash Time 12/18/2022 09:30 PM Date Notified Time Notified 12/20/2022 02:19 PM On Emergency Hit and Run Government Property Property Active School Zone				Tags				
Crash Type DT4000 (STA	NDARD CRASH	l)		Amende	ed	Secondary Crash		
ees, coming					Photos By	·		
LY 9:30 PM, UNIT ' INIT 1 WAS WEST	1, A 2018 BLUE CH BOUND ON LUEDT	EVROLET KE ROAD	CRUZE BEARING WI # / D. THE POSTED SPEED L	APM1226 WAS BE IMIT WAS 45 MPI	I. THE ROAD V	VAS SNOW COVERED AND		
	Active Sc Crash Type DT4000 (STA	Active School Zone Crash Type DT4000 (STANDARD CRASH itch and ees, coming Glides Frough curve Crash Type DT4000 (STANDARD CRASH Crash Type DT4000 (STANDARD CRASH CLY 9:30 PM, UNIT 1, A 2018 BLUE CH INIT 1 WAS WEST BOUND ON LUEDT VE, UNIT 1 SLIDE ACROSS THE ROA		Active School Zone School Bus Related NO Crash Type DT4000 (STANDARD CRASH) Not to scale Not to scale	Active School Zone NO Tags Crash Type DT4000 (STANDARD CRASH) Amenda Not to scale N	Active School Zone School Bus Related NO Tags Crash Type DT4000 (STANDARD CRASH) Amended Not to scale Photos By Additional Info NONE Additional Info Sides O1 Luedtke Road Luedtke Road		

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. $1 \quad \text{of} \quad 5$

22-12709

WISCONSIN MOTOR VEHICLE CRASH REPORT

Lo	cation									
	LUEDTKE RD				Latitude			Longitu	de	
123	34 FT S				43.5623962	205		-90.059	9102453	
-	KATUIN RD			-	X Coordinate)		Y Coord	dinate	
	THE TOWN OF WINFIE SAUK COUNTY	LD			252937.687	75	4827818.5		18.5	
	SAUK COUNT I			-	Structure Typ	be				
					NO STRUC	TURE				
Cra	ash Scene 📃									
Firs	t Harmful Event				First Harmful	Event Lo	ocation			
DIT	СН				SHOULDE	R LEFT				
	nner of Collision				Light Condition					
		EHICLE IN TRANSPORT			DARK/UNL					
Roa	ad Surface Condition(s)				Roadway Fa	ctor(s)				
SN	OW, ICE									
Env	vironment Factor(s)									
NO	NE				ROAD SUF ETC)	RFACE	CONDITION	(WET, IC	CY, SNOW, SLUSH,	
We	ather Condition(s)				210)					
	EAR									
Anii	mal Type				Relation To 1			D		
Cro	sh Classification - Location							T ON ROAD		
	BLIC PROPERTY				Crash Classification - Jurisdiction NO SPECIAL JURISDICTION					
Trib	al Land				Access Control Special Study				Special Study	
					NO CONTROL					
Within Interchange Area Junction Location Interse					ection Type					
NO		NON-JUNCTION		NOT AN I	NTERSECT	ΓΙΟΝ				
	it Summary 🛛 💻									
	t Status			-	Classification Unit Type					
	TRANSIT		D CLASS				AUTOMOBILE			
							Operating As Endorsements			
	SSENGER CAR al Occs	Train/Bus # Recorded	Total # Cita	tions Issued	ed Total Traile		ilers Total HazMat Types		Mat Types	
2		Hall/Dus # Recorded	10tai # Cita 2	lions issued	0		515	0	imat Types	
	urance?	Direction Of Travel		One of Time	-	peed Lim	nit	Total Lan	es	
	KNOWN	WESTBOUND	Pre	CrashTire Mark		5	2			
Mos	st Harmful Event: Collision		Special Fun		[`		Emergency		icle Use	
TR	EE		NO SPEC	IAL FUNC	ΓΙΟΝ		NOT APP	LICABLE	i i i i i i i i i i i i i i i i i i i	
Tra	ffic Way		Traffic Cont	Traffic Control			Traffic Control Inoperative/Missing			
	O-WAY, NOT DIVIDED		NO CONT	ROL			NO Road Grade LEVEL			
	face Type		Road Curva							
	ACKTOP (BITUMINOU	S)	CURVE R	IGHT						
Tru NO	ck Bus or HazMat									
	Vehicle									
	License Plate Number		Plate Type	•	S	t	Country of Is	suance		
	APM1226		AUT - AUTOMOBI				UNITED STATES			
	Vehicle Identification Nu	Make			ear	Model				
0	1G1BE5SM2J714141	CHEVRO	CHEVROLET 2018			CRUZE				
	Color	, ,	Body Style			Bus Use				
	BLU - BLUE	SD - SED								
		Vehicle Damage								
Щ	Initial Contact Point								7 8 9 10 11	
IICLE	11 - LEFT FRONT CO	ORNER	09 - LEF	T SIDE MID			DE FRONT,	11 -	7 8 9 10 11 6 3 12	
EHICLE			09 - LEF LEFT FR		NER, 12 - F			11 -		

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

2 of 5



22-12709

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage		Vehicle Removed By					
					PERATOR ehicle Factors				
		NEGOTIATING CURVE	Ň						
		Driver Prior Action Other		N	IOT APPLICABLE				
		Driver Actions		•					
_	Е	SPEED TOO FAST/COND							
UNIT	VEHICLE								
2	μ								
	~								
		Owner Name			Owner Address				
2	01	NICHOLE (608) 566-5187	DECOR	AH	532 LAUREL ST REEDSBURG, W	53959 115			
•	0	(000) 500-5107			KEEDOBOKO, W	,00			
		Companya Of Franks							
		Sequence Of Events							
	0	CROSS CENTERLINE							
	02	Event DITCH							
	03	Event TREE							
	4	Event							
	40 Freir								
	1	ndividual							
		Driver ALLISON RAUPP			Citations Issued Sex				
	AL	(608) 495-9877	UFF		2 Date of Birth	FEMALE Race			
⊢	INDIVIDUAL				Date of Birth	WHITE			
NU	N	Address			Driver License Number	r			
-	ND	S2949 STATE ROAD 23 REEDSBURG, WI 53959,	us						
	_	, , , , , , , , , , , , , , , , , , , ,							
		On Duty	Crash		Safety Equipment				
	Saf	fety Equipment			SHOULDER & LAP BELT				
		Row	Seat Pos						
		01 - FRONT ROW	07 - LE	FT					
		Helmet Use	Helmet Use			Helmet Compliance			
		Eye Protection			Tint Compliance				
5	001	Injury Se	verity		Airbag				
0	ō	Injury NO API			DEPLOYED-COMBINATION				
			Ejection Pat	n CTED/NOT APPL			Trapped/Extricated NOT TRAPPED		
		Medical Transport			EMS Agency Identifier		EMS Run #		
		NOT TRANSPORTED							
		Hospital			Date of Death		Time of Death		
		Distracted By	d By Source	1	1				
		Distracted By Action UNKNOWN							
		Striking	Jnit #	Location					
		Non Motorist							

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 3 of 5

6TL0D1PTMZ

22-12709

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action									
UNIT	NDIVIDUAL	Action									
	N										
		Action Other							To/From School		
	Ľ	Drug & Alcohol NO				Suspected Drug Use					
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type	1		Alcohol Test Results			
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test Results				
01	001	Drug Type					•				
		Individual Condition									
		NOT OBSERVED									
	L I	ndividual									
	_	Passenger ISABELLA OLSON				Citations Issued Sex 0 FEMALE					
⊢	DUA					Date of Birth	Race WHITE				
UNIT	INDIVIDUAL	Address 532 LAUREL ST REEDSBURG, WI 53959 , US				Driver License Number					
	Saf	On Duty Crash			Safety Equipment						
		Row Seat Position 01 - FRONT ROW 09 - RIGHT				SHOULDER & LAP	BELT				
		Helmet Use	I			Helmet Compliance					
		Eye Protection				Tint Compliance					
0	8 Injury NO APPARENT INJURY				NJURY	Airbag NON DEPLOYED					
		Ejected NOT EJECTED	Ejection Path					Trapped/Extricated NOT TRAPPED			
		Medical Transport NOT TRANSPORT	ED			EMS Agency Identifier		EMS Run #			
	Hospital					Date of Death		Time of Death			
	Distracted By Source										
		Distracted By Action									
		Non Motorist	Striking Ur	nit #	Location						
					This		0.4-1-	Crach Date	40/48/2022		

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 4 of 5

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Action						
	AL							
UNIT	INDIVIDUAL							
5	DIV							
	4							
		Action Other						To/From School
	L	Drug & Alcohol	Suspected Alco	hol Use	Suspected Drug Use			
	Alcohol Test Given Alcohol Test Ty				Alcohol Test Result			
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results		
2	002	Drug Type						
-	0							
		Individual Condition						
		APPEARED NORM	IAL					
	١	Violations						
	01	UTC Number BG024476	Issue To? 001	Statute Number 343.43(1)(d)	Description VIOLATE GDL REST	RICTIONS - PAS	SSENGER (1ST)	
	02	UTC Number BG024477	Issue To? 001	Statute Number 346.57(3)	Description DRIVING TOO FAST	FOR CONDITIO	NS	