

6TL092T5SM
23-00960

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL092T5SM

Document Number Override		Primary Crash Document#	Agency Crash Number 23-00960	Investigating Officer/Deputy DEPUTY A. KING	
Crash Date 01/29/2023		Crash Time 01:24 AM	Date Arrived 01/29/2023	Time Arrived 01:36 AM	
Date Notified 01/29/2023		Time Notified 01:25 AM	Total Units 01	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input type="checkbox"/> Reportable	Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash	

Description

Diagram <p style="text-align: center;">non-reportable slide off</p>	Reconstruction By
	Photos By
	Additional Information

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

Location

ON LYNDON RD 12 FT N OF CTHP SB IN THE TOWN OF DELLONA IN SAUK COUNTY	Latitude 43.590750684	Longitude -89.847343432
	X Coordinate 270148.6875	Y Coordinate 4830359.5
	Structure Type	

6TL092T5SM
23-00960

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Crash Scene

First Harmful Event DITCH		First Harmful Event Location ROADSIDE	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT		Light Condition DARK/UNLIT	
Road Surface Condition(s) SNOW		Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS			
Weather Condition(s) SNOW			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control PARTIAL CONTROL	Special Study
Within Interchange Area YES	Junction Location INTERSECTION	Intersection Type T-INTERSECTION	

Unit Summary

UNIT 01	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 45	Total Lanes 2	
	Most Harmful Event: Collision With DITCH		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control STOP SIGN		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade DOWNHILL	
	Truck Bus or HazMat NO					

Sequence Of Events

UNIT 01 02 03 04	Event DITCH
	Event
	Event
	Event

Policy Holder

Insurance Company UNKNOWN	Name
-------------------------------------	------

Individual

IT INDIVIDUAL	Individual	Citations Issued	Sex
		Date of Birth	Race

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UN	INDIV	Address		Driver License Number					
		Safety Equipment		On Duty Crash	Safety Equipment				
		Row		Seat Position					
		Helmet Use		Helmet Compliance					
		Eye Protection		Tint Compliance					
		01	001	Injury		Injury Severity	Airbag		
				Ejected		Ejection Path	Trapped/Extricated		
				Medical Transport		EMS Agency Identifier	EMS Run #		
				Hospital		Date of Death	Time of Death		
				Distracted By		Distracted By Source			
Distracted By Action									
Non Motorist				Striking Unit #	Location				
Prior Action									
Action									
UNIT	INDIVIDUAL			Action Other				To/From School	
		Drug & Alcohol		Suspected Alcohol Use		Suspected Drug Use			
		Alcohol Test Given		Alcohol Test Type		Alcohol Test Results			
		Drug Test Given		Drug Test Type		Drug Test Results			
		Drug Type							
		01	001	Individual Condition					