6TL0BNZM57 23-01880

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT **BARABOO, WI 53913** (608) 356-4895

	Document Number Override	Primary Crash Document# Crash Time 11:18 PM		Agency Crash Number 23-01880 Date Arrived 02/22/2023		Investigating Officer/Deputy DEPUTY K. RENZ Time Arrived 11:50 PM			
157	Crash Date 02/22/2023								
NZN	Date Notified 02/22/2023	Time Notified 11:22 PM		Total Units 01		Total Injured 00	Total Killed 00		
0.08	On Emergency Hi	t and Run	Lane Closu	ıre	☐ Work Zone	Trailer or	Towed		Reporting Threshold
6T L	Government Property	Active School Zone		School Bus Related NO		Tags			
	□ Crash Type □ DT4000 (STANDARD CRASH))		Amended			Secondary Crash

Description Diagram Reconstruction By Photos By RENZ 9148 Additional Information **PHOTOS** Not drawn to scale

| I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 2/22/2023 AT APPROXIMATELY 11:18 P.M., UNIT 1 WAS TRAVELING WESTBOUND ON HWY 154. UNIT 1 BEGAN LOSING CONTROL DUE TO THE SNOW AND ICE ON THE ROADWAY. UNIT 1 BEGAN SLIDING AND ENTERED THE DITCH ON THE NORTH SIDE OF THE ROAD. UNIT 1 SUSTAINED MINOR DAMAGE TO THE FRONT OF THE VEHICLE. THERE WERE NO REPORTED INJURIES BY THE LONE OCCUPANT. UNIT 1 WAS REMOVED FROM THE SCENE BY CRAIG'S TOWING.

Crash Time 11:18 PM

1 of 4

Crash Date 02/22/2023

6TL0BNZM57 23-01880

Location

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/22/2023

Crash Time 11:18 PM

	ON STH154 WB					Latitude 43.482034997		Longitude -89.988934469	
	OF GROTE HILL RD IN THE TOWN OF REEDS	X Coordinate	X Coordinate		Y Coord 481868	linate			
	IN SAUK COUNTY			Structure Type NO STRUCTURE		401000	4010000.3		
	Crash Scene			no o mo	010112				
	_			T=:		.,			
	First Harmful Event DITCH			First Harmfu ROADSIDI	E	ocation			
	Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT				Light Condition DARK/UNLIT				
	Road Surface Condition(s)				Roadway Factor(s)				
	WET, SNOW, SLUSH, ICE	WET, SNOW, SLUSH, ICE							
	Environment Factor(s)			7					
	WEATHER CONDITIONS			ROAD SUI	RFACE C	CONDITION	(WET, IC	Y, SNOW, SLUSH,	
	Weather Condition(s) SNOW, FREEZING RAIN OR FREEZING DRIZZLE								
	Animal Type				Relation To Trafficway TRAFFICWAY - ON ROAD				
	Crash Classification - Location PUBLIC PROPERTY				Crash Classification - Jurisdiction NO SPECIAL JURISDICTION				
	TribalLand			Access Con				Special Study	
	Within Interchange Area NO	Junction Location NON-JUNCTION		Intersection Type NOT AN INTERSECTION					
	Unit Summary -								
	Unit Status Vehicle Operating As C				· · · · · · · · · · · · · · · · · · ·				
	Unit Status			Classification		1	Du =		
_			Vehicle Operating As (Classification		Unit Type AUTOMO Operating A		ments	
٤	Unit Status IN TRANSIT	E		Classification		AUTOMO		ments	
_	Unit Status IN TRANSIT Vehicle Type	. E Train/Bus#Recorded			Total Traile	AUTOMO Operating A	s Endorse	ments Mat Types	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance?	Train/Bus#Recorded Direction Of Travel	Total#Citations Issue 0 Pre CrashTin	d (0 Speed Lim	AUTOMO Operating A	S Endorsei Total Haz 0 Total Land	MatTypes	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total#Citations Issue 0 Pre CrashTir Mark	d (0	AUTOMO Operating A ers	Total Haz Total Lane 2	MatTypes es	
_	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V	Train/Bus#Recorded Direction Of Travel WESTBOUND	Total#Citations Issue 0 Pre CrashTin	d (0 Speed Lim	AUTOMO Operating A ers nit Emergency NOT APP	Total Haz 0 Total Lane 2 Motor Veh	MatTypes es icle Use	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision W	Train/Bus#Recorded Direction Of Travel WESTBOUND With	Total#Citations Issue 0 Pre CrashTir Mark Special Function	d (0 Speed Lim	AUTOMO Operating A ers iit Emergency	Total Haz 0 Total Lane 2 Motor Veh	MatTypes es icle Use	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Citations Issue 0 Pre CrashTir Mark Special Function NO SPECIAL FUNC	d (0 Speed Lim	AUTOMO Operating A ers it Emergency NOT APP Traffic Conf	Total Haz 0 Total Lane 2 Motor Veh LiCABLE	MatTypes es icle Use	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS Total # Citations Issue 0 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature	d (0 Speed Lim	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lane 2 Motor Veh LiCABLE	MatTypes es icle Use	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS Total # Citations Issue 0 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature	d (0 Speed Lim	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lane 2 Motor Veh LiCABLE	MatTypes es icle Use	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS Total#Citations Issue 0 Pre CrashTir Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT	d (0 Speed Lim 55	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz Total Lane Total Lane Motor Veh LICABLE rol Inopera	MatTypes es icle Use	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total # Citations Issue 0 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI	ction	D Speed Lim 555	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lane 2 Motor Veh LICABLE rol Inopera	MatTypes es icle Use	
04	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS) Truck Bus or HazMat NO Vehicle License Plate Number ASE5375 Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel WESTBOUND With	D CLASS Total # Citations Issue 0 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBIL	CTION SELE Y	D Speed Lim 555 Sit WI 'ear	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of is UNITED S	Total Haz 0 Total Lane 2 Motor Veh LICABLE rrol Inopera	MatTypes es icle Use	
UNIT 01	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number ASE5375 Vehicle Identification Nur SALYM2EV6LA26738 Color	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total#Citations Issue 0 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB! Make LAND ROVER Body Style	CTION SELE Y 2	Speed Lin 555 Sit VI Year	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S	Total Haz 0 Total Lane 2 Motor Veh LICABLE rrol Inopera	MatTypes es icle Use	
UNIT 01	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number ASE5375 Vehicle Identification Nur SALYM2EV6LA26738 Color BLK - BLACK	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total#Citations Issue 0 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOBI Make LAND ROVER Body Style UT - SPORT UTIL	CTION SELE Y 2	Speed Lin 555 Sit VI Year	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model RANGE RO	Total Haz 0 Total Lane 2 Motor Veh LICABLE rrol Inopera	MatTypes es icle Use	
UNIT 01	Unit Status IN TRANSIT Vehicle Type (SPORT) UTILITY VEHICL Total Occs 1 Insurance? YES Most Harmful Event: Collision V DITCH Traffic Way TWO-WAY, NOT DIVIDED Surface Type BLACKTOP (BITUMINOUS Truck Bus or HazMat NO Vehicle License Plate Number ASE5375 Vehicle Identification Nur SALYM2EV6LA26738 Color	Train/Bus # Recorded Direction Of Travel WESTBOUND With	Total#Citations Issue 0 Pre CrashTin Mark Special Function NO SPECIAL FUNC Traffic Control NO CONTROL Road Curvature STRAIGHT Plate Type AUT - AUTOMOB! Make LAND ROVER Body Style	CTION SELE Y 2	Speed Lin 555 Sit VI Year	AUTOMO Operating A ers Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model RANGE RO	Total Haz 0 Total Lane 2 Motor Veh LICABLE rrol Inopera	MatTypes es icle Use	

6TL0BNZM57

23-01880

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By CRAIGS TOWING						
		What Driver Was Doing GOING STRAIGHT Driver Prior Action Other		Vehicle Factors						
				NOT APPLICABLE						
TINO	VEHICLE	Driver Actions SPEED TOO FAST/COND								
۶	10	Owner Name VIBHASH KUMAR (608) 739-2812		Owner Address 134 E RICHARDS I OREGON, WI 5357						
		Sequence Of Events								
	5	Event DITCH								
	8	Event								
	03	Event								
	3	Event								
 -		Policy Holder								
N N		Insurance Company STATE-FARM-GENERAL-INS-CO		Individual VIBHASH KUMAR						
		individual	valiurat							
		Driver VIBHASH KUMAR (608) 739-2812 Address 134 E RICHARDS RD # 3 OREGON, WI 53575 , US		Citations Issued	, , , , , , , , , , , , , , , , , , , 					
	JEML			0	Sex MALE					
_				Date of Birth	Race ASIAN OR NATIVE HAWAIIAN OR OTHER PACIFIC ISLAN					
TNO.	INDNI			Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES						
	Sai	On Dut	y Crash	Safety Equipment	Safety Equipment					
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT						
		HelmetUse		Helmet Compliance						
	Eye Protection			TintCompliance						
٦	8	Injury Severity Injury NO APPARENT INJURY		Airbag NON DEPLOYED						
		Ejected Ejection Path NOT EJECTED NOT EJECTED/NOT AP				Trapped/Extricated NOT TRAPPED				
		Medical Transport		EMS Agency Identifier		EMS Run#				
		NOT TRANSPORTED		D-4-4/2						
		Hospital		Date of Death Time of Death		Time of Death				
		Distracted By NOT A	ted By Source APPLICABLE (NOT DISTF	RACTED)						
		Distracted By Action NOT DISTRACTED								

Crash Date 02/22/2023
Crash Time 11:18 PM

6TL0BNZM57 23-01880

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 02/22/2023

Crash Time 11:18 PM

	Non Motorist	Location				
	Prior Action					
UNIT	Action					
	Action Other					To/From School
	Drug & Alcohol NO	cohol Use	Suspected Drug Use NO			
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	e		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	3	
2 2	Drug Type	·				
	Individual Condition APPEARED NORMAL					