

6TL0B3P3K2  
SC23-02234

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

6TL0B3P3K2

Document Number Override		Primary Crash Document #		Agency Crash Number <b>SC23-02234</b>		Investigating Officer/Deputy <b>DEPUTY J. GREENWOOD</b>	
Crash Date <b>03/06/2023</b>		Crash Time <b>08:10 AM</b>		Date Arrived <b>03/06/2023</b>		Time Arrived <b>08:31 AM</b>	
Date Notified <b>03/06/2023</b>		Time Notified <b>08:16 AM</b>		Total Units <b>01</b>		Total Injured <b>00</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency		<input type="checkbox"/> Hit and Run		<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	
<input type="checkbox"/> Trailer or Towed		<input type="checkbox"/> Reporting Threshold					

Description

Diagram		Reconstruction By	
<p>Trout RD</p> <p>Not to Scale</p>		Photos By <b>DEPUTY GREENWOOD</b>	
		Additional Information <b>PHOTOS</b>	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS TRAVELING EASTBOUND ON TROUT RD AND LOST CONTROL EXITING A CURVE DUE TO SLIPPERY ROADS. UNIT 1 ENTERED THE SOUTH DITCH CAUSING DAMAGE.

**Location**

ON TROUT RD 889 FT E OF IH90 EB IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude <b>43.612004677</b>	Longitude <b>-89.80380617</b>
	X Coordinate <b>273743.125</b>	Y Coordinate <b>4832600.5</b>
	Structure Type <b>NO STRUCTURE</b>	

**Crash Scene**

First Harmful Event <b>DITCH</b>	First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>00 - NO COLLISION W/VEHICLE IN TRANSPORT</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>SNOW, SLUSH</b>	Roadway Factor(s)  <b>ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)</b>	
Environment Factor(s) <b>WEATHER CONDITIONS</b>		
Weather Condition(s) <b>CLOUDY, RAIN, FOG</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

**Unit Summary**

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>	
	Vehicle Type <b>PASSENGER CAR</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>1</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>NO</b>	Direction Of Travel <b>EASTBOUND</b>	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>DITCH</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>		Road Grade <b>DOWNHILL</b>	
	Truck Bus or HazMat <b>NO</b>				

**Vehicle**

<b>UNIT</b>	<b>VEHICLE</b>	License Plate Number <b>AKT6019</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>1B3HE78K77D229928</b>	Make <b>DODGE</b>	Year <b>2007</b>	Model <b>CALIBER</b>
		Color <b>RED - RED</b>	Body Style <b>HB - HATCHBACK</b>		Bus Use
		Initial Contact Point <b>01 - RIGHT FRONT CORNER</b>	Vehicle Damage <b>01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 03 - RIGHT SIDE MIDDLE, 04 - RIGHT SIDE REAR</b>		
		Extent Of Damage <b>DISABLING DAMAGE</b>			



UNIT	Towed Due To Damage <b>TOWED DUE TO DISABLING DAMAGE</b>		Vehicle Removed By <b>PLATTS WRECKER</b>		
	What Driver Was Doing <b>GOING STRAIGHT</b>		Vehicle Factors		
	Driver Prior Action Other		<b>NOT APPLICABLE</b>		
	Driver Actions <b>SPEED TOO FAST/COND</b>				
01	01	Owner Name <b>MELINDA CLARK</b>		Owner Address <b>420 S WALNUT ST REEDSBURG, WI 53959 , US</b>	
		<b>Sequence Of Events</b>			
01	01	Event <b>DITCH</b>			
		Event			
		Event			
		Event			
01	01	<b>Individual</b>			
		Driver <b>CYLE KELTNER (608) 547-2662</b>		Citations Issued <b>1</b>	Sex <b>MALE</b>
		Address <b>715 S ADAMS ST NEW LISBON, WI 53950 , US</b>		Date of Birth	Race <b>WHITE</b>
				Driver License Number	
01	001	<b>Safety Equipment</b>		Safety Equipment	
		On Duty Crash			
		Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>	
		Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance			
<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	Airbag <b>NON DEPLOYED</b>		
Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>		Trapped/Extricated <b>NOT TRAPPED</b>	
Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
<b>Distracted By</b>		Distracted By Source <b>NOT APPLICABLE (NOT DISTRACTED)</b>			
<b>Distracted By Action</b>		<b>NOT DISTRACTED</b>			
<b>Non Motorist</b>		Striking Unit #	Location		

UNIT	Prior Action			
	Action			
	Action Other			To/From School
	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>
	Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results
	Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results
	Drug Type			
	Individual Condition <b>APPEARED NORMAL</b>			
	<b>Violations</b>			
	01	UTC Number <b>BC937269</b>	Issue To? <b>001</b>	Statute Number <b>343.44(1)(a)</b>