


6TL0BJ1GNG

Document Number Override		Primary Crash Document #		Agency Crash Number 23-03873		Investigating Officer/Deputy DEPUTY J. MACASKILL	
Crash Date 04/20/2023		Crash Time 02:00 PM		Date Arrived 04/20/2023		Time Arrived 02:10 PM	
Date Notified 04/20/2023		Time Notified 02:06 PM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input type="checkbox"/> Reportable		Crash Type PRIVATE PROPERTY/PARKING LOT				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By	
 <p style="text-align: center;">Unit 1 Unit 1</p> <p style="text-align: center;">Unit 2</p> <p style="text-align: center;">Walgreens Drive-thru</p> <p style="text-align: right;">Not Drawn to Scale</p>		Photos By	
		Additional Information NONE	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 4/20/23 AT APPROXIMATELY 1400, UNIT 1 BACKED INTO UNIT 2 WHILE THEY WERE BOTH IN THE DRIVE-THRU LINE AT WALGREENS. OPERATOR OF UNIT 1 STATED THEY DIDN'T KNOW THERE WAS ANYONE BEHIND THEM WHILE BACKING UP. BOTH OPERATORS INITIALLY REPORTED NO DAMAGE.

Location

PARKING LOT CTHBD NB LOT IN THE VILLAGE OF WEST BARABOO IN SAUK COUNTY	Latitude 43.475340204	Longitude -89.769275237
	X Coordinate 276023.9375	Y Coordinate 4817328.5
	Structure Type	

Crash Scene

First Harmful Event PARKED MOTOR VEHICLE		First Harmful Event Location IN PARKING LANE OR ZONE	
Manner of Collision 03 - FRONT TO REAR		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway NON TRAFFICWAY - PARKING LOT	
Crash Classification - Location PRIVATE PROPERTY		Crash Classification - Jurisdiction PRIVATE PROPERTY	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	

Unit Summary

UNIT	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit	Total Lanes	
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way PARKING LOT OR PRIVATE PROPERTY		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature		Road Grade LEVEL	
	Truck Bus or HazMat NO					

Vehicle

UNIT	VEHICLE	License Plate Number ADR7176				Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 1GNKRHKD4FJ296051				Make CHEVROLET	Year 2015	Model TRAVERSE
		Color GRY - GRAY				Body Style UT - SPORT UTILITY VEHICLE		Bus Use
		Initial Contact Point 06 - REAR				Vehicle Damage		
		Extent Of Damage NO DAMAGE				00 - NO DAMAGE		



WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR	
	What Driver Was Doing BACKING		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions UNSAFE BACKING			
01 01	Owner Name CHRISTINA ESPINOZA (920) 229-2371		Owner Address 2045 VIKING DR REEDSBURG, WI 53959 , US	
	Sequence Of Events			
01 02 03 04	Event PARKED MOTOR VEHICLE			
	Event			
	Event			
	Event			
UNIT	Policy Holder			
	Insurance Company PROGRESSIVE-CLASSIC-INS-CO		Individual CHRISTINA ESPINOZA	
UNIT INDIVIDUAL	Individual			
	Driver CHRISTINA ESPINOZA (920) 229-2371		Citations Issued 0	Sex FEMALE
	Address 2045 VIKING DR REEDSBURG, WI 53959 , US		Date of Birth	Race HISPANIC
			Driver License Number	
01 001	Safety Equipment		On Duty Crash	
			Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source UNKNOWN		
Distracted By Action		UNKNOWN		

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
	Action Other					To/From School	
	01	001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
			Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
			Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
			Drug Type				
			Individual Condition NOT OBSERVED				

Unit Summary

UNIT	02	Unit Status LEGALLY PARKED		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
		Vehicle Type PASSENGER CAR					Operating As Endorsements	
		Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0		
		Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre Crash Tire Mark		Speed Limit	Total Lanes	
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT			Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way PARKING LOT OR PRIVATE PROPERTY			Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature		Road Grade LEVEL	
		Truck Bus or HazMat NO						

UNIT	VEHICLE	Vehicle						
		License Plate Number 55713DS		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES		
		Vehicle Identification Number 3C4PDDBG5HT574189		Make DODGE	Year 2017	Model JOURNEY		
		Color BLU - BLUE		Body Style UT - SPORT UTILITY VEHICLE		Bus Use		
		Initial Contact Point 12 - FRONT		Vehicle Damage				
		Extent Of Damage NO DAMAGE		00 - NO DAMAGE				
		Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR				

UNIT VEHICLE	What Driver Was Doing LEGALLY PARKED		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions NO CONTRIBUTING ACTION			
	Owner Name DONALD KELLER (608) 415-8639		Owner Address 707 ELLIS AVE BARABOO, WI 53913 , US	
02 02	Sequence Of Events			
	01	Event MOTOR VEH IN TRANSPORT		
	02	Event		
	03	Event		
04	Event			
UNIT	Policy Holder			
	Insurance Company LIBERTY-MUTUAL-INS-CO		Individual DONALD KELLER	
UNIT INDIVIDUAL	Individual			
	Passenger DONALD KELLER (608) 415-8639		Citations Issued 0	Sex MALE
	Address 707 ELLIS AVE BARABOO, WI 53913 , US		Date of Birth	Race WHITE
			Driver License Number	
02 002	Safety Equipment		On Duty Crash	
			Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag UNKNOWN
Ejected UNKNOWN		Ejection Path UNKNOWN		Trapped/Extricated UNKNOWN
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source		
Distracted By Action				
Non Motorist		Striking Unit #	Location	

UNIT	Prior Action		
	Action		
	Action Other		To/From School
	Drug & Alcohol		
	Suspected Alcohol Use NO		Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results
	Drug Type		
	Individual Condition NOT OBSERVED		
	02	002	