#### 6TL0D0GSL8 23-04951

Wisconsin Motor Vehicle Crash

Form DT4000

#### **WISCONSIN MOTOR VEHICLE CRASH REPORT**

SAUK COUNTY SHERIFFS DEPARTMEN **1300 LANGE COURT BARABOO, WI 53913** (608) 356-4895

Crash Date 05/18/2023

	Document Number Override	Primary Crash Document #  Crash Time 08:52 PM		Agency Crash Number 23-04951  Date Arrived 05/18/2023		Investigating Officer/Deputy DEPUTY G. AKERS				
ρ	Crash Date <b>05/18/2023</b>					Time Arrived 09:01 PM				
<b>ELLODOGSL</b>	Date Notified <b>05/18/2023</b>	Time Notified 08:56 PM	Time Notified		Inits	Total Injured 01	Total Injured Total Kill		ed	
ב בי	On Emergency Hi	t and Run Lane Closu		ure Work Zone School Bus Related NO		Trailer or Towed		Reporting Threshold		
	Government Property					Tags				
	<b>▼</b> Reportable	Crash Type DT4000 (STA	ANDARD CRASH	<b>1</b> )		Amend	led			Secondary Crash
	Diagram  I, a sworn law enforcement  V1 WAS TRAVELING SOUTH ON CHOWEVER THE VEHICLE CROSSE	TY RD H. THE DF	RIVER STATED THA	AT HE BE	GAN TO NOT FEEL WELL	_, THE DRIVER AT	Add PH	ditional Infor	rmation	EVEHICLE OVER.

### 6TL0D0GSL8 23-04951

Location

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/18/2023

	108 OF	CTHH SB 2 FT N CTHP SB			Latitude 43.594875474  X Coordinate 265290.9375			Longitude -89.907716313  Y Coordinate		
		THE TOWN OF DELLON SAUK COUNTY	IA				4830986.5			
					S	Structure Type				
	Cra	sh Scene								
	First	t Harmful Event			F	irst Harmful Event	Location			
	DIT	СН			R	ROADSIDE				
		ner of Collision				Light Condition				
		NO COLLISION W/VEH	IICLE IN TRANSPORT			DUSK				
	Roa	d Surface Condition(s)			Roadway Factor(s)					
	DR	Υ								
	Envi	ironment Factor(s)								
	NOI	NE .			l <sub>N</sub>	IONE				
		ather Condition(s)								
	CLC	YDUC								
	Anin	nal Type			R	Relation To Trafficway				
					Т	RAFFICWAY - 0	ON ROAD			
		ash Classification - Location				rash Classification				
		BLIC PROPERTY				NO SPECIAL JURISDICTION				
	I riba	al Land				Access Control Special Study			Special Study	
	\\/i+b	nin Interchange Area	Junction Location		Intersection 7	NO CONTROL				
	NO	=	NON-JUNCTION			N INTERSECTION				
		t Summary Status		Vehicle Ope	rating As Clas	sification	Unit Type			
	IN TRANSIT									
	IN T	TRANSIT		D CLASS	5		TRUCK			
_		TRANSIT icle Type						As Endorser	ments	
10	Vehi		RUCK				TRUCK	As Endorser	ments	
<b>1</b> 0	Vehi <b>UTI</b>	icle Type	RUCK Train/Bus # Recorded	D CLASS  Total # Citati		Total Tra	TRUCK Operating A		ments Mat Types	
6	Vehi UTI Tota 1	icle Type LITY TRUCK/PICKUP T al Occs	Train/Bus # Recorded	D CLASS		Total Tra	TRUCK Operating A	Total Haz	Mat Types	
01	Vehi UTI Tota 1 Insu	icle Type  LITY TRUCK/PICKUP T al Occs  irance?	Train/Bus # Recorded  Direction Of Travel	Total # Citati	ions Issued	Total Tra  0 Speed L	TRUCK Operating A	Total Haz  0 Total Lane	Mat Types	
10	Vehi UTII Tota 1 Insu	icle Type  LITY TRUCK/PICKUP T al Occs  irance?	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	Total # Citati	ions Issued CrashTire Mark	Total Tra	TRUCK Operating A	Total Haz  0 Total Lane 2	Mat Types es	
	Vehi UTII Tota 1 Insu NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	Total # Citati 2 Pre ( Special Fund	ions Issued CrashTire Mark	Total Tra 0 Speed L 55	TRUCK Operating A	Total Haz  0 Total Land 2 Motor Vehi	Mat Types es	
	Vehi UTII Tota 1 Insu NO Mos TRE	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	Total # Citati 2 Pre ( Special Fund	ions Issued  CrashTire  Mark  ction  IAL FUNCTIO	Total Tra 0 Speed L 55	TRUCK Operating A ailers imit Emergency NOT APP	Total Haz  0 Total Land 2 Motor Vehi	Mat Types es	
	Vehi UTII Tota 1 Insu NO Mos TRE	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	D CLASS  Total # Citati 2  Pre (  Special Fund NO SPECI	ions Issued  CrashTire  Mark ction IAL FUNCTIO	Total Tra 0 Speed L 55	TRUCK Operating A ailers imit Emergency NOT APP	Total Haz  0 Total Land 2 Motor Vehi	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos TRE Traff	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W  EE  fic Way	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	D CLASS  Total # Citati 2  Pre ( Special Func NO SPECI Traffic Contr	ions Issued  CrashTire  Mark  ction  IAL FUNCTION  ROL	Total Tra 0 Speed L 55	TRUCK Operating A ailers imit Emergency NOT APP Traffic Conf	Total Haz  0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos: TRE Traff TW( Surf: BLA	icle Type  LITY TRUCK/PICKUP T al Occs  Irrance?  It Harmful Event: Collision W EE fiic Way  O-WAY, NOT DIVIDED face Type  ACKTOP (BITUMINOUS	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	D CLASS  Total # Citati 2  Pre ( Special Func NO SPECI  Traffic Contr NO CONTI	ions Issued  CrashTire  Mark ction IAL FUNCTION ROL	Total Tra 0 Speed L 55	TRUCK Operating A  ailers  imit  Emergency NOT APP  Traffic Cont	Total Haz  0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos TRE Traff TWG Surfa	icle Type  LITY TRUCK/PICKUP T al Occs  strance?  st Harmful Event: Collision W EE fic Way  O-WAY, NOT DIVIDED face Type  ACKTOP (BITUMINOUS sk Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI  Traffic Contr NO CONTI Road Curvat	ions Issued  CrashTire  Mark ction IAL FUNCTION ROL	Total Tra 0 Speed L 55	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz  0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos TRE Traff TWO Surfa BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED face Type  ACKTOP (BITUMINOUS ck Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI  Traffic Contr NO CONTI Road Curvat	ions Issued  CrashTire  Mark ction IAL FUNCTION ROL	Total Tra 0 Speed L 55	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz  0 Total Land 2 Motor Vehi LICABLE	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos TRE Traff TWO Surfa BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W  EE fic Way  O-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  ck Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI Traffic Contr NO CONTI Road Curvat CURVE RI	ions Issued  CrashTire  Mark ction IAL FUNCTION ROL	Total Tra 0 Speed L 55	TRUCK Operating A ailers imit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz  0 Total Land 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos TRE Traff TWO Surfa BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W EE fic Way  O-WAY, NOT DIVIDED face Type  ACKTOP (BITUMINOUS ck Bus or HazMat  Vehicle  License Plate Number	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI Traffic Contr NO CONTI Road Curvat CURVE RI	ions Issued  CrashTire  Mark  ction  IAL FUNCTION  FOL  ture  GHT	Total Tra 0 Speed L 55	TRUCK Operating A ailers imit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL	Total Haz  0 Total Land 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos TRE Traff TWO Surfa BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irrance?  It Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED face Type  ACKTOP (BITUMINOUS  ck Bus or HazMat  Vehicle  License Plate Number  UD5663	Train/Bus # Recorded  Direction Of Travel  SOUTHBOUND  ith	D CLASS  Total # Citati 2  Pre ( Special Func NO SPECI Traffic Contr NO CONTI Road Curvat CURVE RI  Plate Type LTK - LIG	ions Issued  CrashTire  Mark ction IAL FUNCTION ROL	Total Tra 0 Speed L 55 ON	TRUCK Operating A ailers imit Emergency NOT APP Traffic Conf NO Road Grade LEVEL  Country of Is UNITED S	Total Haz  0 Total Land 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Mos TRE Traff TWO Surfa BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irrance?  It Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED  face Type  ACKTOP (BITUMINOUS  Sk Bus or HazMat  Vehicle  License Plate Number  UD5663  Vehicle Identification Num	Train/Bus # Recorded  Direction Of Travel SOUTHBOUND  ith	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI Traffic Contr NO CONTI Road Curvat CURVE RI	ions Issued  CrashTire  Mark  ction  IAL FUNCTION  FOL  ture  GHT	Total Tra 0 Speed L 55 ON	TRUCK Operating A ailers imit Emergency NOT APP Traffic Conf NO Road Grade LEVEL  Country of Is UNITED S' Model	Total Haz  0 Total Land 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Moss TRE Traff Two Surf: BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irrance?  It Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED face Type  ACKTOP (BITUMINOUS  ck Bus or HazMat  Vehicle  License Plate Number  UD5663	Train/Bus # Recorded  Direction Of Travel SOUTHBOUND  ith	D CLASS  Total # Citati 2  Pre ( Special Func NO SPECI Traffic Contr NO CONTI Road Curvat CURVE RI  Plate Type LTK - LIG Make	ions Issued  CrashTire  Mark  ction  IAL FUNCTION  FOL  ture  GHT	Total Tra 0 Speed L 55 ON	TRUCK Operating A ailers imit Emergency NOT APP Traffic Conf NO Road Grade LEVEL  Country of Is UNITED S	Total Haz  0 Total Land 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
	Vehi UTII Tota 1 Insu NO Moss TRE Traff Two Surf: BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  It Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  ix Bus or HazMat  Vehicle  License Plate Number  UD5663  Vehicle Identification Numi  1FTYR44E22PA80899	Train/Bus # Recorded  Direction Of Travel SOUTHBOUND  ith	Total # Citati 2  Pre ( Special Funch NO SPECI  Traffic Contr NO CONTI  Road Curvat CURVE RI  Plate Type LTK - LIG Make FORD	ions Issued  CrashTire  Mark ction IAL FUNCTION ROL ture GHT	Total Tra 0 Speed L 55 ON	TRUCK Operating A  ailers  imit  Emergency NOT APP  Traffic Cont NO  Road Grade LEVEL  Country of Is UNITED S' Model RANGER	Total Haz  0 Total Land 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use	
	Vehit UTII Tota 1 Insu NO Moss TRE Traff TWC Surfs BLA Truc NO	Icle Type  LITY TRUCK/PICKUP T al Occs  Irrance?  It Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED  Tace Type  ACKTOP (BITUMINOUS  Ick Bus or HazMat  Vehicle  License Plate Number  UD5663  Vehicle Identification Numi  1FTYR44E22PA80899  Color  GRN - GREEN  Initial Contact Point	Train/Bus # Recorded  Direction Of Travel SOUTHBOUND  ith	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI  Traffic Contr NO CONTI  Road Curvat CURVE RI  Plate Type LTK - LIG Make FORD Body Style	ions Issued  CrashTire  Mark ction IAL FUNCTION ROL ture GHT  GHT  GHT TRUCK	Total Tra 0 Speed L 55 ON	TRUCK Operating A  ailers  imit  Emergency NOT APP  Traffic Cont NO  Road Grade LEVEL  Country of Is UNITED S' Model RANGER	Total Haz  0 Total Land 2 Motor Vehi LICABLE trol Inoperat	Mat Types es icle Use tive/Missing	
	Vehit UTII Tota 1 Insu NO Moss TRE Traff TWC Surfs BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED  face Type  ACKTOP (BITUMINOUS  ix Bus or HazMat  Vehicle  License Plate Number  UD5663  Vehicle Identification Numi  1FTYR44E22PA80899  Color  GRN - GREEN  Initial Contact Point  12 - FRONT	Train/Bus # Recorded  Direction Of Travel SOUTHBOUND  ith	D CLASS  Total # Citati 2  Pre C Special Func NO SPECI Traffic Contr NO CONTI Road Curvat CURVE RI  Plate Type LTK - LIG Make FORD Body Style PK - PICK Vehicle Dar	ions Issued  CrashTire Mark ction IAL FUNCTION ROL ture GHT  SHT TRUCK  KUP mage	Total Tra 0 Speed L 55 ON  St WI Year 2002	TRUCK Operating A ailers imit  Emergency NOT APP Traffic Cont NO Road Grade LEVEL  Country of Is UNITED S' Model RANGER Bus Use	Total Haz 0 Total Lane 2 Motor Vehi LICABLE trol Inoperat e	Mat Types es icle Use tive/Missing	
	Vehit UTII Tota 1 Insu NO Moss TRE Traff TWC Surfs BLA Truc NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED face Type  ACKTOP (BITUMINOUS et Bus or HazMat  Vehicle  License Plate Number  UD5663  Vehicle Identification Num  1FTYR44E22PA80899  Color  GRN - GREEN  Initial Contact Point  12 - FRONT  Extent Of Damage	Direction Of Travel SOUTHBOUND  (ith	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI  Traffic Contr NO CONTI  Road Curvat CURVE RI  Plate Type LTK - LIG Make FORD Body Style PK - PICK Vehicle Dar  01 - RIGH	ions Issued  CrashTire Mark ction IAL FUNCTION ROL ture GHT  HT TRUCK  KUP mage HT FRONT C	Total Tra 0 Speed L 55 ON	TRUCK Operating A  ailers  imit  Emergency NOT APP  Traffic Cont NO Road Grade LEVEL  Country of Is UNITED S' Model RANGER Bus Use	Total Haz 0 Total Lane 2 Motor Vehi LICABLE trol Inoperat e	Mat Types es icle Use tive/Missing  7 8 9 10 11 6	
	Vehit UTII Tota 1 Insu NO Most TRE Truct NO	icle Type  LITY TRUCK/PICKUP T al Occs  irance?  it Harmful Event: Collision W  EE  fic Way  O-WAY, NOT DIVIDED  face Type  ACKTOP (BITUMINOUS  ix Bus or HazMat  Vehicle  License Plate Number  UD5663  Vehicle Identification Numi  1FTYR44E22PA80899  Color  GRN - GREEN  Initial Contact Point  12 - FRONT	Direction Of Travel SOUTHBOUND  (ith	D CLASS  Total # Citati 2  Pre ( Special Fund NO SPECI  Traffic Contr NO CONTI  Road Curvat CURVE RI  Plate Type LTK - LIG Make FORD Body Style PK - PICK Vehicle Dar  01 - RIGH	ions Issued  CrashTire Mark ction IAL FUNCTION ROL ture GHT  HT TRUCK  KUP mage HT FRONT C	Total Tra   0   Speed L   555   ON   St   WI   Year   2002	TRUCK Operating A  ailers  imit  Emergency NOT APP  Traffic Cont NO Road Grade LEVEL  Country of Is UNITED S' Model RANGER Bus Use	Total Haz 0 Total Lane 2 Motor Vehi LICABLE trol Inoperat e	Mat Types es icle Use tive/Missing	

## **6TL0D0GSL8** 23-04951

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/18/2023

		Towed Due To Damage		V	ehicle Removed By				
		TOWED DUE TO DISABLII	NG DAMA	GE F	PLATTS WRECKER				
	What Driver Was Doing NEGOTIATING CURVE			V	Vehicle Factors  NOT APPLICABLE				
	Driver Prior Action Other				IOI AFFLICABLE				
		Driver Actions		<u> </u>					
	щ	FAILURE TO CONTROL							
L	길								
5	VEHICLE								
	>								
		Owner Name			Owner Address				
_	_	GABRIEL MAGRIZ MARCH	ł		713 S PRESTON U				
2	9	(608) 477-8796			REEDSBURG, WI	53959 , US			
	Ş	Sequence Of Events Event							
	01	CROSS CENTERLINE							
	02	Event DITCH							
	03	Event TREE							
	04	Event							
	0								
	ı	Individual							
		Driver			Citations Issued				
	4	GABRIEL MAGRIZ MARCH			2	MALE			
_	INDIVIDUAL				Date of Birth	Race			
EN	Ĭ	Address			Driver License Number				
ر ر		713 S PRESTON UNIT 214			STATE: WISCONSIN COUNTRY: UNITED STATES				
	_	REEDSBURG, WI 53959 ,		STALE. MISSONSIN SOCIETATI. SINIES					
		On Duty	^rach		Safety Equipment				
	Saf	ety Equipment	Siasii		Safety Equipment				
		Row	Seat Position		SHOULDER & LAP BELT				
		01 - FRONT ROW	07 - LE	FT					
		Helmet Use			Helmet Compliance				
		Eye Protection			Tint Compliance				
_	Ξ,	Injury Severity			Airbag				
6	90			IOR INJURY	NON DEPLOYED				
		*	Ejection Pa		IOADI E		Trapped/Extricated		
		NOT EJECTED NOT EJECTED/NOT APP  Medical Transport		EMS Agency Identifier		NOT TRAPPED  EMS Run #			
					6001024		REPD2305927		
				Date of Death Time of Death		Time of Death			
		SIXTY-FOURTH STREET L							
		Distracted By NOT AF	d By Source PLICABL	E (NOT DISTRAC	CTED)				
		NOT DISTRACTED							
		Non Motorist Striking U	Jnit #	Location					

# **6TL0D0GSL8** 23-04951

### WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 05/18/2023

l		Prior Action									
İ		Action									
	¥										
LNO	7										
5	₹										
	INDIVIDUAL										
•		A 11 OII						T./5			
		Action Other						To/From School			
			Suspected Alco	hol Use	Suspected Drug Use						
	L	Drug & Alcohol	NO		NO						
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results				
		TEST NOT GIVEN		Davis Took Tons							
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results					
10	001	Drug Type									
•	ŏ										
		Individual Condition									
		APPEARED NORM	/AL								
		ALL EARLY HORNIAL									
	,	Violations									
	2	UTC Number BG945082	Issue To? <b>001</b>	Statute Number 344.62(1)	Description OPERATE MOTOR \	/EHICLE W/O IN	SURANCE				
	0			` ,							
	02	UTC Number BG945083	Issue To? <b>001</b>	Statute Number 346.57(2)	Description FAILURE TO KEEP	VEHICLE UNDER	R CONTROL				
I				J	l						