6TL0C884K6

23-05052

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Document # Crash Time		Agency Crash Number 23-05052 Date Arrived		Investigating Officer/Deputy DEPUTY T. SUTHERLAND Time Arrived DEFLAP DM				
9	Crash Date									
4	05/20/2023 Date Notified	04:50 PM Time Notified		05/20/2023 Total Units		05:18 PM Total Injured Total Killed		-d		
Ď	05/20/2023	04:56 PM		01		00 00			lieu	
61L0C884K6	On Emergency	and Run	Lane Clos		Work Zone		iler or	Towed	Reporting Threshold	
9	Government Property		hool Zone	School NO	Bus Related	Tags				
	✓ Reportable	Crash Type DT4000 (STA	NDARD CRAS	H)		Am	ended		Secondary Crash	
	Description Diagram									
	D&W Road D&W Road Not To Scale	nt officer, agr					Ac	Iditional Info		
	ON 05-20-23 UNIT 1 WAS NORTHB TRUCK TURNING AND SWERVED	OUND ON CTH H	I. THERE WAS A T	RUCK MAK	ING A LEFT TURN ONT	O D&W ROAD				

23-05052

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	LOC	ation								
		D AND W RD			La	atitude		Longitude		
		TW		43	3.587417424		-89.953549181			
		CTHH NB HE TOWN OF DELLO		Х	X Coordinate		Y Coordinate			
			MA	20	261561.71875		4830289			
	in c			St	Structure Type					
						NO STRUCTURE				
	~ ~~	sh Scene 📃								
	-				1					
		Harmful Event				rst Harmful Event I				
	DIT			-	HOULDER LEF	Γ				
	Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT					Light Condition				
						AYLIGHT				
	Road	d Surface Condition(s)			R	oadway Factor(s)				
	DR۱	(
	Envi	ronment Factor(s)								
	NO	NE			N	ONE				
	Wea	ther Condition(s)				-				
	CLE	AR								
	Anim	nal Type			Re	Relation To Trafficway				
					т	TRAFFICWAY - NOT ON ROAD				
	Cras	h Classification - Location)		Cr	rash Classification	- Jurisdiction			
	PUBLIC PROPERTY				Ν	NO SPECIAL JURISDICTION				
	Triba	Tribal Land				Access Control Special Study				
						NO CONTROL				
	With	-			Intersection T					
	20		INTEROFOTION		TINTEDOE	OTION				
	NO		INTERSECTION		T-INTERSE	CTION				
	Uni	t Summary	INTERSECTION							
	Uni	t Summary	INTERSECTION		erating As Class		Unit Type			
	Unit Unit IN T	Status RANSIT	INTERSECTION	Vehicle Ope	erating As Class		AUTOMOE			
	Unit Unit IN T Vehi	Status RANSIT cle Type			erating As Class		AUTOMOE	BILE s Endorsements		
01	Unit Unit IN T Vehi	Status RANSIT			erating As Class		AUTOMOE			
	Unit Unit IN T Vehi (SP	Status RANSIT cle Type		D CLASS	erating As Class		AUTOMOE Operating As			
	Unit Unit IN T Vehi (SP	Status RANSIT cle Type ORT) UTILITY VEHICI	LE	D CLASS	erating As Class	sification	AUTOMOE Operating As	s Endorsements		
	Unit Unit IN T Vehi (SP Tota 1	Status RANSIT cle Type ORT) UTILITY VEHICI	LE	D CLASS	erating As Class	Sification	AUTOMOE Operating As	s Endorsements Total HazMat Types		
01	Unit Unit IN T Vehi (SP Tota 1	Status (RANSIT cle Type ORT) UTILITY VEHICI I Occs rance?	L E Train/Bus # Recorded	D CLASS	erating As Class	Total Tra	AUTOMOE Operating As illers mit	s Endorsements Total HazMat Types 0 Total Lanes 2		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES	Status (RANSIT cle Type ORT) UTILITY VEHICI I Occs rance?	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND	D CLASS	tions Issued CrashTire Mark	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES	Status (RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? S t Harmful Event: Collision	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND	D CLASS	tions Issued CrashTire Mark	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES Most DIT Traff	Status (RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? CH I Harmful Event: Collision CH ic Way	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark CiAL FUNCTIC	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use		
01	Unit Unit IN T Vehi (SP Tota 1 Insu YES DIT Traff TW(Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance? B Harmful Event: Collision CH ic Way D-WAY, NOT DIVIDED	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark inction CiAL FUNCTIO Trol FROL	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES Most DIT Traff TW(C Surfa	Status (RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? Harmful Event: Collision CH ic Way D-WAY, NOT DIVIDED ace Type	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark hiction CIAL FUNCTIO trol rROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit Unit IN T Vehi (SP4 Tota 1 Insur YES Most DIT Traff TW0 Surfa	Status (RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? CH ICH IC Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark hiction CIAL FUNCTIO trol rROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit Unit IN T Vehi (SP4 Tota 1 Insu YES Most DIT Traff TWC Surfa BLA Truc	Status (RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? Harmful Event: Collision CH ic Way D-WAY, NOT DIVIDED ace Type	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark hiction CIAL FUNCTIO trol rROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? I Harmful Event: Collision CH To Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark hiction CIAL FUNCTIO trol rROL ature	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? St Harmful Event: Collision CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark CiAL FUNCTIO FOL ature IGHT	Total Tra 0 Speed Li 55	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With	D CLASS	tions Issued CrashTire Mark CiAL FUNCTIO FOL ature IGHT	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance		
01	Unit Unit IN T Vehi (SP Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? CH I Harmful Event: Collision CH IC Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ARH7019	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With S)	D CLASS	tions Issued CrashTire Mark CiAL FUNCTIO FOL ature IGHT	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance		
	Unit Unit Unit IN T Vehi (SP Tota 1 Insuu YES DIT Traff TW(Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? CH CH CH CH CH CH CH CH CH CH	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With S)	D CLASS	tions Issued CrashTire Mark CiAL FUNCTIO FOL ature IGHT	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance		
	Unit Unit IN T Vehi (SP Tota 1 Insur YES Most DIT Traff TWC Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? E Harmful Event: Collision CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ARH7019 Vehicle Identification Nuu 3C4PDCAB6ET2645	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With S)	D CLASS	tions Issued CrashTire Mark iction CrashTire Mark iction CrashTire Mark ICAL FUNCTIO TOL IGHT JTOMOBILE	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model JOURNEY	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance		
	Unit Unit Unit IN T Vehi (SP Tota 1 Insuu YES DIT Traff TW(Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI I Occs rance? Tharmful Event: Collision CH Tc Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ARH7019 Vehicle Identification Nuu 3C4PDCAB6ET2645 Color	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With S)	D CLASS	tions Issued CrashTire Mark notion CiAL FUNCTIC Trol TROL ature IGHT JTOMOBILE	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance		
UNI 01	Unit Unit IN T Vehi (SP4 Tota 1 Insuu YES Most Traff TW0 Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI OCCS rance? t Harmful Event: Collision CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ARH7019 Vehicle Identification Nui 3C4PDCAB6ET2645 Color RED - RED	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With S)	D CLASS	tions Issued CrashTire Mark inction IAL FUNCTIC ital IGHT IGHT	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model JOURNEY	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance		
01 UNII 01	Unit Unit IN T Vehi (SP Tota 1 Insur YES DIT Traff TTWC Surfa BLA Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICI ORT) UTILITY VEHICI I Occs rance? Tance? Ta	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With S)	D CLASS	tions Issued CrashTire Mark inction IAL FUNCTIC ital IGHT IGHT	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model JOURNEY	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance		
UNI 01	Unit Unit IN T Vehi (SP4 Tota 1 Insuu YES Most Traff TW0 Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICI OCCS rance? t Harmful Event: Collision CH ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number ARH7019 Vehicle Identification Nui 3C4PDCAB6ET2645 Color RED - RED	LE Train/Bus # Recorded Direction Of Travel NORTHBOUND With S)	D CLASS	tions Issued CrashTire Mark action Cital FUNCTIC Trol TROL ature IGHT JTOMOBILE	Total Tra 0 Speed Li 55 DN	AUTOMOE Operating As illers mit Emergency I NOT APPL Traffic Contr NO Road Grade DOWNHIL Country of Iss UNITED ST Model JOURNEY	s Endorsements Total HazMat Types 0 Total Lanes 2 Motor Vehicle Use ICABLE ol Inoperative/Missing L suance ATES		

23-05052

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage TOWED BUT NOT DUE TO	DISABLING DAMAG	Vehicle Remo	-				
		What Driver Was Doing		Vehicle Factors					
		NEGOTIATING CURVE							
		Driver Prior Action Other		NOT APPLI	CABLE				
UNIT	VEHICLE	Driver Actions FAILURE TO CONTROL, R INATTENTIVE, CARELESS			P IN DESIG	GNATED LANE, C	OPERATED MOTOR VE	EHICLE IN	
01	01	Owner Name TATIANA EDWARDS MOG (608) 733-9668	Owner Address 1455 PINEVIEW DRIVE REEDSBURG, WI 53959, US						
		Sequence Of Events							
	01	Event DITCH							
	02	Event							
	03	Event							
	04	Event							
_		Policy Holder							
UNIT		Insurance Company	Individual						
5		FOUNDERS-INS-CO	TATIANA EDWARDS MOQUETE						
	I	Individual							
		Driver TATIANA EDWARDS MOQUETE (608) 733-9668		Citations Issued Sex					
	١L			0		FEMALE			
⊨	INDIVIDUAL	(000) / 00 0000	Date of Birt	ih	Race BLACK/AFRICAN AMERICAN				
UNIT	N	Address 1455 PINEVIEW DRIVE	Driver License Number						
	IND	REEDSBURG, WI 53959 , US		STATE: WASHINGTON COUNTRY: UNITED STATES					
		On Duty	Crash	Safety Equ	inmont				
	Saf	fety Equipment	Glasif	Salety Equ	ipment				
	1	Row Seat Position		SHOULDER & LAP BELT					
		01 - FRONT ROW Helmet Use	07 - LEFT	Helmet Compliance					
		Eye Protection		Tint Compliance					
9	001	Injury Severity Injury NO APPARENT INJURY		Airbag NON DEPLOYED					
	0	Ejected Ejection Path		Trapped/Extricated					
		NOT EJECTED NOT EJECTED/NOT API		PLICABLE		NOT TRAPPED			
		Medical Transport NOT TRANSPORTED	EMS Agency Identifier		EMS Run #				
	Hospital		Date of Death Time of Death		Time of Death				
		Distracted By NOT AF	d By Source						
		Distracted By Action		,					
		NOT DISTRACTED							

6TL0C884K6 23-05052

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motorist	Striking Unit #	Location						
		Prior Action								
UNIT	INDIVIDUAL	Action								
		Action Other						To/From School		
	L	Drug & Alcohol	Suspected Alcohol U NO	se	Suspected Drug Use NO					
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results			
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results				
6	001	Drug Type								
		APPEARED NORN								