

6TL0BC3B78
23-05611

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0BC3B78

Document Number Override		Primary Crash Document #		Agency Crash Number 23-05611		Investigating Officer/Deputy DEPUTY W. VERTEIN	
Crash Date 06/02/2023		Crash Time 08:51 AM		Date Arrived 06/02/2023		Time Arrived 09:08 AM	
Date Notified 06/02/2023		Time Notified 08:53 AM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p>	Reconstruction By
	Photos By W. VERTEIN #9122
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON THE DESCRIBED DATE, TIME, AND LOCATION, UNIT 1 WAS TRAVELING SOUTHBOUND AND UNIT 2 WAS TRAVELING NORTHBOUND. THE OPERATOR OF UNIT 1 ATTEMPTED TO MAKE A LEFT TURN IN FRONT OF UNIT 2. UNIT 2 STRUCK UNIT 1 ON THE PASSENGER SIDE. NO REPORTED INJURIES.

Location

ON MAIN ST/ STH33 WB 25 FT N OF E NORTH ST IN THE VILLAGE OF LA VALLE IN SAUK COUNTY	Latitude 43.583089003	Longitude -90.129743523
	X Coordinate 247318.828125	Y Coordinate 4830329.5
	Structure Type NO STRUCTURE	

Crash Scene


First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ON ROADWAY	
Manner of Collision 01 - ANGLE	Light Condition DAWN	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location INTERSECTION	Intersection Type FOUR-WAY INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 30	Total Lanes 2
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	License Plate Number ACC1509	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1FADP5EU9HL101219	Make FORD	Year 2017	Model C-MAX	
		Color SIL - SILVER (ALUMINUM)	Body Style HB - HATCHBACK		Bus Use	
		Initial Contact Point 04 - RIGHT SIDE REAR	Vehicle Damage 03 - RIGHT SIDE MIDDLE, 04 - RIGHT SIDE REAR, 05 - RIGHT REAR CORNER			
		Extent Of Damage DISABLING DAMAGE				



WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By SHIELDS TOWING		
	What Driver Was Doing LEFT TURN		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions FAILED TO YIELD RIGHT-OF-WAY				
01	01	Owner Name ARTHUR NAEBIG		Owner Address S1250 ELK CT LA VALLE, WI 53941 , US	
		Sequence Of Events			
UNIT	01	Event CROSS CENTERLINE			
		Event LEFT TURN			
		Event MOTOR VEH IN TRANSPORT			
		Event			
UNIT	01	Policy Holder			
		Insurance Company 1ST-AUTO-&-CASUALTY-INS-CO	Individual ARTHUR NAEBIG		
UNIT	01	Individual			
		Driver PATRICIA ALBERT (608) 464-3527		Citations Issued 0	Sex FEMALE
		Address S1250 ELK CT LA VALLE, WI 53941 , US		Date of Birth	Race WHITE
				Driver License Number	
01	001	Safety Equipment		On Duty Crash	
				Safety Equipment	
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
Distracted By		Distracted By Source			
UNKNOWN		Distracted By Action			

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
		Action Other					
		To/From School					
		Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
		Drug Type					
		Individual Condition APPEARED NORMAL					

Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
		Vehicle Type PASSENGER CAR					Operating As Endorsements	
		Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0		
		Insurance? YES	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 30	Total Lanes 2		
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT			Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way TWO-WAY, NOT DIVIDED			Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature STRAIGHT		Road Grade LEVEL	
		Truck Bus or HazMat NO						

UNIT	VEHICLE	Vehicle				
		License Plate Number AEZ7530	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1ZVFT80N965166408	Make FORD	Year 2006	Model MUSTANG	
		Color BLK - BLACK	Body Style CP - COUPE		Bus Use	
		Initial Contact Point 01 - RIGHT FRONT CORNER	Vehicle Damage 01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 12 - FRONT			
		Extent Of Damage FUNCTIONAL DAMAGE				
		Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	What Driver Was Doing GOING STRAIGHT		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions NO CONTRIBUTING ACTION			
	Owner Name RANDY RABUCK (608) 415-9984		Owner Address 258 3RD ST REEDSBURG, WI 53959 , US	
UNIT 02	Sequence Of Events			
	01	Event MOTOR VEH IN TRANSPORT		
	02	Event		
	03	Event		
	04	Event		
UNIT	Policy Holder			
	Insurance Company ERIE-INS-CO		Individual RANDY RABUCK	
UNIT INDIVIDUAL	Individual			
	Driver RANDY RABUCK (608) 415-9984		Citations Issued 0	Sex MALE
	Address 258 3RD ST REEDSBURG, WI 53959 , US		Date of Birth	Race WHITE
			Driver License Number	
UNIT 002	Safety Equipment		On Duty Crash	
			Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				
Non Motorist				
Striking Unit #		Location		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Prior Action		
	Action		
	Action Other		To/From School
	Drug & Alcohol		
	Suspected Alcohol Use NO		Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results
	Drug Type		
	Individual Condition APPEARED NORMAL		
	02	002	