

6TL0B3P3KD
SC23-06138

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0B3P3KD

Document Number Override	Primary Crash Document #	Agency Crash Number SC23-06138	Investigating Officer/Deputy DEPUTY J. GREENWOOD		
Crash Date 06/13/2023	Crash Time 12:46 PM	Date Arrived 06/13/2023	Time Arrived 01:14 PM		
Date Notified 06/13/2023	Time Notified 12:48 PM	Total Units 02	Total Injured 00	Total Killed 00	
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input checked="" type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable	Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash	

Description

Diagram <p>Not to Scale</p>	Reconstruction By
	Photos By
	Additional Information NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS EB STH 33 AND WAS SLOWING/STOPPING FOR A CAR THAT WAS TURNING IN FRONT OF IT. UNIT 2 WAS EB BEHIND UNIT 1. UNIT 2 WAS SLOWING DOWN AND WAS UNABLE TO STOP AND REAR ENDED UNIT 1

Location

ON STH33 EB 1213 FT W OF WEBSTER LN IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.5146146	Longitude -89.793262289
	X Coordinate 274230.28125	Y Coordinate 4821755.5
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT		First Harmful Event Location ON ROADWAY	
Manner of Collision 03 - FRONT TO REAR		Light Condition DAYLIGHT	
Road Surface Condition(s) WET		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLOUDY			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE			Operating As Endorsements		
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

Vehicle

UNIT	VEHICLE	License Plate Number AGL4057	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 2HKYF18413H573592	Make HONDA	Year 2003	Model PIOLT	
		Color SIL - SILVER (ALUMINUM)	Body Style UT - SPORT UTILITY VEHICLE		Bus Use	
		Initial Contact Point 06 - REAR	Vehicle Damage 05 - RIGHT REAR CORNER, 06 - REAR, 07 - LEFT REAR CORNER			
		Extent Of Damage MINOR DAMAGE				



WISCONSIN MOTOR VEHICLE
CRASH REPORT


UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing SLOW/STOPPING		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
01	01	Owner Name BENOIT LETENDRE		Owner Address 905 ASH ST BARABOO, WI 53913 , US	
		Sequence Of Events			
UNIT	01	Event MOTOR VEH IN TRANSPORT			
		Event			
		Event			
		Event			
UNIT	01	Policy Holder			
		Insurance Company USAA-GENERAL-INDEMNITY-CO	Individual BENOIT LETENDRE		
UNIT	01	Individual			
		Driver MADELEINE LETENDRE (608) 393-3158	Citations Issued 0	Sex FEMALE	
		Address 905 ASH ST BARABOO, WI 53913 , US		Date of Birth	Race
		Driver License Number			
UNIT	01	Safety Equipment		On Duty Crash	
				Safety Equipment	
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
UNIT	001	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED	
		Medical Transport NOT TRANSPORTED	EMS Agency Identifier	EMS Run #	
		Hospital	Date of Death	Time of Death	
		Distracted By			
		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action NOT DISTRACTED					

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
		Action Other					
		To/From School					
		Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
		Drug Type					
		Individual Condition APPEARED NORMAL					

Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification A CLASS		Unit Type TRUCK		
		Vehicle Type TRUCK TRACTOR (SEMI ATTACHED)					Operating As Endorsements	
		Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 1	Total HazMat Types 0		
		Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2		
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT			Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way TWO-WAY, NOT DIVIDED			Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature STRAIGHT		Road Grade LEVEL	
		Truck Bus or HazMat TRUCK OR TRUCK COMBINATION > 10,000LBS GVWR/GCWR						

UNIT	VEHICLE	Vehicle			
		License Plate Number 21439Z	Plate Type APO - APPORTIONED	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 4V4NC9EH9LN228686	Make VOLVO	Year 2020	Model VLN760
		Color MAR - MAROON (BURGUNDY)	Body Style TK - TRUCK		Bus Use
		Initial Contact Point 12 - FRONT	Vehicle Damage		
		Extent Of Damage NO DAMAGE	00 - NO DAMAGE		
		Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR		



6TL0B3P3KD
SC23-06138

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	What Driver Was Doing SLOW/STOPPING		Vehicle Factors			
	Driver Prior Action Other		NOT APPLICABLE			
	Driver Actions NO CONTRIBUTING ACTION					
	Owner Name SKINNER TRANSFER CORP		Owner Address 2020 EAST MAIN ST REEDSBURG, WI 53959 , US			
UNIT 02	Sequence Of Events					
	01	Event MOTOR VEH IN TRANSPORT				
	02	Event				
	03	Event				
	04	Event				
UNIT 02	Policy Holder					
	Insurance Company TRAVELERS-INDEMNITY-CO,-THE		Organization/Company SKINNER TRANSFER CORP			
UNIT TRAILER/ 02	Trailer/Towed					
	Trailer Plate # 795482	Plate Type STL - SEMI	Make HYTR	State WI	Country of Issuance UNITED STATES	
	Unit Type SEMI TRAILER	Organization/Company SKINNER TRANSFER CORP			Address 2020 EAST MAIN ST REEDSBURG, WI 53959 , US	
	Vehicle Identification Number 3H3V532C7MR104039					
UNIT INDIVIDUAL 02	Individual					
	Driver ROBERT KETELBOETER (608) 432-1287		Citations Issued 0	Sex MALE		
	Address W1848 64TH ST LYNDON STATION, WI 53944 , US		Date of Birth	Race WHITE		
			Driver License Number			
UNIT 002	Safety Equipment		On Duty Crash			
			Safety Equipment SHOULDER & LAP BELT			
	Row 01 - FRONT ROW	Seat Position 07 - LEFT				
	Helmet Use		Helmet Compliance			
	Eye Protection		Tint Compliance			
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED		
	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #		

		Hospital	Date of Death	Time of Death	
		Distracted By Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
		Distracted By Action NOT DISTRACTED			
		Non Motorist	Striking Unit #	Location	
		Prior Action			
UNIT	INDIVIDUAL	Action			
		Action Other			To/From School
		Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results
		Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results
		Drug Type			
		Individual Condition		APPEARED NORMAL	
				Carrier	
				<input checked="" type="checkbox"/> Use Vehicle Owner Same as Carrier	Source DRIVER
				Name SKINNER TRANSFER CORP USDOT# 74466	Address 2020 EAST MAIN ST REEDSBURG, WI 53959 , US
UNIT	TRUCK BUS	GVWR		Vehicle Configuration	Cargo Body Type
		MORE THAN 26,000 LB		TRUCK TRACTOR/SEMI-TRAILER	VAN/ENCLOSED BOX
		US DOT #		Carrier Type	Permitted Load
		74466		INTERSTATE CARRIER	NOT APPLICABLE
		<input type="checkbox"/> OS/OW Load	WI Permit Number	<input type="checkbox"/> Permitted Vehicle On Permitted Route	<input type="checkbox"/> Escort Vehicle Required By Permit
Measured Height		Measured Length	Measured Width	Measured Weight	