

6TL0BGSFK2
23-07201


WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

6TL0BGSFK2

Document Number Override		Primary Crash Document #		Agency Crash Number 23-07201		Investigating Officer/Deputy DEPUTY D. KROLIKOWSKI		
Crash Date 07/07/2023		Crash Time 12:06 PM		Date Arrived 07/07/2023		Time Arrived 12:18 PM		
Date Notified 07/07/2023		Time Notified 12:06 PM		Total Units 02		Total Injured 00	Total Killed 00	
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input checked="" type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold		
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags		
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash

Description

Diagram 	Reconstruction By
	Photos By
	Additional Information NONE
<input checked="" type="checkbox"/> I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.	
UNIT 2 WAS EAST BOUND SLOWING FOR BACKED UP TRAFFIC AHEAD OF IT IN THE CONSTRUCTION ZONE. UNIT 1 WAS APPROACHING UNIT 2 FROM BEHIND AND COULD NOT SLOW IN TIME TO AVOID A COLLISION. UNIT 1 STRUCK THE REAR OF UNIT 2.	

6TL0BGSFK2

23-07201

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON STH23 EB 1123 FT E OF STH23 EB IN THE TOWN OF REEDSBURG IN SAUK COUNTY	Latitude 43.532618474	Longitude -89.960377654
	X Coordinate 260793.53125	Y Coordinate 4824222.5
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT		First Harmful Event Location ON ROADWAY	
Manner of Collision 03 - FRONT TO REAR		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		BACKUP DUE TO REGULAR CONGESTION, WORK ZONE (CONSTRUCTION/MAINTENANCE/UTILITY)	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	
Work Zone Crash Location TRANSITION AREA		Work Zone Crash Type INTERMITTENT OR MOVING WORK	
Workers Present NO		Law Enforcement Present NO	
Work Zone Speed Limit 55	Advisory/Regulatory Speed Limit REGULATORY	Normal Posted Speed Limit 55	

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR			Operating As Endorsements		
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type CONCRETE		Road Curvature STRAIGHT		Road Grade HILLCREST	
	Truck Bus or HazMat NO					
01	Vehicle					
	License Plate Number ASB3778		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
	Vehicle Identification Number 1N4BA41E56C802693		Make NISSAN	Year 2006	Model MAXIMA	

6TL0BGSFK2

23-07201

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT VEHICLE	Color BLU - BLUE	Body Style SD - SEDAN	Bus Use
	Initial Contact Point 12 - FRONT	Vehicle Damage 12 - FRONT	
	Extent Of Damage DISABLING DAMAGE		
	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE	Vehicle Removed By STEVES AUTO SERVICE	
	What Driver Was Doing GOING STRAIGHT	Vehicle Factors NOT APPLICABLE	
UNIT VEHICLE	Driver Prior Action Other		
	Driver Actions FOLLOWING TOO CLOSE		
	Owner Name ASHLEY HINZE (608) 495-9496	Owner Address S3042 AULT RD REEDSBURG, WI 53959 , US	
Sequence Of Events			
UNIT	01 Event MOTOR VEH IN TRANSPORT		
	02 Event		
	03 Event		
	04 Event		
UNIT	Policy Holder		
	Insurance Company STATE-FARM-GENERAL-INS-CO	Individual ALEYAH CHAMPLIN	
UNIT INDIVIDUAL	Individual		
	Driver ALEYAH CHAMPLIN (608) 495-9496	Citations Issued 1	Sex FEMALE
		Date of Birth	Race
	Address S3042 AULT RD REEDSBURG, WI 53959 , US	Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES	
UNIT	Safety Equipment		On Duty Crash
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	Safety Equipment SHOULDER & LAP BELT
	Helmet Use		Helmet Compliance
	Eye Protection		Tint Compliance
	Injury	Injury Severity NO APPARENT INJURY	Airbag DEPLOYED-FRONT
01 001	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
	Medical Transport NOT TRANSPORTED	EMS Agency Identifier	EMS Run #

6TL0BGSFK2

23-07201

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

UNIT	Hospital		Date of Death		Time of Death	
	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
	Distracted By Action NOT DISTRACTED					
	Non Motorist		Striking Unit #		Location	
	Prior Action					
	Action					
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
Drug Type						
Individual Condition APPEARED NORMAL						
Violations						
01	001	01	UTC Number BG942210	Issue To? 001	Statute Number 346.14(1m)	Description AUTOMOBILE FOLLOWING TOO CLOSELY

Unit Summary

UNIT	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type (SPORT) UTILITY VEHICLE				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type CONCRETE		Road Curvature CURVE - UNKNOWN DIRECTION		Road Grade HILLCREST	
	Truck Bus or HazMat NO					
	Vehicle					
	License Plate Number AAM9003			Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES

02

6TL0BGSFK2

23-07201

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

02 UNIT VEHICLE	Vehicle Identification Number 3GNAXUEV3LS589447		Make CHEVROLET	Year 2020	Model EQUINOX	
	Color GRY - GRAY		Body Style UT - SPORT UTILITY VEHICLE		Bus Use	
	Initial Contact Point 06 - REAR		Vehicle Damage 06 - REAR			
	Extent Of Damage FUNCTIONAL DAMAGE					
	Towed Due To Damage NOT TOWED		Vehicle Removed By			
	What Driver Was Doing SLOW/STOPPING		Vehicle Factors			
	Driver Prior Action Other		NOT APPLICABLE			
02 UNIT VEHICLE	Driver Actions NO CONTRIBUTING ACTION					
	Owner Name MONICA THERESE MCCOACH (608) 999-1879		Owner Address 2118 HUNTINGTON PARK DR REEDSBURG, WI 53959 , US			
Sequence Of Events						
02 UNIT VEHICLE	01	Event MOTOR VEH IN TRANSPORT				
	02	Event				
	03	Event				
	04	Event				
02 UNIT VEHICLE	Policy Holder					
	Insurance Company USAA-CASUALTY-INS-CO		Individual MONICA MCCOACH			
02 UNIT INDIVIDUAL	Individual					
	Driver MONICA MCCOACH (608) 999-1879		Citations Issued 0	Sex FEMALE		
			Date of Birth	Race WHITE		
Address 2118 HUNTINGTON PARK DR REEDSBURG, WI 53959 , US		Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES				
02 UNIT VEHICLE	Safety Equipment		On Duty Crash			
			Safety Equipment SHOULDER & LAP BELT			
	Row 01 - FRONT ROW	Seat Position 07 - LEFT				
	Helmet Use		Helmet Compliance			
	Eye Protection		Tint Compliance			
02 UNIT VEHICLE	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED		
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED		

