



6TL0D1PTNG

Document Number Override		Primary Crash Document #		Agency Crash Number 23-07034		Investigating Officer/Deputy DEPUTY S. MESSNER	
Crash Date 07/03/2023		Crash Time 09:16 PM		Date Arrived 07/03/2023		Time Arrived 09:27 PM	
Date Notified 07/03/2023		Time Notified 09:16 PM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input checked="" type="checkbox"/> Trailer or Towed		<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input type="checkbox"/> Reportable		Crash Type PRIVATE PROPERTY/PARKING LOT		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

Diagram		Reconstruction By	
Not to scale			
			
<p>Private drive</p> <hr/> <p>Trailer strikes unit 1 while Unit 2 turns left onto another private drive</p>  <p>Unit 2 with trailer, westbound</p> <p>Unit 1 pulled over to let Unit 2 with trailer go pass</p> <p>Private drive</p>		Photos By DEP. S. MESSNER #9134	
		Additional Information PHOTOS	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 7/3/2023, AT APPROXIMATELY 9:16 PM, UNIT 1, A WHITE DODGE 1500 RAM TRUCK, BEARING KS PLATE #818PRW, BEING DRIVEN BY JOSE A. VILLEGAS SOTO, IDENTIFIED BY HIS CA DRIVER'S LICENSE, WAS ON A PRIVATE DRIVE AT JELLY STONE CAMPGROUND, S1915 ISHNALA ROAD, TOWNSHIP OF DELTON, SAUK COUNTY, WISCONSIN. UNIT 1 PULLED TO THE SIDE OF THE PRIVATE DRIVE TO ALLOW UNIT 2, A 2014 WHITE FORD F150 BEARING WISCONSIN REGISTRATION PLATE # PT9585, WAS BEING DRIVEN BY BRENNAN J. GASSER, AN EMPLOYEE OF JELLYSTONE PARK. UNIT 2 WAS PULLING A TRAILER. WHILE TURNING LEFT THE REAR CORNER OF THE TRAILER STRUCK THE REAR CORNER OF THE UNIT 1. NO INJURIES OCCURRED. I PHOTOGRAPHED THE UNITS. BRENT GASSER, THE OWNER OF THE BUSINESS, UNIT 1 AND TRAILER PULLED BY UNIT 1 ARRIVED ON SCENE, PROVIDED INSURANCE INFORMATION AND PROVIDED INFORMATION TO PARTIES INVOLVED. ITSEL C. AVELINO SALAZAR WITNESSED THE EVENT AND ACTED AS TRANSLATOR FOR JOSE A. VILLEGAS SOTO. NO INJURIES OCCURRED. INCIDENT DOCUMENTED. BOTH DRIVERS WERE ABLE TO REMOVE THEIR OWN UNITS.

Location

PRIVATE PROPERTY S1915 ISHNALA RD (FIRE S1915) IN THE TOWN OF DELTON IN SAUK COUNTY	Latitude 43.576676912	Longitude -89.799329882
	X Coordinate 273972.0625	Y Coordinate 4828665
	Structure Type FIRE	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location OFF ROADWAY, LOCATION UNKNOWN	
Manner of Collision 06 - SIDESWIPE/OPPOSITE DIRECTION	Light Condition DARK/UNLIT	
Road Surface Condition(s) DRY	Roadway Factor(s) OTHER	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway NON TRAFFICWAY - OTHER	
Crash Classification - Location PRIVATE PROPERTY	Crash Classification - Jurisdiction PRIVATE PROPERTY	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status LEGALLY PARKED	Vehicle Operating As Classification D CLASS	Unit Type TRUCK		
	Vehicle Type UTILITY TRUCK/PICKUP TRUCK			Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit N/A	Total Lanes
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way PARKING LOT OR PRIVATE PROPERTY		Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT	Road Grade UPHILL	
	Truck Bus or HazMat NO				

Vehicle

VEHICLE	License Plate Number 818PRW	Plate Type LTK - LIGHT TRUCK	St KS	Country of Issuance UNITED STATES
	Vehicle Identification Number 1C6RR7PMXGS379142	Make RAM	Year 2016	Model 1500 CREW
	Color WHI - WHITE	Body Style		Bus Use
	Initial Contact Point 07 - LEFT REAR CORNER	Vehicle Damage 07 - LEFT REAR CORNER		
	Extent Of Damage MINOR DAMAGE			




UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR	
	What Driver Was Doing LEGALLY PARKED		Vehicle Factors	
	Driver Prior Action Other			
	Driver Actions NO CONTRIBUTING ACTION			
01	Owner Name RICARDO MORENO		Owner Address 13270 ANTHONY DR SAINT GEORGE, KS 66535 9557, US	
	Sequence Of Events			
01 02 03 04	Event MOTOR VEH IN TRANSPORT			
	Event			
	Event			
	Event			
UNIT	Policy Holder			
	Insurance Company NATIONWIDE-MUTUAL-INS-CO		Individual JOSE VILLEGAS SOTO	
UNIT INDIVIDUAL	Individual			
	Occupant Of Motor Vehicle Not In Transport JOSE VILLEGASSOTO		Citations Issued 0	Sex MALE
			Date of Birth	Race HISPANIC
	Address 1113 RAMONA AVE SN BERNRDNO, CA , US		Driver License Number	
01 001	Safety Equipment		On Duty Crash	
			Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	NONE USED - VEHICLE OCCUPANT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	Airbag UNKNOWN
Ejected UNKNOWN		Ejection Path UNKNOWN		Trapped/Extricated UNKNOWN
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source		
Distracted By Action				

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
	Action Other					To/From School	
	01	001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
			Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
			Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
			Drug Type				
			Individual Condition APPEARED NORMAL				

Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type TRUCK		
		Vehicle Type UTILITY TRUCK/PICKUP TRUCK					Operating As Endorsements	
		Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 1	Total HazMat Types 0		
		Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit N/A	Total Lanes		
		Most Harmful Event: Collision With PARKED MOTOR VEHICLE			Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way PARKING LOT OR PRIVATE PROPERTY			Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature STRAIGHT		Road Grade UPHILL	
		Truck Bus or HazMat NO						

UNIT	VEHICLE	Vehicle					
		License Plate Number PT9585		Plate Type LTK - LIGHT TRUCK	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1FTBF2A66EEB46886		Make FORD	Year 2014	Model F250	
		Color WHI - WHITE		Body Style PK - PICKUP		Bus Use	
		Initial Contact Point 00 - NON-COLLISION		Vehicle Damage			
		Extent Of Damage NO DAMAGE		00 - NO DAMAGE			
		Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR			



UNIT VEHICLE	What Driver Was Doing LEFT TURN		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions NO CONTRIBUTING ACTION				
	Owner Name R AND G INC		Owner Address S1915 ISHNALA RD BARABOO, WI 53913 , US		
Sequence Of Events					
01 02 03 04	Event LEFT TURN				
	Event				
	Event				
	Event				
UNIT 02	Policy Holder				
	Insurance Company AMERICAN-FAMILY-INS-CO			Organization/Company R AND G INC	
UNIT TRAILER/ 02	Trailer/Towed				
	Trailer Plate #	Plate Type	Make HSMI	State	Country of Issuance
	Unit Type UTILITY TRAILER	Organization/Company R AND G INC			Address S1915 ISHNALA RD BARABOO, WI 53913 , US
	Vehicle Identification Number 69869				
UNIT INDIVIDUAL	Individual				
	Driver BRENNAN GASSER		Citations Issued 0	Sex MALE	
	Address S1778A ISHNALA RD BARABOO, WI 53913 , US		Date of Birth	Race WHITE	
		Driver License Number			
02 002	Safety Equipment		On Duty Crash		
			Safety Equipment		
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
	Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED			EMS Agency Identifier		EMS Run #

UNIT	Hospital		Date of Death		Time of Death	
	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
	Distracted By Action		NOT DISTRACTED			
	Non Motorist		Striking Unit #		Location	
	Prior Action					
	Action					
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given		Alcohol Test Type		Alcohol Test Results	
	TEST NOT GIVEN					
Drug Test Given		Drug Test Type		Drug Test Results		
TEST NOT GIVEN						
Drug Type						
Individual Condition						
APPEARED NORMAL						

Witness

WITN ESS 01	Individual ITSEL AVELINO SALAZAR		Address 411 KENOSHA ST WALWORTH, WI 53184 , US		Date of Birth