
# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	е	Primary Crash D	Document #	Agency <b>23-081</b>	Crash Number	Investigating Officer/Deputy DEPUTY Z. DRILL			
OL.	Crash Date <b>07/30/2023</b>		Crash Time 03:55 AM		Date Arrived <b>07/30/2023</b>		Time Arrived 03:55 AM			
R2K	Date Notified 07/30/2023		Time Notified 03:55 AM		Total Units <b>02</b>		Total Injured <b>01</b>	Total Killed 00		
- 	On Emergency Hit		and Run Lane Closu		ure Work Zone		Trailer or Towed		Reporting Threshold	
eTL	Government Property		Active Sc	hool Zone	School Bus Related NO		Tags			
	<b>✓</b> Reportable		Crash Type DT4000 (STANDARD CRASH)				Amended		Secondary Crash	
1	Description <b>—</b>									



I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

WHILE TRAVELING NORTH ON COUNTY RD A, DRIVER OF UNIT ONE CRESTED THE HILL NEAR \$1903 COUNTY RD A AND OBSERVED A VEHICLE STOPPED I THE ROADWAY, POSSIBLY TURNING WEST INTO STEEL'S TRAILER COURT, WITH NO OTHER VEHICLES COMING IN THE OPPOSITE LANE. DRIVER OF UNIT ONE ATTEMPTED TO STOP BUT WAS UNABLE TO AND STRUCK THE REAR END OF UNIT 2. UNIT 2 SLID WEST INTO THE DITCH LINE STRIKING THE FIRE NUMBER FOR \$1903 AND COMING TO REST IN THE DITCH. UNIT 1 CONTINUED FORWARD WITH HEAVY FRONT END DAMAGE AND CAME TO REST ON THE EAST SIDE OF THE ROADWAY. BOTH VEHICLES REMOVED BY TOW TRUCK FROM THE SCENE. NEITHER VEHICLE HAD AIRBAG DEPLOYMENT. DRIVER OF UNIT TWO TRANSPORTED BY EMS FOR MINOR INJURIES. DRIVER OF UNIT ONE SUSTAINED NO INJURIES. DRIVER OF UNIT 1 CITED FOR NO INSURANCE AND NON REGISTRATION OF AUTO.

Location

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 07/30/2023

	_	CTHA NB ' MI S				Latitude 43.575525934			Longitude -89.738396506	
	IN T	SHERRILINN DR THE TOWN OF DELTON BAUK COUNTY	N			X Coordinate 278888			dinate <b>73</b>	
	"	AUR COUNTY			Structure Type NO STRUCTURE					
	Cra	sh Scene			\\					
		Harmful Event			First	Harmful Event I	ocation			
		TOR VEH IN TRANSPO	ORT		ON	ROADWAY				
		ner of Collision			-	t Condition				
		FRONT TO REAR				RK/UNLIT				
		d Surface Condition(s)			Road	dway Factor(s)				
	DRY	<b>(</b>								
	Envi	ronment Factor(s)								
	NON	NE			ОТН	IER				
	Wea	ther Condition(s)								
	CLE	AR								
	Anim	nal Type			Rela	tion To Trafficw				
						AFFICWAY - C		N ROAD		
		h Classification - Location			Crash Classification - J NO SPECIAL JURI Access Control NO CONTROL					
		BLIC PROPERTY al Land						RISDICTION Special Study		
	THDE	ai Land								
	With	in Interchange Area	Junction Location		pe					
	NO	-	NON-JUNCTION		NOT AN INTERSECTION					
	Unit	t Summary -								
	<b>UIII</b>			Unit Status Vehicle Operating As C						
				Vehicle Ope	erating As Classific	cation	Unit Type			
	Unit IN T	Status RANSIT		Vehicle Ope	erating As Classific	cation	AUTOMOI			
	Unit IN T Vehi	Status 'RANSIT cle Type	<b>-</b>	·	erating As Classific	cation			ments	
2	Unit IN T Vehi	Status RANSIT cle Type ORT) UTILITY VEHICLI		D CLASS	-		AUTOMOI Operating A	s Endorse		
	Unit IN T Vehi	Status 'RANSIT cle Type	E Train/Bus # Recorded	·	-	Total Tra	AUTOMOI Operating A	s Endorse	ments zMat Types	
	Unit IN T Vehi (SP) Total 1	Status RANSIT cle Type ORT) UTILITY VEHICLI		D CLASS  Total # Citat 2	ions Issued	Total Tra	AUTOMOI Operating A	s Endorse Total Haz	zMat Types	
10	Unit IN T Vehi (SP) Total 1	Status RANSIT cle Type ORT) UTILITY VEHICLI Occs	Train/Bus # Recorded	Total # Citat 2	-	Total Tra	AUTOMOI Operating A	Total Haz  Total Lar  Z	zMat Types nes	
	Unit IN T Vehic (SPC Total 1 Insur NO Most	Status  RANSIT  cle Type  ORT) UTILITY VEHICLI I Occs  rance?	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith	Total # Citat 2 Pre	ions Issued  CrashTire  Mark	Total Tra 0 Speed Li 55	AUTOMOI Operating A	Total Haz  0  Total Lar  2  Motor Veh	zMat Types nes nicle Use	
10	Unit IN T Vehic (SP) Tota 1 Insur NO Most	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  t Harmful Event: Collision W  TOR VEH IN TRANSPO	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith	Total # Citat 2 Pre Special Fun NO SPEC	ions Issued  CrashTire  Mark  ction  IAL FUNCTION	Total Tra 0 Speed Li 55	AUTOMOI Operating A sillers imit Emergency NOT APPI	Total Haz  O Total Lan  2 Motor Veh	zMat Types nes nicle Use	
10	Unit IN T Vehic (SP) Tota 1 Insui NO Most MO Traff	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI I Occs  rance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  ic Way	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith	Total # Citat 2 Pre	cions Issued  CrashTire  Mark  ction  IAL FUNCTION	Total Tra 0 Speed Li 55	AUTOMOI Operating A sillers imit Emergency NOT APPI	Total Haz  O Total Lan  2 Motor Veh	zMat Types nes nicle Use	
10	Unit IN T Vehic (SPC Tota 1 Insur NO Most MO Traff TWC	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  t Harmful Event: Collision W  TOR VEH IN TRANSPO	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith	Total # Citat 2 Pre ( Special Fun NO SPEC	crashTire Mark ction IAL FUNCTION rol	Total Tra 0 Speed Li 55	AUTOMOI Operating A ailers mit Emergency NOT APPI Traffic Control	Total Haz  0 Total Lan  2 Motor Veh LICABLE	zMat Types nes nicle Use	
10	Unit IN T Vehi (SPC Tota 1 Insui NO Most MO Traff TWC	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  TIC Way  D-WAY, NOT DIVIDED	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT	D CLASS  Total # Citat 2  Pre 0  Special Fun NO SPEC  Traffic Contr	crashTire Mark ction IAL FUNCTION ROL	Total Tra 0 Speed Li 55	AUTOMOI Operating A iilers  mit  Emergency NOT APPI Traffic Conti	Total Haz  0 Total Lar  2 Motor Veh LICABLE	zMat Types nes nicle Use	
10	Unit IN T Vehi (SPC Total 1 Insui NO Most MO Traff TWC Surfa BLA	Status  RANSIT  cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  t Harmful Event: Collision W  TOR VEH IN TRANSPO  ic Way  D-WAY, NOT DIVIDED  ace Type	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT	D CLASS  Total # Citat 2  Pre 0  Special Fun NO SPEC  Traffic Contr NO CONT	crashTire Mark ction IAL FUNCTION ROL	Total Tra 0 Speed Li 55	AUTOMOI Operating A  iilers  mit  Emergency NOT APPI Traffic Contr NO Road Grade	Total Haz  0 Total Lar  2 Motor Veh LICABLE	zMat Types nes nicle Use	
10	Unit IN T Vehi (SPC Tota 1 Insur NO Most MO Traff TWC Surfa BLA Truc NO	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  ic Way  O-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT	D CLASS  Total # Citat 2  Pre 0  Special Fun NO SPEC  Traffic Contr NO CONT	crashTire Mark ction IAL FUNCTION ROL	Total Tra 0 Speed Li 55	AUTOMOI Operating A  iilers  mit  Emergency NOT APPI Traffic Contr NO Road Grade	Total Haz  0 Total Lar  2 Motor Veh LICABLE	zMat Types nes nicle Use	
10	Unit IN T Vehi (SPC Tota 1 Insur NO Most MO Traff TWC Surfa BLA Truc NO	Status  RANSIT  cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT	D CLASS  Total # Citat 2  Pre 0  Special Fun NO SPEC  Traffic Contr NO CONT	crashTire Mark ction IAL FUNCTION rol ROL ture	Total Tra 0 Speed Li 55	AUTOMOI Operating A  iilers  mit  Emergency NOT APPI Traffic Contr NO Road Grade	Total Haz  Total Haz  Total Lar  Motor Veh  LICABLE  Total Inopera	zMat Types nes nicle Use	
10	Unit IN T Vehi (SPC Tota 1 Insur NO Most MO Traff TWC Surfa BLA Truc NO	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI I Occs  rance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  ic Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  k Bus or HazMat	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT	D CLASS  Total # Citat 2  Pre Special Fun NO SPEC  Traffic Contr NO CONT Road Curva STRAIGH	crashTire Mark ction IAL FUNCTION rol ROL ture	Total Tra 0 Speed Li 55	AUTOMOI Operating A  illers  mit  Emergency NOT APPI Traffic Conti NO Road Grade HILLCRES	Total Haz  O Total Lar  2 Motor Veh LICABLE  rol Inopera	zMat Types nes nicle Use	
UNIT 01	Unit IN T Vehi (SPC) Tota 1 Insur NO Most MO Traff TWC Surfa BLA	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  Cocs  Tance?  THARMFUL Event: Collision W  TOR VEH IN TRANSPO  TOR WAY, NOT DIVIDED  TOR TOP (BITUMINOUS  TOR WAY  TOR VEH IN TRANSPO  TOR WAY	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT  S)	D CLASS  Total # Citat 2  Pre of Special Fundaments NO SPEC  Traffic Contract NO CONTRACT Road Curva STRAIGHT  Plate Type AUT - AU Make	CrashTire Mark ction IAL FUNCTION rol ROL ture T	Total Tra 0 Speed Li 55	AUTOMOI Operating A  illers  mit  Emergency NOT APPI Traffic Contr NO Road Grade HILLCRES  Country of Is: UNITED ST	Total Haz  Total Haz  Total Lar  Motor Veh  LICABLE  Tol Inopera	zMat Types nes nicle Use	
10	Unit IN T Vehi (SPC Tota 1 Insur NO Most MO Traff TWC Surfa BLA Truc NO	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  Tance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  TOR VEH IN T	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT  S)	Total # Citat 2  Pre (  Special Fun NO SPEC  Traffic Contr NO CONT Road Curva STRAIGH  Plate Type AUT - AU  Make MITSUBIS	CrashTire Mark ction IAL FUNCTION rol ROL ture T	Total Tra 0 Speed Li 55	AUTOMOI Operating A  iilers  mit  Emergency NOT APPI Traffic Contr NO Road Grade HILLCRES  Country of Is UNITED ST	Total Haz  Total Haz  Total Lar  Motor Veh  LICABLE  Tol Inopera	zMat Types nes nicle Use	
UNIT 01	Unit IN T Vehi (SPC) Tota 1 Insur NO Most MO Traff TWC Surfa BLA	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  Cocs  Tance?  THARMFUL Event: Collision W  TOR VEH IN TRANSPO  TOR WAY, NOT DIVIDED  TOR TOP (BITUMINOUS  TOR WAY  TOR VEH IN TRANSPO  TOR WAY	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT  S)	Total # Citat 2  Pre o  Special Fun NO SPEC  Traffic Contr NO CONT  Road Curva STRAIGH  Plate Type AUT - AU  Make MITSUBIS  Body Style	CrashTire Mark ction IAL FUNCTION rol ROL ture T	St WI Year 2017	AUTOMOI Operating A  illers  mit  Emergency NOT APPI Traffic Conti NO Road Grade HILLCRES  Country of Is UNITED ST Model OUTLANDI	Total Haz  Total Haz  Total Lar  Motor Veh  LICABLE  Tol Inopera	zMat Types nes nicle Use	
01 UNIT 01	Unit IN T Vehi (SPA Tota 1 Insur NO Most MO Trafff TWC Surfa BLA Truc NO Unit	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  Tance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  TOR VEH IN T	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT  S)	Total # Citat 2  Pre o  Special Fun NO SPEC  Traffic Contr NO CONT  Road Curva STRAIGH  Plate Type AUT - AU  Make MITSUBIS  Body Style	CrashTire Mark ction IAL FUNCTION TOI ROL ture T TOMOBILE SHI	St WI Year 2017	AUTOMOI Operating A  illers  mit  Emergency NOT APPI Traffic Conti NO Road Grade HILLCRES  Country of Is UNITED ST Model OUTLANDI	Total Haz  Total Haz  Total Lar  Motor Veh  LICABLE  Tol Inopera	zMat Types nes nicle Use the sative/Missing	
01 UNIT 01	Unit IN T Vehi (SPA Tota 1 Insur NO Most MO Trafff TWC Surfa BLA Truc NO Unit	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  Tance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  IC Way  D-WAY, NOT DIVIDED  ACKTOP (BITUMINOUS  IK Bus or HazMat  Vehicle  License Plate Number  ABN7100  Vehicle Identification Num  JA4AP3AU6HZ056836  Color  RED - RED  Initial Contact Point  12 - FRONT	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  Vith  ORT  S)	D CLASS  Total # Citat 2  Pre d Special Fun NO SPEC  Traffic Contr NO CONT  Road Curva STRAIGHT  Plate Type AUT - AU Make MITSUBIS Body Style UT - SPO Vehicle Da 01 - RIGH	CrashTire Mark ction IAL FUNCTION rol ROL ture T TOMOBILE SHI RT UTILITY VE mage HT FRONT COF	St WI Year 2017	AUTOMOI Operating A  illers  mit  Emergency NOT APPI Traffic Conti NO Road Grade HILLCRES  Country of Is UNITED S1 Model OUTLANDI Bus Use	Total Haz 0 Total Lar 2 Motor Veh ICABLE rol Inopera	zMat Types nes nicle Use ative/Missing	
UNIT 01	Unit IN T Vehi (SPA Tota 1 Insurance MO) Trafff TWO Surfa BLA Truck NO	Status  RANSIT  Cle Type  ORT) UTILITY VEHICLI  I Occs  rance?  I Harmful Event: Collision W  TOR VEH IN TRANSPO  IC Way  D-WAY, NOT DIVIDED  ace Type  ACKTOP (BITUMINOUS  Ik Bus or HazMat  Vehicle  License Plate Number  ABN7100  Vehicle Identification Num  JA4AP3AU6HZ056836  Color  RED - RED  Initial Contact Point	Train/Bus # Recorded  Direction Of Travel  NORTHBOUND  With  ORT  S)	Total # Citat 2  Pre G Special Fun NO SPEC Traffic Contr NO CONT Road Curva STRAIGHT  Plate Type AUT - AU Make MITSUBIS Body Style UT - SPO Vehicle Da 01 - RIGH FRONT, 2	crashTire Mark ction IAL FUNCTION rol ROL ture T TOMOBILE SHI RT UTILITY VE	St WI Year 2017	AUTOMOI Operating A  illers  mit  Emergency NOT APPI Traffic Conti NO Road Grade HILLCRES  Country of Is UNITED S1 Model OUTLANDI Bus Use	Total Haz 0 Total Lar 2 Motor Veh ICABLE rol Inopera	zMat Types nes nicle Use ative/Missing	

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 07/30/2023

Race WHITE				
Driver License Number				
STATE: WISCONSIN COUNTRY: UNITED STATES				
Safety Equipment				
Helmet Compliance				
Tint Compliance				
Airbag				
NON DEPLOYED				
Trapped/Extricated				
NOT TRAPPED EMS Run #				
EMS Run #				
Time of Death				
T N				

## WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 07/30/2023

		Prior Action											
 		Action											
		7.6											
	٩L												
╘	INDIVIDUAL												
LNO													
_	<u></u>												
	=												
		Action Other											To/From School
			Cuor	ected Alco	hal Haa			Cuanacted Drug Llas					
	L	Drug & Alcohol	NO	Decled Alco	noi Use			Suspected Drug Use <b>NO</b>					
		Alcohol Test Given			A	Icohol Test Ty	ype				Alcohol Tes	t Results	
		TEST NOT GIVEN				•	,,						
		Drug Test Given				rug Test Type	е		Drug <sup>-</sup>	Test Results			
		TEST NOT GIVEN											
2	001	Drug Type											
	0												
		Individual Condition											
		APPEARED NORM	/IAL										
	1	Violations			_			T =					
	01	UTC Number BG020160	001	ıe To? I	344.6	e Number <b>2(1)</b>	Description OPERATE MOTOR VEHICLE W/O INSURANCE						
	UTC Number   Issue To?   Statute Number						Description						
	02	BG020161	001		341.0	4(1)	NON-REGISTRATION OF AUTO, ETC						
		t Summary <b>•</b>											
		Status						ehicle Operating As Classi	ification	ı	Unit Type	=	
		Cle Type					D CLASS			AUTOMOBILE Operating As Endorsements			
05		SENGER CAR								3			
	Total	Occs		Train/Bus	# Reco	rded	Total # Citations Issued Total			Total Traile	ers	Total Hazi	Mat Types
	1						0		0		0		
	Insur	rance?		Direction (			l	Pre CrashTire		Speed Limit		Total Lanes 2	
L N N			on Wi	_	OUNL	,	L Sr	Mark Decial Function		55	Emergency		cle Use
⋾	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT						NO SPECIAL FUNCTION				NOT APPLICABLE		
	Traff	ic Way					Traffic Control				Traffic Control Inoperative/Missing		
		D-WAY, NOT DIVIDE	ED					O CONTROL			NO Road Grade DOWNHILL		
		ace Type ACKTOP (BITUMINO	nie,					oad Curvature TRAIGHT					
		k Bus or HazMat	<i>J</i> U3)				3	IRAIGHT			DOWNHIL	.L	
	NO	. Duo or rialinat											
	,	Vehicle											
		License Plate Number					Plate Type St				Country of Issuance		
				ADC9467					AUT - AUTOMOBILE WI UNITED STAT		ATES	TES	
		ADC9467						Aalca			NA 1 1		
02	)2	ADC9467  Vehicle Identification I	Numb	er				Make MITSURISHI		Year 2018	Model MIRAGE		
02	02	ADC9467 Vehicle Identification NML32F3FJ0JHF09	Numb	oer			N	MITSUBISHI		Year 2018	Model MIRAGE Bus Use		
05	02	ADC9467  Vehicle Identification I	Numb	per			N				MIRAGE		
02	02	ADC9467 Vehicle Identification I ML32F3FJ0JHF09 Color	Numb	per			N	MITSUBISHI Body Style			MIRAGE		

#### 6TL0CR2KT0

23-08171

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Щ		Γ	Vehicle Damage							
⊨	VEHICLE			04 - RIGHT SIDE REA	AR. 05 - RIGHT RI	EAR CORNER.	7 8 9 10 11				
LNO	Ĭ	Extent Of Damage		06 - REAR, 07 - LEFT REAR CORNER, 08 - LEFT SIDE							
_	Æ	DISABLING DAMAGE		REAR, 12 - FRONT							
		Towed Due To Damage		Vehicle Removed By		L					
		TOWED DUE TO DISABI		BILLS TOWING							
		What Driver Was Doing		Vehicle Factors							
		LEFT TURN									
		Driver Prior Action Other		NOT APPLICABLE							
		Driver Actions									
	ш	UNKNOWN									
⊢											
LNO	¥										
ر	VEHICL										
		Owner Name		Owner Address							
	٠.	DAVID CHRISTIAN		S1903 COUNTY F							
05	02	(608) 408-0476		BARABOO, WI 53	3913 , US						
	9	Sequence Of Events									
		Event									
	2	MOTOR VEH IN TRANSF	PORT								
	٥.	Event									
	05	DITCH									
		Event									
	03	OTHER FIXED OBJECT									
	4	Event									
	04										
_	1	Policy Holder									
LNO		Insurance Company Individual									
$\supset$		GERMANTOWN-MUTUA	L-INS-CO	DAVID CHRISTIAN							
		Individual									
		Driver		Citations Issued	Sex						
		DAVID CHRISTIAN		0	MALE						
	₹	(608) 408-0476		Date of Birth	Race						
<b>—</b>	2				WHITE						
	IDINIDUAL	Address		Driver License Number							
_	9	S1903 COUNTY ROAD A	'	STATE: WISCONSIN COUNTRY: UNITED STATES							
	=	BARABOO, WI 53913 ,U	JS								
	0-4	On Du	ty Crash	Safety Equipment							
	Sai	fety Equipment									
		Row	Seat Position	SHOULDER & LAP	BELT						
		01 - FRONT ROW	07 - LEFT								
		Helmet Use		Helmet Compliance							
		Eye Protection		Tint Compliance							
	61	Injury C	Severity	Airbox							
02	002	Injury SUSP	PECTED MINOR INJURY	Airbag NON DEPLOYED							
		Ejected	Ejection Path			Trapped/Extricated					
		NOT EJECTED	NOT EJECTED/NOT APP	LICABLE		NOT TRAPPED					
		Medical Transport	1	EMS Agency Identifier		EMS Run #					
		EMS GROUND		6000123		804					
		Hospital		Date of Death		Time of Death					
		ST CLARE HOSP									

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 07/30/2023

		Distracted E	Distracted By Source UNKNOWN	e							
		Distracted By Action									
		UNKNOWN									
	,	Non Motori	Striking Unit #	Location							
		Prior Action Prior Action									
UNIT	INDIVIDUAL	Action									
		Action Other						To/From School			
	Ĺ	Drug & Alcoh	Suspected Alcohol L	Jse	Suspected Drug Use NO						
		Alcohol Test Given		Alcohol Test Type	oe		Alcohol Test Results				
		Drug Test Given TEST NOT GIVE	EN	Drug Test Type	Drug Test Result						
02	005	Drug Type									
		Individual Condition	n								
		APPEARED NO	RMAL								
	Pro	perty Owner									
PROP 01	Gove	ernment JK COUNTY 3) 355-4855			Address \$1903 COUNTY RD A BARABOO, WI 53913	, US					
	Fixe	d Objects St	ruck								
	5		Struck Object OTHER FIXED OBJE	СТ			Structure Number	Damage Tag Number 338346			