6TL0D5DZ0P 23-10180

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

| | verride | Primary Crash [| Document # | 23-10 | | DEPUTY | g Officer/Deputy J. HUNTER | 1 | |
|---------------------------------|---------|--|-----------------|--------------------------------|-----------|-----------------------|--------------------------------------|---------------------|--|
| Crash Date 09/17/2023 | | Crash Time 01:22 AM | | Date Arrived 09/17/2023 | | Time Arrived 01:32 AM | | | |
| Date Notified 09/17/2023 | | Time Notified 01:22 AM | | Total Units 01 | | Total Injured Total P | | (illed | |
| On Emergency Hi | | t and Run Lane Closure | | | Work Zone | Trailer or Towed | | Reporting Threshold | |
| Governme Propert | | Active School Zone School Bus Related NO | | | Tags | | | | |
| ✓ Reportable | | Crash Type DT4000 (STA | NDARD CRASH | l) | | Amend | ded | Secondary Crash | |
| Diagram | | Scot | t Rd. west of H | Y 23 | 01 | not to scale | Photos By SGT. LUBE Additional Info | ER, #11 | |

6TL0D5DZ0P 23-10180

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 09/17/2023

Crash Time 01:22 AM

| | Loc | ation | | | | | | | | | |
|---|---|--|--|---|--|-------------------------------|---|---|--|------------------------------------|--|
| ł | | SCOTT LN | | | | Latitude | | | Longitud | | |
| | 1079 FT W OF STH23 WB IN THE TOWN OF DELTON | | | | | 43.579498926 | | -89.827387122 | | | |
| | | | | | | | | Y Coord | | | |
| | IN SAUK COUNTY | | | | | | | | 482905 | 4829055 | |
| | | | | | | | Structure Type NO STRUCTURE | | | | |
| (| Cra | sh Scene | | | 1 | | | | | | |
| 1 | First | Harmful Event | | | | First Harmf | ful Event L | ocation | | | |
| | DITCH | | | | | | ER LEF | Γ | | | |
| | Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT | | | | | Light Condition | | | | | |
| | | | | | | DARK/UN | | | | | |
| | Road Surface Condition(s) DRY | | | | | | actor(s) | | | | |
| | | ironment Factor(s) | | | | | | | | | |
| | NOI | | | | | NONE | | | | | |
| | | ather Condition(s) | | | | | | | | | |
| | | EAR | | | | | | | | | |
| | | nal Type | | | | | | | | | |
| | AIIII | пагтуре | | | Relation To Trafficway TRAFFICWAY - ON ROAD | | | | | | |
| | Crash Classification - Location PUBLIC PROPERTY | | | | | Crash Class | sification · | - Jurisdiction | | | |
| | | | | | | NO SPECIAL JURISDICTION | | | | | |
| | Tribal Land | | | | Access Control NO CONTROL | | | | Special Study | | |
| | | | | | | ction Type AN INTERSECTION | | | | | |
| | NO | | NON-JUNCTION | | NOT AN II | NTERSEC | CTION | | | | |
| | | | NON-JUNCTION | | NOT AN II | NTERSEC | CTION | | | | |
| Į | Uni | t Summary Status | NON-SONCTION | Vehicle Ope | erating As Cla | | CTION | Unit Type | | | |
| | Uni Unit | t Summary | NON-SONCTION | Vehicle Ope | erating As Cla | | CTION | Unit Type TRUCK | | | |
| | Unit Unit IN T Vehi | t Summary Status FRANSIT icle Type | | | erating As Cla | | CTION | | s Endorser | ments | |
| | Unit Unit IN T Vehi | Status RANSIT icle Type LITY TRUCK/PICKUP | TRUCK | D CLASS | erating As Cla | | | TRUCK Operating A | | | |
| | Unit Unit IN T Vehi | t Summary Status FRANSIT icle Type | | D CLASS | erating As Cla | | Total Tra | TRUCK Operating A | | ments Mat Types | |
| - | Unit Unit IN T Vehi UTII Tota 1 | Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs rance? | TRUCK Train/Bus # Recorded Direction Of Travel | D CLASS Total # Cita 1 | erating As Cla | | Total Tra 0 Speed Li | TRUCK Operating A | Total Haz | Mat Types | |
| - | Unit Unit IN T Vehi UTII Tota 1 Insu | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs rance? KNOWN | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND | Total # Cita 1 | erating As Cla tions Issued CrashTire Mark | | Total Tra | TRUCK Operating A illers | Total Haz 0 Total Land | Mat Types es | |
| 5 | Unit Unit IN T Vehi UTII Tota 1 Insu | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs rance? KNOWN t Harmful Event: Collision N | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND | Total # Cita 1 Pre Special Fun | erating As Cla tions Issued CrashTire Mark | assification | Total Tra 0 Speed Li | TRUCK Operating A | Total Haz 0 Total Land 2 Motor Vehi | Mat Types es | |
| - | Unit Unit IN T Vehi Tota 1 Insu UNI Mos | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs rance? KNOWN t Harmful Event: Collision N | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND | Total # Cita 1 Pre Special Fun | tions Issued CrashTire Mark action CIAL FUNCT | assification | Total Tra 0 Speed Li | TRUCK Operating A illers mit Emergency | Total Haz 0 Total Land 2 Motor Vehi | Mat Types es icle Use | |
| | Unit Unit IN T Vehi UTII Tota 1 Insu UNI Mos DIT Traff | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs France? KNOWN t Harmful Event: Collision V CH fic Way O-WAY, NOT DIVIDED | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont | tions Issued CrashTire Mark Cidal FUNCT trol ROL | assification | Total Tra 0 Speed Li | TRUCK Operating A illers mit Emergency NOT APPI Traffic Contr | Total Haz 0 Total Land 2 Motor Vehi LICABLE ol Inoperati | Mat Types es icle Use | |
| | Unit Unit IN T Vehi UTII Tota 1 Insu UNI Mos DIT Traff TWO | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs rance? KNOWN t Harmful Event: Collision V CH fic Way O-WAY, NOT DIVIDED ace Type | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With | Total # Cita Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva | tions Issued CrashTire Mark motion CIAL FUNCT | assification | Total Tra 0 Speed Li | TRUCK Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade | Total Haz 0 Total Land 2 Motor Vehi LICABLE ol Inoperati | Mat Types es icle Use | |
| - | Unit Unit IN T Vehi Tota 1 Insu UNIT Moss DIT Traff TWG Surfa | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs rance? KNOWN It Harmful Event: Collision V CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS) | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont | tions Issued CrashTire Mark motion CIAL FUNCT | assification | Total Tra 0 Speed Li | TRUCK Operating A illers mit Emergency NOT APPI Traffic Contr | Total Haz 0 Total Land 2 Motor Vehi LICABLE ol Inoperati | Mat Types es icle Use | |
| 5 | Unit Unit IN T Vehi Tota 1 Insu UNIT Moss DIT Traff TWG Surfa | T Summary Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs FRANSIT ICLE Type LITY TRUCK/PICKUP II Occs FRANSIT ICLE Type LITY TRUCK/PICKUP ICLE Type KNOWN IT Harmful Event: Collision No CH ITCLE Type FIGURE Type ACKTOP (BITUMINOUS EXEK Bus or HazMat | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With | Total # Cita Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva | tions Issued CrashTire Mark motion CIAL FUNCT | assification | Total Tra 0 Speed Li | TRUCK Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade | Total Haz 0 Total Land 2 Motor Vehi LICABLE ol Inoperati | Mat Types es icle Use | |
| - | Unit Unit IN T Vehi Tota 1 Insu UNIT Mos DIT Traff TWC Surf BLA Truc | Status FRANSIT icle Type LITY TRUCK/PICKUP IN Occs FRANSIT ICLE Type LITY TRUCK/PICKUP IN OCCS FRANCE? KNOWN IT HARMFUL Event: Collision IN CH IT GENERAL TOTAL TO | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With | Total # Cita Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva | tions Issued CrashTire Mark motion CIAL FUNCT | FION | Total Tra 0 Speed Li 45 | TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL | Total Haz 0 Total Land 2 Motor Vehi LICABLE | Mat Types es icle Use | |
| | Unit Unit IN T Vehi Tota 1 Insu UNIT Mos DIT Traff TWC Surf BLA Truc | t Summary Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs France? KNOWN t Harmful Event: Collision V CH fic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS ck Bus or HazMat Vehicle License Plate Number | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With | Total # Cita 1 Pre Special Fur NO SPEC Traffic Cont NO CONT Road Curva STRAIGH | tions Issued CrashTire Mark nction EIAL FUNCT trol TROL ature T | assification | Total Tra 0 Speed Li 45 | TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: | Total Haz 0 Total Land 2 Motor Vehi LICABLE Tol Inoperation | Mat Types es icle Use | |
| | Unit Unit IN T Vehi Tota 1 Insu UNIT Mos DIT Traff TWC Surfa BLA Truc | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs France? KNOWN It Harmful Event: Collision V CH ffic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ek Bus or HazMat Vehicle License Plate Number RW2936 | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH | tions Issued CrashTire Mark action EIAL FUNCT trol TROL ature T | assification | Total Tra 0 Speed Li 45 St | TRUCK Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST | Total Haz 0 Total Land 2 Motor Vehi LICABLE Tol Inoperation | Mat Types es icle Use | |
| | Unit Unit IN T Vehi Tota 1 Insu UNIT Mos DIT Traff TWC Surfa BLA Truc | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs France? KNOWN It Harmful Event: Collision V CH ffic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ek Bus or HazMat Vehicle License Plate Number RW2936 Vehicle Identification Nur | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With S) | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make | tions Issued CrashTire Mark motion CIAL FUNCT trol ROL ature T | FION | Total Tra 0 Speed Li 45 St WI Year | TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: | Total Haz 0 Total Land 2 Motor Vehi LICABLE Tol Inoperation | Mat Types es icle Use | |
| | Unit Unit Unit Vehi Vehi Tota 1 Insu UNI Mos DIT Traff TWO Surfa BLA Truc | Status FRANSIT icle Type LITY TRUCK/PICKUP al Occs France? KNOWN It Harmful Event: Collision V CH ffic Way O-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS Ek Bus or HazMat Vehicle License Plate Number RW2936 | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With S) | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH | tions Issued CrashTire Mark Inction CIAL FUNCT Trol TROL ature T | FION | Total Tra 0 Speed Li 45 St | TRUCK Operating A illers mit Emergency NOT APPI Traffic Conti NO Road Grade LEVEL Country of Is: UNITED S1 Model | Total Haz 0 Total Land 2 Motor Vehi LICABLE Tol Inoperation | Mat Types es icle Use | |
| | Unit Unit Unit Vehi Vehi Tota 1 Insu UNI Mos DIT Traff TWO Surfa BLA Truc | TSummary Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs France? KNOWN It Harmful Event: Collision No CH fic Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOUS EX Bus or HazMat Vehicle License Plate Number RW2936 Vehicle Identification Nur 2GCEK19V4X118278 | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With S) | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make CHEVRO Body Style PK - PIC | tions Issued CrashTire Mark Inction CIAL FUNCT TOIL CROL STATE CHART TRUCK CLET CROL CROCK CHART TRUCK CLET CROCK | FION | Total Tra 0 Speed Li 45 St WI Year | TRUCK Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model SILVERAD | Total Haz 0 Total Land 2 Motor Vehi LICABLE Tol Inoperation | Mat Types es icle Use | |
| | Unit Unit Vehi Vehi Vehi Vehi Vehi Vehi Vehi Vehi | Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs Trance? KNOWN It Harmful Event: Collision Note CH fife Way O-WAY, NOT DIVIDED IACKTOP (BITUMINOUS) ISK Bus or HazMat Vehicle License Plate Number RW2936 Vehicle Identification Nur 2GCEK19V4X118278 Color BLK - BLACK Initial Contact Point | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With S) | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make CHEVRO Body Style | tions Issued CrashTire Mark Inction CIAL FUNCT TOIL CROL STATE CHART TRUCK CLET CROL CROCK CHART TRUCK CLET CROCK | FION | Total Tra 0 Speed Li 45 St WI Year | TRUCK Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model SILVERAD | Total Haz 0 Total Land 2 Motor Vehi LICABLE Tol Inoperation | Mat Types es icle Use tive/Missing | |
| | Unit Unit Unit IN T Vehi Tota 1 Insu UNIT Traff TWG Surfa BLA Truc NO | T Summary Status FRANSIT icle Type LITY TRUCK/PICKUP II Occs France? KNOWN It Harmful Event: Collision No CH fific Way O-WAY, NOT DIVIDED face Type ACKTOP (BITUMINOUS EX Bus or HazMat Vehicle License Plate Number RW2936 Vehicle Identification Nur 2GCEK19V4X118278 Color BLK - BLACK | TRUCK Train/Bus # Recorded Direction Of Travel WESTBOUND With S) | Total # Cita 1 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type LTK - LIC Make CHEVRO Body Style PK - PICI Vehicle Da | tions Issued CrashTire Mark Inction CIAL FUNCT TOIL CROL STATE CHART TRUCK CLET CROL CROCK CHART TRUCK CLET CROCK | FION | Total Tra 0 Speed Li 45 St WI Year | TRUCK Operating A illers mit Emergency NOT APPL Traffic Contr NO Road Grade LEVEL Country of Is: UNITED ST Model SILVERAD | Total Haz 0 Total Land 2 Motor Vehi LICABLE Tol Inoperation | Mat Types es icle Use | |

6TL0D5DZ0P 23-10180

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 09/17/2023

Crash Time 01:22 AM

| 1 1 | | Towed Due To Damage | | Vehicle Removed By | | | | | |
|------|-----------------------|--------------------------------------|-------------------|-----------------------|---------------|--------------------|--|--|--|
| | | TOWED DUE TO DISABLING | DAMAGE | PLATTS WRECKER | | | | | |
| | | | DANIAGE | | | | | | |
| | | What Driver Was Doing GOING STRAIGHT | | Vehicle Factors | | | | | |
| | | | | NOT APPLICABLE | | | | | |
| | | Driver Prior Action Other | | NOT ALL EIGHDEE | | | | | |
| | | Driver Actions | | | | | | | |
| | 111 | Diver Actions | | | | | | | |
| ⊢ | 7 | | | | | | | | |
| UNIT | \ | | | | | | | | |
| ⊃ ∣ | VEHICLE | | | | | | | | |
| | > | | | | | | | | |
| | | Owner Name | | Owner Address | | | | | |
| | | ROBERT CARLIN (608) 495- | 9553 | 424 FRANKLIN S | Т | | | | |
| 2 | 0 | | | REEDSBURG, W | 153959 , US | | | | |
| | | | | | | | | | |
| | , | Sequence Of Events | | | | | | | |
| | 01 | Event | | | | | | | |
| | 0 | DITCH | | | | | | | |
| | 02 | Event | | | | | | | |
| | 8 | Event | | | | | | | |
| | 03 | | | | | | | | |
| | 04 | Event | | | | | | | |
| | | | | | | | | | |
| | ı | Individual | | | | | | | |
| | | Driver | | Citations Issued Sex | | | | | |
| | إ | ROBERT CARLIN (608) 495- | 9553 | 1 MALE | | | | | |
| | INDIVIDUAL | | | Date of Birth | Race WHITE | | | | |
| ţ | | | | | | | | | |
| LIND | | Address 424 FRANKLIN ST | | Driver License Numbe | r | | | | |
| | Ξ | REEDSBURG, WI 53959 , U | S | STATE: WISCONSI | N COUNTRY: UN | ITED STATES | | | |
| | | | | | | | | | |
| | l. | On Duty Cr | ash | Safety Equipment | | | | | |
| | Saf | ety Equipment | | carety _qa.p.mem | | | | | |
| | | Row | Seat Position | RESTRAINT USE U | INKNOWN | | | | |
| | | 01 - FRONT ROW | 07 - LEFT | | | | | | |
| | | Helmet Use | | Helmet Compliance | | | | | |
| | | E D : : | | | | | | | |
| | | Eye Protection | | Tint Compliance | | | | | |
| | _ | Injury Seve | ritv | Airbag | | | | | |
| 0 | 90 | | RENT INJURY | NON DEPLOYED | | | | | |
| | | | ection Path | | | Trapped/Extricated | | | |
| | | NOT EJECTED N | OT EJECTED/NOT AP | PLICABLE | | NOT TRAPPED | | | |
| | | Medical Transport | | EMS Agency Identifier | | EMS Run # | | | |
| | | NOT TRANSPORTED | | | | | | | |
| | | Hospital | | Date of Death | Date of Death | | | | |
| | | Distracted By Source | | | | | | | |
| | | Distracted By UNKNOWN | | | | | | | |
| | | Distracted By Action UNKNOWN | | | | | | | |
| | Non Motorist Location | | | | | | | | |
| | | NOIT WOUTST | | | | | | | |

6TL0D5DZ0P 23-10180

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 09/17/2023

Crash Time 01:22 AM

| Action | | | | | | |
|----------------------|---|--|--------------------------------------|--|------------------------------------|--------------------------------------|
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| Action Other | | | | | | To/From School |
| | | | | | | |
| Drug & Alcohol | Suspected Alco | hol Use | Suspected Drug Use | | | |
| _ | 120 | Alcohol Toot Type | | | Alashal Test Posults | |
| | | | | | | |
| Drug Test Given | | Drug Test Type | | Drug Test Results | | |
| | | | | | | |
| Drug Type | | | | | | |
| | | | | | | |
| Individual Condition | | | | | | |
| UNDER THE INFLI | UENCE OF MI | EDICATIONS/DRUGS | / ALCOHOL | | | |
| | | | | | | |
| | I. + 0 | 0 | In: | | | |
| BG110208 | 1ssue To? 001 | 346.63(1)(a) | OPERATING WHILE | UNDER THE IN | FLUENCE | |
| | Action Other Drug & Alcohol Alcohol Test Given TEST GIVEN Drug Test Given TEST NOT GIVEN Drug Type Individual Condition UNDER THE INFL Violations UTC Number | Action Other Drug & Alcohol Alcohol Test Given TEST GIVEN Drug Test Given TEST NOT GIVEN Drug Type Individual Condition UNDER THE INFLUENCE OF ME Violations UTC Number Issue To? | Action Other Drug & Alcohol YES | Action Other Drug & Alcohol Suspected Alcohol Use YES Suspected Drug Use NO | Action Other Drug & Alcoho YES | Action Other Drug & Alcohol YES |