
6TL0D7W16G

23-11125

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895



This report does not include any CJIS data. $1 \quad \text{of} \quad 4$

23-11125

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Loc	ation									
f		RIVATE PROPERTY					Latitude		Longitu	Longitude	
		350 CRAWFORD ST				43.487308281		-89.74	3612608		
		RE E4350)				X Coordinate			Y Coord		
	IN T	THE TOWN OF BARAE	300			277739.0			48186	02	
	IN S	SAUK COUNTY			Structure Type						
					FIRE						
	Cra	sh Scene									
Ī	First	Harmful Event				First Harm	nful Event L	ocation			
		DITCH					SHOULDER RIGHT				
		ner of Collision	Light Cond								
			HICLE IN TRANSPORT			DARK/U					
		d Surface Condition(s)				Roadway	Factor(s)				
	WE.	т									
Ì	Envi	ironment Factor(s)									
	WE	ATHER CONDITIONS				NONE					
	Wea	ather Condition(s)									
	RAI										
	Anim	nal Type				Relation To Trafficway					
	<u></u>					NON TRAFFICWAY - OTHER					
		sh Classification - Location				Crash Classification - Jurisdiction PRIVATE PROPERTY					
		ibal Land				Access Control Special Study					
						NO CONTROL					
	With	thin Interchange Area Junction Location Inte				ection Type					
	NO		NON-JUNCTION NOT AN			N INTERSECTION					
l	Uni	t Summary 🛛 💻									
ו ן 		t Summary Status		Vehicle Ope	erating As C	lassification		Unit Type			
	Unit IN T	Status FRANSIT		Vehicle Ope	-	assification	I	AUTOMO			
	Unit IN T Vehi	Status FRANSIT icle Type		-	-	lassification	I			ments	
01	Unit IN T Vehi PAS	Status TRANSIT icle Type SSENGER CAR	Troip/Dup # Departed	D CLASS				AUTOMO Operating A	s Endorse		
	Unit IN T Vehi PAS Tota	Status FRANSIT icle Type	Train/Bus # Recorded	D CLASS			Total Trai	AUTOMO Operating A	As Endorse	ments zMat Types	
	Unit IN T Vehi PAS Tota 1	Status IRANSIT icle Type SSENGER CAR il Occs		D CLASS	tions Issued	1	Total Trai 0	AUTOMO Operating A	As Endorse	zMat Types	
01	Unit IN T Vehi PAS Tota 1	Status IRANSIT icle Type SSENGER CAR il Occs rance?	Train/Bus # Recorded Direction Of Travel NOT ON ROADWAY	D CLASS	tions Issued	1	Total Trai	AUTOMO Operating A	As Endorse	zMat Types	
01	Unit IN T Vehi PAS Tota 1 Insur YES	Status IRANSIT icle Type SSENGER CAR il Occs rance?	Direction Of Travel	D CLASS	tions Issued CrashTire Mark	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency	s Endorse Total Haz 0 Total Lar Motor Veh	Mat Types les icle Use	
	Unit IN T Vehi PAS Tota 1 Insur YES	Status FRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision	Direction Of Travel	D CLASS	tions Issued CrashTire Mark	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers	s Endorse Total Haz 0 Total Lar Motor Veh	Mat Types les icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES Most DIT Traff	Status FRANSIT icle Type SSENGER CAR I Occs rance? S t Harmful Event: Collision CH fic Way	Direction Of Travel NOT ON ROADWAY With	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont	S Endorse	Mat Types les icle Use	
01	Unit IN T Vehi PAS Tota 1 Insui YES DIT Traff PAF	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA	Direction Of Travel NOT ON ROADWAY With	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lar Total Lar Motor Ver LICABLE rol Inopera	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insur YES DIT Traff PAF Surfa	Status FRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type	Direction Of Travel NOT ON ROADWAY With TE PROPERTY	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff PAF Surfa BLA	Status FRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU	Direction Of Travel NOT ON ROADWAY With TE PROPERTY	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES Most DIT Traff PAF Surfa BLA	Status FRANSIT icle Type SSENGER CAR il Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat	Direction Of Travel NOT ON ROADWAY With TE PROPERTY	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES Moss DIT Traff PAF Surfa BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat	Direction Of Travel NOT ON ROADWAY With TE PROPERTY	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC trol ROL ature	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES Moss DIT Traff PAF Surfa BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU kk Bus or HazMat Vehicle	Direction Of Travel NOT ON ROADWAY With TE PROPERTY	D CLASS	tions Issued CrashTire Mark notion IAL FUNC trol TROL ature EFT	1	Total Trai 0 Speed Lir	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES Moss DIT Traff PAF Surfa BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat	Direction Of Travel NOT ON ROADWAY With TE PROPERTY	D CLASS	tions Issued CrashTire Mark notion IAL FUNC trol TROL ature EFT		Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES DIT Traff BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU kk Bus or HazMat Vehicle License Plate Number	Direction Of Travel NOT ON ROADWAY With TE PROPERTY S)	D CLASS	tions Issued Mark notion IAL FUNC TROL ature EFT		Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES Moss DIT Traff PAF Surfa BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU kk Bus or HazMat Vehicle License Plate Number APZ8718	Direction Of Travel NOT ON ROADWAY With TE PROPERTY S)	D CLASS	tions Issued Mark Inction IAL FUNC TROL Ature EFT		Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES DIT Traff BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number APZ8718 Vehicle Identification Nut 1G1PC5SH5C721193 Color	Direction Of Travel NOT ON ROADWAY With TE PROPERTY S)	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type AUT - AL Make CHEVRO Body Style	tions Issued Mark Inction IAL FUNC TROL Ature EFT JTOMOBII		Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	zMat Types ies icle Use	
01	Unit IN T Vehi PAS Tota 1 Insuu YES DITO Traff PAR Surfr BLA Truce NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU ik Bus or HazMat Vehicle License Plate Number APZ8718 Vehicle Identification Num 1G1PC5SH5C721193 Color SIL - SILVER (ALUM	Direction Of Travel NOT ON ROADWAY With TE PROPERTY S)	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type AUT - AL Make CHEVRO Body Style SD - SED	tions Issued Mark Inction IAL FUNC TROL Ature EFT JTOMOBII		Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model CRUZE	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	zMat Types ies icle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES Most DIT Traff PAF Surfa BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number APZ8718 Vehicle Identification Nut 1G1PC5SH5C721193 Color SIL - SILVER (ALUM Initial Contact Point	Direction Of Travel NOT ON ROADWAY With TE PROPERTY S) mber 33 INUM)	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva CURVE LI Plate Type AUT - AL Make CHEVRO Body Style	tions Issued Mark Inction IAL FUNC TROL Ature EFT JTOMOBII		Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model CRUZE	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	zMat Types ies icle Use	
UNIT 01	Unit IN T Vehi PAS Tota 1 Insu YES Most DIT Traff PAF Surfa BLA Truc NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU ACKTOP (BITUMINOU ACKTOP (BITUMINOU ACKTOP (BITUMINOU ACKTOP (BITUMINOU COLOR License Plate Number APZ8718 Vehicle Identification Nuu 1G1PC5SH5C721193 Color SIL - SILVER (ALUM Initial Contact Point 14 - UNDERCARRIA	Direction Of Travel NOT ON ROADWAY With TE PROPERTY S) mber 33 INUM)	D CLASS	tions Issued Mark Diction BIAL FUNC Trol ROL Ature EFT JTOMOBII	TION	Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model CRUZE	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	Mat Types les licle Use tive/Missing	
01	Unit IN T Vehi PAS Tota 1 Insuu YES DITO Traff PAR Surfr BLA Truce NO	Status FRANSIT icle Type SSENGER CAR al Occs rance? S t Harmful Event: Collision CH fic Way RKING LOT OR PRIVA ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number APZ8718 Vehicle Identification Nut 1G1PC5SH5C721193 Color SIL - SILVER (ALUM Initial Contact Point	Direction Of Travel NOT ON ROADWAY With TE PROPERTY S) mber 33 INUM)	D CLASS	tions Issued Mark Inction IAL FUNC TROL Ature EFT JTOMOBII	TION	Total Trai 0 Speed Lir N/A	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade DOWNHII Country of Is UNITED S Model CRUZE	Total Haz 0 Total Lar Motor Ver LICABLE rol Inopera L suance	2Mat Types les licle Use titve/Missing	

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

2 of 4

6TL0D7W16G

23-11125

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage			Vehicle Removed By						
		NOT TOWED What Driver Was Doing				OPERATOR					
		BACKING	ng		ver	Vehicle Factors					
		Driver Prior Action Other			NOT APPLICABLE						
		Driver Actions									
	Щ	NO CONTRIBUTIN	IG ACTIO	N							
UNIT	VEHICLE										
Ξ	Ē										
	>										
		Owner Name				Owner Address					
	6	JOEL DINGAMNAYAL				E9430 DELLWOOD RD # 209 REEDSBURG, WI 53959, US					
	•	(608) 745-2673				REEDSBORG, W	155555 , 05				
						l					
		Sequence Of Ev Event									
	6	DITCH									
	02	Event									
	0										
	03	Event									
		Event									
	8										
⊢		L Policy Holder									
UNIT		Insurance Company				Individual					
		PROGRESSIVE-CLASSIC-INS-CO				JOEL DINGAMNAYAL					
	I	Individual									
		Driver JOEL DINGAMNAYAL				Citations Issued Sex 0 MALE					
	NDIVIDUAL	(608) 745-2673				Date of Birth	MALE Race				
⊢						BLACK/AFRICAN AMERICAN					
UNIT	≥	Address		_	1	Driver License Number					
2	P	E9430 DELLWOOD RD # 209 REEDSBURG, WI 53959 ,US									
	-										
		On Duty Crash				Safety Equipment					
	Saf	fety Equipment			ľ						
		Row		Seat Position 07 - LEFT		SHOULDER & LAP BELT					
		01 - FRONT ROW									
		Helmet Use			'	Helmet Compliance					
		Eye Protection				Tint Compliance					
0	001	Injury Severity			Airbag						
Ŭ	•	Ejected		RENT INJURY	1	NON DEPLOYED		Trapped/Extricated			
		NOT EJECTED	Ejection Path TED NOT EJECTED/NOT A			ABLE		NOT TRAPPED			
		Medical Transport				EMS Agency Identifier	r	EMS Run #			
		NOT TRANSPORTED									
		Hospital				Date of Death Time of Death					
	Distracted Dr. Course										
	Distracted By Distracted By Source UNKNOWN										
		Distracted By Action									
	UNKNOWN										

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 3 of 4

6TL0D7W16G 23-11125

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		Non Motorist	Striking Unit #	Location					
		Prior Action							
UNIT	INDIVIDUAL	Action							
		Action Other						To/From School	
	L	Drug & Alcohol	Suspected Alcohol U NO	lse	Suspected Drug Use NO				
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type			Alcohol Test Results		
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	3		
6	001	Drug Type		·		·			
		Individual Condition							
		APPEARED NORMAL							