

6TL0D6N04T  
23-11606

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

6TL0D6N04T

Document Number Override		Primary Crash Document #	Agency Crash Number <b>23-11606</b>	Investigating Officer/Deputy <b>DEPUTY B. STODDARD</b>	
Crash Date <b>10/26/2023</b>		Crash Time <b>05:15 AM</b>	Date Arrived <b>10/26/2023</b>	Time Arrived <b>05:37 AM</b>	
Date Notified <b>10/26/2023</b>		Time Notified <b>05:15 AM</b>	Total Units <b>01</b>	Total Injured <b>00</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input checked="" type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone	School Bus Related <b>NO</b>	Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p> <p>Not to Scale</p>	Reconstruction By
	Photos By
	Additional Information <b>NONE</b>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 OPERATOR IS THE TOWNSHIP CHAIRMAN AND WAS INSPECTING THE ROAD. UNIT 1 OPERATOR WAS BACKING AND BACKED INTO THE EAST SHOULDER. UNIT 1 OPERATOR BACKED ONTO THE EDGE OF A CONCRETE BOX CULVERT END. UNIT 1 OVERTURNED AND CAME TO REST ON IT'S RIGHT SIDE IN THE DITCH AT THE EAST END OF THE BOX CULVERT.

6TL0D6N04T  
23-11606

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

Location

ON BREEZY HILL RD 0.31 MI N OF WALL STREET RD IN THE TOWN OF FAIRFIELD IN SAUK COUNTY	Latitude <b>43.497078778</b>	Longitude <b>-89.600155523</b>
	X Coordinate <b>289778.15625</b>	Y Coordinate <b>4819301.5</b>
	Structure Type	

Crash Scene

First Harmful Event <b>OVERTURN/ROLLOVER</b>	First Harmful Event Location <b>SHOULDER RIGHT</b>	
Manner of Collision <b>00 - NO COLLISION W/VEHICLE IN TRANSPORT</b>	Light Condition <b>DARK/UNLIT</b>	
Road Surface Condition(s) <b>WET</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>		
Weather Condition(s) <b>RAIN</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

Unit Summary

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>	Unit Type <b>TRUCK</b>		
	Vehicle Type <b>UTILITY TRUCK/PICKUP TRUCK</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>SOUTHBOUND</b>	<input type="checkbox"/> <b>Pre CrashTire Mark</b>	Speed Limit <b>45</b>	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>OVERTURN/ROLLOVER</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>				

<b>UNIT</b>	<b>Vehicle</b>				
	<b>VEHICLE</b>	License Plate Number <b>306188F</b>	Plate Type <b>LTK - LIGHT TRUCK</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>5TFUU4EN6CX035235</b>	Make <b>TOYOTA</b>	Year <b>2012</b>	Model <b>TACOMA</b>
		Color <b>BLU - BLUE</b>	Body Style <b>PK - PICKUP</b>	Bus Use	
		Initial Contact Point <b>05 - RIGHT REAR CORNER</b>	Vehicle Damage <b>01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 03 - RIGHT SIDE MIDDLE, 04 - RIGHT SIDE REAR, 05 - RIGHT REAR CORNER, 06 - REAR, 12 - F</b>		
Extent Of Damage <b>DISABLING DAMAGE</b>					



6TL0D6N04T

23-11606

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

UNIT VEHICLE	Towed Due To Damage <b>TOWED DUE TO DISABLING DAMAGE</b>		Vehicle Removed By <b>CRAIGS TOWING</b>	
	What Driver Was Doing <b>BACKING</b>		Vehicle Factors	
	Driver Prior Action Other		<b>NOT APPLICABLE</b>	
	Driver Actions <b>RAN OFF ROADWAY</b>			
01 01	Owner Name <b>LARSEN FARMS (608) 963-3211</b>		Owner Address <b>S4060 COUNTY ROAD T BARABOO, WI 53913 , US</b>	
	<b>Sequence Of Events</b>			
01 01	01	Event <b>OVERTURN/ROLLOVER</b>		
	02	Event		
	03	Event		
	04	Event		
UNIT	<b>Policy Holder</b>			
	Insurance Company <b>AUTO-OWNERS-INS-CO</b>		Organization/Company <b>LARSEN FARMS</b>	
UNIT INDIVIDUAL	<b>Individual</b>			
	Driver <b>EUGENE LARSEN (608) 963-3211</b>		Citations Issued <b>0</b>	Sex <b>MALE</b>
	Address <b>S4060 COUNTY ROAD T BARABOO, WI 53913 , US</b>		Date of Birth	Race <b>WHITE</b>
	Driver License Number <b>STATE: WISCONSIN COUNTRY: UNITED STATES</b>			
01 001	<b>Safety Equipment</b>		On Duty Crash	
	Row <b>01 - FRONT ROW</b>		Seat Position <b>07 - LEFT</b>	
	Safety Equipment <b>SHOULDER &amp; LAP BELT</b>		Helmet Compliance	
	Helmet Use		Tint Compliance	
	Eye Protection		Airbag <b>DEPLOYED-SIDE</b>	
	<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	
Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>		
Trapped/Extricated <b>NOT TRAPPED</b>		Medical Transport <b>NOT TRANSPORTED</b>		
EMS Agency Identifier		EMS Run #		
Hospital		Date of Death		
Time of Death		<b>Distracted By</b>		
Distracted By Source <b>NOT APPLICABLE (NOT DISTRACTED)</b>		Distracted By Action <b>NOT DISTRACTED</b>		

6TL0D6N04T

23-11606

# WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT  
1300 LANGE COURT  
BARABOO, WI 53913  
(608) 356-4895

<b>UNIT</b>	<b>Non Motorist</b>	Striking Unit #	Location			
		Prior Action				
	<b>INDIVIDUAL</b>	Action				
		Action Other			To/From School	
		<b>Drug &amp; Alcohol</b>	Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>		
		Alcohol Test Given <b>TEST NOT GIVEN</b>	Alcohol Test Type		Alcohol Test Results	
	<b>01</b>	<b>001</b>	Drug Test Given <b>TEST NOT GIVEN</b>	Drug Test Type	Drug Test Results	
			Drug Type			
			Individual Condition <b>APPEARED NORMAL</b>			
	<b>Property Owner</b>					
<b>PROP OWNER</b>	<b>01</b>	Government <b>TOWNSHIP OF FAIRFIELD</b> (608) 356-3485		Address <b>E13594 FAIRFIELD RD</b> <b>BARABOO, WI 53913 , US</b>		
		<b>Fixed Objects Struck</b>				
<b>01</b>	Striking Unit	Struck Object		Structure Number	Damage Tag Number	
	<b>01</b>	<b>BRIDGE PARAPET END</b>				