6TL0F8QXW2

SC23-11570

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Document Number Overrie	de Primary Crash	Document #		y Crash Number - 11570		Officer/Deputy	
Crash Date 10/25/2023	Crash Time 08:33 AM			rrived /2023	Time Arrived 08:37 AM Total Injured Total Killed 01 00		
Date Notified 10/25/2023				Inits			Killed
On Emergency	Hit and Run		sure	Work Zone	Trailer	or Towed	Reporting Threshold
Government Property	Active S	chool Zone	School NO	Bus Related	Tags		
✓ Reportable	Crash Type DT4000 (STA	ANDARD CRAS	iH)		Amend	ed	Secondary Crash
Description						Reconstructio	_
Ø						Photos By DEPUTY GF	REENWOOD
	STH 33					Additional Info PHOTOS	rmation
				_			
			Not	to Scale			
✔ I, a sworn law enformed and a sworn law	orcement officer, agr	ee that I have r	not adde	d any CJIS data in th	nis report.		
UNIT 1 WAS EB ON STH 3	3. UNIT 1 STRUCK A DEE	ER CAUSING THE	AIRBAGS	TO DEPLOY. DRIVER OF	UNIT ONE SUSTA	INED A RIGHT	FOREARM INJURY.

This report does not include any CJIS data. 1 of 5 $\,$

SC23-11570

WISCONSIN MOTOR VEHICLE CRASH REPORT

	0.48	STH33 EB 8 MI W				Latitude 43.52565	5483		Longitud -89.846	de 5 824778
1	IN T	MIRROR LAKE RD HE TOWN OF EXCEL	X Coordinate 269942.8125		Y Coord 482312	linate				
	IN 5	AUK COUNTY				Structure Type NO STRUCTURE				
С	cra	sh Scene 📃								
Π	First	Harmful Event				First Harm	nful Event L	ocation		
		N DOMESTICATED AN	NIMAL (ALIVE)			ON ROA	DWAY			
							dition			
	00 - NO COLLISION W/VEHICLE IN TRANSPORT						НТ			
1	Road	d Surface Condition(s)				Roadway	Factor(s)			
١	WE	т								
	Envi	ronment Factor(s)				-				
I	NO	NE				NONE				
١	Wea	ther Condition(s)								
•	CLC	DUDY, RAIN								
	Anim DEE	nal Type E R					o Trafficwa CWAY - O	•		
(Cras	h Classification - Location				Crash Clas	ssification -	Jurisdiction		
		al Land				Access Co				Special Study
						NO CONTROL				
	With NO	in Interchange Area	Junction Location NON-JUNCTION		Intersection Type NOT AN INTERSECTION					
	Ini	t Summary								
		L Summary —								
		Status		Vehicle Ope	erating As C	lassification	I	Unit Type		
Π	Unit			Vehicle Ope D CLASS	erating As C	lassification	l	Unit Type AUTOMO	BILE	
1	Unit IN T Vehi	Status TRANSIT cle Type	-		erating As C	lassification				ments
(Unit IN T Vehi (SP)	Status RANSIT cle Type ORT) UTILITY VEHICL		D CLASS				AUTOMO Operating A	s Endorse	
	Unit IN T Vehi (SP)	Status TRANSIT cle Type	E Train/Bus # Recorded				Total Trail	AUTOMO Operating A	s Endorse	ments Mat Types
	Unit IN T Vehi (SP (SP Tota 2	Status RANSIT cle Type ORT) UTILITY VEHICL		D CLASS	tions Issued	1	Total Trail	AUTOMO Operating A	s Endorse	:Mat Types
	Unit IN T Vehi (SP (SP Tota 2	Status RANSIT cle Type ORT) UTILITY VEHICI I Occs rance?	Train/Bus # Recorded	D CLASS		1	Total Trail	AUTOMO Operating A	s Endorse Total Haz 0	:Mat Types
	Unit IN T Vehi (SP (SP Tota 2 Insu Insu YES	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? S t Harmful Event: Collision 1	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency	s Endorse Total Haz 0 Total Lan 2 Motor Veh	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insur YES Most	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark ction IAL FUNC	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency NOT APP	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insur YES Most NOI Traff	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types es icle Use
	Unit IN T Vehi (SP (SP Tota 2 Insu Not Not Traff	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insur YES Most NON Traff Tw(Surfa	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insu YES Most NOI Traff TW(Surfa BLA	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insu YES Most NOI Traff TW(Surfa BLA	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insu YES Most NOI Traff Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? A DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture	1	Total Trail 0 Speed Lin	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insu YES Most NOI Traff Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Tharmful Event: Collision ' N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL tture T		Total Trail 0 Speed Lin 55	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insu YES Most NOI Traff Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Tharmful Event: Collision ' N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 575PWY	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE) S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T		Total Trail 0 Speed Lin 55 St WI	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP(Tota 2 Insuu YES Most Traff TW(Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision ' N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 575PWY Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE) S) S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL tture T		Total Trail 0 Speed Lin 55 St WI Year	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP Tota 2 Insu YES Most NOI Traff Surfa BLA Truc NO	Status RANSIT cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 575PWY Vehicle Identification Nur 2FMPK4J92KBC167	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE) S) S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T		Total Trail 0 Speed Lin 55 St WI	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S Model EDGE	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP(Tota 2 Insuu YES Most Traff TW(Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision ' N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 575PWY Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE) S) S)	D CLASS	tions Issued CrashTire Mark Iction IAL FUNC rol ROL Iture T		Total Trail 0 Speed Lin 55 St WI Year 2019	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit IN T Vehi (SP(Tota 2 Insu YES Most NOI Traff TW(Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 575PWY Vehicle Identification Nur 2FMPK4J92KBC1670 Color BLU - BLUE Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE) S) S)	D CLASS	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T		Total Trail 0 Speed Lin 55 St WI Year 2019	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S Model EDGE	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use tive/Missing
	Unit IN T Vehi (SP(Tota 2 Insu YES Most NOI Traff TW(Surfa BLA Truc NO	Status Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 575PWY Vehicle Identification Nur 2FMPK4J92KBC1670 Color BLU - BLUE Initial Contact Point 12 - FRONT	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE) S) S)	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AL Make FORD Body Style UT - SPC Vehicle Da 01 - RIGI	tions Issued Mark ction IAL FUNC rol ROL iture T ITOMOBII PRT UTILI mage HT FRON		Total Trail 0 Speed Lin 55 St WI Year 2019 LE	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S Model EDGE	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use
	Unit Unit IN T Vehii (SP) Tota 2 Insui YES Most Trafff TWC Surfa BLA Truc NO	Status RANSIT Cle Type ORT) UTILITY VEHICL I Occs rance? Harmful Event: Collision 1 N DOMESTICATED AN ic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOU k Bus or HazMat Vehicle License Plate Number 575PWY Vehicle Identification Nur 2FMPK4J92KBC1670 Color BLU - BLUE Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND With NIMAL (ALIVE) S S mber 03	D CLASS Total # Cita 0 Pre Special Fun NO SPEC Traffic Cont NO CONT Road Curva STRAIGH Plate Type AUT - AL Make FORD Body Style UT - SPC Vehicle Da 01 - RIGI	tions Issued CrashTire Mark ction IAL FUNC rol ROL iture T ITOMOBII PRT UTILIT mage		Total Trail 0 Speed Lin 55 St WI Year 2019 LE	AUTOMO Operating A lers nit Emergency NOT APP Traffic Cont NO Road Grade LEVEL Country of Is UNITED S [*] Model EDGE Bus Use	s Endorsei Total Haz 0 Total Lan 2 Motor Veh LICABLE rol Inopera	Mat Types es icle Use tive/Missing

Wisconsin Motor Vehicle Crash Form DT4000

This report does not include any CJIS data.

2 of 5



SC23-11570

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage TOWED DUE TO DIS		DAMAGE		hicle Removed By				
		What Driver Was Doing	ABLING	5 DAMAGE		EVES AUTO SERV hicle Factors	ICE			
		GOING STRAIGHT Driver Prior Action Other			ve					
					NC	OT APPLICABLE				
UNIT	VEHICLE	Driver Actions NO CONTRIBUTING	ACTIO	N	I					
01	01	Owner Name RONALD THO (608) 768-0287	MPSON	ı		Owner Address 529 BABB AVE REEDSBURG, WI	53959 , US			
	:	Sequence Of Eve	nts							
	2	Event NON DOMESTICATE	D ANIN	IAL (ALIVE)						
	02	Event								
	03	Event								
	8	Event								
F		Policy Holder								
UNIT		Insurance Company OWNERS-INS-CO				Individual RONALD THOMPS	ON			
		Individual								
						Citations Issued Sex				
	AL	RONALD THOMPSON (608) 768-0287				0 MALE Date of Birth Race				
⊢	D					WHITE				
UNIT	INDIVIDUAL	Address 529 BABB AVE REEDSBURG, WI 539	959 ,U	s	1	Driver License Number	-			
		On	n Duty Cr	ash		Safety Equipment				
	Sat	fety Equipment								
		Row 01 - FRONT ROW		Seat Position 07 - LEFT	:	SHOULDER & LAP	BELT			
		Helmet Use			Helmet Compliance					
		Eye Protection				Tint Compliance				
6	001		ury Seve	rity FED MINOR INJURY		Airbag DEPLOYED-FRON	r			
	-	Ejected		ection Path			•	Trapped/Extricated		
		NOT EJECTED	N	OT EJECTED/NOT AP	PLIC	CABLE		NOT TRAPPED		
		Medical Transport				EMS Agency Identifier 6001024		EMS Run #		
		EMS GROUND Hospital				Date of Death		Time of Death		
			stracted I	By Source						
		Distracted By NO	OT APP	LICABLE (NOT DISTR	RAC	red)				
		NOT DISTRACTED								
								O D	40/05/0000	

Wisconsin Motor Vehicle Crash Form DT4000 This report does not include any CJIS data. 3 of 5

6TL0F8QXW2

SC23-11570

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Non Motorist	Striking Un	it #	Location							
		Prior Action										
		Action										
F	INDIVIDUAL											
UNIT	DIVI											
	Z											
		Action Other							To/From School			
			Suspected	Alcohol II	60	Suspected Drug Use						
	L	Drug & Alcohol	NO			NO						
		Alcohol Test Given TEST NOT GIVEN			Alcohol Test Type)		Alcohol Test Results				
		Drug Test Given TEST NOT GIVEN			Drug Test Type		Drug Test Results	i				
0	001	Drug Type					·					
		Individual Condition										
		APPEARED NORM	APPEARED NORMAL									
		Individual										
		Passenger SHERRY THOMPSON (608) 768-0287				Citations Issued	Sex					
	_					0 FEMALE						
∟	INDIVIDUAI					Date of Birth	Race WHITE					
UNIT	DIVI	Address 529 BABB AVE					er					
	Z	REEDSBURG, WI	53959 , U	S								
	Saf	fety Equipment	On Duty Cr	ash		Safety Equipment						
		Row		Seat Po	sition	SHOULDER & LAF						
		01 - FRONT ROW Helmet Use										
						Helmet Compliance						
		Eye Protection				Tint Compliance						
6	02	Injury Severity NO APPARENT I				Airbag						
	0	Ejected		ection Pa		DEPLOYED-CURT	AIN	Trapped/Extricated				
		NOT EJECTED			CTED/NOT APP	LICABLE NOT TRA		NOT TRAPPED				
		Medical Transport NOT TRANSPORTED				EMS Agency Identifier		EMS Run #				
		Hospital	20			Date of Death		Time of Death				
		Distracted Pu	Distracted	By Source)							
		Distracted By Distracted By Action										
			Otellein - 12	:+ #	Loootica							
		Non Motorist	Striking Un	it #	Location							
Nisco	nsin N	Motor Vehicle Crash			This repor	t does not include any C	JIS data.	Crash Date	10/25/2023			

6TL0F8QXW2

SC23-11570

WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action					
		Action					
UNIT	INDIVIDUAL						
		Action Other	ahol I Isa	Suspected Drug Use			To/From School
	L	Drug & Alcohol NO		NO			
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type			Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	3	
6	002	Drug Type					
		Individual Condition					
		APPEARED NORMAL					