6TL0DRXHK1

23-12703

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash D	ocument #	Agency 23-127	Crash Number			Officer/Deputy	
2	Crash Date 11/26/2023	Crash Time 07:32 AM		Date Arrived 11/26/2023			Time Arrived 07:42 AM		
PICUDRAHA	Date Notified 11/26/2023	Time Notified 07:32 AM		Total Ui	nits		Total Injured 00	Total Kil	led
ב	On Emergency Hit	and Run	Lane Closu	ıre	Work Zone		Trailer	or Towed	Reporting Threshold
	Government Property	Active Sch	nool Zone	School NO	Bus Related		Tags		
	✓ Reportable	Crash Type DT4000 (STAN	NDARD CRASH)			Amend	ed	Secondary Crash
	Description Diagram								
		N	ot to Scale			w⊲ (Z ←	Photos By	,
				USH 1	2			Additional Inf PHOTOS	ormation
	I, a sworn law enforceme	USH 12, SOUTHB	OUND. UNIT 1 ST	ARTED T	O FISHTAILING AND			CH. ON THE V	VAY INTO THE DITCH UNIT 1
	STRUCK A POLE AND CONTINUED	ON. UNIT 1 CAM	IE TO A STOP UP A	AGAINST	A TREE.				

6TL0DRXHK1 23-12703

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/26/2023

Crash Time 07:32 AM

	loc	ation									
		RAMP IH90 EB				Latitude			Longi	tude	
	459	FTN				43.566306622		_	78636636		
	OF USH12 EB IN THE VILLAGE OF LAKE DELTON IN SAUK COUNTY					X Coordinate			Y Coordinate		
						275604.4375			4827	457	
						Structure Type					
						NO STR	UCTURE				
	Cra	sh Scene									
•	First	Harmful Event				First Harm	nful Event Lo	ocation			
	OTHER POST, POLE OR SUPPORT					ROADSIDE					
		ner of Collision					Light Condition				
		NO COLLISION W/VE				HT					
	Roa	d Surface Condition(s)				Factor(s)					
	SNC	OW, SLUSH									
	Envi	ronment Factor(s)				†					
	WE	ATHER CONDITIONS				NONE					
	Weather Condition(s)										
	SNO	ow									
	Animal Type Crash Classification - Location PUBLIC PROPERTY Tribal Land					Relation To Trafficway					
							CWAY - O	•			
							ssification -				
							NO SPECIAL JURISDICTION				
						Access Control			Special Study		
						NO CON	ITROL				
		in Interchange Area	Junction Location		Intersecti		OTION				
	NO	. =	NON-JUNCTION		NOT AN	INTERSE	CHON				
		t Summary Status		I Vahiala On	orating As (Nassification		Turat			
				D CLASS	-	Classification Unit Type AUTOMOBILE					
	IN TRANSIT Vehicle Type			D CLASS	DOLAGO			Operating As Endorsements			
5		SENGER CAR									
	Tota	l Occs	Total # Citations Issued		Total Trailers		Total HazMat Types				
	1			0 Pre CrashTire							
		rance?	Direction Of Travel							anes	
	YES SOUTHBOUND						45		4		
	Most Harmful Event: Collision With OTHER POST, POLE OR SUPPORT			· ·	Special Function NO SPECIAL FUNCTION			Emergency Motor Vehicle Use NOT APPLICABLE			
	Traffic Way Traffic Control			trol			Traffic Control Inoperative/Missing				
	DIVIDED HWY W/TRAFFIC BARRIER			NO CONT	NO CONTROL			NO			
		Surface Type			Road Curvature			Road Grade			
		ACKTOP (BITUMINOU: k Bus or HazMat	S)	CURVE R	CURVE RIGHT			UPHILL			
	NO	K Bus or Hazmat									
	,	Vehicle									
	License Plate Number			Plate Type			St	Country of Is			
		524YBL	AUT - AUTOMOBILE Make TOYOTA		WI	UNITED STATES					
5	10	Vehicle Identification Nur				Year	Model COROLLA				
0	0	5YFBU4EE8DP16722				2013					
	Color GRY - GRAY				Body Style Bus Use SD - SEDAN						
	☐ Initial Contact Point				Vehicle Damage			1			
⊨		01 - RIGHT FRONT CORNER			1 Sand Barrago					7 8 9 10 11	
	01 - RIGHT FRONT CORNER Extent Of Damage FUNCTIONAL DAMAGE			01 - RIG	01 - RIGHT FRONT CORNER		R			6 2 2 2 12	
_									5 4 3 2 1		

6TL0DRXHK1

23-12703

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/26/2023

Crash Time 07:32 AM

		Towed Due To Damage		Vehicle Removed By					
		TOWED DUE TO DISABLING DAMAGE		CRAIGS TOWING					
		What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors					
				Verlicle Factors					
				NOT APPLICABLE					
		Driver Prior Action Other		NOT ALL LIOADEL					
		Duiven Astions							
		Driver Actions	DAN OEE BOADWAY						
_	Щ	SPEED TOO FAST/COND	, RAN OFF ROADWAY						
Ę	$\overline{\mathbf{c}}$								
UNIT	VEHICLE								
	VE								
		Owner Name		Owner Address					
_		JANE LUKASZEWICZ		3 CEDAR TRL WISCONSIN DELLS, WI 53965 , US					
6	01	(847) 897-8183							
		Sequence Of Events							
		Event							
	01	DITCH							
		Event							
	02	OTHER POST, POLE OR	SUPPORT						
	~	Event							
	03								
	+	Event							
	04								
		Policy Holder							
LIND		Insurance Company		Individual					
É		STATE-FARM-GENERAL	-INS-CO	JANE LUKASZEWICZ					
			-1110-00						
	ı	ndividual							
	INDIVIDUAL	JANE LUKASZEWICZ (847) 897-8183		Citations Issued					
				0 FEMALE Date of Birth Race WHITE					
╘	<u>ا</u>								
L	2	Address		Driver License Number					
	불				STATE: WISCONSIN COUNTRY: UNITED STATES				
	_	3 CEDAR TRL WISCONSIN DELLS WIE	53965 IIS	STATE: WISCONS	SIN COUNTRY: UN	ITED STATES			
	=	3 CEDAR TRL WISCONSIN DELLS, WI	53965 , US	STATE: WISCONS	SIN COUNTRY: UN	ITED STATES			
	=	WISCONSIN DELLS, WI			SIN COUNTRY: UN	ITED STATES			
		WISCONSIN DELLS, WI		STATE: WISCONS Safety Equipment	SIN COUNTRY: UN	ITED STATES			
		WISCONSIN DELLS, WISCON	y Crash	Safety Equipment		ITED STATES			
		WISCONSIN DELLS, WISCON	y Crash Seat Position			ITED STATES			
		Fety Equipment Row 01 - FRONT ROW	y Crash	Safety Equipment SHOULDER & LA		ITED STATES			
		WISCONSIN DELLS, WISCON	y Crash Seat Position	Safety Equipment		ITED STATES			
		Fety Equipment Row 01 - FRONT ROW Helmet Use	y Crash Seat Position	Safety Equipment SHOULDER & LA Helmet Compliance		ITED STATES			
		Fety Equipment Row 01 - FRONT ROW	y Crash Seat Position	Safety Equipment SHOULDER & LA		ITED STATES			
	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection	Seat Position 07 - LEFT	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance		ITED STATES			
01	Sat	Row 01 - FRONT ROW Helmet Use Injury S	Seat Position 07 - LEFT	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag	P BELT	ITED STATES			
01		Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury S NO AF	Seat Position 07 - LEFT everity PARENT INJURY	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance	P BELT				
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury S NO AF	Seat Position 07 - LEFT everity PARENT INJURY Ejection Path	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED	P BELT	Trapped/Extricated			
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED	Seat Position 07 - LEFT everity PARENT INJURY	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE	P BELT	Trapped/Extricated NOT TRAPPED			
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport	Seat Position 07 - LEFT everity PARENT INJURY Ejection Path	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED	P BELT	Trapped/Extricated			
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED	Seat Position 07 - LEFT everity PARENT INJURY Ejection Path	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identified	P BELT	Trapped/Extricated NOT TRAPPED EMS Run #			
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport	Seat Position 07 - LEFT everity PARENT INJURY Ejection Path	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE	P BELT	Trapped/Extricated NOT TRAPPED			
01	Sat	Fety Equipment Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT everity PPARENT INJURY Ejection Path NOT EJECTED/NOT AP	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identified	P BELT	Trapped/Extricated NOT TRAPPED EMS Run #			
01	Sat	Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT everity PPARENT INJURY Ejection Path NOT EJECTED/NOT AP	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identified Date of Death	P BELT	Trapped/Extricated NOT TRAPPED EMS Run #			
01	Sat	Row 01 - FRONT ROW Helmet Use Eye Protection Injury NO AF Ejected NOT EJECTED Medical Transport NOT TRANSPORTED Hospital	Seat Position 07 - LEFT everity PPARENT INJURY Ejection Path NOT EJECTED/NOT AP	Safety Equipment SHOULDER & LA Helmet Compliance Tint Compliance Airbag NON DEPLOYED PLICABLE EMS Agency Identified Date of Death	P BELT	Trapped/Extricated NOT TRAPPED EMS Run #			

6TL0DRXHK1 23-12703

WISCONSIN MOTOR VEHICLE CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

Crash Date 11/26/2023

Crash Time 07:32 AM

		Non Motorist Striking Unit #	Location				
		Prior Action					
LIND	INDIVIDUAL	Action					
		Action Other					To/From School
	ı	Drug & Alcohol NO	ol Use	Suspected Drug Use NO			
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	е		Alcohol Test Results	
		Drug Test Given TEST NOT GIVEN	Drug Test Type		Drug Test Results	3	
6	001	Drug Type					
		Individual Condition					
		APPEARED NORMAL					