## 6TL0D2XVRF

23-13129

## WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

	Document Number Override	Primary Crash Docu	ment #	Agency 23-13	r Crash Number <b>129</b>		Investigating Officer/Deputy DEPUTY B. GOODREAU			
RF	Crash Date 12/07/2023	Crash Time 09:31 PM		Date Arrived 12/07/2023		Time Arrived 09:45 PM				
6TL0D2XVRF	Date Notified 12/07/2023	Time Notified 09:33 PM		Total U <b>01</b>	Total Units <b>01</b>		Total Injured Total Kil		lled	
OD:	On Emergency	t and Run		ure 🗌 Work Zone		Traile	Trailer or Towed		Reporting Threshold	
6TL	Government Property	Active Schoo	l Zone	School NO	Bus Related	Tags				
	✓ Reportable	Crash Type DT4000 (STANDA	ARD CRASH	H)		Amen	ded		Secondary Crash	
	Description									
	Diagram	Ableman Rd					Photo		By TY SHERIFF	
						F	Additi REC	ional Inforn ONSTRU	nation JCTION	
			1001 ×	<u>}</u>	HWY 136					
	ITEMS AND UNITS NOT SCALE APROX. SQUENCE OF EVENT BG9113.									
	✓ I, a sworn law enforcement	nt officer, agree th	nat I have n	ot addee	d any CJIS data in ti	his report.	1			
	UNIT 1 WAS TRAVELING EB ON HV WAY OF A DEER AND CRASHED IN						I RD, SH	HE HAD TO	) SWERVE OUT OF THE	

23-13129

## WISCONSIN MOTOR VEHICLE CRASH REPORT

#### SAUK COUNTY SHERIFFS DEPARTMEN 1300 LANGE COURT BARABOO, WI 53913 (608) 356-4895

		ation								
	ON ABLEMAN RD								Longitu	de
	65 FT N					43.490555	5639		-89.923	3762745
	OF RIVER ST/ STH136 EB IN THE TOWN OF EXCELSIOR IN SAUK COUNTY					X Coordinate		Y Coord	linate	
						263587.96875 4819		481944	46	
							уре			
L			NO STRU	CTURE						
C	Cra	sh Scene 📃								
Γ	First	Harmful Event				First Harmf	ul Event l	ocation		
							WAY			
	Man	ner of Collision				Light Condition DARK/UNLIT				
	00 -	NO COLLISION W/VE	HICLE IN TRANSPORT							
	Road	d Surface Condition(s)					Roadway Factor(s)			
	DR۱	r								
F	Envi	ronment Factor(s)								
	NO	NE								
F	Wea	ther Condition(s)								
	CLE	EAR								
ŀ	Anim	nal Type				Relation To	Trafficwa	ау		
					TRAFFICWAY - ON ROAD					
		h Classification - Location				Crash Classification - Jurisdiction NO SPECIAL JURISDICTION				
-	Triba	al Land						Special Study		
	Within Interchange Area     Junction Location     Intersecti       YES     INTERSECTION     T-INTER						ROL	L		
						ion Type RSECTION				
					T-INTERS	SECTION				
	أما		MTEROEOTION		T-INTERS	SECTION				
L		t Summary		Vehicle One						
l	Unit	t Summary			erating As Cl			Unit Type	SII F	
	Unit IN T	t Summary Status		Vehicle Ope D CLASS	erating As Cl			AUTOMO		ments
	Unit <b>IN T</b> Vehi	t Summary			erating As Cl					ments
	Unit IN T Vehi PAS	t Summary Status RANSIT cle Type	Train/Bus # Recorded	D CLASS	erating As Cl	assification	Total Tra	AUTOMOI Operating A	s Endorse	ments zMat Types
	Unit IN T Vehi PAS	t Summary Status RANSIT ICIE Type SSENGER CAR		D CLASS	erating As Cl	assification	Total Tra 0	AUTOMOI Operating A	s Endorse	
	Unit IN T Vehi PAS Tota 1	t Summary Status RANSIT ICIE Type SSENGER CAR		D CLASS	erating As Cl tions Issued	assification		AUTOMOI Operating A ilers	s Endorse Total Haz	zMat Types
	Unit IN T Vehi PAS Tota 1 Insu	t Summary Status RANSIT Icle Type SSENGER CAR I Occs	Train/Bus # Recorded	D CLASS	erating As Cl	assification	0	AUTOMOI Operating A ilers	s Endorse Total Haz <b>0</b>	zMat Types
	Unit IN T Vehi PAS Tota 1 Insur UNI	t Summary Status RANSIT Icle Type SSENGER CAR I Occs rance?	Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency	s Endorse Total Haz <b>0</b> Total Lan <b>2</b> Motor Veh	zMat Types es icle Use
	Unit IN T Vehi PAS Tota 1 Insur UNI	t Summary Status RANSIT ICLE Type SSENGER CAR I Occs rance? KNOWN t Harmful Event: Collision N	Train/Bus # Recorded Direction Of Travel EASTBOUND	D CLASS	tions Issued CrashTire Mark	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers	s Endorse Total Haz <b>0</b> Total Lan <b>2</b> Motor Veh	zMat Types es icle Use
	Unit IN T Vehi PAS Tota 1 Insur UNF Most DIT Traff	t Summary Status RANSIT ICLE Type SSENGER CAR I Occs I Occs I Cocs I Annote Collision I CH Ific Way	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Diction CIAL FUNC	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insu UNF Most DIT Traff	t Summary Status RANSIT ICLE Type SSENGER CAR I Occs I Occs I Annote Content of the content of t	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark inction CiAL FUNC	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE ol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insur UNF DIT Traff Two Surfa	t Summary Status RANSIT Cole Type SSENGER CAR OCCS rance? KNOWN t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction IAL FUNC trol ROL ature	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE ol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota Insur UNI Most DIT Traff TW( Surfa	t Summary Status RANSIT Cele Type SSENGER CAR OCCS Trance? KNOWN t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS)	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction IAL FUNC trol ROL ature	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE ol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota Insur UNI Most DIT Traff TW( Surfa	t Summary Status RANSIT Cole Type SSENGER CAR OCCS rance? KNOWN t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction IAL FUNC trol ROL ature	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE ol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DIT Traff Tw( Surfa BLA Truc NO	t Summary Status RANSIT Cele Type SSENGER CAR OCCS Trance? KNOWN t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS)	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction IAL FUNC trol ROL ature	assification	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	s Endorse Total Haz 0 Total Lan 2 Motor Veh LICABLE ol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DIT Traff Tw( Surfa BLA Truc NO	t Summary Status TRANSIT Cole Type SSENGER CAR OCCS Trance? KNOWN t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat	Train/Bus # Recorded Direction Of Travel EASTBOUND With	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC Trol ROL ature T	TION	<b>0</b> Speed Li	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade	s Endorse Total Haz O Total Lan 2 Motor Veh ICABLE rol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DIT Traff Tw( Surfa BLA Truc NO	t Summary Status TRANSIT Cele Type SSENGER CAR OCCS Trance? KNOWN t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AVL6243	Train/Bus # Recorded Direction Of Travel EASTBOUND With S)	D CLASS	tions Issued CrashTire Mark Inction CIAL FUNC Trol ROL ature T	TION	0 Speed Li 55 St St WI	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL	s Endorse Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insur UNI Most DIT Traff TWC Surfa BLA Truc	t Summary Status TRANSIT Cele Type SSENGER CAR OCCS Trance? KNOWN t Harmful Event: Collision N CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AVL6243 Vehicle Identification Nur	Train/Bus # Recorded Direction Of Travel EASTBOUND With S S)	D CLASS	tions Issued CrashTire Mark inction IAL FUNC trol ROL ature T	E I	0 Speed Li 55 St St WI Year	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model	s Endorse Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insui UNI Most DIT Traff TW( Surfa Surfa BLA Truc NO	t Summary Status TRANSIT CICLE Type SSENGER CAR I OCCS Trance? KNOWN T Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AVL6243 Vehicle Identification Nur 2G1WC58146924017	Train/Bus # Recorded Direction Of Travel EASTBOUND With S) S)	D CLASS	tions Issued CrashTire Mark notion ClAL FUNC trol rrol ROL ature T	E I	0 Speed Li 55 St St WI	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA	s Endorse Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insur UNI Most DIT Traff TWC Surfa BLA Truc	t Summary Status TRANSIT Cele Type SSENGER CAR OCCS Trance? KNOWN t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AVL6243 Vehicle Identification Nur 2G1WC58146924017 Color	Train/Bus # Recorded Direction Of Travel EASTBOUND With S) S)	D CLASS	tions Issued CrashTire Mark notion IAL FUNC trol ROL ature T	E I	0 Speed Li 55 St St WI Year	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model	s Endorse Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insu UNI Most DITO Traff Truc Surfa Surfa	t Summary Status TRANSIT Cicle Type SSENGER CAR I Occs Trance? KNOWN t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AVL6243 Vehicle Identification Nur 2G1WC58146924017 Color RED - RED	Train/Bus # Recorded Direction Of Travel EASTBOUND With S) S)	D CLASS	tions Issued CrashTire Mark ICCION IAL FUNC ITOI ROL ature T JTOMOBIL	E I	0 Speed Li 55 St St WI Year	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA	s Endorse Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insu UNI Most DITO Traff Truc NO	t Summary Status TRANSIT Cicle Type SSENGER CAR I Occs Trance? KNOWN t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AVL6243 Vehicle Identification Nur 2G1WC58146924017 Color RED - RED Initial Contact Point	Train/Bus # Recorded Direction Of Travel EASTBOUND With S) S)	D CLASS	tions Issued CrashTire Mark ICCION IAL FUNC ITOI ROL ature T JTOMOBIL	E I	0 Speed Li 55 St St WI Year	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA	s Endorse Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types les icle Use
	Unit IN T Vehi PAS Tota 1 Insu UNI Most DITO Traff Truc Surfa Surfa	t Summary Status TRANSIT Cicle Type SSENGER CAR I Occs Trance? KNOWN t Harmful Event: Collision V CH fic Way D-WAY, NOT DIVIDED ace Type ACKTOP (BITUMINOUS k Bus or HazMat Vehicle License Plate Number AVL6243 Vehicle Identification Nur 2G1WC58146924017 Color RED - RED	Train/Bus # Recorded Direction Of Travel EASTBOUND With S) S)	D CLASS	tions Issued CrashTire Mark Inction IAL FUNC Trol ROL ature T UTOMOBIL DLET DLET DAN amage	E 2	0 Speed Li 55 St WI Year 2006	AUTOMOI Operating A illers mit Emergency NOT APPI Traffic Cont NO Road Grade LEVEL Country of Is UNITED ST Model IMPALA	s Endorse Total Haz 0 Total Lan 2 Motor Veh ICABLE Tol Inopera	Mat Types es icle Use tive/Missing

### 6TL0D2XVRF

23-13129

## WISCONSIN MOTOR VEHICLE CRASH REPORT

		Towed Due To Damage		V	ehicle Removed By				
		NOT TOWED		C	PERATOR				
		What Driver Was Doing		V	Vehicle Factors				
	LEFT TURN								
		Driver Prior Action Other		N	NOT APPLICABLE				
UNIT	VEHICLE	Driver Actions EXCEED SPEED LIMIT, FAI	LURE TO	D CONTROL, RAI	N OFF ROADWAY				
01	01	Owner Name MCCOY MARTIN GEORGES	SON		Owner Address S3884 MOUNTAIN BARABOO, WI 53				
	ļ	Sequence Of Events							
	01	Event MOTOR VEH TRAN OTHER	RDWY						
	02	Event DITCH							
	03	Event							
	04	Event							
	l	Individual							
	١L	Driver MELINDA GEORGESON			Citations Issued <b>1</b>	Sex FEMALE	EMALE		
E	DUA				Date of Birth	Race WHITE			
UNIT	INDIVIDUAL	Address 2047 VIKING DR REEDSBURG, WI 53959 , US			Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES				
	Sat	On Duty Crash fety Equipment			Safety Equipment				
		Row 01 - FRONT ROW	Seat Position <b>07 - LEFT</b>		SHOULDER & LAP BELT				
		Helmet Use		Helmet Compliance					
		Eye Protection			Tint Compliance				
01	001				Airbag				
0	õ	Injury NO APPA			DEPLOYED-FRONT	T			
			jection Pa	<sup>th</sup> CTED/NOT APPL	ICABLE		Trapped/Extricated NOT TRAPPED		
		Medical Transport			EMS Agency Identifier		EMS Run #		
		NOT TRANSPORTED							
		Hospital			Date of Death Time o		Time of Death		
		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)							
		Distracted By Action NOT DISTRACTED							
		Non Motorist	it #	Location					

### 6TL0D2XVRF

23-13129

# WISCONSIN MOTOR VEHICLE CRASH REPORT

		Prior Action						
		Action						
	_							
L	NΑ							
UNIT								
	INDIVIDUAL							
	Z							
		Action Other						To/From School
			Suggested Ales	halllaa	Supported Drug Line			
	L	Drug & Alcohol	Suspected Alco YES	noruse	Suspected Drug Use			
		Alcohol Test Given		Alcohol Test Type			Alcohol Test Results	
		TEST GIVEN			BREATH TEST (PBT)		04	
		Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	;	
0	001	Drug Type						
	0							
		Individual Condition						
		UNDER THE INFLU	UENCE OF MI	EDICATIONS/DRUGS	ALCOHOL			
		Violations						
	01	UTC Number BG024655	Issue To? 001	Statute Number <b>346.57(2)</b>	Description FAILURE TO KEEP			
		-	I					