

6TL0D2XVRN
24-00453

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SAUK COUNTY SHERIFFS DEPARTMENT
1300 LANGE COURT
BARABOO, WI 53913
(608) 356-4895

Location

ON STH23 EB 53 FT W OF SIMPSON RD IN THE TOWN OF EXCELSIOR IN SAUK COUNTY	Latitude 43.547359615	Longitude -89.887258949
	X Coordinate 266758.875	Y Coordinate 4825651.5
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event DITCH	First Harmful Event Location ON ROADWAY	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/UNLIT	
Road Surface Condition(s) WET, SNOW, SLUSH	Roadway Factor(s) NONE	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW, SLEET/HAIL, SEVERE WINDS		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 55	Total Lanes 2
	Most Harmful Event: Collision With DITCH	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	License Plate Number ATM4013	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 2FMGK5CC4BBD11469	Make FORD	Year 2011	Model FLEX	
		Color SIL - SILVER (ALUMINUM)	Body Style UT - SPORT UTILITY VEHICLE		Bus Use	
		Initial Contact Point 00 - NON-COLLISION	Vehicle Damage			
		Extent Of Damage NO DAMAGE	00 - NO DAMAGE			



WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By CRAIGS TOWING		
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions SPEED TOO FAST/COND				
01	01	Owner Name SAMMY PAMIAS MATOS		Owner Address 535 N MAIN ST # 5 ADAMS, WI 53910 , US	
		Sequence Of Events			
UNIT	01	Event MOTOR VEH IN TRANSPORT			
		Event DITCH			
		Event			
		Event			
UNIT	01	Policy Holder			
		Insurance Company ALLSTATE-INS-CO	Individual SAMMY PAMIAS MATOS		
UNIT	01	Individual			
		Driver SAMMY PAMIAS MATOS	Citations Issued 0	Sex MALE	
			Date of Birth	Race HISPANIC	
		Address 535 N MAIN ST # 5 ADAMS, WI 53910 , US	Driver License Number		
UNIT	01	Safety Equipment		On Duty Crash	
				Safety Equipment	
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
		Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance			
UNIT	001	Injury		Airbag	
		Injury Severity NO APPARENT INJURY		NON DEPLOYED	
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED	
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #
Hospital		Date of Death	Time of Death		
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action		NOT DISTRACTED			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location	
		Prior Action				
		Action				
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
	Drug Type					
	Individual Condition APPEARED NORMAL					
	01	001				